

ASS. REC'D BY

RECS3/III19007584/Ucd302

Special Instruction

SALES/STAFF  
MUMEN

MARKUS

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of III

Date/Time: 2/4/19 @ 5:18pm

Estimated Cost:

Bill to:

OD / TT / WS / TT RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No:

SJU 8567A

Insured:

SHA 72434

at Workshop n/a

Power Autocare

Tel:

8181 2212

of 1 Kaki Bkt Rd 6 # 02-11 Autobay

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh  
(Client's Record)

D.O.A. 26/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 9:36am @ 30/4/19

Person Contacted: Gung

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJU 8567A - X
	SHA 72434 - CS/IN209005525/Yng!
	After repair: 2/5/2019 1132am
	D.O.A. 11/3/2019

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: *SJU 8567A*  
 at Workshop m/s *Power Plus Care.*  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: *SJU 8567A* Yr Regn: *31/12 09*  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *CM /*  
 Make: *Honda Jazz* c.c. *1339*  
 Colour: *Black* A/C: Insured / Std / NI / NA  
 Sp. Reading: *268/18* T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *MRHGE 67509P 0208-7*  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: *185/55R16*  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S
	<i>0</i>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm R/Bal. 6 mm  
 D.O.A. *26/4/19* D.O.I. *30/4/19* *10:50 AM*  
 Survey held at \_\_\_\_\_

Bal. or Market Value: *13k.*  
 IDAC Accident Rpt: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS *2709w*  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or  
*Rear o/s.*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>L1A 8625 Ind.</i>
<i>29/5/19</i>	<i>NO settlement. pass lawyer check with Repair activity.</i>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: 1  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_) ) S + RS SI  
 : Interview (\$ \_\_\_\_\_) ) Photos  
 : Tech. Invs (\$ \_\_\_\_\_) ) Others  
 : Weekend (\$ \_\_\_\_\_) )  
 Report Format : PRC  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)  
 TOTAL \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		30 Apr 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

[Main](#)   
 [Reference](#)   
 [Claim Details](#)   
 [Documents](#)   
 [Show All](#)

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:			
Main Claimant:	GREEN FOREST TRANSPORT, Co. Reg. No.: 53372709W		
Vehicle Reg. No.:	SJU8567A	Date of Loss:	26/04/2019 11:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA7243U	Policy No. (Claimant):	
		Excess:	
Repairer:	Power Autocare (HQ) 1 Kaki Bukit Ave 6, #02-11 Kai Bukit @ Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/05/2019]		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Monday, 29 April 2019 5:18 PM  
**To:** Wendy Jiang; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Natalie Ng; Sundari Nagarajan - III  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJU8567A (Accident involving SJU8567A and SHA7243U on 26.04.2019)  
**Attachments:** sha7243u\_20190429143211.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SJU8567A  
III INSURED VEHICLE NO. : SHA7243U  
DATE OF LOSS : 26.04.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Wendy Jiang [mailto:wendy\_jiang@rssolomon.com]  
**Sent:** 29 April, 2019 4:22 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Natalie Ng <natalie\_ng@rssolomon.com>  
**Subject:** Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJU8567A (Accident involving SJU8567A and SHA7243U on 26.04.2019)

Dear Gabriel,

We refer to your email of even date.

We write to inform that our clients will be appointing their Surveyors.

In this respect, please arrange your surveyors to contact Mr. Gary Chen of Power Auto Care at mobile no. 8181 2212 for a pre-repair survey of our client's vehicle located at 1 Kaki Bukit Road 6 #02-11 Autobay @ Kaki Bukit Singapore 417883.

Thank you and Best Regards

Yours sincerely  
Wendy Jiang | Legal Executive

**R. S. Solomon LLC | 正氣律師事務所**

**Advocates & Solicitors | Commissioner for Oaths**

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e [wendy\\_jiang@rssolomon.com](mailto:wendy_jiang@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

---

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Mon, Apr 29, 2019 at 2:46 PM Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Our Ref. : RSS/1904-7219(PAC)(PD)  
Your Ref. :

W: Wendy Jiang  
E : wendy\_jiang@rssolomon.com

26 April 2019

**India International Insurance Pte Ltd**  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Kind Attn: Motor Claim Dept



R. S. SOLOMON LLC  
ADVOCATES & SOLICITORS

By Fax: [6224 4174]  
& PDX: [8172]

Dear Sirs,

**PRE-REPAIR SURVEY  
ACCIDENT INVOLVING SJU8567A & SHA7243U ON 26<sup>TH</sup> APRIL 2019 AT ABOUT 1155  
HRS**

We act for the owners ("our Clients") of vehicle no. SJU8567A.

2. We hereby notify you of a road traffic accident on 26<sup>th</sup> April 2019 at about 1155 hours at JEM drop off point involving our Client's vehicle and vehicle registration no. SHA7243U driven by your insured/insured's driver. A copy of our Clients' Accident Statement is enclosed.
3. As a result of the accident, our Clients' vehicle has been damaged. Before our Clients proceed to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Clients shall proceed to repair their vehicle without further reference to you.

Yours faithfully,

**R. S. SOLOMON LLC**  
ADVOCATES & SOLICITORS

ENCL



**> Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	2709W
<b>Vehicle Details</b>	
Vehicle No.:	SJU8567A
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ GLI 1.3 M
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	L13Z11705634
Chassis No.:	MRHGE67509P020857
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,988.00
Original Registration Date:	31 Dec 2009
First Registration Date:	31 Dec 2009
Transfer Count:	3
Actual ARF Paid:	\$14,988.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2019
PARF Rebate Amount:	\$7,494.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$1,141.00
<b>Total Rebate Amount:</b>	<b>\$8,635.00</b>

The information contained herein is correct as at 30 Apr 2019

OK

**SELL YOUR CAR YOURSELF**  
Get listed until it's sold + we will handle all the paperwork!

**POST AN AD NOW!**

jazz Price Range Depreciation 2009 Vehicle Type Submit Advanced Search

Home » Used Cars » Lei Fu Trading Co. » Honda Jazz 1.3A L

Honda Jazz 1.3A L

Overview Financial Insurance Accessories Similar Research Photos Map

<b>Price</b>	\$16,800	<b>Reg Date</b>	06-Oct-2009 (5mths 5days COE left)
<b>Depreciation</b>	N.A.	<b>Manufactured</b>	2008
<b>Mileage</b>	N.A.	<b>Transmission</b>	Auto
<b>Road Tax</b>	\$590 /yr	<b>OMV</b>	\$20,547
<b>Dereg Value</b>	\$10,948 as of today (change)	<b>ARF</b>	\$20,547
<b>COE</b>	\$15,589	<b>Power</b>	73.0 kW (97 bhp)
<b>Engine Cap</b>	1,339 cc	<b>No. of Owners</b>	4
<b>Curb Weight</b>	1,060 kg		
<b>Type of Vehicle</b>	Hatchback		



Shortlist Compare Add note  
Report Error More Actions

**Features**

1.3L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Paddle Shifters, Reverse Sensors, Knockdown Rear Seats. View specs of the Honda Jazz (2008-2014)

**Accessories**

Sports Rims, Leather Seats, Factory Fitted Audio, Reverse Sensors, Retractable Mirrors With Signal Indicators.

**Description**

Selling Cheap! Very Well Maintained Unit, Sporty And Sleek Looking. Road Tax Till Oct 2019. No Repair Needed. Trade In Welcomed, Do Call For A Viewing Appointment Today.

**Category**

PARF Car

**Status**

Available

**Resources**

**Car Valuation - Free**  
Find out the market value of your existing car for free. Get started

**Vehicle Evaluation**  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Seller Information**

<b>Company</b>	Lei Fu Trading Co. » dealer's pricelist » 24 vehs sold   9 vehs available	
<b>Address</b>	61 Ubi Avenue 2 #04-01 Search cars nearby this location	
<b>Location</b>	Automobile Megamart	
<b>Office No</b>	67469005	
<b>Contact Person(s)</b>	Tan	96942466
	Wee Beng	91040878

Posted on: 27-Apr-2019 | Last Updated on: 27-Apr-2019

Upfront Payment [» more Financial info](#)

Transfer Fee \$25

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

**Das WeltAuto.**  
Used cars you can trust. Guaranteed.

Low on mileage. High on savings.



jazz

Price Range ▾

Depreciation ▾

2009 ▾

Vehicle Type ▾



Home » Used Cars » Cycle & Carriage.Fulco Motor Dealer » Honda Jazz 1.3A L

## Honda Jazz 1.3A L

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



**Price** \$16,800

**Depreciation** ⓘ \$12,030 /yr  
View models with similar depre

**Reg Date** 17-Nov-2009  
(6mths 14days COE left)

**Mileage** 126,000 km (13.3k /yr)

**Manufactured** ⓘ 2008

**Road Tax** ⓘ \$590 /yr

**Transmission** Auto

**Dereg Value** ⓘ \$11,182 as of today (change)

**OMV** ⓘ \$20,547

**COE** ⓘ \$16,747

**ARF** ⓘ \$20,547

**Engine Cap** 1,339 cc

**Power** 73.0 kW (97 bhp)

**Curb Weight** ⓘ 1,060 kg

**No. of Owners** ⓘ 2

**Type of Vehicle** Hatchback

### Features

Responsive 1.3L I-VTEC Engine, Smooth 5 Speed CVT Transmissions, 2 SRS Airbags, ABS, Key Immobilizer, Knockdown Rear Seats! View specs of the Honda Jazz (2008-2014)

### Accessories

Paddle Shifter, Black Color Leather Upholstery, Solar Films, Reverse Sensors.


### Description

One Of The Lowest Mileage Unit. 100% Accident Free! No Repair Needed. No Hidden Fees! Free Servicing! Free Professional Grooming Upon Purchase! Call Now, Don't Miss!


### Category

PARF Car

Compare



### Price Chart



Click on the point to view

MS1116054100 / STA INSPECTION PTE LTD - Sin Ming  
 ENTRY DATE & TIME: 28/04/2019 15:45  
 SUBMITTED BY: Wong Lip Yong

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/04/2019 15:45
Date Of Accident	28/04/2019 11:55
Exact Location Of Accident	JEM DROP OFF POINT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU8567A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GREEN FROG TRANSPORT
Co Reg No	53372709W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-69006141
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095493383-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	WEE KEE TOON ADRIAN
NRIC No	S7613339E
Date Of Birth	04/04/1976
Occupation	OUTDOOR
Date Of Driving Pass	10/02/1995
Driving Experience	24 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93833081
Fax Number	
Contact Number	
EMail Address	ADRIANWEEKT@HOTMAIL.COM

Address	BLK 643 ANG MO KIO AVE 5 #08-3005
Postcode	560643
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SHA7243U
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	TAXI
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/04/2019 15:45
Date Of Accident	26/04/2019 11:55
Exact Location Of Accident	JEM DROP OFF POINT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJU8567A
Insured/Policyholder	
Name Of Registered Owner	GREEN FROG TRANSPORT
Co Reg No	53372709W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-69006141
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095493383-01
Cover Note Number	
Driver	
Name of Driver	WEE KEE TOON ADRIAN
NRIC No	S7613339E
Date Of Birth	04/04/1976
Occupation	OUTDOOR
Date Of Driving Pass	10/02/1995
Driving Experience	24 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93833081
Fax Number	
Contact Number	
EEmail Address	ADRIANWEEKT@HOTMAIL.COM

Address	BLK 643 ANG MO KIO AVE 5 #08-3005
Postcode	560643
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7243U
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	TAXI
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: 26/4/2019  
 1420




  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 26/4/2019  
 1420

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.: 72/4/19

# Jurong Gateway Road

SKETCH PLAN



A: SSU 8567A

B: SHA 7243U

JGM Drop off point / Taxi Stand

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the mentioned date & time, I am driving vehicle SSU 8567A along the driveway drop off point at JGM. When I stop to give way to oncoming traffic, I felt an impact and found a taxi SHA 7243U had collided onto my right rear bumper.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 26/4/2019

1420

*[Signature]* 26/4/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2019 <a href="#">Edit Reg</a>		29 Apr 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>GREEN FOREST TRANSPORT</b> , Co. Reg. No.: 53372709W								
Vehicle Reg. No.:	<b>SJU8567A</b>	Date of Loss:	26/04/2019 11:00 - :59 [111 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT19040735</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHA7243U</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Power Autocare (HQ)</b> 1 Kaki Bukit Ave 6, #02-11 Kai Bukit @ Autobay, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 10/05/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SJU8567A (MCT19040735)  
[SHA7243U]  
TP  
GREEN FOREST TRANSPORT  
Apr 26 2019 11:00AM  
[-]  
Power Autocare

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <span style="border: 1px solid black; padding: 2px;">View in Browser</span>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
2	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
3	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
4	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
5	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
6	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
7	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
8	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
9	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
10	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
11	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
12	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
13	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
14	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
15	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
16	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
17	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
18	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
19	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
20	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
21	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
22	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
23	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
24	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
25	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
26	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
27	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
28	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
29	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
30	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
31	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
32	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
33	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
34	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
35	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
36	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>
37	31/05/19 11:30	<b>General View</b>	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
39	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
40	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
41	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
42	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
43	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
44	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
45	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
46	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
47	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
48	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
49	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
50	31/05/19 11:30	General View	Load JPG	<input checked="" type="checkbox"/>
51	31/05/19 11:33	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	31/05/19 11:33	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	31/05/19 11:33	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	31/05/19 11:33	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	31/05/19 11:33	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	31/05/19 11:33	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 08:53	Singapore Accident Statement	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III19007584/JCD3E2  
**Date:** 10/06/2019

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
<b>Claimant Vehicle No :</b> SJU8567A	<b>Insured Vehicle No :</b>	SHA7243U	
Date of Loss: 26/04/2019	Nature of Claim:	TP	Claim No: MCT19040735

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJU8567A</b>	Engine No:	L13Z11705634
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	MRHGE67509P020857
Reg. Date:	31/12/2009 (Man. Year: 2009)	Odometer:	268118 km
Colour:	Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	29/04/2019	
Date Inspected:	30/04/2019	Inspected At: Power Autocare (HQ) 1 Kaki Bukit Ave 6, #02-11 Kai Bukit @ Autobay Singapore 417883
Estimated Period of Repair:	0.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2019)
<b>Parts:</b> 144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJU8567A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >