

CS3/CTI19007604/Bcd322

Mr Lim

ASSIGNMENT (Office)

ehong Boon Sen

CTI

Date/Time

30/4/19 @ 11:19 am

Estimated Cost

Bill to

OD (IT) WNT/TP RRS / OD RRS / EVA / INV / MYTC

To inspect Vehicle No

FT2884B

Insured

SJC 4701C

at Workshop no

Yuh Hong Motor

Tel

6288 0450

of

81k 10 Amk Ind. park 2 #05-38/37

Policy No

DMPCSN1224701806

Claim No

SNM 19D201834002

Sum Insured

Branch

Make of Vehicle

D.O.A.

29/04/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:56pm 30/4/19

Person Controlled

Steven

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

FT2884B-X

SJC 4701C-X

REF:

CT1

ASSIGNMENT

From:

Date: 30/4/19

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FT 2884B

at Workshop m/s

Yuh Loong Motor

of Blk 10 Ang Mo Kio Ind Park 2A #05-23

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FT 2884B

Yr Regn: 5/4/2001

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Jeep

C.C 150

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

Not readable

T/Radio: Insured / Std / NI / N

Eng/No:

VLXIM 879556

C/No:

251X2BAYK34074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 3.0 / 10

R: 3.0 / 10

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

L/Bal.

mm

L/Bal.

D.O.A.

24/4/19

D.O.I.

30/4/19

Survey held at

Yuh Loong Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Range 1600/2 - 2600/2

7/5/2019

3,800/2
MV 4500/2
PV 324/2
NV 4176/2
3,476/2

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Report Format :

PRS

Lump Sum / I.B.I. (\$))

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

150

Transportation:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

) S + RS. SI

) Photos

) Others

TOTAL

150

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 30 April 2019 11:19 AM
To: joycelyn@legaloptions.biz
Cc: assignments
Subject: RE: FW: OUR REF: SNM19D201834 / YOUR REF: 19-A31-10324-VL.TS.JS

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sir

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Joycelyn [mailto:joycelyn@legaloptions.biz]
Sent: Tuesday, 30 April, 2019 11:02 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: FW: OUR REF: SNM19D201834 / YOUR REF: 19-A31-10324-VL.TS.JS

Dear Sir,

Our client has rejected your list of surveyors.

We provide you herewith our client's list of surveyors: -

	Surveyor	Contact Person
1.	OH APPRAISAL SERVICES	OH HAN CHEONG
2.	PAR AUTOMOTIVE CONSULTANCY	B J LOI

3.	UNITED APPRASAL AND MANAGEMENT PTE LTD	MARC
4.	AUTO PERFORMANCE APPRAISAL	LEK BOON HWEE
5.	SINCERE APPRAISAL SERVICES	DAVE CHANG
6.	L H TEO	MR TEO
7.	PRO-OPTION SERVICES	LIAW CHEONG SAN

If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Please find the the venue for inspection as follows:-

M/s Yuh Loong Motor Company P/L

Blk 10 Ang Mo Kio Industrial Park 2, #05-38/37, S568047.

Person to contact : Steven - 6288 0450 (Please call to make appointment before going down)

Thanks n regards,

Joycelyn Sim

Legal Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2807 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

On Tue, Apr 30, 2019 at 10:58 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Tuesday, 30 April, 2019 10:53 AM

To: 'joycelyn@legalopttions.biz' <joycelyn@legalopttions.biz>

Subject: OUR REF: SNM19D201834 / YOUR REF: 19-A31-10324-VL.TS.JS

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4791C
Vehicle Details	
Vehicle No.:	FT2884B
Vehicle to be Exported:	No
Intended Deregistration Date:	07 May 2019
Vehicle Make:	VESPA
Vehicle Model:	EXCEL 150
Primary Colour:	Blue
Manufacturing Year:	2000
Engine No.:	VLX1M879556
Chassis No.:	MH2S1X2BAYK340749
Maximum Power Output:	-
Open Market Value:	\$2,340.00
Original Registration Date:	05 Apr 2001
First Registration Date:	05 Apr 2001
Transfer Count:	2
Actual ARF Paid:	\$351.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,711.00
COE Rebate Amount:	\$324.00
Total Rebate Amount:	\$324.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 07 May 2019

OK

[Post a New Comment](#)

Vespa

🕒 12 hours ago by sellinglah (/sellinglah)

💰 S\$5,500

♥️ 13 Likes

📦 Used

☰ In Class 2B (/categories/class-2b-1595)

📄 Vespa
COE - 2021
(Can renew for 10years)

[read more](#)

Make

Vespa

Type

Scooter

Insurance

Insure this vehicle with AXA. Premiums start from S\$206.28

BUY AXA
INSURANCE
NOW

Getting This

📍 Meet-up


Woodlands (<https://www.google.com/maps/place/1.4377383,103.78513>)

Meet The Seller



sellinglah (/sellinglah/)

Joined 2 years ago.

Verified 

Reviews

5.0 ★★★★★(1)

YOU MAY ALSO LIKE

Chat

Make Offer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2019 13:24
Date Of Accident	24/04/2019 11:15
Exact Location Of Accident	FROM SUNGEI RD TO ROCHOR CANAL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FT2884B
Insured/Policyholder	
Name Of Registered Owner	KOH LIANG SENG
NRIC No	S0834791C
Email Address	RAYMONDKOH@ERA.COM.SG
Mobile Phone No	(LOCAL) +65-94759981
Alternative Phone No	Others-94759981

Vehicle Particulars

Manufacturer	VESPA
Model	EXCEL 150
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5070786752-04
Cover Note Number	

Driver

Name of Driver	KOH LIANG SENG
NRIC No	S0834791C
Date Of Birth	09/12/1943
Occupation	OUTDOOR
Date Of Driving Pass	10/02/1964
Driving Experience	55 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94759981

Fax Number	
Contact Number	OTHERS-94759981
EMail Address	RAYMONDKOH@ERA.COM.SG
Address	BLK 224 SERANGOON AVENUE 4 #04-157
Postcode	550224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO: T/20190426/2053. WILL REPAIR & CLAIM AT YUH LOONG MOTOR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC4701C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KOH LIANG SENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FT2884B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 29-4-2019

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached Police report.

Will repair and claim at Yuh Keng Motor Co.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 29-4-2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE POLICE FORCE

one - (new) green motor

01-15/16/17



T/20190426/2053

1 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20190426/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/04/2019 14:18	Video Report No.:	Station Diary No.: 30
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: KOH LIANG SENG			Address: APT BLK 224 SERANGOON AVENUE 4 #04-157 SINGAPORE 550224	
ID Type / ID No.: NRIC NO / S0834791C			Contact No.: Home/Office:	Mobile: 94759981
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 75	Date of Birth: 09/12/1943	Type of Informant: Rider	
Race: Chinese			Language:	Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/04/2019 11:15	Type of Location: Bend
Location: Along Road 1 SUNGEI ROAD ROCHOR CANAL ROAD FROM SUNGEI ROAD TO ROCHOR CANAL ROAD AT THE U-TURN STOP INFRONT OF SIM LIM SQUARE				
Weather: Sunny		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FT2884B	Motorcycle	VESPA	EXCEL 150	Blue		0
SJC4701C	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FT2884B	NTUC Income Insurance Co-Operative Limited	5070786752-04	05/04/2019	04/04/2020



**SINGAPORE
POLICE FORCE**



T/20190426/2053

2 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20190426/2053

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	KOH LIANG SENG	ID No.	S0834791C
Related Vehicle	FT2884B (Motorcycle)	Contact No.	94759981
Hospital/Clinic	HOUGANG POLYCLINIC	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	26/04/2019	Date Discharge	26/04/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 24/04/2019 at 1115hrs, I was riding my vehicle FT2884B along Sungei Road towards Rochor Canal Road. I stopped at the U-Turn stop in front of Sim Lim Square as the traffic was heavy along Rochor Canal towards Bukit Timah Road.

As I find it safe to make a U-Turn, vehicle SJC4701C collided onto the rear of my bike. I did not fall from my vehicle as I withstand the impact. My left leg was swollen, my right hips hurt and my whole body is aching after the impact.

The owner of the vehicle was Kumar, HP:96915661, who informed me that he will not be paying for the damages of my vehicle and told me to lodge a police report and informed that he will be reporting this matter to his insurance. That is all.



**SINGAPORE
POLICE FORCE**



T/20190426/2053

3 of 3

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20190426/2053


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 MUHAMMAD ALIF RIDHWAN BIN BAHARIN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AET / Sgt 2 GEAK ENG CECILIA SN 154 Contact No.: 65476404 Stamp: NP168 Singapore Police Force

Signature Of Informant: 
Date/Time: 26/04/2019 14:18
Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Apr 2019		30 Apr 2019 16:40 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	KOH LIANG SENG , ID: S0834791C								
Vehicle Reg. No.:	FT2884B	Date of Loss:	24/04/2019 11:00 - :59 [216 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201834C02	Policy/Cover Note No.:	DMPCSN1224701806						
Vehicle Reg. No. (Insured):	SJL4701C	Policy No. (Claimant):	5070786752-04						
		Excess:	S\$0.00						
Repairer:	Yuh Loong Motor Company Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #05-37/38 AMK Autopoint, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 10/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FT2884B (SNM19D201834C02)

[SJL4701C]




























TP

KOH LIANG SENG













Apr 24 2019 11:00AM

[-]

Yuh Loong Motor Company Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	29/04/19 14:28	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	29/04/19 13:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	29/04/19 13:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	29/04/19 13:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	29/04/19 13:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	29/04/19 13:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	29/04/19 13:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/06/19 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/04/19 16:41	PRI CONTACT	 Load PDF	
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	29/04/19 14:12	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	29/04/19 14:12	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	29/04/19 14:12	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	29/04/19 14:12	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	29/04/19 14:12	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser			
Assessment Reports			
			1 per page <input type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail Print
1	29/04/19 14:28	Accident Statement	 Load HTM <input type="checkbox"/>
Photos/Images			
			3 per page <input type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail Print
1	29/04/19 13:33	Accident Photo	 Load JPG <input type="checkbox"/>
2	29/04/19 13:33	Accident Photo	 Load JPG <input type="checkbox"/>
3	29/04/19 13:33	Accident Photo	 Load JPG <input type="checkbox"/>
4	29/04/19 13:33	Accident Photo	 Load JPG <input type="checkbox"/>
5	29/04/19 13:33	Accident Photo	 Load JPG <input type="checkbox"/>
6	29/04/19 13:33	Accident Photo	 Load JPG <input type="checkbox"/>
Documentation			
			1 per page <input type="checkbox"/>
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail Print
1	29/04/19 14:12	Sketch Plan	 Load JPG <input type="checkbox"/>
2	29/04/19 14:12	Sketch Plan #2	 Load JPG <input type="checkbox"/>
3	29/04/19 14:12	Sketch Plan #3	 Load JPG <input type="checkbox"/>
4	29/04/19 14:12	Sketch Plan #4	 Load JPG <input type="checkbox"/>
5	29/04/19 14:12	Sketch Plan #5	 Load JPG <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19007604/BCD3E2

Date: 25/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1224701806

Claimant Vehicle
No : FT2884BInsured Vehicle
No : SJL4701C

Date of Loss: 24/04/2019

Nature of Claim: TP

Claim
No: SNM19D201834C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FT2884B

Make & Model: VESPA EXCEL, 150cc 150 (A)

Reg. Date: 05/04/2001 (Man. Year: 2000)

Colour: Blue

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: VLX1M879556

Chassis No: MH2S1X2BAYK340749

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 3.0/10

Rear Tyre Size: 3.0/10

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/04/2019

Date Inspected: 30/04/2019 Inspected At:

Yuh Loong Motor Company Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #05-
37/38 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,600.00 - \$2,600.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jun 2019)	
Parts:	N/A	VESPA EXCEL 150cc 150 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FT2884B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >