



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD	Ref : CC4/ASM19007606/R1ga3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811	Date : 30-08-2019
ATTN: LYNN KHONG	Code : ASM



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SMA 6066L	<b>Veh. Inspected</b>	SLH 30D
<b>Policy No.</b>	GA396012/1	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M01LU3	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	LYNN KHONG	<b>Assign Date</b>	30/04/2019

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HONDA VEZEL 1.5X CVT	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	RU11209067	<b>Colour</b>	GREY
<b>Odometer</b>	057304	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	DUNLOP	6 mm
<b>L/H Front Tyre</b>	215/60 R16	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	215/60 R16	DUNLOP	6 mm
<b>L/H Rear Tyre</b>	215/60 R16	DUNLOP	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	28/04/2019	<b>Inspection Date</b>	09/05/2019
<b>Survey held at</b>	TTS EUROCARS PTE LTD 383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**