

Version

INSURANCE OWNER

CC 4 / III 1900

7615, R2 9/13/19

LINK

IDAC

Surveyor:

MRB

DOI:

ASSIGNMENT

2/9/19

Date / Time:

20/4/19

Registered in Merimen

20/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.

SHA 46344

Name of Insured

CPPL

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

25/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.

M719140724

Policy No.

M8M0015

Make / Model:

Hyundai

Place of Accident:

COMMONWEALTH HUE W TMS
CLEMINT

If NO, Driver Name / Age:

TERRY TAY

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SEK 539AK

INSRS:
WSP:
Tel:
Liability:
RMKS:Kian
TeongINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

8/5/19
23/5KEY CHANGE - X
SHA 46344 - Y
SEEK liability from III - Pending approval
Pending finalised from Resu

5/8/19

File pass to typist type report

22/8/19

Sett mandate via merimen

26/8/19

mandate approve via merimen

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup)

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorization To Acc:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

1070.00

Reav Ended TP

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

150.00

(S 50 x 3 days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

S\$

7.49

Medical

S\$

Disbursement:

S\$

(e.g. Tow) Independent

Legal Cost

S\$

Total:

S\$

1227.49

Global Sum S\$:

1200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

1200.00

Name 1:

Kian Teong Auto Centre

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: III

18669

ASSIGNMENT

From:

Date: 2.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 5399K

at Workshop n/s Kian Tiong Auto

of 176 sin ming Drive #01-08

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

"wup"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKX 5399K

Yr Regn: 2015 / Dec

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN QASHQAI 1.2 c.c 1197

Colour:

W4176

A/C: Insured / Std / NI / NA

Sp. Reading:

52396

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

5JN F6A J11 41539579

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt orMod: Nil / ☒ R / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

25/05/19

D.O.I.

22/05/19

Survey held at

KIAN TIONG AUTO

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/8/19

Confirm U/S \$1000.00 with 3 working days

(Est. \$2626.80)
72.1)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
Sin Ming AutoCare Singapore 575721
Tel No. : 64556268 Fax No. : 64555166
E-Mail : info@ktauto.com.sg
Website : www.ktauto.com.sg
Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04-005 IOB BUILDING (049711)
GMG BUILDING SINGAPORE 068900

Attention : Motor Claim Department
Contact : 63478100 Fax No. : 62244174/62257743

Estimate : ES000416

Date : 02/05/2019
Vehicle Num. : SKX 5399 K
Make/Model : NISSAN QASHQAI-2015
Chassis/Eng# : SJNFEAJ11U1539579/HRA2214036A / 2015
Accident Date : 02/05/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|---|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 SET | REAR BUMPER <i>cut - 1 x su</i> | | |
| 3. | 1 | REAR BUMPER BRACKET <i>1 x su</i> | | |
| 4. | 1 SET | REAR BUMPER REINFORCEMENT <i>1 x su</i> | | |
| 5. | 1 | REAR BUMPER REINFORCEMENT BRACKET <i>1 x su</i> | | |
| | | TOW HOOK COVER <i>9E-</i> | | |

List Total S\$:

- | | | | | |
|----|-------|------------------------------|--|--|
| 1. | 1 SET | NETT ITEMS : | | |
| | | REVERSE SENSOR <i>1 x su</i> | | |

Nett Total S\$:

LABOUR :
LABOUR FEES:
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
TO SPRAY PAINT REAR END PANNEL
TO SPRAY PAINT REAR BUMPER UNITS (two colours)
TO REMOVE AND CHANGE ALL DMAGED PARTS
TO KNOCK AND REPAIR ALL DAMAGED PARTS
TO REMOVE AND REFIT REAR EXHUAUST TO FACILATE REPAIR
TO CHECK TAILALAMP AND SENSOR WIRING

Labour Total S\$:

Rasul
Hp 90010068
3 days
43
02/05/19 @ 1130

1,260.00	755
68.00	
695.00	775
68.00	
115.80	20
2,206.80	542.50

220.00	X
220.00	

Repair after
300
350
300
com
120.00
60
80.00

500.00	
500.00	
120.00	X
80.00	
1,200.00	

710

E. & O.E.

Total S\$: 3,626.80



for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

IRCA Auto Centre hereby notify the Repairer of the following:

- To ensure better service to the customer.
- To display damaged parts using insurance.
- Parts prices are subject to contribution.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification is allowed.
- Supplementary items must be returned and subject to final approval from Insurance Company.

Acknowledged by Repairer:
Signature:
Date:

542.50
710.00
1252.50
20%
1602
43-1000
3 days

LABOUR FEES:
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
TO SPRAY PAINT REAR END PANNEL
TO SPRAY PAINT REAR BUMPER UNITS (two colours)
TO REMOVE AND CHANGE ALL DMAGED PARTS
TO KNOCK AND REPAIR ALL DAMAGED PARTS
TO REMOVE AND REFIT REAR EXHUAUST TO FACILATE REPAIR
TO CHECK TAILALAMP AND SENSOR WIRING

Labour Total S\$:

300
500.00
300
500.00
com
120.00
60
80.00
1,200.00

E. & O.E.

Total S\$: 3,626.80



Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 29 April 2019 10:29 AM
To: info@ktauto.com.sg; assignments@lkkauto.com; admin-a@lkk.com
Cc: Pooi Chin Han Daniel
Subject: RE: Pre-repair survey for SKX5399K

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKX5399K and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: info@ktauto.com.sg [mailto:info@ktauto.com.sg]
Sent: 29 April, 2019 9:20 AM
To: Motor Claim - III <motorclaim@iii.com.sg>; assignments@lkkauto.com; admin-a@lkk.com
Subject: RE: Pre-repair survey for SKX5399K

Dear Sirs,

Please help to assign LKK Auto for joint survey.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: 4/26/19 1:54 PM
To: "info@ktauto.com.sg" <info@ktauto.com.sg>
Subject: RE: Pre-repair survey for SKX5399K

1.46pm @ 29/4/19
wendy
Car not in
awake on 2/5/19.

undefinedundefinedundefined

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]

Sent: 26 April, 2019 12:34 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: Pre-repair survey for SKX5399K

Dear Mdm,

Kindly please help to arrange for a pre-repair survey for our client vehicle SKX5399K, your insured vehicle SHA 4634 U. Direct settlement with India Insurance is our 1st priority.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.

Print Received Message

This mail is associated with :

***SKX5399K (MCT19040724)**

[SHA4634U]

TP

WANG YIZHENG, GARRICK

Apr 25 2019 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

Kian Teong Auto Centre

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/05/2019 09:39 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$0.00) - SKX5399K - Claim Handler: Pooi Chin Han Daniel

Approved:0.00:We are agreeable to a DIRECT SETTLEMENT in this matter.

View Received Message

This mail is associated with :

***SKX5399K (MCT19040724)
[SHA4634U]**

TP
WANG YIZHENG, GARRICK
Apr 25 2019 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
Kian Teong Auto Centre

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **22/05/2019 17:40 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1227.49) - SKX5399K - Claim Handler: Pool Chin Han Daniel

Approved:1227.49:

DOCUMENTS SUMMARY

There are no documents.

**KIAN TEONG AUTO CENTRE**

*Blk 176 Sin Ming Drive #01-08, Sin Ming AutoCare
Singapore 575721*

Tel: 64556268 Fax: 64555166

TO: INDIA INSURANCE

DATE: 20/07/2019

ATTN: MOTOR CLAIM DEPT

REF:

RE: LETTER OF DEMAND FOR SKX 5399 K

Please find below breakdown claim of the vehicle no: SKX 5399 K

Repair cost: \$ 1070.00 (INCL GST)

Loss of used: 3 days x \$60.00 = \$180.00

LTA Search Fees \$7.49

Total amount: \$ 1,257.49

Your kind assistance on above matter would be appreciated

Thanks & Regards,

Wendy Siew – Mobile: 91786498



KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08, Sin Ming AutoCare

Singapore 575721

Tel: 64556268 Fax: 64555166

Letter of Authorization

Re: Accident on 29/4/17 involving vehicles number
element.

I, Meng Yizheng ^{owner} NRIC NO: S82118666 hereby authorize Kian Teong Auto Centre to handle and proceed all claims for my vehicle accident dated 29/4/17. Vehicle involved 3K X 53991C and 3HA H6349. I authorize Kian Teong Auto Centre to sign all necessary documents in connection with and arising out of the above claim with payment issue to Kian Teong Auto Centre.

[Signature]

Name & Signature of Owner

[Signature]

Name & Signature of Witness

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MCT19040724

Claimant Ref: SHA 4634U

Kian Teong Auto Centre

We/I, _____ ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 1,200.00 (~~Global Sum~~ ~~repair cost~~) ~~S\$~~ (~~loss of use/rental~~) ~~S\$~~ (~~search fee~~) vehicle no. SKX 5399K that was damaged pursuant to the accident which occurred on 25/04/2019 (date) at COMMONWEALTH AVE TWS CLEMENTI (location) involving vehicle no. SHA 4634U (insured vehicle). This is pursuant to the inspection conducted on 02/05/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner WANG YIZHENG, GARRICK ("the third party claimant") of vehicle no. SKX 5399K to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKX 5399K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,200.00 to KIAN TEONG AUTO CENTRE

Dated this 3rd day of June 2019

CLAIMANT:

Signature:

Signed by "the workshop" (workshop)

Name:

NRIC:

Address:

Nationality:

Occupation:

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



MPB

Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

Singaporean

Admin

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING, SINGAPORE 049711

Contact : 63476100 Fax No. : 62244174 / 62257743

Tax Invoice : KT042344

Invoice Date : 05/09/2019

Vehicle Num. : SKX 5399 K

Make/Model : NISSAN QASHQAI

Mileage(Km) :

PO/WO/RO# :

Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		ACCIDENT REPAIR	1,000.00	1,000.00

SingDollars : One Thousand Seventy Only



E. & O.E.

Total S\$: 1,000.00
GST@7% S\$: 70.00
Amount Due S\$: 1,070.00

Terms : Cash

Customer's Signature/Co. Stamp

for KIAN TEONG AUTO CENTRE

Cheque must be crossed and made payable to "Kian Teong Auto Centre"

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
Sin Ming AutoCare Singapore 575721
Tel No. : 64556268 Fax No. : 64555166
E-Mail : info@ktauto.com.sg
Website : www.ktauto.com.sg
Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING, SINGAPORE 049711

Contact : 63476100 Fax No. : 62244174 / 62257743

Tax Invoice : KT042344

Invoice Date : 05/09/2019
Vehicle Num. : SKX 5399 K
Make/Model : NISSAN QASHQAI
Mileage(Km) :
PO/WO/RO# :
Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		ACCIDENT REPAIR	1,121.50	1,121.50

SingDollars : One Thousand Two Hundred & Cents One Only

E. & O.E.

Total S\$: 1,121.50
GST@7% S\$: 78.51
Amount Due S\$: 1,200.01
=====

Terms : Cash

Customer's Signature/Co. Stamp

for KIAN TEONG AUTO CENTRE

Cheque must be crossed and made payable to "Kian Teong Auto Centre"

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 26 Apr 2019 / 12:27:42

Receipt Date/Time : 26 Apr 2019 / 12:27:42

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190426-001468

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SHA4634U As at 25 Apr 2019/23:59:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SHA4634U Enquiry Fee 20190426122536668951	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			-0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx7788			
	Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2019 Edit Reg		29 Apr 2019 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	WANG YIZHENG, GARRICK, ID: S8211866G								
Vehicle Reg. No.:	SKX5399K	Date of Loss:	25/04/2019 13:00 - :59 [40 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19040724	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHA4634U	Policy No. (Claimant):	5105080881						
		Excess:							
Repairer:	Kian Teong Auto Centre (HQ) BLK 176 SIN MING DRIVE #01-08 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (22/08/2019): Alert - Adj Mandate Approved (S\$1227.49) - SKX5399K - Claim Handler: Pooi Chin H... - III_SG (09/05/2019): Alert - Adj Mandate Approved (S\$0.00) - SKX5399K - Claim Handler: Pooi Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX5399K (MCT19040724)
[SHA4634U]

TP

WANG YIZHENG, GARRICK
Apr 25 2019 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
Kian Teong Auto Centre

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/08/19 16:51	General View		Load JPG	
2	22/08/19 16:51	General View		Load JPG	
3	22/08/19 16:51	General View		Load JPG	
4	22/08/19 16:51	General View		Load JPG	
5	22/08/19 16:51	General View		Load JPG	
6	22/08/19 16:51	General View		Load JPG	
7	22/08/19 16:51	General View		Load JPG	
8	22/08/19 16:51	General View		Load JPG	
9	22/08/19 16:51	General View		Load JPG	
10	22/08/19 16:51	General View		Load JPG	
11	22/08/19 16:51	General View		Load JPG	
12	22/08/19 16:51	General View		Load JPG	
13	22/08/19 16:51	General View		Load JPG	
14	22/08/19 16:51	General View		Load JPG	
15	22/08/19 16:51	General View		Load JPG	
16	22/08/19 16:51	General View		Load JPG	
17	22/08/19 16:51	General View		Load JPG	
18	22/08/19 16:51	General View		Load JPG	
19	22/08/19 16:51	General View		Load JPG	
20	22/08/19 16:51	General View		Load JPG	
21	22/08/19 16:51	General View		Load JPG	
22	22/08/19 16:51	General View		Load JPG	
23	22/08/19 16:51	General View		Load JPG	
24	22/08/19 16:51	General View		Load JPG	
25	22/08/19 16:51	General View		Load JPG	
26	22/08/19 16:51	General View		Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/05/19 14:42	EMAIL_FROM_III_DD_29042019		Load PDF	
2	06/05/19 10:14	TP ESTIMATE- MARKED		Load PDF	
3	06/05/19 10:14	TP GIA REPORT		Load PDF	
4	21/08/19 16:41	LTA SEARCH		Load PDF	
5	21/08/19 16:41	LOD		Load PDF	
6	27/09/19 12:05	WORKSHOP INVOICE		Load PDF	
7	27/09/19 12:05	AUTHORISATION TO ACT FORM		Load PDF	
8	27/09/19 12:05	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	06/05/19 08:54	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19007615/R1WB3Q2

Date: 27/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SKX5399K Insured Vehicle No: SHA4634U
 Date of Loss: 25/04/2019 Nature of Claim: TP Claim No: MCT19040724

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX5399K
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2214036A
 Reg. Date: 17/12/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1539579
 Colour: White Odometer: 52396 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,426.80	542.50	1,884.30	77.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	710.00	490.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,626.80	1,252.50	2,374.30	65.47
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	3,626.80	1,000.00	2,626.80	72.43
+ GST 7.00/7.00% (S\$)	253.88	70.00	183.88	72.43
Nett Amount (S\$)	3,880.68	1,070.00	2,810.68	72.43
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,227.49		
Global Sum Settlement (S\$)		1,200.00		

INSPECTION

Date of Assignment: 29/04/2019
 Date Inspected: 02/05/2019 Inspected At:

Kian Teong Auto Centre (HQ)
 BLK 176 SIN MING DRIVE #01-08
 SIN MING AUTOCARE
 Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2019)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX5399K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,260.00 F	*755.00 FL
2	1		*SET REAR BUMPER BRACKET	Serviceable	68.00 F	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	695.00 F	*- FL
4	1		*SET REAR BUMPER REINFORCEMENT BRACKET	Serviceable	68.00 F	*- FL
5	1		*TOW HOOK COVER	Deformed	115.80 F	*20.00 FL
6	1		*SET REVERSE SENSOR	Serviceable	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,426.80	775.00
- List Item Discount on L Items 0.00/30.00% (S\$)	0.00	232.50
Total Parts (S\$)	2,426.80	542.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS. TO SPRAY PAINT REAR END PANEL AND REAR BUMPER UNITS.	New	500.00	300.00
2	TO REMOVE AND CHANGE ALL DAMAGED PARTS. TO KNOCK AND REPAIR ALL DAMAGED PARTS.	New	500.00	350.00
3	TO REMOVE AND REFIT REAR EXHAUST TO FACILITATE REPAIR.	New	120.00	0.00
4	TO CHECK TAILLAMP AND SENSOR WIRING.	New	80.00	60.00
Gross Labour Cost (\$\$)			1,200.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >