

ASS. REC. BY:

REF: CS3/SMO19007618/Tle d307

Special Instruction:

Surveyor: TAUFIKH

ASSIGNMENT (Office)

Meiwhan

From (Person): Melvin Ye

of SMO

Date/Time: 30.4.2019 4.15p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 7628m

Insured: GBE 8850K

at Workshop m/s Ngee Ngee motor

Tel: 67775392

of BKK, NO 22 Pandan Loop

Policy No: D19MTPVE006629

Claim No: CMTD1902102

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 27.4.2019
2.5.2019

CA / REV / REP. / REV 24 HRS

mwp

H.O.D. Endorsement:

Date/Time: 30.4.19 4.23p.m

Person Contacted: Jessie

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	GBF 7628m - X	
	GBE 8850K - X	
	Dismantle: 3/5/2019	
	After repair: 21/5/2019	


Chryslor Taufik

REF:

Samp

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh _____
 (Policy Condition) _____
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: GBF 7628M Yt Regn: 2017 Moch
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Hiace c.c. 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 40924 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KDH205024045
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: 6 / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/80R15
 R: 195/80R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 2/5/19 @ 3pm
 Survey held at Ngee Ngee
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$8000 - \$9000, 10 days
 18/6/2019

Date/Time, File Pass to?

: Prel. Report
 : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

1) _____
 Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	100
Transportation:	60
S + PS. SI	60
Photos	
Others	11
TOTAL	231

Report Format: PRQ

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Apr 2019		30 Apr 2019 16:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YL DELIVERY & SERVICE, Co. Reg. No.: 53058137W		
Main Claimant:	EDMUND VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201625244G		
Vehicle Reg. No.:	GBF7628M	Date of Loss:	27/04/2019 15:00 - :59
Claim Type:	TP / CMTD1902102	Policy/Cover Note No.:	D19MTPCVE000629 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE8850K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ngee Ngee Motor () Block K, No. 22 Pandan Road, 128240 West Coast - Tel: 67775382		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/05/2019]		
Driver/Custodian (Insured):	KEE MENG SIANG, DANIEL (YI MINGXIANG) (), NRIC: S8719376D, Tel: +6581593323 Email:		
Adj Asg. Remarks:	WS: MS JESSIE		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Yvonne <yvonne@ealc.com.sg>
Sent: Tuesday, 30 April, 2019 4:15 PM
To: Teo, Grace; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin; Henry, Irene James
Subject: [PRI] CMTD1902102/MYE - PRI/ GBE8850K & GBF7628M ACC ON 27.04.19 [EAL.2019.6293.MK.ya - GBF7628M]

Our ref : 2019.6293.MK.ya - **GBF7628M**
Your ref : **GBE8850K**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

Sompo Insurance Pte. Ltd
No. 50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s Sompo Insurance Pte. Ltd		
Vehicle GBF7628M inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: EDMUND VEHICLE RENTAL PTE LTD

ACCIDENT INVOLVING GBF7628M & GBE8850K ON 27 APRIL 2019 ALONG SELETAR NORTH LINK (NEAR SELETAR AIRPORT) AT ABOUT 1510 HOURS

We refer to the above matter wherein we are instructed to act for **EDMUND VEHICLE RENTAL PTE LTD**, the owner of vehicle no. **GBF7628M**.

Further to your email dated Tuesday, 30 April 2019 3:36 PM, there is no agreement to the surveyors proposed by parties.

Our client's vehicle **GBF7628M** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Ngee Ngee Motor
Blk K, No. 22 Pandan Loop
(West Coast Road, Jurong Town),
Singapore 128219
Tel: 67775382 (Ms Jessie)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 30 April 2019 3:36 PM
To: Yvonne <yvonne@ealc.com.sg>; 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1902102/MYE - PRI/ GBE8850K & GBF7628M ACC ON 27.04.19 [EAL.2019.6293.MK.ya - GBF7628M]

Our Reference: CMTD1901608/SYH
Your Reference: EAL.2019.6293.MK.ya - GBF7628M

Date: 30/04/2019

Without Prejudice
EMAIL ONLY

Attention:
M/S EAST ASIA LAW COPORATION

Dear Yvonne,

ACCIDENT INVOLVING GBE8850K & GBF7628M ON 27.04.2019

We refer to your Notice of Accident dated 30/04/2019.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

Kindly provide us the address of location and contact for our motor surveyor to conduct the pre-repair survey.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Yvonne [<mailto:yvonne@ealc.com.sg>]

Sent: Tuesday, April 30, 2019 3:14 PM

To: Claims - Motor Survey

Subject: Sompo Insured GBE8850K [EAL.2019.6293.MK.ya - GBF7628M]

Our ref : 2019.6293.MK.ya - **GBF7628M**

Your ref : **GBE8850K**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

Sompo Insurance Pte. Ltd
No. 50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Attn: Motor Claims Department
NOTICE OF ACCIDENT

For your information only
Owner of **GBE8850K**
YL Delivery & Service
211 Yishun Street 21
#02-05
Singapore 760211

Dear Sir/Madam,

CLAIMANT: EDMUND VEHICLE RENTAL PTE LTD

ACCIDENT INVOLVING GBF7628M & GBE8850K ON 27 APRIL 2019 ALONG SELETAR NORTH LINK (NEAR SELETAR AIRPORT) AT ABOUT 1510 HOURS

We are instructed by **EDMUND VEHICLE RENTAL PTE LTD** to notify you (the insurer of **GBE8850K**) of a road traffic accident on **27 APRIL 2019 ALONG SELETAR NORTH LINK (NEAR SELETAR AIRPORT) AT ABOUT 1510 HOURS** involving our client's vehicle registration number **GBF7628M** and vehicle registration number **GBE8850K** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.
mo

As a result of the accident, our client's vehicle **GBF7628M** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Carlink Consultancy - Patrick Ng

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5244G
Vehicle Details	
Vehicle No.:	GBF7628M
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2643137
Chassis No.:	KDH2015024045
Maximum Power Output:	-
Open Market Value:	\$35,204.00
Original Registration Date:	06 Mar 2017
First Registration Date:	06 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$1,761.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Mar 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,287.00
COE Rebate Amount:	\$32,590.00
Total Rebate Amount:	\$32,590.00

The information contained herein is correct as at 19 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 09:17
Date Of Accident	27/04/2019 15:10
Exact Location Of Accident	SELETAR NORTH LINK (NEAR SELETAR AIRPORT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF7628M
Insured/Policyholder	
Name Of Registered Owner	EDMUND VEHICLE RENTAL PTE LTD
Co Reg No	201625244G
Email Address	EDMUNDEV@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62652017

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086597038-02
Cover Note Number	

Driver

Name of Driver	IMRAN
Passport No/FIN	G8151729R
Date Of Birth	01/06/1988
Occupation	OUTDOOR
Date Of Driving Pass	29/12/2016
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93452924
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	71 WOODLANDS AVENUE 10 #06-07 WOODLANDS INDUSTRIAL XCHANGE
Postcode	737743
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE8850K
Vehicle Make/Model/Colour	
Details Of Properties	FRONT
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KEE MENG SIANG DANIEL
NRIC/Passport Number	S8719376D
Contact Number	81593323
Address	YL DELIVERY SERVICES
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2012
29-4-15



Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 27/04/19 @ 3:10 PM, I WAS DRIVING MY VEHICLE ALONG SELETTER NORTH LINK (NEAR SELETTER AIRPORT). I ALREADY STOPPED MY VEHICLE ON TEMPORARY RED LIGHT, THEN SUDDENLY ONE VEHICLE PLATE NO GBE 8850K HIT MY VEHICLE BEHIND.

LAST ENTRY

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

25/21A
 29-4-19
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019		30 Apr 2019 16:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	YL DELIVERY & SERVICE, Co. Reg. No.: 53058137W		
Main Claimant:	EDMUND VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201625244G		
Vehicle Reg. No.:	GBF7628M	Date of Loss:	27/04/2019 15:00 - :59 [25 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1902102	Policy/Cover Note No.:	D19MTPCVE000629 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE8850K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ngee Ngee Motor () Block K, No. 22 Pandan Road, 128240 West Coast - Tel: 67775382		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/05/2019]		
Driver/Custodian (Insured):	KEE MENG SIANG, DANIEL (YI MINGXIANG) (), NRIC: S8719376D, Tel: +6581593323 Email:		
Adj Asg. Remarks:	WS: MS JESSIE		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***GBF7628M (CMTD1902102)**
[GBE8850K]
TP
EDMUND VEHICLE RENTAL PTE LTD
Apr 27 2019 3:00PM
[YL DELIVERY & SERVICE]
Ngee Ngee Motor

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>
Assessment Reports				1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/04/19 16:34	Accident Statement <small>From:SC - Reg. No: GBE8850K, Claimant: YL DELIVERY & SERVICE</small>	Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	19/06/19 17:26	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	19/06/19 17:27	Photographs of Damaged Parts	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	19/06/19 17:27	Photographs of Damaged Parts	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
84	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	19/06/19 17:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	19/06/19 17:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/04/19 15:28	Pre-Repair Survey - GIA	 Load PDF	
2	30/04/19 16:33	Pre-Repair Survey - ASSIGN LKK	 Load PDF	
3	30/04/19 16:33	Pre-Repair Survey - Ngee Ngee Motor	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19007618/T1CD3E2

Date: 21/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPCVE000629
Claimant Vehicle No :	GBF7628M	Insured Vehicle No :	GBE8850K
Date of Loss:	27/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1902102

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF7628M	Engine No:	1KD2643137
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2015024045
Reg. Date:	06/03/2017 (Man. Year: 2016)	Odometer:	40924 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	30/04/2019		
Date Inspected:	02/05/2019	Inspected At:	Ngee Ngee Motor Block K, No. 22 Pandan Road Singapore 128240
Estimated Period of Repair:	10.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 -\$9,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Jun 2019)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7628M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >