

Inspector: Kelvin

REF: CC3/1M219007634 K19d3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / ITP RES / OD RES / EVA / INV / MV  
 To Inspected Vehicle No: \_\_\_\_\_  
 At Workshop m/s: \_\_\_\_\_  
 Insured: **SME 6501B**  
 Policy No: **MT107986**  
 Claims No: **M1903100**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vch: \_\_\_\_\_

(Policy Condition)

Remark: The vch had commenced its repair at the time of inspection.



Ball or Market Value:

IDAG Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repair: **7** days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Vch No: **SHC 14222** Yr Regn: **20 Dec 2017**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / T.O. / Prime Mover /  
 Truck / Trailer or  
 Make: **Hyundai I40** cc: **1685**  
 Colour: **Blue** A/C: **Inst** / Std / Nil / NA  
 Sp. Reading: **316720** T/Radio: **Inst** / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **LCMH 1841 4AH 4100 009**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inord / Jammed / Leaked / Burnt or  
 Brake: Inord / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD / Rim or  
 Tyre Size: F: **205/60R16**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GV / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Hankook**  
 Front Rear  
 R/Bal: **7** mm R/Bal: **7** mm  
 L/Bal: **7** mm L/Bal: **7** mm  
 D.O.A: **30/4/19** D.O.L: **30/4/19**  
 Survey held at: **CDAE (Logan)**  
 Des. of Damages: Fri / Rear / O/S / N/S / U/C / Roof/Top or  
**Rear**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 14222 - LCH/AXA UU26200/14/18/18 D OA - 20/12/2017 To Kin PIP
	SME 6501B - x
07/5/19	U.S. Star email. GIA & estimate to TMI.
8/5/19	Chms PIP 1690.42 / 1207. LRed 0436.96, 21%
RECEIVED 08 MAY 2019	

Date/Time, File Pass to?

☐ : Prel. Report

1) 08/5/19

☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: **2**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (S)

☐ : Interview (S)

☐ : Test (S)

☐ : Other (S)

Survey Fee:

Transportation:

☐ S + PS ☐ S

Photo:

Other:

Other:

Other:

MT107986  
1690.42

8/5/2019

## **Shiau Chan (LKKAuto)**

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 2 May 2019 11:55 AM  
**To:** Motor Claims  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -COMFORTDELGRO ENGINEERING PTE LTD, DOA: 30/04/2019, SHC 1422Z (TP VEHICLE), SME 6501B (OI VEHICLE)  
**Attachments:** SHC1422 GIA.pdf; SHC1422 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 1422Z at M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 30/04/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2019 14:30
Date Of Accident	30/04/2019 10:15
Exact Location Of Accident	KPE TWDS CITY BEFORE AIRPORT RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1422Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	TAN THIOU KOK
NRIC No	S0133189B
Date Of Birth	28/07/1952
Occupation	OUTDOOR
Date Of Driving Pass	17/07/1975
Driving Experience	43 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97966147
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 451 CHOA CHU KANG AVENUE 4 #06-147
Postcode	680451
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME6501B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG XIN DE
NRIC/Passport Number	S9045437D
Contact Number	96743274
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

# **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CONFIDENTIAL INFORMATION RELATES TO  
CO REG NO: 199N13821F

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Loke Wei Yeng

30/4/19

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/4/19 at about 10:15 hrs, I was driving at above said location with a male pax onboard. Shortly veh in front applied brake to stopped and I follow suit. A split second later, I felt an impact from my taxi behind followed by a jerk. Veh B came from behind collided onto the rear portion of my taxi. No injury reported in this accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION (P) LTD  
CO REG NO 1874521P


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*Loke Wei Yeng*  
30/4/19

Printed Name of the Driver:





COMFORT


Date/Time: 30.04.2019 15:16 Page: 1

Team:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO:	305291884
OWNER	COMFORT TRANSPORTATION PTE LTD		REGN NO.	SHC1422Z	
IS	7010045		MAKE:	HYUNDAI	
OMER NO.	383 SIN MING DRIVE		MODEL	I-40	
ESS	Singapore SINGAPORE 575717		YR OF MANU.	20.12.2017	
(R)	65508755		CHASSIS CODE	KMHLE41UMHU100009	
(P)			DATE/TIME IN	30.04.2019 12:05	
			TARGET DATE		
			COMPLETION DATE/TIME		

JOB DESCRIPTION

Accident Date: 30.04.2019  
NATURE: 3P 30.04.2019

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



WORKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
Acknowledgement Slip		Exit Pass	
No.	SHC1422Z	Vehicle No.	SHC1422Z
LKE		Signature/Date	
Name of Service Advisor		Date	
Returned to Service Reception upon collection		To be kept by Security Guard	

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHC 1422Z

DATE 30/4/2019 14:58

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Return</i>			\$ 553.00	
	Rear Bumper Clip 10 pcs <i>na</i>			\$ 22.00	
	Rear Bumper Bracket <i>X 1 pc</i>		\$ 35.60	\$ 71.20	
	Rear Bumper Under Cover <i>cut</i>			\$ 228.00	
	<i>Rear Bumper grommet x 2 pc</i>				
	<i>Rear Bumper Emblem "i40" na</i>				
	<b>SUB TOTAL</b>		<i>\$ 27.90</i>	<b>\$ 874.20</b>	
	<b>LESS 20%</b>			<b>\$ 174.84</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 699.36</b>	
	Rear Bumper Rubber Mat <i>X 1 pc</i>			\$ 50.00	Nett
	Rear Bumper Advertisement Logo <i>na</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>na</i>		\$ 100.00	\$ 200.00	Nett
	Rear Bumper Reverse Sensor <i>1 pc</i>			\$ 135.70	Nett
				<b>\$ 435.70</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ <del>400.00</del> <i>200</i>	
	Spray Painting Charge			\$ <del>30.00</del> <i>10.00</i>	
	Wiring Charge			\$ <del>80.00</del> <i>20</i>	
	Remove/Refix Reverse Sensor			\$ <del>10.00</del> <i>0</i>	
	<i>Marina Fee</i>				
	<b>TOTAL LABOUR</b>			<b>\$ 810.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,945.06</b>	
<p><i>Kalvin (UCC)</i></p> <p><i>30/4/19 1545hrs</i></p> <p><i>2 By,</i></p> <p><i>PIP</i></p> <p><i>Before Paint photo</i></p>					<p>* This estimate is valid for 30 days only.</p> <p>* Third party survey is on "Vehicle Condition" basis.</p> <p>* No major modifications (to chassis)</p> <p>* Supplementary item(s) must be recovered and is subject to final approval from Insurance Company.</p> <p>Acknowledged by Repairs:</p> <p>Signature:</p> <p>Date:</p>
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/04/2019
Vehicle Reg. No.:	SHC1422Z	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	20/12/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDHU730809	Chassis No:	KMHLB41UMHU100009
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,107.38
Miscellaneous Items	10.00
Labour	1,010.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>2,127.38</b>
<b>+ GST 7.00% (\$\$)</b>	<b>148.92</b>
<b>Nett Amount (\$\$)</b>	<b>2,276.30</b>

**This claim is handled by: LIM KWOK ENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 30 Apr 2019)**Parts:** 143      HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC1422Z/30/04/2019 18:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*553.00 FL <i>pe</i>
2	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>pe</i>
3	1		*REAR BUMPER BRACKET LH	20.00	0.00	*35.60 FL <i>goc</i>
4	1		*REAR BUMPER BRACKET RH	20.00	0.00	*35.60 FL <i>goc</i>
5	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL <i>cup</i>
6	1		*REAR BOOTLID 140 EMBLEM	20.00	0.00	*27.90 FL <i>me</i>
7	1		*REAR BUMPER ADVERTISEMENT LOGO	0.00	0.00	*50.00 FL <i>me</i>
8	1		*REAR FENDER ADVERTISEMENT LOGO LH	0.00	0.00	*100.00 FL <i>me</i>
9	1		*REAR FENDER ADVERTISEMENT LOGO RH	0.00	0.00	*100.00 FL <i>me</i>
10	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*135.70 FL <i>short</i>

F=Franchise part, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,287.80</b>
<b>- List Item Discount on L Items (\$\$)</b>	<b>180.42</b>
<b>Total Parts (\$\$)</b>	<b>1,107.38</b>

ComfortDelGro Engineering Pte Ltd/SHC1422Z/30/04/2019 18:39. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	200 400.00
2	SPRAY PAINTING CHARGE	New	500 500.00
3	WIRING CHARGE	New	30.00 X
4	REMOVE/REFIX REVERSE SENSOR	New	30 80.00
Gross Labour Cost (S\$)			1,010.00

ComfortDelGro Engineering Pte Ltd/SHC1422Z/30/04/2019 18:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our Job Ref No 305291884  
Date : 07.05.19

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508569  
Fax: 6546 6156

### FINALIZATION FORM

To : LKK  
Attn : Mr KALVIN ANG  
Vehicle Reg No. SHC1422Z CTPL


Fax :


30.04.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE SME6501B
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$800.42
  - (b) Labour Charges \$890.00
  - Total for Part-By-Part Repair Cost \$1,690.42
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : Kalvin  
Date : 8/5/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 02.05.2019  
Time: 14:04:16  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305291884  
REGN NO : SHC14222  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 30.04.2019 12:05  
ACCIDENT DATE : 30.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	553.00	20.00	442.40
0002 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004 04-01-0103-0787-G	I40VC EMBLEM-I40	1 L	27.90	20.00	22.32
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00-	135.70

SUB-TOTAL : 800.42

JOB NATURE

0000 20-05	RENEW ADVERTISEMENT STICKER-	250.00
0001 L	MERIMEN CHARGE	10.00
0002 L	PANEL BEATING	200.00
0003 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0004 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 890.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.05.2019

Time: 14:04:16

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305291884  
REGN NO : SHC1422Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 30.04.2019 12:05  
ACCIDENT DATE : 30.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,690.42

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2019 18:24	30 Apr 2019 18:39 <b>S\$2,127.38</b>	02 May 2019 13:49	<b>S\$1,690.42</b>	<b>S\$1,690.42</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>HAN MING GUANG</b> , ID: S8526404D								
Main Claimant:	<b>CTPL</b>								
Vehicle Reg. No.:	<b>SHC1422Z</b>	Date of Loss:	30/04/2019 10:00 - :59 [16 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / M1903100</b>	Policy/Cover Note No.:	MT107986 (Comprehensive) Coverage: 10/10/2018 - 09/10/2020						
Vehicle Reg. No. (Insured):	<b>SME6501B</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Fiona Gan Bee Song</b> - 65926378]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 13/05/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SHC1422Z (M1903100)  
[SME6501B]  
TP  
CTPL  
Apr 30 2019 10:00AM  
[HAN MING GUANG]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)								Thumbnail	Print
1	30/04/19 18:39	Repairer Estimates								Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)								Thumbnail	Print
1	02/05/19 11:06	Accident Statement From: SC - Reg. No: SME6501B, Claimant: HAN MING GUANG								Load HTM	
2	02/05/19 13:49	Accident Statement From: SC - Reg. No: SME6501B, Claimant: HAN MING GUANG								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
2	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
3	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
4	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
5	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
6	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
7	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
8	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
9	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
10	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
11	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
12	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
13	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
14	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
15	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
16	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
17	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
18	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
19	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
20	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
21	02/05/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>
22	06/05/19 08:27	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>
23	06/05/19 08:27	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>
24	06/05/19 08:27	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)								Thumbnail	Print
1	30/04/19 18:40	E-filed GIA report								Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)								Thumbnail	Print
1	02/05/19 11:06	SHC1422Z GIA REPORT								Load PDF	
2	02/05/19 13:48	LKK NOTIFICATION TO SURVEY CDGE-ASSINGED								Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19007634/K1QD3Q2

Date: 10/05/2019

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT107986

Claimant Vehicle No: SHC1422Z

Insured Vehicle No: SME6501B

Date of Loss: 30/04/2019

Nature of Claim: TP

Claim No: M1903100

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1422Z

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDHU730809

Reg. Date: 20/12/2017 (Man. Year: 2016)

Chassis No: KMHLB41UMHU100009

Colour: Blue

Odometer: 316720 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,107.38	1,050.42	56.96	5.14
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,010.00	630.00	380.00	37.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,127.38</b>	<b>1,690.42</b>	<b>436.96</b>	<b>20.54</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>148.92</b>	<b>118.33</b>	<b>30.59</b>	<b>20.54</b>
<b>Nett Amount (S\$)</b>	<b>2,276.30</b>	<b>1,808.75</b>	<b>467.55</b>	<b>20.54</b>

### INSPECTION

Date of Assignment: 02/05/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 30/04/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC1422Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER BRACKET LH	Serviceable	35.60 FL	*- FL
4	1		*REAR BUMPER BRACKET RH	Serviceable	35.60 FL	*- FL
5	1		*REAR BUMPER UNDER COVER	Cut	228.00 FL	*228.00 FL
6	1		*REAR BOOTLID 140 EMBLEM	Necessary	27.90 FL	*27.90 FL
7	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	*50.00 F
8	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	*100.00 F
9	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	*100.00 F
10	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 F	*135.70 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,287.80</b>	<b>1,216.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>180.42</b>	<b>186.18</b>
<b>Total Parts (\$\$)</b>	<b>1,107.38</b>	<b>1,050.42</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	30.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			1,010.00	630.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;