

ASS. REC. BY:

REF: CS3/SMD19007675/RIC d34

Special Instruction:

Surveyor: RASHIASSIGNMENT (Office)From (Person): Hwang Shiang Yiof SMDDate/Time: 2.5.2019 8:44a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKL 3684mInsured: PA 93137at Workshop m/s TK car RepairTel: 97463035of 176 sin ming # 01-12Policy No: D18MTSCBU000633Claim No: CMTD1902118

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.4.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 25.19 9:57a.m

Person Contacted:

LOW

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction
	Estimate (X)
	SKL 3684m-X
	PA 93137-X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2019		02 May 2019 08:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JIN TAO BUS SERVICE, Co. Reg. No.: 49317100B		
Main Claimant:	PHUA WOON SOON ROGER, ID: S8124053A		
Vehicle Reg. No.:	SKL3684M	Date of Loss:	30/04/2019 09:00 - :59
Claim Type:	TP / CMTD1902118	Policy/Cover Note No.:	D18MTSCBU000633 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	PA9313T	Policy No. (Claimant):	
		Excess:	
Repairer:	Tk Car Repairs Pte Ltd (HQ) 176 SIN MING DRIVE, #01-12 SIN MING AUTOCARE, 575721 Sin Ming - Tel: 6453 2598 / 6453 9730		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/05/2019]		
Adj Asg. Remarks:	WS: MR LOW 97463035 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4053A
Vehicle Details	
Vehicle No.:	SKL3684M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	640I GRAN COUPE 4DR SR LED DSC NAV HUD
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	05808603N55B30A
Chassis No.:	WBA6A02030DZ11997
Maximum Power Output:	235.0 kW (315 bhp)
Open Market Value:	\$81,627.00
Original Registration Date:	31 Oct 2013
First Registration Date:	31 Oct 2013
Transfer Count:	1
Actual ARF Paid:	\$118,929.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2023
PARF Rebate Amount:	\$83,250.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$92,289.00
COE Rebate Amount:	\$39,205.00
Total Rebate Amount:	\$122,455.00

The information contained herein is correct as at 14 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 14:35
Date Of Accident	30/04/2019 09:40
Exact Location Of Accident	BEDOK NORTH AVE 1 / BEDOK NORTH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL3684M
Insured/Policyholder	
Name Of Registered Owner	PUAH WOON SOON ROGER
NRIC No	S8124053A
Email Address	ROGERPHUA@RHSYNERGY.COM
Mobile Phone No	(LOCAL) +65-98202073
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	BMW
Model	640I GRAN COUPE 4DR SR LED DSC NAV HUD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ19-001036
Cover Note Number	12/02/2018 TO 30/04/2019

Driver

Name of Driver	PUAH WOON SOON ROGER
NRIC No	S8124053A
Date Of Birth	13/08/1981
Occupation	INDOOR
Date Of Driving Pass	24/01/2000
Driving Experience	19 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98202073
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	ROGERPHUA@RHSYNERGY.COM

Address	8 ANG MO KIO CENTRAL 3 #11-12
Postcode	567744
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9313T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MT TAN
NRIC/Passport Number	S2083601F
Contact Number	92388380
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN

Accident Date: 30/04/2019 Time: 09:40am Location: Bedok North Ave 1 / Bedok North Rd
 My Vehicle A: SKL3684M Vehicle B: PA9313T Vehicle C/Others: _____



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Bedok North Ave 1 towards Bedok North St 3. At the junction of Bedok North Rd, front vehicles came to a stop. I stopped too.
 After a while, a passenger van PA9313T came from behind & hit onto the rear of my car.
 I was alone at the time of accident.

() Claim OD / TP at Ah Lim Motor (☒) Claim OD / TP at other workshop () Reporting Only

Remarks : Please forward a copy of my efile accident report to

My workshop : TK Car repairs P/L.
 Email Address : tklow50@hotmail.com
 & Myself :
 Email Address : rogerphua@RHSynergy.com

Note : Please take note that your insurer have **14 days timeframe** for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Vehicle: - SKL3684M

Policyholder's Signature
 Date & Time:

Driver's Signature (If driver is not the policyholder)
 Date & Time

Witnessed by Reporting Centre
 Personnel



30/04/19

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

**PRIVATE CAR
Comprehensive**

Certificate No.: DMPPHQ18-001036

Form: MX3

Excess:

Insured

SGD2,500.00

1. Index Mark and Registration Number of Vehicles
SKL3684M

2. Name of Policyholder
PHUA WOON SOON ROGER

3. Effective Date of the Commencement of Insurance for the purpose of the Act
12/02/2018

4. Date of Expiry of Insurance
30/04/2019

5. Person or Classes of Persons entitled to drive*
(a) The Policyholder
(b) The specific person(s) whose name is lodged in the Schedule.

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use*
Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover :

- (a) use for hire or reward
- (b) use for racing, pace-making, reliability trials or speed testing and on race track
- (c) use for the carriage of goods (other than samples) in connection with any trade or business
- (d) use for any purpose in connection with the Motor Trade
- (e) use by any other persons than those defined as entitled to drive in paragraph 5 above

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

HP: Tokyo Century Leasing (Singapore) Pte Ltd
unwsbh/HO/A000059/Ong Cheu Peng Brenda




A Member of Citystate

Authorised Signatory
EQ Insurance Company Limited






































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Apr 2019		02 May 2019 08:44 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	JIN TAO BUS SERVICE , Co. Reg. No.: 49317100B								
Main Claimant:	PHUA WOON SOON ROGER , ID: S8124053A								
Vehicle Reg. No.:	SKL3684M	Date of Loss:	30/04/2019 09:00 - :59 [66 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1902118	Policy/Cover Note No.:	D18MTSCBU000633 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	PA9313T	Policy No. (Claimant):							
		Excess:							
Repairer:	Tk Car Repairs Pte Ltd (HQ) 176 SIN MING DRIVE, #01-12 SIN MING AUTOCARE, 575721 Sin Ming - Tel: 6453 2598 / 6453 9730								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by WONG, LEE SIN LORRIANCE - 6329 5175]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/05/2019]								
Adj Asg. Remarks:	WS: MR LOW 97463035 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS 		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL3684M (CMTD1902118)
[PA9313T]
TP
PHUA WOON SOON ROGER
Apr 30 2019 9:00AM
[JIN TAO BUS SERVICE]
Tk Car Repairs Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
2	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
3	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
4	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
5	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
6	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
7	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
8	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
9	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
10	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
11	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
12	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
13	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
14	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
15	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
16	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
17	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
18	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
19	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
20	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
21	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
22	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
23	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
24	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
25	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
26	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
27	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
28	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
29	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
30	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
31	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
32	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
33	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
34	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
35	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
36	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			
37	14/05/19 12:09	General View								Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/05/19 12:09	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/05/19 12:09	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/05/19 12:09	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/05/19 12:09	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/05/19 12:09	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/05/19 12:09	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/04/19 17:25	Pre-Repair Survey	 Load JPG	<input checked="" type="checkbox"/>
2	30/04/19 17:27	Third Party E-filed GIA report(M)	 Load PDF	
3	02/05/19 08:43	Pre-Repair Survey - AGREED LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19007675/R1CD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000633
Claimant Vehicle No :	SKL3684M	Insured Vehicle No :	PA9313T
Date of Loss:	30/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1902118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL3684M	Engine No:	05808603N55B30A
Make & Model:	BMW 640I, 3.0 Gran Coupe (F13) (A)	Chassis No:	WBA6A02030DZ11997
Reg. Date:	31/10/2013 (Man. Year: 2013)	Odometer:	72421 km
Colour:	White		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35Z R19	Rear Tyre Size:	275/35Z R19
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/05/2019	
Date Inspected:	02/05/2019 Inspected At:	Tk Car Repairs Pte Ltd (HQ) 176 SIN MING DRIVE, #01-12 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2019)	
Parts:	N/A	BMW 640I 3.0 Gran Coupe (F13) (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL3684M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >