ASSIGNMENT (Office) From (Person) Chong boom Sen of C11 Dute/Time: 2.6.2019 9.33 Estimated Copt: Bill to: OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS To Inspect Vehicle No: SEA 61797 Insured: At Workshop m/s Paul Hor Batterins & moder Tel: 67419666 of 1 take Bubt Mre 6 & 01-109 Policy No: DMP(SN/807891901 Claim No: SNM/9D 2018 06 C0] Sum Insured: Brows: \$1000.00 Make of Veh: (Chent's Regrid) CA (REV) REP. / REV 24 HRS Date/Time: 2.5.2019 9.400.m Person Contacted: Paul Vehicle IN OUT Date/Time: Action/instruction Followed from Boon Sency via merimen 25/19 Reve approved from Boon Sency via merimen 25/19 Reve approved from Boon Sency via merimen 25/19 Reve approved from Boon Sency via merimen	ASS, REC. BY:		CS/C1190076	49 / UV	d3 Dyackil Instruction:	_
Estimated Cost. OD/FF/WS/TP RES/OD RES/EVA/INV/MV/CS To Inspect Vehicle No: SKA 61797 Insured: 1			ASSIGNMENT CTL	[(Office)	Detn/Time: 2.6. 2017 9 33	a m
Instruct: Instruct:	Estimated Cost					
Policy No. DMPCSN1807891901 Sum Insured: Make of Veh: (Cheart's Record) CA (REV) / REP. / REV 24 HRS Date/Time: 2.5.2019 9400.m Person Contacted: Date/Time: Action/Instruction Fahmall (V) SKA 61797 - Date/Time Revert via merimen 25/19 Revert via merimen	To Inspect Vel	icle No: SkA 613	191		Insured:	_
Sum Insured: Make of Veh: (Chent's Record) CA (REV) / REP. / REV 24 HRS Date/Time: 2-5.2419 9400.m Person Contacted: Paul Vehicle IN OUT Date/Time: Action/instruction Fahmal (V) SKA 61797 - X 2 5 19 Revert via meriment 2 5 19 Revert via meriment Ska approved from Boon Seng via meriment						
Make of Voli: (Chent's Beyord) CA (REV) / REP. / REV 24 HRS Date/Time: 2-5.2019 9400 m Person Contacted: Paul Vehicle III) OUT Date/Time: Action/instruction Followship (V) SKA 61797 - VIA merimen 2 5 19 Revert VIA merimen 2 5 19 Revert VIA merimen 2 5 19 Revert VIA merimen	Policy No. 01	nPCSN180789190	1	Claim No:	SNM19D2018 06(0)	
Make of Voli: (Chent's Beyord) CA (REV) / REP. / REV 24 HRS Date/Time: 2-5.2019 9400 m Person Contacted: Paul Vehicle III) OUT Date/Time: Action/instruction Foliman (V) SKA 61797 - 2 5 19 Revert via merimen 2 5 19 Revert via merimen Boon Sena via merimen	Sum Insured:			Excess	\$1000.00	
CA REV / REP. / REV 24 HRS Date/Time: 2-5.24 9.400 m Person Contacted: Paul Vehicle III) OUT Date/Time: Action/instruction Palman (V) SKA 61797 - X 2 5 19 Revert via merimen 2 5 19 Revert via merimen Boon Sena via merimen	Make of Veh:				D.O.A. 21.4. 2019	
2/5/19 Revert via merimen 2/5/19 Revert via merimen 2/5/19 Rever approved from Boon Sena via merimen	CA (REY)	REP. / REV 24 HRS	erson Contacted:	Paul_	63	
2/5/19 Revert via merimen 2/5/19 Revert via merimen 2/5/19 Revert via merimen	Date/Time	Action/Instruction Fol	N) Marin			
2/5/19 Reve approved from Boon Seng via merimen			.0030			
2/5/19 Reve approved from Boon Seng via merimen	25/19	Revert via	merimen			
2/5/19 @402pm Informed Paul C/A ex \$1000 by amril	2/5/19	Rece approved	d from Bo	on Seno	via merimen	
	2/5/19	@ 402 pm Info	rmed Paul	CA	ex \$1000 by amxil	4.

2000

T. 179

2	ASSIGNMI	SNT	70 -	
From Date: 3-5	- 2019 Veh No.	SKA 617	Yr Rogn:	3/11
Estimated Cost:		.Cat LM.Cycle / Bus / Van		ver I
OD TP / WS / TP RES / OD RES / EVA / INV / MV	T	ruck/Trailer or	1	
To Inspect Vehicle No. SkA 6179T	Make		€ 250 (Gi 00	1796
at Workshop min Paul Hoe Batteries	200	Black		Std / NL/ NA
1 kaki Byti+ Ave 6 \$ 01-109	Sp.Rea		7 T/Radio: Insured /	Std / NI / NA
Insured	Eng/No.	word		
Policy No.	C/No.	WOOZ	12047243;	71147
Claims No.	Gen, Co	and: Good Fair / Poor / B	umt	110
Sum Insured Excess:	Steering	: lyorder / Jammed / Leal	ked/Burnt or	
(Client's Record)	Brake:	norder Lammed / Leal	ked / Burnt or	
Make of Veh	Modi :	NII ISIRID I STO AIRI		
	Y* Tyre St	te: F: 2 }	45/45-20	212
(Policy Condition)		R:		'/
Remark: The veh had commonced its	N/S O/S BS/DU	JN / EXNOVA / GY / FS / L	IZA MIC OHTSU / PIR /	SUMI/
repair at the time of inspection.	TOYO	/YOKO or		
Bal. or Market Value: (VC -	Front	1	Rear	6
IDAC Accident Rport: Consistent? : Yes	or No R/Bal.	/O mm	R/Ball.	mm
GIA / PR Seen: Consistent? : Yes	or No L/Bal.	6,000	L/Bal &	S mm
Est Repairs. 4 days Res.: Yes	or No D.O.A.	21/4/19	0.0.1. 2/	5/18
Lum Sum: 20 % 3 Val. Yes	or No Survey	held at	- 7	()
) Des. of	Damages : Frt / Rear / C	O/S / N/S / U/C / Rooff	top or
CA / REV REP. / 24 HRS	Vehicle: IN / OUT	of o	10.	
Date: Person Contacted: A ##	(253) The	U/C / Chassis frame / I	Body Structure affected	due to collision.
Date / Time Action / Instruction	22.60	/		
Male midnight rate 1	1A 3940/ 19	rs. 1/24. Nej /3500		
1 / myer 1 15 4 t. 95 , hudle	3382.63			
Male midnight call & myer 15.45.95, hadle	2700 who WA	sand (Red	6443.30 439)
CBAY. TANGO 1/5 EDG	700010	/ / 00	, , , , ,	
	RECEIVED	0 9 MAY 2019		
Outefrime, File Pans to? : Prell. Report	Days O	f Repair: 4		
1) : Final Report	Resurv	ey No. of Trip:	Survey Fee:	
Date/Time, File Return 197			Tramportation	
als- typist		Site Insp (\$)_S+RSQ	
		Interview (\$) Photos	
Report Format : Merimen		Tech Invs (\$) Offers	270
Lump Sum / I.B.I: (\$ 8700 =	y .	Weekend (\$	y.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:189607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	3 Anson Ro	ngleaf Tower	From:	EKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933		
Attn:	Chong Boo	n Sen	Date:	021	May 2019	
		Prelimin	ary Adv	ice		
Vehicle	e No	: SKA6179T		Accid	ent Date	21/04/2019
Make			B	Policy	No.	: DMPCSN1807891901
Assign	ment Date	: 02/05/2019		Exces	is.	: S\$1,000.00
- COVERN	f Inspection	: 02/05/2019			Juration of Repair	4.00
	ction At	PAUL HOE BATTERIES & MOTOR 1 KAKI BUKIT AVE 6 #01-109 SINGAPORE 417883	SERVICE	S (HC))	
Point	of Impact / G	eneral Description of Damages				
The ve	ehicle sustaine	ed impact / damages front o/s portion a	and parts cl	aimed	d are consistent to t	he accident.
		Repairer's Estimate (Gross)	-1	S\$	15,143.30	
		Revised Amount		S\$	10,889.51	
				S\$	0.00	
		Check Items (Estimated)		S\$		
		Total	- 6	29	10,889.51	
		Lump Surn Repair (estimated)	3	S\$	8,700.00	
		Total Loss Consideration				
		New for Old Value	1	S\$		
		Pre-Accident Value	:	S\$	52,000.00	
		COE / PARF Rebate	1	S\$	39,407.00	
		Salvage Value	1	S\$		
		Margin for Repair	25	S\$	12,593.00	
		Brake System : In Order Steering System : In Order Tyre Condition (Front) : 6/6 mm Tyre Condition (Rear) : 6/6 mm				
Rema	rks					
(×)	The vehicl	e is repairable at our adjusted amount your authorisation.	. We have	also d	confirmed excess a	nd policy coverage. Kind
()	The vehicl	e is uneconomical to be repaired, you	are advised	i to in	vite tender for the w	vreck.
()	Other com	ments:				

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	ubmitted Adj Assigned Adj F		Adj Submitted	Ins Auth'ed	Status	
Main	02 May 2019		02 May 2019 09:33 Assign				New Assignm Cancel Case	ent
	Main	Ref	erence	Cla	im Details	Documer	its	Show All
Description (Charles) and Clark	UBFOLDER DET	CONTRACTOR OF THE PARTY OF THE			ATTERNOLOGICA CONTRACTOR OF THE PARTY OF THE	Annual Control of the	ited by insure	1
Insured: Vehicle Re	n No.:	SKA6			IMITED, Co. Reg. N ste of Loss:	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW	/2019 00:00 - :5	in.
-	Daim Type:		NM19D201806	22.00	Policy/Cover Note No.:		DMPCSN1807891901 (Comprehensive)	
		Excess:				S\$1,000.00 KI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tei:		
Repairer:								
Handling 1	Insurer:	Sen]	aiping Insurance	e (Singapor	e) Pte. Ltd. (HQ) - T	61: 0389 0111 [Handled by Chor	ng soon
Adjuster:					- Tel: 6256-3561			
Driver/Cu	stodian:	KANG H	WEE CHEW (48 / F	emale), f	RIC: S71072288, T	el: +6594503710	Email: NOEMAIL	
ASSOCIA	TED MAIL REC	EIVED				View All	Compose C	ase Mail
There are	no mail for this o	ase.				2,140,000		
ALL ASS		S Type Task G	roup Subject	Handler	View All Search	Tasks Crea	te New Task Created Or	Complete Done

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 2 May 2019 4:07 PM

To:

phbms@yahoo.com; SUR

Subject:

SKA 6179T-DOA:21/4/2019 (CHINA TAIPING OD)

Dear Paul,

As instructed by our client, please proceed to repair the insured vehicle SKA 6179T (Excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with:

*SKA6179T (SNM19D201806C01)

OD
Apr 21 2019 12:00AM
[FAITH INTERNATIONAL PRIVATE LIMITED]
Paul Hoe Batteries & Motor Services

From	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 02/05/2019 15:47 PM.					
Го	LKK HQ					
Subject	Alert - Adj Mandate Approved (S\$8700.00) - SKA6179T - Claim Handler: Chong Boon Sen					
Approved:	8700.00.					
Approved:	:8700.00.					
- A. A	ENTS SUMMARY					

SGCARMART.COM

Login 5

- New Cars

Overview

Used Cars

Sell My Car

Directory

Similar

Products

٠

Insurance

Dhotos

Articles

.

Citigold Enjoy greater transparency on transactions

E-Class E250

Price Range

Arressories

Depreciation

2011

Vehicle Type

N

٠

Map

Home » Used Cars » William Lee Car Aircon Engineering » Mercedes-Benz E-Class E250 CG1

Insurance

Mercedes-Benz E-Class E250 CGI

Financial

OFCITION	rinanciai Insurance	Accessories Simil	ar Research	Photos
Price	\$56,800			
Depreciation ①	\$13,720 /yr View models with similar	Reg Date ar depre	10-Jun-2011 (2yrs 1mth 7days Co	OE left)
Mileage	N.A.	Manufactured (*)	2010	
Road Tax 💮	\$974 /yr	Transmission	Auto	
Dereg Value 🕜	\$45,283 as of today (ch	nange) OMV 🗇	\$55,808	
COE ①	\$56,001	ARF (7)	\$55,808	
Engine Cap	1,796 cc	Power	150.0 kW (201 bhp)	
Curb Weight 💮	1,650 kg	No. of Owners	2	
Type of Vehicle	Luxury Sedan			

Features

1.8L 4 Cylinders In-line Turbocharged Engine Producing 210BHP And 310NM. SRS Airbags, ABS, ESP, Immobilizer, Multi Function Steering. View specs of the Mercedes-Benz E-Class Salpon (2009-2013)

Accessories

Keyless Entry/start, Electric Memory Seats, Front & Rear Parking Sensors, Reverse Camera, Side Blind, Motorized Rear Blind.

Description

Major Servicing Done With Many Wear And Tear Parts Replaced, Oil Change Regularly Every 7k KM, All With Receipt To Prove. PPS Done For 1 Year, Always Parked Under Shelter, Immaculate Condition. Comfortable Drive With Low Maintenance Cost. Owner Consignment Unit!

Category

PARF Car, Premium Ad Car.

Status

Availabl-

Compare














Click on the point to view

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	5220G	
Vehicle No.:	SKA6179T	
Vehicle to be Exported:	No	
Intended Deregistration Date:	02 May 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	E250 CGI A	
Primary Colour:	Black	
Manufacturing Year:	2010	
Engine No.:	27186030176217	
Chassis No.:	WDD2120472A371183	
Maximum Power Output:	150.0 kW (201 bhp)	
Open Market Value:	\$53,487.00	
Original Registration Date:	17 Mar 2011	
First Registration Date:	17 Mar 2011	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$53,487.00 2674)	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	16 Mar 2021	
PARF Rebate Amount: Intended COE Rebate Details	\$29,417.00	
COE Expiry Date:	16 Mar 2021	
COE Category:	E - Open Category	
COE Period(Years):	10	
QP Paid:	\$58,890.00	
COE Rebate Amount:	\$9,990.00	
Total Rebate Amount:	\$39,407.00	

The information contained herein is correct as at 02 May 2019

ОК

MSAT19052395 / Sng Ah Tee Mutor & Panel Service Pte Ltd - Plomeer ENTRY DATE & TIME: 23/04/2019 12:23 SUBMITTED BY: JOYCE TAN LAI CHIN

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 23/04/2019 18:03

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report

23/04/2019 12:23

Date Of Accident

21/04/2019 00:40

Exact Location Of Accident

JUNCTION OF WOODLAND AVE 2 & AVE 1

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKA6179T

Insured/Policyholder

Name Of Registered Owner

FAITH INTERNATIONAL PRIVATE LIMITED

Co Reg No

197100926W

Email Address

DEBORAH@FAITH-INTL.COM

Mobile Phone No.

Alternative Phone No

Office-67481996

Vehicle Particulars

Manufacturer

MERCEDES-BENZ

Model

E250-1.8 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for

repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

DMPCSN1807891901

Cover Note Number

Driver

Name of Driver

KANG HWEE CHEW

NRIC No

S7107228B

Date Of Birth

25/02/1971

Occupation

INDOOR

Date Of Driving Pass

Driving Experience

19/02/1998 21 YEARS AND 2 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-94503710

Fax Number

Contact Number

EMail Address

NOEMAIL

E-FILE 5/2/2019

BLK 158 YUNG LOH RD Address

#12-54

610158 Postcode

Was driver an employee of the insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLIDED INTO MOTORCYCLIST Type Of Accident

CLEAR Weather Conditions Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JRR3912 (MOTORCYCLE)

Number of vehicles (including own vehicle) involved in

the accident

NO Was any body injured in the Accident?

NO Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

NO

YES

NO

If Yes, Please state which Police Station

Police Station Name

JURONG NPP

Police Station Address

ROAD: 158 YUNG LOH ROAD #01-58, POSTCODE: 610158, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20190423/2061. REMARK: I WAS UNABLE TO MAKE THE REPORT ON 22/04/2019, AS I WAS IN HOSPITAL

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

JRR3912

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

* No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future dalms.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements undes-any regulations, laws or court orders.



Policyholder's Signature Date & Time:

Orivor's Signature

lif driver is not the policyh

Date & Time:

Reporting Centre Be

Name

NRIC/FIN No.1

TAM AWARED THAT MY IT SURER MAY HAVE A 14 DAYS TRIFFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY, I WILL CHECK MY POLICY FOR MORE DETAILS.

SK	Εl	CH	PL	AN
	-	-		

CONTRACTOR IN	TITISIP Woodland Due 2 ISTANCES OF THE ACCIDENT
40000	circumstances
sher to	Police Report 7/20190423/2061
S.AS.ANON	Claim own policy Claim third party Claim Oth TP at other works hop For record purpose Policy No. DM PCSN 1807-891901
CLARATION	regoing particulars are tryle in every respect. Insurer China venno SKP61



中国太平保险(新加坡)有限公司 THIS INSURANCE (SINGAPORE) PTE. LTD.

Co Reg No. 2002083848

NOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE

Vehicles (Third-Pury Risks and Compensation) Act (Cooper to for Variables (Third-Purty Risks and Compensation Roles, 1960 Road Transport Act, 1967 (Molayand) Molter Vehicles (Third-Purty Risks) Roles, 1950 (Malayand)

MICE R 200 DR0999E Cov.Type: C PLM 326853

ORIGINAL

CE	DT	BE1	CA	ти.	Blin

DHPCBHI801891901

Engine No :27186036176217 Chally | MD02120472A371183

1. Index Mark and Registration

Number of Vehicle

4. Data of Employ of Insurance

BEAG3797

2. Name of Policy Holder

PATER INTERNATIONAL PTG 140

Effective date of the Commoncement of insurance for the purposes of the Regulations. 17 March. 2019 Ordinance of Enactment.

Hamad Drivers Ex Sect. 2 \$5500.00 Additional &s Other than Hamed Drivers:

Ex Sect. I - Age <= 25...... #33,000.00

Ex Sect. I - Age >= 26...... #\$500.00

16 Hersch 2020

. Age as et date ef socident

5. Parsons or Classes of Persons entitled to drive"

Any person who is driving on the Policyholder's order of with their permission.

Provided that the person driving is permitted in accordance with the licensing or other lave or requisitions to drive the Mutue Vehicle or has been as permitted and is not disqualified by order of a Court of law or by reason of any enectment or regulation in that behalf from driwing the Noter Vehicle.

6. Limitations as to use:"

Use for social, domestim and pleasure purposes and for the Policyholder's business. The policy does not cover use for him or re-and tuition driving test racing page-making, reliability trial, speed-testing, the corriege of goods other than complex in communition with any trade or business or use for any purpose is unnection with the Mutar Trade.

Encare whichever is applicable for lesses occurring outside Singapore (Constructive Total Loss/Theft) will be deshied.

One time Waiver of Excess for the first 551,000 will apply to the Insures and Named Drivers in the event

HIME PURCHASE CO. : DOG BANK ATD AS MP OWNER

Limitations randored inoperative by Section 5 of the Mosor Venicles (Third-Party Fashs and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act 1997 (Malaysta), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINCAPORE) PTE. LTD.


Issued By:

thorised Officer

Authorised Signatory

3 Anum Road #16 00 Spreeded Tower Segopore 070909 Tel 6389 0111 Fax: 6225 3592 Widade: www.sg.cntaping.com

IC,DL





POLICE REPORT





1 of 3

Report No. T/20190423/2061

Police Station Of Origin: Jurong NPP 158 Yung Loh Road #01-58 SINGAPORE 610158

Tel No: 1800-2659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/04/2019 13:28			Vide Report No.:	Station Diary No.: 30	
Informan	t's Partici	ulars	STORING STOR		
Name of	Informant		Address: APT BLK 158 YUNG LO	OH ROAD #12-54 SINGAPORE 610158	
ID Type / ID No.: NRIC NO / S7107228B			Contact No.: Home/Office: Mobile: 94503790		
Nationality SINGAPO	y: ORE CITIZ	EN	Email:		
Sex: Female	Age: 48	Date of Birth: 25/02/1971	Type of Informant:		
Race: Chinese			Language: Institution / School Nam		
Occupation: Company director			Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 21/04/2019 00:4	Type of Location: Straight Road
Location: Along Road 1 WOODLAND Near to Wood Weather: Clear		Road Surface:		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Wo	Traffic Volume: Light	
Type of Collis	ion: ing Vehicles - Head To			Anyone conveyed by ambulance:

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRR3912	Motorcycle				Seriously Damaged	
SKA6179T	Car	MERCEDES BENZ	E250 CGI A		Seriously Damaged	

Details of Person Involved	CONTRACTOR OF THE PARTY OF THE
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:

Jurona NPP



2 of 3 Report No. T/20190423/2061 158 Yung Loh Road #01-58 SINGAPORE

Tel No: 1800-2659999

CONTINUATION OF REPORT

Driver	THE RESERVE THE PERSON NAMED IN COLUMN TWO	the same of the last		ALC: N		
Name	KANG HWEE CHEW		ID No.		S7107228B	
Related Vehicle	SKA6179T (Car)		Conta	ct No.	94503790	
Hospital/Clinic NIL			Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL	
Date Treatment	NIL	Date Disch		NIL		
No. of Days gran	Degree of	injury	NIL			

On the 21/04/2019 at about 0040hrs, I was travelling in my vehicle SKA6179T along Woodlands Avenue 2 on lane 3 when there was a foreign motorcycle JRR3912 in front of my vehicle.

We were then approaching a traffic light when the traffic light then turned red and the said motorcycle rider then applied brakes and I then stopped my vehicle and couldn't stop in time and collided onto the rear of the said motorcycle who was infront of me and the said rider then fell onto the road surface as a result of the collision.

No visible injuries was observed on the said motorcyclist. No police or ambulance came to scene. My vehicle front right headlight and bumper suffered serious damages as a result of the collision. I was then advised by my insurance company to lodge a traffic accident report as it involves as foreign vehicle. That's all.

I did not managed to exchange particulars with him as he informed that he was not injured and my phone battery was flat on that day. However, I did provide my name and phone number to him asking him to stay in contact with me.





Police Station Of Origin: Jurong NPP 158 Yung Loh Road #01-58 SINGAPORE 610158 Tel No: 1800-2659999

3 of 3 Report No. T/20190423/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 2 GOH WEI JIE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 23/04/2019 13:28
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt MOHAMAD ZULFAZDLI BIN :- ABDULLAH Contact No.: 65476204	Classification Of Case:

Paul Hoe Batteries & Motor Services

Blk 1 Kaki Bukit Ave 6, #01-109 AutoBay @ Kaki Bukit, Singapore 417883 Tel: 67419686 Fax: 67476918

Date:

24 April 2019

120 M H

The Motor Claims Department China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: 6389 6177

Fax: 6224 7478 / 6224 7175

Email: claimsdept@sg.cntaiping.com

anale .

900960g

2/5 #8700/ 4/5

The pld. 18/1/

OWN DAMAGE CLAIM UNDER POLICY NO. DMPCSN1807891901 REPAIR QUOTATION FOR SKA6179T MERCEDES BENZ E250

	Qty	L	(\$)
Front bumper cover	1		>-5 1,522.00 —
Front bumper side retainer L/R	2		OCSCN 130.00 WC
Front bumper reinforcement	1		670.00
Front bumper inner foam	1		T1 250.00
Front bumper lower grille	1		2 1 85.00 X
Front bumper tow cover	1		70.00
Front bumper retaining clip set	1		95.00
RH head light assy	1		3/2 3,200.00
RH headl light bracket	1		4 7 250.00 X
RH head light spray jet unit	1		cm 125.00 -
RH head light spray jet cover	1		71. 2 55.00
RH head light spray jet cover hinge	1		M - S 85.00
RH front fender	1	1057.45	suf /32 (1,075,00 -
RH front fender splash shield	1		70.1 175.00
RH front fender splash shield clip set	1	N. Nacotat	1 PC 76.00 _
RH front fender chrome trim	1	142	Acr 150.00 —
RH front fender "Blue Efficiency" emblem	1		1 1 75.00 X
Front bonnet	1	1545.12	54/34(2,600,00
Front bonnet hinge L/R	2		1 1 290.00 X
Front bonnet lock assy	1		105.00 ×
Mercedes Benz mascot	1		n → 90.00 ×
Daytime running light back grille RH	1		7~1 49.00
Daytime running light RH	1		51 0300.00
Air inlet flap RH	1		11 65.00 🗴
Front grille	1		Cm 680.00
Front parking sensor set	1	214	4-5 1,100.00
Front support top panel	1		170.00 X
			Total of the above 13,537.00
			Less 10% 1,353.70 10705
			Total Cost of parts 12,183.30 9 6 39 5

LABOUR

To remove/refix radiator and conduct pressure test for prevent leak.

To remove/refix aircon condenser and vacuum/charge gas.

11 150.00 X

11 150.00 X

To check wiring/repair where needed.

60.00 X Page 2/2

OWN DAMAGE CLAIM UNDER POLICY NO. DMPCSN1807891901 REPAIR QUOTATION FOR SKA6179T MERCEDES BENZ E250

To align head light and focus head light beams.

120.00 30

Labour charges for renewing/repair and aligning damaged and affected parts/areas.

1,200.00 520

Spray painting of all affected parts/areas.

1,200.00 700

Towing fee.

11 80.00 X

Total Cost of labour

2,960.00

10889.51

Total Repair Cost

15,143.30

Yours faithfully

Paul Hoe Batteries & Motor Services

1 Kaki Bukit Ave 6 #01-109, #02-25

AutoBay@Kala Buka, Singapore 417883 fel: 6741 9686, 6748 9386 Tel/Fax: 6747 6918

Paul Hoe Batteries & Motor Services

uno Consult, at a hence notify

of spinor pointing

vity is on a "Water Properties" basis

Description of the company of the reconstruct and is a subject to the company of the company of

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Our File No:

CS/CTI19007679/UVD3N2

Date:

13/05/2019

REFERENCE

Insured/Claimant: PRIVATE LIMITED FAITH INTERNATIONAL

Policy No:

DMPCSN1807891901

Date of Loss:

21/04/2019

Nature of Claim:

OD

Claim No:

SNM19D201806C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKA6179T

Make & Model:

MERCEDES-BENZ E250, 1.8 (A) 17/03/2011 (Man. Year: 2010)

Engine No: Chassis No:

Odometer:

27186030176217 WDD2120472A371183

200123 km

Reg. Date: Colour:

Price:

Black

Engine Capacity: Market Value/New Car

Sum Insured (S\$):

1796 cc

\$\$52,000.00

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

45.56

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

245/457R17

Rear Tyre Size:

14,143.30

245/45ZR17

Front Left Side: Front Right Side: Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side:

Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items		Repairer's 12,183.30 0.00	Adjuster's 9,639.51 0.00	2,543.79 0.00	Diff % 20.88
Labour Paintwork Labour		2,960.00 0.00	1,250.00 0.00	1,710.00 0.00	57.77
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	15,143.30	10,889.51	4,253.79	28.09
,	Approved Total (Overridden) (S\$) - Excess (S\$)	1,000.00	1,000.00	0.00	0.00

INSPECTION

Date of Assignment:

02/05/2019

Date Inspected:

02/05/2019 Inspected At:

Nett Amount (S\$)

Paul Hoe Batteries & Motor Services

6,443.30

(HQ)

7,700.00

1 KAKI BUKIT AVE 6 #01-109

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2019)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:		no print-code for SKA6179T)
Validity:	These estimate numbers with t	es are valid only if they contain the print code (above) on all estimate pages, running page he END OF ESTIMATES marker on the last estimate page
Further Info:	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER COVER	Distorted	1,522.00 FL	*1,522.00 FL
2	1	*FRONT BUMPER SIDE RETAINER L/R	O/s Cracked	130.00 FL	*65.00 FL
3	1	*FRONT BUMPER REINFORCEMENT	Repair	670.00 FL	*- FL
4	1	*FRONT BUMPER INNER FOAM	Tom	250.00 FL	*250.00 FL
5	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	85.00 FL	*- FL
6	1	*FRONT BUMPER TOW COVER	Missing	70.00 FL	*70.00 FL
7	1	*FRONT BUMPER RETAINING CLIP SET	Necessary	95.00 FL	*95.00 FL
В	1	*RH HEAD LIGHT ASSY	Broken	3,200.00 FL	*3,200.00 FL
9	1	*RH HEAD LIGHT BRACKET	Not Necessary	250.00 FL	*-FL
10	1	*RH HEAD LIGHT SPRAY JET UNIT	Cracked	125.00 FL	
11	1	*RH HEAD LIGHT SPRAY JET COVER	Torn	55.00 FL	
12	1	*RH HEAD LIGHT SPRAY JET COVER HINGE	Missing	85.00 FL	*85.00 FL
13	1	*RH FRONT FENDER	Bent/Buckled	1,075.00 FL	*1,051.45 FL
14	1	*RH FRONT FENDER SPLASH SHIELD	Torn	175.00 FL	*175.00 FL
15	1	*RH FRONT FENDER SPLASH SHIELD CLIP SET	Necessary	76.00 FL	
16	1	*RH FRONT FENDER CHROME TRIM	Necessary	150.00 FL	
17	1	*RH FRONT FENDER BLUE EFFICIENCY EMBLEM	Not Necessary	75.00 FL	
18	1	*FRONT BONNET	Bent/Buckled	The state of the s	*2,545.12 FL
19	2	*FRONT BONNET HINGE L/R	Not Necessary	290.00 FL	933449
20	1	*FRONT BONNET LOCK ASSY	Not Necessary	105.00 FL	
21	1	*MERCEDES BENZ MASCOT	Not Necessary	90.00 FL	
22	1	*DAYTIME RUNNING LIGHT BACK GRILLE RH	Twisted	49.00 FL	*49.00 FL
23	1	*DAYTIME RUNNING LIGHT RH	Broken	300.00 FL	
24	1	*AIR INLET FLAP RH	Not Necessary	65.00 FL	
25	1	*FRONT GRILLE	Cracked	680.00 FL	
26	1	*FRONT PARKING SENSOR SET	Missing	1,100.00 FL	
27	1	*FRONT SUPPORT TOP PANEL	Repair	170.00 FL	*- FI
F=Fn	anchise	part. L=ListItemDisc.			
			Sub Total (S\$)		1,071.06
	- List Item Discount on L Items 10.00/10.00% (S\$) 1,353.70				
			Total Parts (S\$)	12,183.30	9,639.51

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE/REFIX RADIATOR AND CONDUCT PRESSURE TEST FOR PREVENT LEAK	New	150.00	0.00
2	TO REMOVE/REFIX AIRCON CONDENSER AND VACUUM/CHARGE GAS	New	150.00	0.00
3	TO ALIGN HEAD LIGHT AND FOCUS HEAD LIGHT BEAMS	New	120.00	30.00
4	LABOUR CHARGES FOR REWIRING/REPAIR AND ALIGNING DAMAGED AND AFFECTED PARTS/AREAS	New	1,200.00	520.00
5	SPRAY PAINTING OF ALL AFFECTED PARTS/AREAS	New	1,200.00	700.00
6	TOWING FEE	New	80.00	0.00
7	TO CHECK WIRING/REPAIR WHERE NEEDED	New	60.00	0.00
	Gross Labo	ur Cost (S\$)	2,960.00	1,250.00
	Report was unsubmitted dur			

< END OF ESTIMATES >