

(000000)

ASS. RES. ETC.

REF:

Q/FCI19007688/K/H372

Special Instruction:

Surveyor

Kenny

ASSIGNMENT (Office)

From Person

CWS

Hunny Kuo

of

FEI

Date/Time: 5:32pm 30/4/19

Estimated Cost

Bill to

OD ☒ WS ☐ TT RES ☐ OD RES ☐ EVA ☐ INV ☐ MY ☐ CS

To Inspect Vehicle No.

SJS 55704

Insured:

SHB 3637M

at Workshop no/

City Auto

Tel:

64531235

of

Blk 160 Sin Ming Ave #05-01

Policy No.

Claim No.

D19002819MF8H

Sum Insured

Excess

Make of Veh.
(Client's Record)

D.O.A.

29/4/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time:

11:31am 01/5/19

Person Contacted:

Yvonne

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJS 55704-CS/CTJ18015657/K/d3e2

DOA: 24/8/2018

SHB 3637M-CCB/AG08026979/KDn

DOA: 1/10/2018

315@3:51pm- Revised preli advise via merimen.

13/5 C/Ly 8-2550 Combined (Red: 2459.72, 49%)

ASS. REC. BY:

REF:

1021

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 810k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STJ 55 770 U Yr Regn: 08, 09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Vios c.c. 1497Colour: M. Orange A/C: Insured / Std / NI / NASp. Reading: 242221 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR0531479305124263Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / A/Rlm orTyre Size: F: 185 160R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Carrimatal

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 27/4/19 D.O.I. 30/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 15m

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass toMV: 10KLTA 6615NV: 3385

RECEIVED 14 MAY 2019

Advertisement sticker receipt

Date/Time, File Pass to?

☐ : Prel. Report1) 1315 typist☐ : Final Report

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I. (\$) 2550/-Days Of Repair: 4Resurvey No. of Trlp: LAdd Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + P.S. SI

Fees

Others

TOTAL

140505018258



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002819MFSH

Date: 3/5/2019

Our Ref: CS/FCI19007688/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJS 5570U

Please be informed that we had conducted the inspection of the abovementioned vehicle
3/5/2019 at the premises of M/s City Auto have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,009.72</u>
Revised Estimate Amount	: S\$ <u>2,710.93</u>
"Check" Items Amount	: S\$ <u>509.03</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-04-2019	Our Ref No. D19002819MFSH
Accident Date	27-04-2019	Claim Type. Third Party
Insured Vehicle	SHB3637M	Third Party Vehicle. SJS5570U
Survey Location	BLK 160, SIN MING DRIVE SIN MING AUTO CITY #05-01	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 0	Fax No. 64537944
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 3 May 2019 3:51 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002819MFSH/1
Attachments: PRELI ADVISED SJS 5570U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJS 5570U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 2 May 2019 11:31 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002819MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 30 April 2019 5:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002819MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3755Z
Vehicle Details	
Vehicle No.:	SJS5570U
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	1NZX948516
Chassis No.:	MR053HY9305124263
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	24 Aug 2009
First Registration Date:	24 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$12,394.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2019
PARF Rebate Amount:	\$6,197.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,336.00
COE Rebate Amount:	\$418.00
Total Rebate Amount:	\$6,615.00

The information contained herein is correct as at 02 May 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SJS5570U
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Chassis No.:	MR053HY9305124263
Propellant:	Petrol
Engine No.:	1NZX948516
Engine Capacity:	1497 cc
Maximum Power Output:	80.0 kW (107 bhp)
Maximum Laden Weight:	1505 kg
Unladen Weight:	1095 kg
Year Of Manufacture:	2009
Original Registration Date:	24 Aug 2009
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
Quota Premium:	\$13,658.00
COE Expiry Date:	23 Aug 2019
Road Tax Expiry Date:	23 Aug 2019
PARF Eligibility Expiry Date:	23 Aug 2019
Inspection Due Date:	23 Aug 2020
Intended Transfer Date:	02 May 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36
ROBINSON RD
CITY HOUSE
SINGAPORE 068877
Attention: Juanita Yvonne Pillai
Contact: -

Fax No.: 65073849

Estimate : QUOT201904-000574(00)

Date : 29/04/2019
Vehicle No. : SJS5570U
Make/Model : TOYOTA VIOS E AUTO

Mileage (km) : 0
Chassis No. : MR053HY9305124263
Accident Date : 27/04/2019 00:00:00
Claim No. : SHB3637M
Reference : SJS5570U
Policy No. : 5097493176

*Not withain
6/1 Long 87
Resurvey After Paint
& days*

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	RH headlamp	1.0	427.80	C/M 427.80 ✓
2	Front bumper	1.0	398.20	Bu 398.20 ✓
3	Front bumper retainer	2.0	53.10	D-1 106.20 ✓
4	Front bumper reinforcement	1.0	360.25	n 360.25 X
5	Front bumper clip	10.0	2.21	nn 22.10 ✓
6	Front RH fender	1.0	594.50	Bu 594.50 ✓
7	Front RH fender brace bracket	1.0	78.70	bu X 78.70 7K
8	Front RH fender inner shield	1.0	168.10	D-1 168.10 ✓
9	Front RH fender inner shield clip	8.0	2.21	n 17.68 ✓
10	Front RH wheel bearing	1.0	90.70	nn 90.70 X
11	Front RH lower arm	1.0	389.50	nn 389.50 X
12	Front RH knuckle arm	1.0	396.15	nn 396.15 X
13	Front RH shock absorber	1.0	369.70	nn 369.70 X

List Total :

25% Discount S\$

3,419.58

854.86

2,564.72

SPECIAL NET :

1	Front RH rim	1.0	350.00	nn 250.00 350.00 ✓
2	Front RH door advertisement sticker	1.0	450.00	(Bill) nn 450.00 ✓

SPECIAL NET Total S\$:

800.00

LABOUR :

* To remove and install front RH suspension	1.0	140.00	nn 140.00 X
* To conduct wheel alignment	1.0	65.00	60.00 65.00 ✓
* To check wiring and lighting	1.0	40.00	20.00 40.00 ✓
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	600.00	480.00 600.00 500
- Spray painting on affected & replace parts	1.0	800.00	600.00 800.00 ✓

1,645.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CONTINUE NEXT PAGE

Page 1 of 2



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201904-000574(00)

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Attention: Juanita Yvonne Pillai

Contact : -

Fax No. : 65073849

Date : 29/04/2019

Vehicle No. : SJS5570U

Make/Model : TOYOTA VIOS E AUTO

Mileage (km) : 0

Chassis No. : MR053HY9305124263

Accident Date : 27/04/2019 00:00:00

Claim No. : SHB3637M

Reference : SJS5570U

Policy No. : 5097493176

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$ 5,009.72

GST 7% S\$ 350.68

Amount Due S\$ 5,360.40


for CITY AUTO PTE LTD



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Attention: Juanita Yvonne Pillai

Contact :-

Fax No. : 65073849

Estimate : QUOT201904-000574(00)

Date : 29/04/2019

Vehicle No. : SJS5570U

Make/Model : TOYOTA VIOS E AUTO

Mileage (km) : 0

Chassis No. : MR053HY9305124263

Accident Date : 27/04/2019 00:00:00

Claim No. : SHB3637M

Reference : SJS5570U

Policy No. : 5097493176

*Not Notified
L1 Imp @ 2550
Repair After Paint
4 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	RH headlamp	1.0	427.80	CM 427.80 ✓
2	Front bumper	1.0	398.20	Bu 398.20 ✓
3	Front bumper retainer	2.0	53.10	Ort 106.20 ✓
4	Front bumper reinforcement	1.0	360.25	n 360.25 X
5	Front bumper clip	10.0	2.21	m 22.10 ✓
6	Front RH fender	1.0	594.50	Bu 594.50 ✓
7	Front RH fender brace bracket	1.0	78.70	Bu 78.70 X
8	Front RH fender inner shield	1.0	168.10	Ort 168.10 ✓
9	Front RH fender inner shield clip	8.0	2.21	m 17.68 ✓
10	Front RH wheel bearing	1.0	90.70	na 90.70 X
11	Front RH lower arm	1.0	389.50	Bu 389.50 X
12	Front RH knuckle arm	1.0	396.15	Lu 396.15 X
13	Front RH shock absorber	1.0	369.70	Lu 369.70 X
List Total :				1,734.58
25% Discount S\$				854.86
				2,564.72
SPECIAL NET :				
1	Front RH rim	1.0	350.00	Not 350.00
2	Front RH door advertisement sticker	1.0	450.00	(Bill) 450.00 X
SPECIAL NET Total S\$:				800.00
LABOUR :				
* To remove and install front RH suspension		1.0	140.00	na 140.00 X
* To conduct wheel alignment		1.0	65.00	65.00 60
* To check wiring and lighting		1.0	40.00	5rd 40.00 20
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts		1.0	600.00	600 600.00
- Spray painting on affected & replace parts		1.0	800.00	600 800.00
				1,645.00

CONTINUE NEXT PAGE

Page 1 of 2



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Attention: Juanita Yvonne Pillai

Contact : -

Fax No. : 65073849

Estimate : QUOT201904-000574(00)

Date : 29/04/2019

Vehicle No. : SJS5570U

Make/Model : TOYOTA VIOS E AUTO

Mileage (km) : 0

Chassis No. : MR053HY9305124263

Accident Date : 27/04/2019 00:00:00

Claim No. : SHB3637M

Reference : SJS5570U

Policy No. : 5097493176

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E

Total S\$: 5,009.72

GST 7% S\$: 350.68

Amount Due S\$: 5,360.40


for CITY AUTO PTE LTD

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007688/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3637M	Veh. Inspected	SJS 5570U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002819MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	30/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305124263	Colour	METALLIC ORANGE	
Odometer	242221	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	CONTINENTAL	7 mm	
L/H Front Tyre	185/60 R15	CONTINENTAL	7 mm	
R/H Rear Tyre	185/60 R15	CONTINENTAL	7 mm	
L/H Rear Tyre	185/60 R15	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2019	Inspection Date	30/04/2019	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 5570U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH HEADLAMP	CRACKED	427.80	427.80
1	FRONT BUMPER	BUCKLED	398.20	398.20
2	FRONT BUMPER RETAINER @\$53.10	DISTORTED	106.20	106.20
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	360.25	-
10	FRONT BUMPER CLIP @\$2.21	NECESSARY	22.10	22.10
1	FRONT RH FENDER	BUCKLED	594.50	594.50
1	FRONT RH FENDER BRACE BRACKET	TO REPAIR SEE LABOUR	78.70	-
1	FRONT RH FENDER INNER SHIELD	DISTORTED	168.10	168.10
8	FRONT RH FENDER INNER SHIELD CLIP @\$2.21	NECESSARY	17.68	17.68
1	FRONT RH WHEEL BEARING	NOT NECESSARY	90.70	-
1	FRONT RH LOWER ARM	SERVICEABLE	389.50	-
1	FRONT RH KNUCKLE ARM	SERVICEABLE	396.15	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	369.70	-
	LESS 25% DISCOUNT		-854.90	-433.65
			2,564.68	1,300.93
SPECIAL NETT ITEMS				
1	FRONT RH RIM (SN)	DENTED	350.00	250.00
1	FRONT RH DOOR ADVERTISEMENT STICKER (SN)	NECESSARY	450.00	450.00
			800.00	700.00
LABOUR				
	TO REMOVE AND INSTALL FRONT RH SUSPENSION.	NOT NECESSARY	140.00	-
	TO CONDUCT WHEEL ALIGNMENT.		65.00	60.00
	TO CHECK WIRING AND LIGHTING.		40.00	20.00
	TO KNOCK, JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT RH FENDER BRACE BRACKET.		600.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		800.00	600.00
			1,645.00	1,180.00

Report Ref No. CS/FC119007688/Ktd3n2



GRAND TOTAL		5,009.68	3,180.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CS/FC19007688/Ktd3n2

MARKET VALUE: \$10,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,615.00=NETT VALUE: \$3,385.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.