

ASS. REC. BY:

REF: CS3/C71/9007692/T1cd3

Special Instruction:

Surveyor: Taufiq

ASSIGNMENT (Office)

From (Person): Ong chin kiat

of CTI

Date/Time: 2.5.2019 11.42a.m

Estimated Cost:

Bill to:

OD (TP) WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLW 49945

Insured: YL 62104

at Workshop m/s Ah Koon motor

Tel: 627 07113

of B1K 1001 Bukit Merah Lane 3 # 01-69

Policy No: DM CVSN15065019044

Claim No: SNM19D201

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.4.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 2.5.19

11.53a.m

Person Contacted:

Anthony

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	SLW 49945 - MBA/MSG 19007564/Y	D.O.A - 29/04/2019
	YL 62104 - X	
	Dismantle: 6/5/2019	
	After repair: 7/5/2019	

Toufik

REF:


CTI

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS WP' - PRS'
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No. SLW 4994S Yt Regn: 2018 Apr 1
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Shuttle C.C. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 24725 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YK 8/2 0/370
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or 5016
 Tyre Size: F: 205 / 5016
 R: 205 / 5016
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 2/5/19 21430
 Survey held at Ah Koon Motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
Range & Days

96000-97000, 8 days
1001 B.M. LMS #01-67

10/6/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: PRE

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150
150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 11:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TUNGSAN FOOD INDUSTRIES PTE LTD, Co. Reg. No.: 199002472E	
Main Claimant:	CHAN JIA SHENG RIO TYLOR, ID: S8611670G	
Vehicle Reg. No.:	SLW4994S	Date of Loss: 29/04/2019 11:00 - :59 [12 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201885C02	DMCVSN15065019044 (Comprehensive) Coverage: 24/02/2019 - 23/02/2020
Vehicle Reg. No. (Insured):	YL6210L	Policy No. (Claimant): 9VPCP1864510
		Excess: S\$0.00
Repairer:	- Not Applicable - (-)	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]	
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/05/2019]	
Driver/Custodian (Insured):	LAI HUEY SIANG (41 / Male) , NRIC: G8180781M Email:	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS								View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
No results.											

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1670G
Vehicle Details	
Vehicle No.:	SLW4994S
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	L15B5461640
Chassis No.:	GK81201390
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,485.00
Original Registration Date:	25 Apr 2018
First Registration Date:	25 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$7,485.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2028
PARF Rebate Amount:	\$5,613.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,400.00
COE Rebate Amount:	\$36,627.00
Total Rebate Amount:	\$42,240.00

The information contained herein is correct as at 19 Jun 2019

OK

for surveyor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 08:54
Date Of Accident	29/04/2019 11:00
Exact Location Of Accident	HOLLAND ROAD FILTERING TO HOLLAND AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW4994S
Insured/Policyholder	
Name Of Registered Owner	CHAN JIA SHENG RIO TYLOR
NRIC No	S8611670G
Email Address	RIOTYLOR@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96844148
Alternative Phone No	OTHERS-91914994

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	
Cover Note Number	9VPCP1864510

Driver

Name of Driver	CHAN MIA CHWEE
NRIC No	S1178490I
Date Of Birth	08/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	19/07/1975
Driving Experience	43 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96844148
Fax Number	
Contact Number	OTHERS-91914994
EMail Address	RIOTYLOR@GMAIL.COM

Address	BLK 148 SILAT ROAD #11-10
Postcode	160148
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL6210L
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LAI HUEY SIANG
NRIC/Passport Number	G8180781M
Contact Number	93628087
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was filtering from Holland Road to Holland Ave. I slowed down ~~at~~ and stopped at the filter to let the cars on my right to pass. Then the lorry, YL62102, drove very fast from behind and bang on to my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: BSL
NRIC/FIN No.: 9201 1234 5678

...CLAIM SUBFOLDER...(Pending for Survey Report)






















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 11:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TUNGSAN FOOD INDUSTRIES PTE LTD , Co. Reg. No.: 199002472E								
Main Claimant:	CHAN JIA SHENG RIO TYLOR , ID: S8611670G								
Vehicle Reg. No.:	SLW4994S	Date of Loss:	29/04/2019 11:00 - :59 [12 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201885C02	Policy/Cover Note No.:	DMCVSN15065019044 (Comprehensive) Coverage: 24/02/2019 - 23/02/2020						
Vehicle Reg. No. (Insured):	YL6210L	Policy No. (Claimant):	9VPCP1864510						
		Excess:	S\$0.00						
Repairer:	- Not Applicable - (-)								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/05/2019]								
Driver/Custodian (Insured):	LAI HUEY SIANG (41 / Male) , NRIC: G8180781M Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




*SLW4994S (SNM19D201885C02)
[YL6210L]
TP
CHAN JIA SHENG RIO TYLOR
Apr 29 2019 11:00AM
[TUNGSAN FOOD INDUSTRIES PTE LTD]

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)						Thumbnail	Print
1	30/04/19 09:08	Accident Statement						Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
2	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
3	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
4	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
5	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
6	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
7	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
8	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
9	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
10	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
11	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
12	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
13	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
14	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
15	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
16	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
17	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
18	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
19	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
20	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
21	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
22	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
23	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
24	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
25	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
26	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
27	19/06/19 18:22	General View						Load JPG	<input checked="" type="checkbox"/>
28	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
29	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
30	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
31	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
32	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
33	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
34	19/06/19 18:22	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>


Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
35	19/06/19 18:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	19/06/19 18:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	19/06/19 18:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	19/06/19 18:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 18:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 18:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/19 11:08	INSD YL6210L GIA REPORT	 Load PDF	
2	02/05/19 11:42	PRS email	 Load PDF	

Linked Accident Report Documents













View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	30/04/19 09:05	Video - Accident	 Load MP4	<input checked="" type="checkbox"/>
2	30/04/19 09:05	Video - Accident	 Load MP4	<input checked="" type="checkbox"/>
3	30/04/19 09:05	Video - Accident	 Load MP4	<input checked="" type="checkbox"/>

Assessment Reports

			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	30/04/19 09:08	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	30/04/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
13	30/04/19 09:05	Identification Card		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	30/04/19 09:05	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	30/04/19 09:05	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19007692/T1CD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN15065019044
Claimant Vehicle No :	SLW4994S	Insured Vehicle No :	YL6210L
Date of Loss:	29/04/2019	Nature of Claim:	TP
		Claim No:	SNM19D201885C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4994S	Engine No:	L15B5461640
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81201390
Reg. Date:	25/04/2018 (Man. Year: 2018)	Odometer:	24725 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/05/2019	
Date Inspected:	02/05/2019 Inspected At:	AH KOON MOTOR BLK 1001 BUKIT MERAH LANE 3 #01-69 SINGAPORE 159718
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 20 Jun 2019)
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLW4994S)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >