

2/03/2002

ASS. REC. BY:

REF: CS/MSG/19007705/UC d302

Special Instruction:

Surveyor: MARCUSASSIGNMENT (Office)

minum

From (Person): Monica chung Rizlan of MSLGDate/Time: 2.5.19 14:27pm

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 8186EInsured: WD 20682at Workshop m/s Blumxi AutomotiveTel: 67452088of 1 Kaki Bukit Ave 6, #01-28Policy No: B 29077585 TMVClaim No: 592101

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 29.4.20193.5.2019

CA / REV / REP. / REV 24 HRS

rupn

H.O.D. Endorsement: _____

Date/Time: 2.5.19 2.42p.mPerson Contacted: sallyVehicle IN / OUT

Date/Time	Action/Instruction
	Estimate (X)
	GBC 8186E - NA / CTI 19007619 / r3
	WD 20682 - NA / CTI 19007619 / r3
	Dismantle: 3/5/2019
	After repair 7/5/2019

DOA - 29/04/2019

DOA - 29/04/2019

REF: MS1G

PRs

ASSIGNMENT

From: Date: 3.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 8186E
at Workshop m/s Blumel Automotive
of 1 Kaki Bukit Ave 6 # 01-28

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No. GBC8186E Yr Regn: 1/13
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 203526 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1MC2E2620001395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-12-15

R:

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No defect.

3-4/12.

RECEIVED 09 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I: (\$)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2019		02 May 2019 14:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	PTKN VEG TRADING, Co. Reg. No.: 5232300J		
Main Claimant:	THE GREEN BOX		
Vehicle Reg. No.:	GBC8186E	Date of Loss:	29/04/2019 11:00 - :59 [65 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 592101	Policy/Cover Note No.:	B29077585TMV (Third Party Only) Coverage: 02/04/2019 - 01/04/2020
Vehicle Reg. No. (Insured):	WD2068Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/05/2019]		
Driver/Custodian (Insured):	TAN BOCK HOCK (), NRIC: S1336979H, Tel: +6597314055 Email: on WP. (MANUAL ASSIGNED) SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT:6745 2088		
Adj Asg. Remarks:			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9872D
Vehicle Details	
Vehicle No.:	GBC8186E
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 URVAN 2.5 5AT ABS AB 5DR PANEL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	YD25337502A
Chassis No.:	JN1MC2E26Z0001395
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	25 Nov 2013
First Registration Date:	25 Nov 2013
Transfer Count:	1
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Nov 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,503.00
COE Rebate Amount:	\$25,300.00
Total Rebate Amount:	\$25,300.00

The information contained herein is correct as at 03 May 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

KOREA TOURISM ORGANIZATION

Unusual Holidays

7D6N Jeju Olle Walking Trails

With Hanok Stay

TA 2146

Find Out More >

Chan's World Holidays

CHAN BROTHERS GROUP OF COMPANIES

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes E 250 Coupe



2 Owners With Very Low Mileage Of 25100 KM. Panoramic Roof. Service By C&C. Direct Owner StarAd

KA-HUP








VALUE FOR MONEY

VALUE FOR TIME

A PEACE OF MIND

HOTLINE: 6741 9997

view our cars

Browse by Category		Sort by Date Posted		20 results/page	
12 vehicles		nv350		Advanced Search Submit	
Search Selection		nv350	Any	Any	2014
		Any	Any	Any	Any
		Any	Any	Any	Available
<div><div></div><div>NO IMAGE AVAILABLE</div></div>		Nissan NV350 2.5M	\$38,500	\$7,240 /yr	26-Aug-2014
		2,488 cc	100,000 km	Van	Available
		Fuel Type: Diesel			
		Full Service By Tan Chong Motor. Loan Available At \$660 Per Month.			
		Posted: 03-May-2019 Tags: 2014 Nissan NV350, 2014 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan			
<div><div></div></div>		Nissan NV350 2.5M	\$44,800	\$8,570 /yr	23-Jul-2014
		2,488 cc	142,240 km	Bus	Available
		Fuel Type: Diesel			
		Think One Automobile & Trading			
		Posted: 02-May-2019 Tags: 2014 Nissan NV350, 2014 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan			
<div><div></div></div>		Nissan NV350 2.5M	\$43,800	\$8,170 /yr	11-Sep-2014
		2,488 cc	95,524 km	Van	Available
		Fuel Type: Diesel			
		A1 Condition, Look As New, No Repair Needed, Low Mileage, Selling Cheapest In Market, 5 Door Diesel Van! 1 Owner Only. Lowest Driveaway And High Trade & High Loan With Low Interest, See To Believe! Hu...			
		Car (S) Pte Ltd			
		Posted: 30-Apr-2019 Tags: 2014 Nissan NV350, 2014 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan			
<div><div></div></div>		Nissan NV350 2.5A	\$40,800	\$7,980 /yr	13-Jun-2014
		2,488 cc	-	Van	Available
		Fuel Type: Diesel			
		Rare 5 Doors Nissan NV350 Auto In The Market. Very Good Condition, Super Low Mileage, Well Kept By Previous Owner, Very Fast And Easy Bank/In House Loan Approve. Full Loan, Ok! Hurry Call To Book A Vi...			
		ABWIN Bus Pte Ltd			
		Posted: 30-Apr-2019 Tags: 2014 Nissan NV350, 2014 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan			
<div><div></div></div>		Toyota Camry takes on Volkswagen's Passat			
		The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.			
		Find out more!			
<div><div></div></div>		Nissan NV350 2.5A	\$43,800	\$8,500 /yr	27-Jun-2014
		2,488 cc	-	Van	Available
		Fuel Type: Diesel			
		100% Accident Free! Wide Space, Suitable For New Startup Business. Engine And Gearbox Is In Excellent Condition. Guaranteed Cheapest In The Market With The Best Condition! Flexible Financing Schemes U...			
		Car (S) Pte Ltd			
		Posted: 28-Apr-2019 Tags: 2014 Nissan NV350, 2014 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan			
<div><div></div></div>		Nissan NV350 2.5M	\$39,800	\$7,820 /yr	04-Jun-2014
		2,488 cc	136,141 km	Van	Available
		Fuel Type: Diesel			
		Agent Unit! Well Maintained, Easy And Flexible In-House Financing Available, Leather Seats, Remote Control Alarm, Pioneer Sound System, Reverse Sensors, Serviced And Maintained By Tan Chong Motor.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 14:28
Date Of Accident	29/04/2019 11:30
Exact Location Of Accident	PASIR PANJANG WHOLESALE CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC8186E
Insured/Policyholder	
Name Of Registered Owner	M/S THE GREEN BOX
Co Reg No	53349872D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82364635

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3033951800
Cover Note Number	

Driver

Name of Driver	DAVID ELIAS JASON
NRIC No	S7247527E
Date Of Birth	12/12/1972
Occupation	OUTDOOR
Date Of Driving Pass	13/07/2009
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82364635
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	219 LOYANG RISE
Postcode	507382
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WD2068Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN BOCK HOCK
NRIC/Passport Number	
Contact Number	97314055
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

30/11/19, 10:30 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

30/11/19, 10:41 AM


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(On 24/11/19 at about 1130am I was in a lot waiting for vehicle B to drive off but the driver made a reverse. I wind down the window (RTH) and shouted at him but he still proceed to reverse and hit the front RTH side of my car (A).

DECLARATION

I declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20/11/19, 10:00am

(to ARM, Sketch Plan Form 2)

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/11/19, 10:45am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.



































...CLAIM SUBFOLDER...(Pending for Survey Report)










































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 14:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PTKN VEG TRADING , Co. Reg. No.: 5232300J								
Main Claimant:	THE GREEN BOX								
Vehicle Reg. No.:	GBC8186E	Date of Loss:	29/04/2019 11:00 - :59 [65 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 592101	Policy/Cover Note No.:	B29077585TMV (Third Party Only) Coverage: 02/04/2019 - 01/04/2020						
Vehicle Reg. No. (Insured):	WD2068Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 03/05/2019]								
Driver/Custodian (Insured):	TAN BOCK HOCK (), NRIC: S1336979H, Tel: +6597314055 Email:								
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED) SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT:6745 2088								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC8186E (592101)
[WD2068Z]
TP
THE GREEN BOX
Apr 29 2019 11:00AM
[PTKN VEG TRADING]
Bluwel Automotive Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	02/05/19 11:40	Accident Statement From: SC - Reg. No: WD2068Z, Claimant: PTKN VEG TRADING	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	09/05/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/19 11:40	E-FILE REPORT (GBC8186E) From: SC - Reg. No: WD2068Z, Claimant: PTKN VEG TRADING	 Load PDF	
2	02/05/19 11:54	TP PRI & SKETCH PLAN	 Load PDF	
3	02/05/19 14:08	SURVEY DISAGREE ON SJE - ASSIGN LKK OI REVERSED & HIT TP	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	02/05/19 14:25	Email - Outsource	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007705/UCD3E2

Date: 14/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29077585TMV

Claimant Vehicle No : GBC8186E

Insured Vehicle No : WD2068Z

Date of Loss: 29/04/2019

Nature of Claim: TP

Claim No: 592101

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC8186E

Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A)

Engine No: YD25337502A

Reg. Date: 25/11/2013 (Man. Year: 2013)

Chassis No: JN1MC2E26Z0001395

Colour: White

Odometer: 203526 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/05/2019

Date Inspected: 03/05/2019 Inspected At:

Bluwei Automotive Service Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 14 May 2019)
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC8186E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >