

ASS. REC. BY:

REF:

TMI / CC3 / TMI19007712 / Kvd312

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: 8LH 4266P

Policy No. MK 000 204

Claims No. M1903124

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 571B 9909P

Yr Regn: 08, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude

c.c. 1995

Colour: M. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 438775

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1AB115AUC

273469

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal. 7 mm

R/Bal. 8 mm

L/Bal. 7 mm

L/Bal. 8 mm

D.O.A. 29/4/19

D.O.A. 30/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

571B 9909P - CC3 / AIG / 18/04/2018 / chb 392

8LH 4266P - X

Q/A: 27/5/2018

25/5/19

Email GIA to TMI

3/5/19

LS \$ 3350 (Red 15,155.38, 83M)

RECEIVED 03 MAY 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 3/5 - typist

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

menmen

Lump Sum / I.B.I. (\$

3350/-

250

10

260

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 17:27 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LCRF PTE. LTD., Co. Reg. No.: 201624597K		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB9909P	Date of Loss:	29/04/2019 10:00 - :59
Claim Type:	TP / M1903124	Policy/Cover Note No.:	MK000204 (Third Party Only) Coverage: 25/02/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLH4266P	Policy No. (Claimant):	
		Excess:	S\$1,600.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/05/2019]		
Adj Asg. Remarks:	OUR INSD HAS NOT RPT THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 May 2019 8:43 AM
To: Ng Wai Yin; 'calvin.er@transcab.com.sg'
Cc: jasminetan@transcab.com.sg; SUR
Subject: RE: SHB 9909P-DOA: 29/4/2019
Attachments: EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$3350/- @ 2 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 May 2019 8:43 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg
Cc: jasminetan@transcab.com.sg; SUR <sur@lkkauto.com>
Subject: SHB 9909P-DOA: 29/4/2019

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$3350/- @ 2 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 2 May 2019 4:16 PM
To: SUR; motorclaims@tokiomarine.com.sg
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD,
DOA: 29/4/2019, SHB 9909P (TP VEHICLE), SLH 4266P (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHB 9909P at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 30/4/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

4/29/2019

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9909P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Apr 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000404
Chassis No.:	VF1ABL15AUC273469
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$54,952.00
COE Rebate Amount:	\$16,027.00
Total Rebate Amount:	\$24,775.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2019 14:29
Date Of Accident	29/04/2019 10:20
Exact Location Of Accident	CHANGI AIRPORT TERMINAL 2 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB9909P
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-97774124

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	YAP CHWEE GIM
NRIC No	S1593178G
Date Of Birth	24/03/1963
Occupation	OUTDOOR
Date Of Driving Pass	22/03/2013
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81231461
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 184 JELEBU ROAD #28-34
Postcode	670184
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 29/04/2019 AT ABOUT 1020HRS, I WAS PARKING MY TAXI INTO THE PARKING LOT AT CHANGI AIRPORT TERMINAL 2 CARPARK. WHEN I WAS ALMOST FULLY PARKED INTO THE LOT, VEHICLE B(SLH4266P) SUDDENLY CAME AT FAST SPEED FROM MY RIGHT AND GRAZED ONTO THE FRONT RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH4266P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Changi Airport Terminal 2
Carpark

A: SHB9909P
B: SLH4266P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

AAD1904-266

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P

Not Authored
61 Smp @ 33501

Vehicle No.:

SHB 9909P

Chassis No.:

VF1ABL15AUC273469

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

29.4.2019

Third Party Insurer :

TOKIO MARINE

Date of Registration :

30/8/2013

PART**LIST**

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK
1	WIPER RESERVOIR MOTOR
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET

\$	<i>Bu</i> 1,259.42 ✓
\$	<i>Dis</i> 181.75 ✓
\$	<i>Su</i> 394.68 X
\$	<i>Dis</i> 150.77 ✓
\$	<i>Su</i> 123.88 X
\$	<i>Su</i> 472.83 X
\$	<i>Su</i> 266.80 X
\$	<i>Su</i> 207.21 X
\$	<i>R</i> 914.08 X
\$	<i>m/c/m</i> 1,184.43 ✓
\$	<i>R</i> 152.15 X
\$	<i>Bu</i> 783.83 ✓
\$	<i>Su</i> 278.84
\$	<i>Su</i> 15.79
\$	<i>Su</i> 130.84
\$	<i>Su</i> 348.25
\$	<i>Su</i> 136.11
\$	<i>Su</i> 270.06
\$	<i>Su</i> 1,707.78
\$	<i>Su</i> 225.36
\$	<i>Su</i> 1,353.75
\$	<i>Su</i> 615.90
\$	<i>Su</i> 89.79

TOTAL	\$	11,264.31
10%	\$	1,126.43
TOTAL	\$	10,137.88

Trans-cab Auto Services Pte Ltd

AAD1904-266

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00 X
		\$	157.50

TOTAL PARTS \$ 10,295.38**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 400
Putty and spray painting of the affected portion.	\$	3,000.00 440
To rust-proofing of the affected areas.	\$	170.00 30
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 X
To replace, refix and top up coolant for radiator	\$	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-266**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909PTo vacuum, replace, refix and recharge Air
Intercooler

\$ ~ 170.00 X

TOTAL \$ 8,210.00**Over All Total \$ 18,505.38****LUMP SUM (REPAIR DAY)****10-DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before final KMS posting
- To display damaged parts for survey
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental parts may be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19007712/KVD3N2

Date: 07/05/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000204
Claimant Vehicle No :	SHB9909P	Insured Vehicle No :	SLH4266P
Date of Loss:	29/04/2019	Nature of Claim:	TP
		Claim No:	M1903124

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9909P	Engine No:	M9R8839C000404
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC273469
Reg. Date:	30/08/2013 (Man. Year: 2013)	Odometer:	438775 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,295.37	3,270.18	7,025.19	68.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,210.00	890.00	7,320.00	89.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,505.37	4,160.18	14,345.19	77.52
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	18,505.37	3,350.00	15,155.37	81.90
+ GST 7.00/7.00% (S\$)	1,295.38	234.50	1,060.88	81.90
Nett Amount (S\$)	19,800.75	3,584.50	16,216.25	81.90

INSPECTION

Date of Assignment:	02/05/2019	
Date Inspected:	30/04/2019 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 07 May 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHB9909P)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Distorted	181.75 FL	*181.75 FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP RH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
11	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
13	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
14	1		*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
15	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
16	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
17	1		*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
18	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
19	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
21	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
22	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
23	1		*FRAME FULL SUPPORT BRACKET	Serviceable	89.79 FL	*- FL
24	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
25	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
26	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
27	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,421.80	3,626.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,126.43	356.02
Total Parts (\$\$)	10,295.37	3,270.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
10	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
Gross Labour Cost (\$\$)			8,210.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >