

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.04.2019

REPAIR ESTIMATE

China Taiping
(CPH)

Time: 14:57:01

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305291883
REGN NO : SHC3211C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 01.02.2019
DATE/TIME IN : 30.04.2019 11:40
ACCIDENT DATE : 29.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2538-G WING MIRROR RH 1 1,054.60 20.00 843.68 ✓

SUB-TOTAL : 843.68

JOB NATURE

0000 PB PANEL BEATING ~~150.00~~ 100

0001 SP SPRAYPAINT CHARGE ~~150.00~~ 50

0002 17-01 WIRING CHECK ~~40.00~~ X

SUB-TOTAL : 340.00

TOTAL : 1,183.68

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Kahin 1000
N 30/4/19 1515h
1 Day
PIP
Before Paint photo

With this repair estimate hence notify
customer to get the following:
• "Third Party" - Spraypainting
• Third Party - Sprayed surface including resurvey
• Workmanship - Workmanship - Satisfaction
• "No Fault" - Workmanship - "No-fault" basis
• "No Fault" - Workmanship - "No-fault" basis
• Subsequent repair work shall be required and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: