

27/03/2019

ASS. REC. BY:

REF: CS/SMO/19067725/19d3n2

Special Instruction:

Summary: Marcus

ASSIGNMENT (Office)

MEMO

From (Person): Gnoh Pau Loong of SMO Date/Time: 25.19 15.53p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT 9522C Insured: 4M 9931P

at Workshop m/s Premium Carz Tel: 6636 9100

of 1 Kaki Bukit Ave 6 # 01-90

Policy No: D19M7PCVE 000322 Claim No: (M71) 1907137

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 1.5.2019

CA / REV / REP. / REV 24 HRS "wp" 3.5.2019 (mor)

Date/Time: 25.19 4.03p.m Person Contacted: An Teng H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SJT 9522C - x		
	4M 9931P - x		
06/5/19 @	SLOPE revised to Gnoh Pau Loong via Marcus.		

REF: SMO

ASSIGNMENT

From: Date: 3.5.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SOT 9522 C
at Workshop n/s: Premium Carz
of 1 Kaki Bukit Ave L A 01-90

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: (morning)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 12k.

ID/C Accident Rpt: Consistent? : Yes or No

GLA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "sup"

Date: Person Contacted: bul. Vehicle: IN / OUT

Veh No: S379522C Yr Regn: 11 / 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Fit c.c. 1339

Colour: S.hev A/C: Insured / Std / NI / NA

Sp. Reading: 222970 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GE61144640

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/55-12.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. 1/5/19	D.O.I. 3/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/5/19	coe 9-11-2019 LTA 8142 with 3888 L/S 3200 confab with Antony. (Red # 750272, 44%)

RECEIVED 07 MAY 2019

Date/Time, File Pass to? : Preli. Report

: Final Report

Date/Time, File Return to?

2)

Report Format: MEX-1P

Lump Sum / I.B.F. (\$) 3200

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation: 250

\$ + RS, SI 10

Photos

Others

TOTAL

260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 06 May 2019

Preliminary Advice

Insured Vehicle No	: YM9931P	Accident Date	: 01/05/2019
TP Vehicle No	: SJT9522C	Assignment Date	: 02/05/2019
Make	: HONDA FIT	Est. Duration of Repair	: 4.00
Date of Inspection	: 03/05/2019		
Inspection At	: PREMIUM CARZ SERVICES PTE LTD (HQ) 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY@KAKI SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,685.44
Revised Amount	:S\$	4,015.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,015.96
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 15:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LIAN YICK CONSTRUCTION PTE LTD, Co. Reg. No.: 199607738G								
Main Claimant:	CHONG SWEE HAI, ID: S7348011F								
Vehicle Reg. No.:	SJT9522C	Date of Loss: 01/05/2019 00:00 - :59							
Claim Type:	TP / CMTD1902137	Policy/Cover Note No.: D19MTPCVE000322							
Vehicle Reg. No. (Insured):	YM9931P	Policy No. (Claimant):							
		Excess:							
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/05/2019]								
Adj Asg. Remarks:	WS: Aun Teng 66369100 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- What Did You Makan Today PT 6
- The new BMW M5 : first look
- Ang Moh whacked local Security Uncle

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Lastest Facelift BMW 535 Sunroof.



Safe Buy. High Value. Low Fuel Consumption. Sporty Yet Powerful Luxury Car. Direct Owner StarAd



Browse by Category

« Back (1 2 3 4 5) Next »

Sort by Date Posted 20 results/page

84 vehicles

Advanced Search Submit

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
fit		Any	Any	2009	Any	Any	Any	Available



Honda Fit 1.3A G (New 5-yr COE) **\$25,800** **\$5,150 /yr** **11-Jun-2009** **1,339 cc** **-** **Hatchback** **Available**

Selling Cheap! Hurry! View Now. We Provide Lowest Interest Rate. Loan And High Trade In Are Available. Package With Unrivald Warranty Complete With Certificate And Test Report. Check Out Our New Offe...

Classic Credit Pte Ltd

Posted: 03-May-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



Honda Fit 1.3A G (COE till 03/2024) **\$27,800** **\$5,670 /yr** **27-Mar-2009** **1,339 cc** **147,002 km** **Hatchback** **Available**

100% Accident Free, High Loan With 100% Approval, Bank/In House Loans Available, Kindly Contact Us For An Appointment Or Visit Us At Our Showrooms Today, Buy And Sell With Assurance From A Credited Co...

Posted: 02-May-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



Honda Fit 1.3A G (COE till 03/2024) **\$26,800** **\$5,520 /yr** **11-Mar-2009** **1,339 cc** **126,000 km** **Hatchback** **Available**

Monthly \$453 (Bank Loan) Full Loan Available! A Fun Car To Drive Daily And Most Fuel Economy Car. Beautifully Done Up To Showroom Condition With No Repaired Needed. Book A Test Drive To Feel The Condit...

SmartCars Boutique Pte Ltd

Posted: 02-May-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



Honda Fit 1.3A GF (COE till 04/2024) **\$33,800** **\$6,760 /yr** **19-Jun-2009** **1,339 cc** **131,000 km** **Hatchback** **Available**

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fu...

Carway

Posted: 02-May-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Honda Fit 1.3A G (New 5-yr COE) **\$26,800** **\$5,350 /yr** **07-May-2009** **1,339 cc** **115,000 km** **Hatchback** **Available**

Full Loan Available At \$600 Plus, We Can Help To Convert To 210 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart...

88 Motor Trading

Posted: 02-May-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda

Honda Fit 1.3A G (New 5-yr COE) **\$26,800** **\$5,350 /yr** **26-May-2009** **1,339 cc** **-** **Hatchback** **Available**

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8011F
Vehicle Details	
Vehicle No.:	SJT9522C
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L13A4156798
Chassis No.:	GE61144640
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,555.00
Original Registration Date:	10 Nov 2009
First Registration Date:	10 Nov 2009
Transfer Count:	0
Actual ARF Paid:	\$14,555.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Nov 2019
PARF Rebate Amount:	\$7,277.00
Intended COE Rebate Details	
COE Expiry Date:	09 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,747.00
COE Rebate Amount:	\$865.00
Total Rebate Amount:	\$8,142.00

The information contained herein is correct as at 03 May 2019

OK

MSMC18050493 / SVE Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 02/05/2019 13:04
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2019 13:04
Date Of Accident	01/05/2019 16:50
Exact Location Of Accident	LOYANG POINT (259 PASIR RIS ST 21)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT9522C
Insured/Policyholder	
Name Of Registered Owner	CHONG SWEE HAI
NRIC No	S7348011F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93250818
Alternative Phone No	OFFICE-93250818

Vehicle Particulars

Manufacturer	HONDA
Model	FIT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105788051
Cover Note Number	

Driver

Name of Driver	CHONG SWEE HAI
NRIC No	S7348011F
Date Of Birth	31/12/1973
Occupation	OUTDOOR
Date Of Driving Pass	30/09/2009
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93250818
Fax Number	
Contact Number	OFFICE-93250818
Email Address	NOEMAIL

Address BLK 267 TAMPINES ST 21 #09-31
 Postcode 520267
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: ZHANG YIN CHUN
 GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 01/05/2019 AT ABOUT 4.50PM, WHILST TRAVELLING ALONG PASIR RIS ST 21 TOWARDS LOYANG POINT CARPARK, VEHICLE B (YM9931P) IN FRONT OF ME STOP. SO, I FOLLOWED SUIT. OUT OF SUDDEN, VEHICLE B IN FRONT ROLL BACKWARDS AND HIT ONTO THE FRONT PORTION OF MY VEHICLE A (SJT9522C)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM9931P
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Registered Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of party liability on the part of the insurance companies.
5. ~~Any false reporting may be referred to the Police for investigation.~~
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the note/mail cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim, collectively the "Purposes".
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

2nd May 19 H4V8M

Reporting Clerk's Personnel's Signature
 Name:
 NRK/IDN No.:

WARRANT, version 04/01/2018 V1

PREMIUM CARE

Sketch Plan #2 Pg. 1

SKETCH PLAN

Vehicle A: S3T9522C
B: YMQ931P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/5/2019 at about 4:50pm, whilst travelling along Pasir Ris St-21 towards Loyang Point, vehicle B (YMQ931P) in front of me stop. So, I followed suit. Out of sudden, vehicle B in front roll backwards and hit into the front portion of my vehicle A (S3T9522C).

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

SUV&MC SketchPlanForm_V3



Date : 2/5/2019

TO: Sompso Insurance (Singapore) Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Our Customer : Chong Swee Hai
Vehicle No : SJT9522C
Model : Honda Fit

Manufacture Year : 2009 (COE:09/11/2019)

Date of Accident : 1/5/2019

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claims Department
Fax : 6221 3147

Re: Repair Estimate For Third Party Claim against YM9931P

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Bonnet <i>DD/SCM</i>	1	\$514.70	\$514.70	✓
2	Bonnet lock <i>11</i>	1	\$88.00	\$88.00	X
3	Bonnet rubber <i>SCM</i>	1	\$50.20	\$50.20	✓
4	Bonnet stopper <i>11</i>	2	\$10.80		X
5	Bonnet hinge <i>11</i>	2	\$28.00	\$56.00	X
6	Front bumper <i>DD/SCM</i>	1	\$557.10	\$557.10	✓
7	Front bumper side retainer RH <i>11</i>	1	\$24.10	\$24.10	X
8	Front bumper side retainer LH <i>11</i>	1	\$24.10	\$24.10	X
9	Front grille <i>SCM</i>	1	\$223.50	\$223.50	✓
10	Front grille chrome <i>11</i>	1	\$114.30	\$114.30	X
11	Front grille "H" logo <i>11</i>	1	\$22.00	\$22.00	X
12	Front bumper tow hook cover <i>11</i>	1	\$24.10	\$24.10	X
13	Front bumper lower grille <i>11</i>	1	\$155.00	\$155.00	X
14	Headlamp RH <i>SCM/SCM</i>	1	\$587.70	\$587.70	✓
15	Headlamp LH <i>SCM/SCM</i>	1	\$587.70	\$587.70	✓
16	Headlamp lower bracket RH <i>11</i>	1	\$35.70	\$35.70	X
17	Headlamp lower bracket LH <i>11</i>	1	\$35.70	\$35.70	X
18	Wiper garnish - center <i>CU7</i>	1	\$480.00	214.70 \$480.00	✓
19	Wiper garnish RH <i>11</i>	1	\$65.00	\$65.00	X
20	Wiper garnish LH <i>CU7</i>	1	\$65.00	\$65.00	✓
21	Front fender LH <i>DD/SCM</i>	1	\$375.60	\$375.60	✓
22	Front fender lamp LH <i>11</i>	1	\$18.20	\$18.20	X
23	Front fender quarter glass garnish LH <i>CU7</i>	1	\$125.00	\$125.00	✓
24	Front fender quarter glass moulding <i>11</i>	1	\$78.10	\$78.10	X
			Total	\$4,306.80	
			Less 20%	\$861.36	
			Sub Total 1	\$3,445.44	
A.	Spare Parts (S/Nett)				
1	Front bumper clip <i>SCM</i>	10	\$5.00	\$50.00	35
2	Front grille clip <i>11</i>	8	\$5.00	\$40.00	X
3	Front fender inner shield clip <i>11</i>	8	\$5.00	\$40.00	X
4	Front number plate with casing <i>11</i>	1	\$70.00	\$70.00	X
			Sub-Total 2	\$200.00	
			Total for Parts	\$3,645.44	
B.	Labour				
1	To check wiring and re-focus headlamp.			\$60.00	30

3301.20
202
2640.96

Co. Reg. No.: 201416720C
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
 Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,000.00	500
3	Spray painting all affected parts & areas.			\$800.00	750
4	To spray anti-rust undercoat.			\$90.00	60
5	To remove and refit front fender quarter glass LH.			\$90.00	11 X
	Total Labour			\$2,040.00	
	Total Repair Cost			\$5,685.44	4015.96

3212.76

Not Authorize
 L/S # 3200 /
 4 days.
 3/5/18
 Wang Jie. Atkinson

Yours faithfully,

 Aun Teng
 f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

I/We, the Receiver, hereby notify the Surveyor of the following:
 • To ensure correct and spray painting
 • To ensure correct and full body survey
 • Surveyor is not to be liable for confirmation
 • To ensure survey on a "without prejudice" basis
 • No oral amendments are allowed
 • Surveyor's work is subject to approval from Insurance Company

Acknowledged by Receiver:
 Signature: _____
 Date: _____

5702.72

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007725/UQD3N2
Date: 09/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPCVE000322
Claimant Vehicle No :	SJT9522C	Insured Vehicle No :	YM9931P
Date of Loss:	01/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902137

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9522C	Engine No:	L13A4156798
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61144640
Reg. Date:	10/11/2009 (Man. Year: 2008)	Odometer:	222970 km
Colour:	Silver		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,662.72	2,675.96	986.76	26.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,340.00	700.00	34.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,702.72	4,015.96	1,686.76	29.58
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	5,702.72	3,200.00	2,502.72	43.89

INSPECTION

Date of Assignment:	02/05/2019	
Date Inspected:	03/05/2019 Inspected At:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2019)
Parts: 144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJT9522C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Bent	514.70 FL	*514.70 FL
2	1		*BONNET LOCK	Not Necessary	88.00 FL	*- FL
3	1		*BONNET RUBBER	Necessary	50.20 FL	*50.20 FL
4	2		*BONNET STOPPER	Not Necessary	21.60 FL	*- FL
5	1		*FRONT BUMPER	Dented / Deformed	557.10 FL	*557.10 FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	24.10 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	24.10 FL	*- FL
8	1		*FRONT GRILLE	Cut	223.50 FL	*223.50 FL
9	1		*FRONT GRILLE CHROME	Not Necessary	114.30 FL	*- FL
10	1		*FRONT GRILLE H LOGO	Not Necessary	22.00 FL	*- FL
11	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	24.10 FL	*- FL
12	1		*HEADLAMP RH	Cracked / Scratched	587.70 FL	*587.70 FL
13	1		*HEADLAMP LH	Cracked / Scratched	587.70 FL	*587.70 FL
14	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	35.70 FL	*- FL
15	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	35.70 FL	*- FL
16	1		*WIPER GARNISH - CENTER	Cut	480.00 FL	*214.70 FL
17	1		*WIPER GARNISH RH	Not Necessary	65.00 FL	*- FL
18	1		*WIPER GARNISH LH	Cut	65.00 FL	*65.00 FL
19	1		*FRONT FENDER LH	Dented / Bent	375.60 FL	*375.60 FL
20	1		*FRONT FENDER LAMP LH	Not Necessary	18.20 FL	*- FL
21	1		*FRONT FENDER QUARTER GLASS GARNISH LH	Cut	125.00 FL	*125.00 FL
22	1		*FRONT FENDER QUARTER GLASS MOULDING	Not Necessary	78.10 FL	*- FL
23	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	155.00 FL	*- FL
24	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*35.00 FS
25	8		*FRONT GRILLE CLIP	Not Necessary	40.00 FS	*- FS
26	8		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
27	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	70.00 FS	*- FS
28	2		*BONNET HINGE	Not Necessary	56.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,528.40	3,336.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	865.68	660.24
Total Parts (\$\$)	3,662.72	2,675.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RE-FOCUS HEADLAMP.	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.	New	1,000.00	500.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.	New	800.00	750.00
4	TO SPRAY ANTI-RUST UNDERCOAT.	New	90.00	60.00
5	TO REMOVE AND REFIT FRONT FENDER QUARTER GLASS LH.	New	90.00	0.00
Gross Labour Cost (\$\$)			2,040.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >