



Your Ref: 14/15/15/VP00/192013

Date: 14th May 2019

Our Ref: CS1/LPC19007740/Dqd3s2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKL 2816G
INSURED VEHICLE: JNR 1256 ACCIDENT DATE: 27/02/2015**

We thank you for your instruction on 29/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKL 2816G from M/s HM Motor Appraisal.
- b) Police Report of Vehicles SKL 2816G and JNR 1256.
- c) Colour damaged vehicle photographs of SKL 2816G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKL 2816G
Make & Model	: Volkswagen Touran
Year of Registration	: 2012
Chassis Number	: WVGZZZ1TZDW041217
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.