

ASS. REC. BY:

REF: CS/CT119007773/30d302 Special Instruction:

Surveyor: Hwee Jie

Meriman

ASSIGNMENT (Office)From (Person): Elaine chong of CTI Date/Time: 2.5.19 17:48pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: WC1828J Insured: XD 3058Jat Workshop m/s Fook Heng motor Tel: 9831 463of 100 Bedok North Ave 4 Pearl Garden #13-1922Policy No: DM CVS N1672251 8022 Claim No: SNM19D201868C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25.4.2019
(Client's Record)CA / REV / REP. / REV 24 HRS rup'' H.O.D. Endorsement: _____Date/Time: 3.5.19 9.29am Person Contacted: Tan Vehicle IN/OUTDate/Time | Action/Instruction | Estimate | Inspection: 29 Sungai kadut street 4| WC1828J - CS / HSB 09011537 / Rbrl | | | D.O.A. - 20/05/2009| XD 3058J - A | | || 8/5/19 | @401pm Mr Tan said pass to lawyer | | || After repair: 8/5/2019 | | |

ASSIGNMENT

From: _____ Date: 3.5.2019

Estimated Cost: _____

OD TP WS TP RES OD RES EVA INV MV

To Inspect Vehicle No: WC 1828J

at Workshop m/s Fook Hung motor

of 29 Sungai Kadut Street 4

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: WC 1828 J Yr Regn: 24 Dec 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan C.C. 13074

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 331253 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: CGB4CL500049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / STD A/Rim /

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "WP"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 295/80R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Golden Crown

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7/7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>2/7</u> mm
D.O.A. <u>25/4/19</u>	D.O.I. <u>3/5/19</u>

Survey held at Fook Hung

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PRS
	Range: \$8500-\$9500 6 days. <i>[Signature]</i> 9/5/2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : PRC

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Survey Fee: 150

Transportation: _____ \$ + RS, _____ SI

Photos _____

Others _____

TOTAL: 150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 17:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAT HONG CONSTRUCTION & TRANSPORT PTE. LTD., Co. Reg. No.: 200613703C								
Main Claimant:	SHENG TRANSPORT TRADING, Co. Reg. No.: 53103547J								
Vehicle Reg. No.:	WC1828J	Date of Loss: 25/04/2019 12:00 - :59 [136 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D201868C02	Policy/Cover Note No.: DMCVSN16722518022 (Comprehensive) Coverage: 05/11/2018 - 04/11/2019							
Vehicle Reg. No. (Insured):	XD3058J	Policy No. (Claimant): 5096279770							
		Excess: S\$0.00							
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/05/2019]								
Driver/Custodian (Insured):	ZHANG LIGUO (32 / Male) , NRIC: G2297909X Email:								
Adj Asg. Remarks:	please contact Mr Tan at 9831 1463 to arrange for Pre repair inspection. Workshop - Fook Heng Motor Service 29 Sungei Kadut Street 4 Singapore 729054								
ASSOCIATED MAIL RECEIVED									
		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3547J
Vehicle Details	
Vehicle No.:	WC1828J
Vehicle to be Exported:	No
Intended Deregistration Date:	08 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	CGB45CLSMNB
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	GE13334216B
Chassis No.:	CGB4CL500049
Maximum Power Output:	-
Open Market Value:	\$123,002.00
Original Registration Date:	24 Dec 2007
First Registration Date:	24 Dec 2007
Transfer Count:	4
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$45,915.00
COE Rebate Amount:	\$39,308.00
Total Rebate Amount:	\$39,308.00

The information contained herein is correct as at 08 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/04/2019 14:06
Date Of Accident	25/04/2019 12:50
Exact Location Of Accident	ISLAND PLANT @ SUNGEI KADUT ST 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC1828J
Insured/Policyholder	
Name Of Registered Owner	SHENG TRANSPORT TRADING
Co Reg No	53103547J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96467137
Alternative Phone No	Office-86783204

Vehicle Particulars

Manufacturer	NISSAN
Model	CGB45LSMNB-13.1 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOBILE EQUIPMENT

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5096279770
Cover Note Number	

Driver

Name of Driver	NATARAJAN ARICHANDRAN
Passport No/FIN	G8440596K
Date Of Birth	23/04/1981
Occupation	OUTDOOR
Date Of Driving Pass	01/08/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86783204

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	XD3058J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

A-WC1828J
B-XD3058J



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS STATIONARY AT THE SWAMP CHECKING AREA AT ISLAND PLANT @ SUNGGI KADUT ST. 4. I SAW 3RD PARTY XD3058J HAS DRIVEN PAST MY VEHICLE INTO THE PLANT. WHEN I FINISHED CHECKING AND WALKING TOWARDS MY VEHICLE, I WAS OPENING THE DRIVER SIDE DOOR AND ABOUT TO GET UP THE VEHICLE AT THAT TIME I HEARD BEEPING SOUND FROM MY BACK.

I SAW 3RD PARTY REVERSING HIS VEHICLE AND COMING TOWARDS ME. I IMMEDIATELY RAN AWAY (AS MY LIFE IS THREATENED). THEN 3RD PARTY REAR HIT ONTO MY VEHICLE DRIVER'S DOOR AREA

AFTER THE ACCIDENT WE EXCHANGED OUR PARTICULARS AND NO INJURIES IN THIS ACCIDENT AND I WANT TO CLAIM 3RD PARTY FOR MY DAMAGES.

3RD PARTY DRIVER: ZHANG LIQUO
 (UP No: 075742452)

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.



Reporting Centre Personnel's Signature
 Date & Time:

N. Aricy
 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: 26/4/19



Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SIARANIC SwampPlantForm_V2

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		02 May 2019 17:48	S\$0.00	S\$0.00 View Rpt		Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TAT HONG CONSTRUCTION & TRANSPORT PTE. LTD., Co. Reg. No.: 200613703C								
Main Claimant:	SHENG TRANSPORT TRADING, Co. Reg. No.: 53103547J								
Vehicle Reg. No.:	WC1828J	Date of Loss:	25/04/2019 12:00 - :59 [136 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201868C02	Policy/Cover Note No.:	DMCVSN16722518022 (Comprehensive) Coverage: 05/11/2018 - 04/11/2019						
Vehicle Reg. No. (Insured):	XD3058J	Policy No. (Claimant):	5096279770						
		Excess:	S\$0.00						
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 13/05/2019]								
Driver/Custodian (Insured):	ZHANG LIGUO (32 / Male) , NRIC: G2297909X Email:								
Adj Asg. Remarks:	please contact Mr Tan at 9831 1463 to arrange for Pre repair inspection. Workshop - Fook Heng Motor Service 29 Sungei Kadut Street 4 Singapore 729054								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC1828J (SNM19D201868C02)
[XD3058J]

TP

SHENG TRANSPORT TRADING

Apr 25 2019 12:00PM

[TAT HONG CONSTRUCTION & TRANSPORT PTE. LTD.]

Fook Heng Motor Service

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>		View <input type="button" value="View in Browser"/>		
Assessment Reports		1 per page <input type="button" value=""/> <input checked="" type="checkbox"/>		
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print
1	26/04/19 14:17	Accident Statement	1 Load HTM	
Photos/Images		3 per page <input type="button" value=""/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
18	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
19	08/05/19 09:56	General View	1 Load JPG	<input checked="" type="checkbox"/>
20	09/05/19 09:48	Photo After Spray	1 Load JPG	<input checked="" type="checkbox"/>
21	09/05/19 09:48	Photo After Spray	1 Load JPG	<input checked="" type="checkbox"/>
22	09/05/19 09:48	Photo After Spray	1 Load JPG	<input checked="" type="checkbox"/>
23	09/05/19 09:48	Photo After Spray	1 Load JPG	<input checked="" type="checkbox"/>
24	09/05/19 09:48	Photo After Spray	1 Load JPG	<input checked="" type="checkbox"/>
Documentation		1 per page <input type="button" value=""/> <input checked="" type="checkbox"/>		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/19 17:46	INSD XD3058J GIA REPORT	1 Load PDF	

Linked Accident Report Documents

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>		View <input type="button" value="View in Browser"/>		
Assessment Reports		1 per page <input type="button" value=""/> <input checked="" type="checkbox"/>		
No	Finalized On	Modern Automotive Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Modern Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/04/19 14:17	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Modern Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	26/04/19 14:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Modern Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/04/19 14:15	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19007773/JCD3E2

Date: 10/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN16722518022
 Claimant Vehicle No: WC1828J Insured Vehicle No: XD3058J
 Date of Loss: 25/04/2019 Nature of Claim: TP Claim No: SNM19D201868C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WC1828J**
 Make & Model: NISSAN CGB45LSMNB, 13.1 D (M) Engine No: GE13334216B
 Reg. Date: 24/12/2007 (Man. Year: 2007) Chassis No: CGB4CLS00049
 Colour: Blue Odometer: 331253 km
 Engine Capacity: 13074 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
 Front Left Side: Golden Crown 7 mm Rear Left Side: Golden Crown 7/7 mm
 Front Right Side: Golden Crown 7 mm Rear Right Side: Golden Crown 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/05/2019
 Date Inspected: 03/05/2019 Inspected At: Fook Heng Motor Service (HQ)
 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922
 Singapore 460100

Estimated Period of Repair: 6.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500.00 -\$9,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 May 2019)

Parts: N/A NISSAN CGB45LSMNB 13.1 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for WC1828J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >