

ASS. REC. BY

REF

883/MSG19007796/Sec302

Special Instruction:

SA/VEY/VA

Meenmen

Free file

ASSIGNMENT (Office)

From (Person):

Chhian Nyuk Pui

of

MS16

Date/Time:

3/5/2019 @ 11:07am

Estimated Cost:

Bill to:

OD / TP / WS / TT RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBC507R

Insured:

YP2125E

at Workshop m/s

pek tiang

Tel:

6755 0688

of

Blk 1017 Yishun Ind. Park A # 01-258

Policy No:

28928656MCC

Claim No:

592143

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

29/04/2019

CA / REV / REP. / REV 24 HRS

imp

H.O.D. Endorsement

Date/Time:

11:45am @ 3/5/19

Person Contacted:

Mr Ang

Vehicle

IN

OUT

Date/Time

Action/Instruction (X) Estimate

GBC507R-CC6/AXA11024816/Redel

DVA: 28/11/2011

YP2125E - X

Dismantle: 6/5/2019


REF: MSIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. ABC507 R Yr Regn: 10 mar 2011
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Fiat Fiorino c.c. 1248
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 143615 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZFA22500000160033
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 175/70 R14
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Komando
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 29/4/19 D.O.I. 3/5/19
 Survey held at Pek Tiong
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PRS
	M.V. ?
	Range: \$9500 - \$11000
	9 days
	MV - \$11000
	PL - \$5326
	NV - \$5674

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 9
 Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + PS. \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		03 May 2019 11:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	PERFECT INSULATION & ENGINEERING PTE LTD, Co. Reg. No.: 201437734K		
Main Claimant:	SOIL DYNAMICS (SINGAPORE) PTE LTD, Co. Reg. No.: 52565440D		
Vehicle Reg. No.:	GBC507R	Date of Loss:	29/04/2019 00:00 - :59 [97 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 592143	Policy/Cover Note No.:	28928656MKC (Comprehensive) Coverage: 05/04/2019 - 04/04/2020
Vehicle Reg. No. (Insured):	YP2125E	Policy No. (Claimant):	
		Excess:	
Repairer:	Pek Tiong Auto Services - Yishun (HQ) BLK 1017 YISHUN INDUSTRIAL PARK A, #01-258, 768759 Yishun - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/05/2019]		
Adj Asg. Remarks:	LIAB: DISPUTE (OI NON REPORTING). TP DISAGREE ON SJE - ASSIGN LKK. CONTACT:PEK TIONG @ 6755 0688.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0585Z
Vehicle Details	
Vehicle No.:	GBC507R
Vehicle to be Exported:	No
Intended Deregistration Date:	08 May 2019
Vehicle Make:	FIAT
Vehicle Model:	FIORINO 1.3MJTD (225.2L20)
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	199A20003604947
Chassis No.:	ZFA22500000160033
Maximum Power Output:	-
Open Market Value:	\$16,614.00
Original Registration Date:	10 Mar 2011
First Registration Date:	10 Mar 2011
Transfer Count:	0
Actual ARF Paid:	\$831.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,011.00
COE Rebate Amount:	\$5,326.00
Total Rebate Amount:	\$5,326.00

The information contained herein is correct as at 08 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 13:17
Date Of Accident	29/04/2019 17:40
Exact Location Of Accident	ADMIRALTY ROAD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC507R
Insured/Policyholder	
Name Of Registered Owner	SOIL DYNAMICS (SINGAPORE) PTE LTD
Co Reg No	52565440D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96353194
Alternative Phone No	OFFICE-63625211

Vehicle Particulars

Manufacturer	FIAT
Model	FIORINO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28894417MKC (COMP)
Cover Note Number	

Driver

Name of Driver	JEGASEELAN VARALAKSON
NRIC No	G3362322X
Date Of Birth	08/10/1990
Occupation	OUTDOOR
Date Of Driving Pass	29/10/2018
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96883699
Fax Number	
Contact Number	OTHERS-82960260
EMail Address	VARAN@SOILDYNAMICS.SG

Address	BLK 332 #02-277 SERANGOON AVE 3
Postcode	550332
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MS LAM TENG CHENG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP2125E
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	VEERIAH SURJIH SEGUVERA
NRIC/Passport Number	G2817413L
Contact Number	81451254
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJK9779B
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Muralidharan

Driver's Signature
(If driver is not the policyholder)
Date & Time:


30 APR 2019



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA - 29/4/19

My Vehicle stop at traffic junction on red light.
 One vehicle suddenly hit at back of my vehicle
 which cause my vehicle move and hit the car in front.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Abdullah
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

30 APR 2019

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2019		03 May 2019 11:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case








































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PERFECT INSULATION & ENGINEERING PTE LTD, Co. Reg. No.: 201437734K								
Main Claimant:	SOIL DYNAMICS (SINGAPORE) PTE LTD, Co. Reg. No.: 52565440D								
Vehicle Reg. No.:	GBC507R	Date of Loss:	29/04/2019 00:00 - :59 [97 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 592143	Policy/Cover Note No.:	28928656MKC (Comprehensive) Coverage: 05/04/2019 - 04/04/2020						
Vehicle Reg. No. (Insured):	YP2125E	Policy No. (Claimant):							
		Excess:							
Repairer:	Pek Tiong Auto Services - Yishun (HQ) BLK 1017 YISHUN INDUSTRIAL PARK A, #01-258, 768759 Yishun - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 04/05/2019]								
Adj Asg. Remarks:	LIAB: DISPUTE (OI NON REPORTING). TP DISAGREE ON SJE - ASSIGN LKK. CONTACT:PEK TIONG @ 6755 0688.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC507R (592143)
[YP2125E]
TP
SOIL DYNAMICS (SINGAPORE) PTE LTD
Apr 29 2019 12:00AM
[PERFECT INSULATION & ENGINEERING PTE LTD]
Pek Tiong Auto Services - Yishun

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
2	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
3	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
4	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
5	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
6	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
7	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
8	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
9	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
10	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
11	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
12	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
13	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
14	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
15	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
16	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
17	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
18	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
19	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
20	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
21	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
22	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
23	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
24	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
25	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
26	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
27	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
28	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
29	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
30	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
31	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
32	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
33	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
34	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
35	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
36	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					
37	08/05/19 09:57	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/05/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
123	08/05/19 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/19 15:06	E-FILE REPORT (SJK9779B)	 Load PDF	
2	02/05/19 15:06	E-FILE REPORT (GBC507R)	 Load PDF	
3	02/05/19 15:47	TP DISAGREE ON SJE- WORKSHOP DETAILS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007796/JCD3E2

Date: 14/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28928656MKC

Claimant Vehicle
No : GBC507R

Insured Vehicle No : YP2125E

Date of Loss: 29/04/2019

Nature of Claim: TP

Claim No: 592143

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC507R

Make & Model: FIAT FIORINO, 1.3 MJTD (A)

Engine No: 199A20003604947

Reg. Date: 10/03/2011 (Man. Year: 2010)

Chassis No: ZFA22500000160033

Colour: Silver

Odometer: 143615 km

Engine Capacity: 1248 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: KOMENDO 7 mm

Rear Left Side: KOMENDO 7 mm

Front Right Side: KOMENDO 7 mm

Rear Right Side: KOMENDO 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/05/2019

Date Inspected: 03/05/2019 Inspected At:

Pek Tiong Auto Services - Yishun (HQ)
BLK 1017 YISHUN INDUSTRIAL PARK A,
#01-258
Singapore 768759

Estimated Period of Repair: 9.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,500.00 - \$11,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 May 2019)

Parts: N/A FIAT FIORINO 1.3 MJTD (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC507R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >