

22/03/2019

ASS. REC. BY:

REF: CS/CT119007797/AV d3n2 Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CT1

Date/Time: 3.5.19 11:48a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EA 999D

Insured: SJP 13534

at Workshop m/s SRS International

Tel: 87180318

of First East Centre 10 Kati Butit Road 2 #03-18

Policy No: DMPCSN30309119044

Claim No: SNM19D201927C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.4.2019

CA / REV / REP. / REV 24 HRS

"up"

6.5.19 (After 1.00p.m)

Date/Time: 3.5.19 1.15p.m

H.O.D. Endorsement:

Person Contacted:

Ken

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (V)
	EA 999D-X	
	SJP 13534-X	
14/6/19	Adrian confirmed LS \$2700 (Red 3476, 561)	

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s - _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: EA999D Yr Regn: 2014, AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Soranto C.C. 2359Colour: Red A/C: Insured / Std / NI / NASp. Reading: 107483 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAKU816MESS09862Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 235/55R19R: 235/55R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/05/19Survey held at SRS InternationalDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Clinic

RECEIVED 14 JUN 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 14/6 - typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019		03 May 2019 11:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HUANG XIAOYANG, ID: S7062352H								
Main Claimant:	LEE GEK KIM, ID: S0296961J								
Vehicle Reg. No.:	EA999D	Date of Loss:	30/04/2019 14:00 - :59 [60 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201927C02	Policy/Cover Note No.:	DMPCSN30309119044 (Comprehensive) Coverage: 12/03/2019 - 11/03/2020						
Vehicle Reg. No. (Insured):	SJP1353Y	Policy No. (Claimant):	2100370409-05						
		Excess:	S\$0.00						
Repairer:	- Not Applicable - (-)								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/05/2019]								
Driver/Custodian (Insured):	HUANG XIAOYANG (48 / Male) , NRIC: S7062352H Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

02 May 2019

SRS International Pte Ltd
First East Centre
10 Kakit Bukit Road 2
#03-18 Singapore 417868

China Taiping Insurance Singapore Pte Ltd
3 Anson Road #16-00
Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033

Requesting a surveyor to conduct an accident damage claim report

Dear Sir/Madam:

I am writing to request for your surveyor to conduct a comprehensive survey on our client **vehicle number - EA999D, Model- KIA SORENTO 2.4 A GDI** for a direct claim settlement. We are located First East Centre, 10 Kakit Bukit Road 2, #03-18 below are the following dates which are client able to send over his car to allow your surveyor to conduct the survey:

Dates:

- a. 13 May 2019 Monday at 10.00am
- b. 14 May 2019 Monday at 10.00am

Details of the other vehicle insured under your company China Taiping Insurance Singapore Pte Ltd. **Vehicle number -SJP1353Y, Model- Honda City.**

I would appreciate it if you would please call me as soon as possible to schedule a time for this inspection, so that we able to make the necessary coordination with our client.

Thank you for your prompt attention to this request.

Sincerely,

Ken Gan M.K

Ken Gan
Mobile: 8718-0318

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6961J
Vehicle Details	
Vehicle No.:	EA999D
Vehicle to be Exported:	No
Intended Deregistration Date:	07 May 2019
Vehicle Make:	KIA
Vehicle Model:	SORENTO 2.4(A) SUNROOF
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	G4KJEH739910
Chassis No.:	KNAKU816ME5509862
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$28,168.00
Original Registration Date:	15 Apr 2014
First Registration Date:	15 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$31,436.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2024
PARF Rebate Amount:	\$22,005.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$78,810.00
COE Rebate Amount:	\$38,901.00
Total Rebate Amount:	\$60,906.00

The information contained herein is correct as at 07 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2019 08:35
Date Of Accident	30/04/2019 14:00
Exact Location Of Accident	GEYLANG METHODIST SCHOOL (GEYLANG EAST CENTRAL)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EA999D
Insured/Policyholder	
Name Of Registered Owner	LEE GEK KIM
NRIC No	S0296961J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94556815
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	KIA
Model	SORENTO 2.4 A GDI
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100370409-05
Cover Note Number	

Driver

Name of Driver	COREY KNG ENG SIONG (COREY KANG YONGXIANG)
NRIC No	S7608792Z
Date Of Birth	20/03/1976
Occupation	INDOOR
Date Of Driving Pass	25/06/1994
Driving Experience	24 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94556815
Fax Number	
Contact Number	
Email Address	COREYKNG@HOTMAIL.COM

Address
Postcode

BLK 167B SIMEI LANE #08-16 SINGAPORE 522167

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured CHILDREN
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

IT WAS RAINING ALONG GEYLANG EAST CENTRAL ON 2 LANE ROAD. CAR NO. SJP1353Y WAS ON THE LEFT LANE. I WAS AT CRUISING SPEED WHEN HE SUDDENLY SWIFT OUT FROM THE LEFT LANE TO CUT OUT TO THE RIGHT LANE AS HIS LANE WAS HALTED BY VEHICLES AND BUSES IN FRONT, I GAVE A SOUNDING HORN AND BRAKE BUT UNFORTUNATELY, THE DRIVER COULD NOT HEAR OR SEE MY APPROACHING CAR DUE TO BLIND SPOT ETC.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP1353Y
Vehicle Make/Model/Colour HONDA CITY
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver HUANG XIAO YANG
NRIC/Passport Number S7062352H
Contact Number 94300899
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan



MOTOR ACCIDENT REPORT FORM

BASIC INFORMATION	
Date of Report:	
Date of Accident:	30/04/19
Exact Location of Accident:	GEYLANG METHODIST SCHOOL (GEYLANG EAST CENTRAL)
Time: 14:05	
DETAILS OF OWN VEHICLE	
Vehicle Registration Number:	E 9991
NRIC/Passport No./FIN:	508969615
Name of Registered Owner:	LEE GEE KIM
Company Reg. No (for Company Veh):	
VEHICLE PARTICULARS	
Manufacturer:	KIA
Model:	CORENTO
Exact Purpose for which vehicle was being used at time of Accident:	<input checked="" type="checkbox"/> Normal Usage <input type="checkbox"/> Others
Are You Claiming Under Your Own Insurance?	<input type="checkbox"/> YES <input type="checkbox"/> NO Reporting Only <input checked="" type="checkbox"/> NO 3rd Party
Vehicle Category:	<input checked="" type="checkbox"/> Private car <input type="checkbox"/> Commercial Vehicle <input type="checkbox"/> Private Hire
INSURANCE DETAILS	
Name of Insurance:	AIG
Type of Coverage:	<input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party
Policy Number:	2100370409-05
Driver when the Accident Happen	
Name of Driver:	COREY KNEING S4N6
Date of Birth:	20/03/1976
Date of Driving Pass:	25/06/1994
Mobile No.:	94556815
Home No.:	-
Address:	11675 SINGAPORE LANE #08-16 (S)
Email Address:	COREYKNE@HOTMAIL.COM
Was the Driver an Employee of the Insured's Company:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No State the relationship of the driver to insured SON
Vehicle Registration Number of driver's Own Vehicle:	
Insurance Company:	
OTHER INFORMATION OF THE ACCIDENT	
Type of Accident:	COLLISION CHANGE/CROSS LANE
Weather Condition:	<input type="checkbox"/> Clear <input checked="" type="checkbox"/> Raining <input type="checkbox"/> Others, please specify
Road Surface:	<input type="checkbox"/> Dry <input type="checkbox"/> Wet <input type="checkbox"/> Others, please specify
Was Anybody Injured:	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes
Was Any other material or Property Damaged:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Any Accident Photo in the Scene of Accident:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Was the Accident reported to police:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Which Police Station:	
Was notice of Intended Prosecution given:	
DETAILS OF OTHER VEHICLE (Please fill Annex A if more vehicles involve)	
Vehicle Registration Number:	SJP13534
NRIC/Passport No./FIN:	
Name of Driver:	HUANG LIM YAN L
Mobile No.:	94300999
Home No.:	
Address:	
Email Address:	
Insurance Company:	
Details of Passenger if any	
Passenger Name:	
Contact Number:	
Gender:	
Details of Injured Person	
Name:	
Address:	
Injured Sustained:	
Were Seatbelts worn:	<input type="checkbox"/> Yes <input type="checkbox"/> No
Were Injured Conveyed to Hospital by Ambulance:	<input type="checkbox"/> Yes <input type="checkbox"/> No

cb 042012

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


30/4/19 @ 1740 HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

It was raining along Geylang East Central
on a 2 lane (Dad). car No. SJP 1353Y was
on the left lane while I was not on the
right lane. I was at cruising speed when he
suddenly swift out from the left lane to cut out
to the right lane as his lane was halted by
vehicles and buses in front. I gave a sounding
horn and brake but unfortunately, the driver
could not hear or see my approaching car due to
blind spot etc.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(QA/RAC, SketchPlanForm_V3)

30/4/19 @ 1740HRS.



15 May 2019

SRS International Pte Ltd
First East Centre
10 Kakit Bukit Road 2
#03-18 Singapore 417868

TP Chinn
Veron.

China Taiping Insurance Singapore Pte Ltd
3 Anson Road #16-00
Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033

Total Repair Cost for Vehicle EA9999D

LKK Auto Consultants to certify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Dear Sir/Madam:

I am writing to you as to report the list of items which needed to repair after you your surveyor have conducted a comprehensive survey on our client **vehicle number - EA999D, Model- KIA SORENTO 2.4 A GDI** for a direct claim settlement. Below are the following items and the cost of repair.

1. Front Door Left - \$1379 ✓ *Dented*
 2. Door Rubber - Weatherstrip Assy - Front Door Side, Left - \$136 ✓ *NEC NEC*
 3. Garnish Assy - Front Door side Left - \$101 ✓ *ut*
 4. Moulding Assy - Side SILL- left - \$315 ✓ *ut*
 5. Garnish Assy - Fender Side Left - \$116 ✓ *ut*
 6. front passenger side fender \$418 ✓ *Dented*
 7. 81335 cover \$158 x *Noe NEC*
 8. 79390 checker \$83 x *500*
 9. spray painting \$1100 *600*
 10. labour to remove all parts \$1500
 11. 6 day rental car \$720
 12. Transfer door hitting \$150.80
- Total amount SGD \$6026.00 *6176 5456*

List: 2465
Less 10%: 2218.50
Labour: 1180
Total: 3398.50
L/S: 2-7/10

We would appreciate your attention to these repairs cost as soon as possible so that we able to have a direct settlement on your end. If you need additional information kindly do not hesitate to contact me please.

Thank you for your prompt attention to this request.

Sincerely,

Ken Gan M.K.

Ken Gan
Mobile: 8718-0318

05 Days

2.7K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007797/AVD3N2

Date: 18/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30309119044	
Claimant Vehicle No :	EA999D	Insured Vehicle No :	SJP1353Y	
Date of Loss:	30/04/2019	Nature of Claim:	TP	Claim No: SNM19D201927C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EA999D	Engine No:	G4KJEH739910
Make & Model:	KIA SORENTO, 2.4 (A)	Chassis No:	KNAKU816ME5509862
Reg. Date:	15/04/2014 (Man. Year: 2014)	Odometer:	107483 km
Colour:	Red		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,706.00	2,218.50	487.50	18.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,180.00	1,570.00	57.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,456.00	3,398.50	2,057.50	37.71
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	5,456.00	2,700.00	2,756.00	50.51

INSPECTION

Date of Assignment:	03/05/2019	
Date Inspected:	06/05/2019	Inspected At:
		SRS INTERNATIONAL PTE. LTD 10 KAKI BUKIT ROAD 2 #03-18 , FIRST EAST CENTRE Singapore 417868

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2019)
Parts:	M1-SUV	KIA SORENTO 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EA999D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LEFT	Dented	1,379.00 F	*1,379.00 FL
2	1		*DOOR RUBBER-WEATHERSTRIP ASSY-FRONT DOOR SIDE,LEFT	Necessary	136.00 F	*136.00 FL
3	1		*GARNISH ASSY-FRONT DOOR SIDE LEFT	Cut	101.00 F	*101.00 FL
4	1		*MOULDING ASSY-SIDE SILL-LEFT	Cut	315.00 F	*315.00 FL
5	1		*GARNISH ASSY-FENDER SIDE LEFT	Cut	116.00 F	*116.00 FL
6	1		*FRONT PASSENGER SIDE FENDER	Dented	418.00 F	*418.00 FL
7	1		*81335 COVER	Not Necessary	158.00 F	*- FL
8	1		*79390 CHECKER	Not Necessary	83.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,706.00	2,465.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	246.50
Total Parts (\$\$)	2,706.00	2,218.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	1,100.00	500.00
2	LABOUR TO REMOVE ALL PARTS	New	1,500.00	600.00
3	TRANSFER DOOR FITTING	New	150.00	80.00
Gross Labour Cost (S\$)			2,750.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >