

ASS. REC. BY:

REF: CS3/FCI/19007804/Used3⁵²

Special Instructions:

From (Person):

Marius

ASSIGNMENT (Office)

From (Person):

Surenfer

of

FCI

Date/Time:

10:04am @ 3/5/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MVTC

To Inspect Vehicle No.:

SJW 7813K

Insured:

SHA 6599A

at Workshop n/a:

precise auto

Tel:

87457367

of

1 kaki Bkt Ave 6 # 02-31/36

Policy No.:

Claim No.:

D19002501 MFS4

Sum Insured:

Excess:

Make of Vch:
(Client's Record)

D.O.A.

24/04/2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement

Date/Time:

11am @ 3/5/2019

Person Contacted:

Aine

Vehicle

IN OUT

Date/Time	Action/Instruction (4) Estimate
	<u>SJW 7813K - X</u>
	<u>SHA 6599A - CC3/AK9/540503/Alha3s2</u>
	<u>Dismantle: 8/5/2019</u>

20A.22/6/2015

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Fc1/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW 7813K

at Workshop m/s Precise

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 18500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS MA 10 295

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SJW 7813K Yr Regn: 19/4/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAT

Make: KIA cerato coupe c.c. 159/

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 163665 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 1KNAFW611LA5231295

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front: Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/4/19 D.O.I. 3/5/19 6.16pm

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/11/13 plus not pros

Date/Time, File Pass to?

Preli. Report Final Report

1) Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$), Interview (\$), Tech. Invs (\$), Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

Empty box for additional information or totals.

MOTOR SURVEY ASSIGNMENT

Date	26-04-2019	Our Ref No. D19002801MFSH
Accident Date	24-04-2019	Claim Type. Third Party
Insured Vehicle	SHA6599A	Third Party Vehicle. SJW7813K
Survey Location	NO. 1 KAKI BUKIT AVE 6 #02-34/36	
Contact Person.	ARINE	
Contact No.	67457367/ 67457367	Fax No. 68413390
Survey Type	WITHOUT PREJUDICE: NO EST. COR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRECISE AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MSME19056092 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 30/04/2019 17:08
 SUBMITTED BY: Chia Pei Ying

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 30/04/2019 17:13

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 17:08
Date Of Accident	24/04/2019 17:30
Exact Location Of Accident	ALONG PANDAN GARDENS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE


Vehicle Registration Number	SJW7813K
Insured/Policyholder	
Name Of Registered Owner	PRECISE CAR RENTAL PTE LTD
Co Reg No	201818221G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98497930
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO KOUP
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5101115310-01
Cover Note Number	
Driver	
Name of Driver	MUHAMAD MUNIRUDDIN BIN MUSTAPHA
NRIC No	S9229784E
Date Of Birth	16/08/1992
Occupation	OUTDOOR
Date Of Driving Pass	28/01/2013
Driving Experience	6 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87795168
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMAD MUNIRUDDIN BIN MUSTAPHA
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJW7813K
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement Please Refer To Police
Report No: T2019 0425/ 2183

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's
Date & Time:

30/4/19
1550hrs

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190425/2183

2 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20190425/2183

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MUHAMAD MUNIRRUDIN BIN MUSTAPHA	ID No.	S9229784E
Related Vehicle	NIL	Contact No.	87795168
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 24/04/2019 at about 1707hrs, I delivered food at Commonwealth Secondary School and afterwards, I drove along pandan gardens and stop my vehicle, SJW7813K at the roadside with my hazard light on. I stop my vehicle for a short while as I was having a bad headache. On the same day around 1530hrs, my vehicle was hit from the rear. I went to make a check and saw a taxi, SHA6599A hit my rear bumper. My rear bumper and exhaust was detached from the vehicle and drop on the road. I had difficulty walking and the taxi driver called for ambulance. Both TP and the ambulance came down to scene and I was conveyed by the ambulance to NTFGH. I received outpatient sick leave from 24/04/2019 to 08/05/2019.

I wish to state that I don't have the taxi driver particulars, the TP IO who attended the scene and details of the accident after I was conveyed. I was contacted by the TP IO on 25/04/2019 to lodge a police report and I will submit my SD card of the car video recording after I have lodge a police report.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8221G
Vehicle Details	
Vehicle No.:	SJW7813K
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE KOUP 1.6 SX MT D/AB 2DR SR
Primary Colour:	Green
Manufacturing Year:	2010
Engine No.:	G4FCAH388012
Chassis No.:	KNAFW611LA5231295
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$14,075.00
Original Registration Date:	19 Apr 2010
First Registration Date:	19 Apr 2010
Transfer Count:	2
Actual ARF Paid:	\$14,075.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2020
PARF Rebate Amount:	\$7,037.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,159.00
COE Rebate Amount:	\$3,258.00
Total Rebate Amount:	\$10,295.00

The information contained herein is correct as at 03 May 2019

OK

- Opel Astra 2016
- Karlmann King - a luxury F150
- Audi Q5 2017

Kia Cerato koup Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Home > Used Cars > Car House Pte Ltd > Kia Cerato Forte Koup 1.6A SX

Kia Cerato Forte Koup 1.6A SX

Overview Financial Accessories Similar Research Photos Map



Price	\$19,800	Reg Date	14-Apr-2010 (11mths 10days COE left)
Depreciation	\$12,650 /yr View models with similar depre	Manufactured	2010
Mileage	72,783 km (8k /yr)	Transmission	Auto
Road Tax	\$738 /yr	OMV	\$15,610
Dereg Value	\$11,028 as of today (change)	ARF	\$15,610
COE	\$34,001	Power	92.7 kW (124 bhp)
Engine Cap	1,591 cc	No. of Owners	3
Curb Weight	1,232 kg		
Type of Vehicle	Sports Car		



Features

Powerful 1.6L 4-Inline Cylinder Engine At 124Hp, Auto Transmission, Sunroof, Multi Steering Controls, Keyless Start/Entry. View specs of the Kia Cerato Forte Koup (2009-2013)

Accessories

Premium Red Leather Seats, Factory Fitted Audio System, Auto Retractable Side Mirrors, Reverse Sensors, Catchy Fog Lamps, Sports Rims.

Description

Weekend Promo! Don't Take The Risk! Buy From A Case Trust Co! This Sporty Koup Will Satisfy The Heart With Its Attractive Styling, Good Acceleration, Responsive Engine Performance And Stability. Comes With A Nice Double Digits Plate Number For The Next Lucky Owner. Its In Excellent Owner Condition And Accident Free, See To Believe! Hurry Before Its Driven Away! GST Included. Deposit \$2000 Only!

Category

PARF Car, Low Mileage Car


Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Seller Information

Company Car House Pte Ltd
 » dealer's pricelist
 » 43 vehs sold | 36 vehs available

Address 210 Turf Club Road Lot B27
 Search cars nearby this location



Car insurance due?

Pay Less or Get \$100*, even if you don't buy.

Get a Quote >

*Terms and conditions apply.

Home » Used Cars » Carzbond » Kia Cerato Forte Koup 1.6A SX

Kia Cerato Forte Koup 1.6A SX

Overview Financial Accessories Similar Research Photos Map

Price	\$16,500		
Depreciation	\$9,950 /yr <small>View models with similar depre</small>	Reg Date	17-Mar-2010 <small>(10mths 13days COE left)</small>
Mileage	153,000 km (16.8k /yr)	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$9,599 as of today (change)	OMV	\$15,654
COE	\$20,340	ARF	\$15,654
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,232 kg	No. of Owners	4
Type of Vehicle	Sports Car		



Features

View specs of the Kia Cerato Forte Koup (2009-2013)

Description

New Roadtax Paid. Call To Offer.

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 16-Mar-2019 | Last Updated on: 02-May-2019

Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$4,950 (change)	Maximum 70% Loan
1st Instalment	\$1,184	Based on 2.98% interest rate
Total Upfront Payment	\$6,159 <small>(Without insurance)</small>	Check with seller for exact figure

Price Chart

Summary



Click on the point to view the vehicle

- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Company Carzbond
 » dealer's pricelist
 » 16 vehs sold | 13 vehs available

Address 210 Turf Club Road Lot C16
 Search cars nearby this location




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FCI19007804/Ucd3s2 Date: 21-05-2019 Code: FC12	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 6599A	Veh. Inspected	SJW 7813K
Policy No.		Coverage (\$)	0.00
Claim No.	D19002801MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	03/05/2019
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW611LA5231295	Colour	GREEN
Odometer	163665 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45ZR17	KUMHO	6 mm
L/H Front Tyre	225/45ZR17	KUMHO	6 mm
R/H Rear Tyre	225/45ZR17	KUMHO	6 mm
L/H Rear Tyre	225/45ZR17	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	24/04/2019	Inspect Date / Time	03/05/2019 (06:16 PM)
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE: \$18,500.00			

Report Ref No. CS3/FCI19007804/Ucd3s2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.