

ASS REC BY:

REF: CS/CT219007807/ VS d3

Special Instructions:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Elaine Cheong

CTI

Date/Time: 3.5.19 13.28 p.m

Estimated Cost

Bill for:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 67556

Insured: SKQ 71180

at Workshop m/s Allswell motor trades

Tel: 66791146

of 25 Defy Love a

Policy No: **DM PCSN3079881801**

Claim No: Sym 19D201828C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 24.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.5.17 2.14 p.m

Person Contacted: chai yee

Vehicle IN/OUT

Date/Time	Action/Instruction
	fishmald (✓)
	SJV 67556 -x
	SKG 7113D -x

REF: C71

ASSIGNMENT

From: Date: 8.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJV 6755G
at Workshop in/s: Allswell Motor Trades
of: 25 Deftu Lane 9

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 1.00 p.m.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 126.

IDAC Accident Report: Consistent? : Yes or No

GPA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: LIA 783/ 9th

Vehicle: IN / OUT

Veh No: SJV 6755G Yr Regn: 210

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Vios CC 1497

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 331271 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053HY9325152910

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/55-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 24/4/19 D.O.I: 2/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

8/5/19 cond cond L/S \$ 1300 with
(\$ 1,264.25 Ret - 49%)

RECEIVED 10 MAY 2019

Date/Time, File Pass to?

10/05/19

Typist

Date/Time, File Return to?

2)

3)

Report Format:

Lump Sum / I.B.I: (\$ 1,300/- H/S)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2019		03 May 2019 13:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z		
Vehicle Reg. No.:	SJV6755G	Date of Loss:	24/04/2019 18:00 - :59
Claim Type:	TP / SNM19D201828C02	Policy/Cover Note No.:	DMPCSN3079881801
Vehicle Reg. No. (Insured):	SKQ7118D	Policy No. (Claimant):	999994370
		Excess:	S\$500.00
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/05/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel: +65 6679 1146

email: ben@allswellmotor.com.sg

Not Authorised
Haha
8/5/19
1/581300/
Whip. Ht. -
3dy.

(3rd party claim against CTI insured SK0711BD)

Estimate repair

Vehicle No. : SJV6T55G
Make & Model : VIOS E AUTO
Chassis No. :
Date of survey :

Submitted by :
COE expiry :
Engine No. :

Ben
09-02-2020

7-1000
757
750

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	RH front door	01	\$820.00		3.05 m
02	RH front door strip	01	\$180.00		2.1
03	RH rear fender	01	\$499.00		repair * R X
				257	
1 set	Special nut				
01	Clips / retainers slide for door clip	01	\$40.00		2.1 X
	RH door internal garnish				
	@ \$40 / pck				
	Labour Description				
01	Disassemble / Assembly of 1/2 body	01	\$600.00		3.00
	RH front door and body.				
02	Spray painting of all affected parts (doors, fender, rocker arm)	01	\$800.00		6.00
				2564.25	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/04/2019 14:20
Date Of Accident	24/04/2019 18:30
Exact Location Of Accident	CAR PARK OF BLK 433 YISHUN AVE 11
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV6755G
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66791146

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994370
Cover Note Number	06 NOV 2018 TO 05 NOV 2019

Driver

Name of Driver	LONG SIAN SENG
NRIC No	S2513247E
Date Of Birth	24/08/1950
Occupation	OUTDOOR
Date Of Driving Pass	24/01/1979
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82991763
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 644 JURONG WEST ST 61 #07-118
Postcode	640644
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER WITH ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ7118D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JOSEPH SENGOL
NRIC/Passport Number	S1372902F
Contact Number	96803417
Address	
Postcode	
Insurance Company Name	

Nature Of Damage -

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature:
Date & Time:

Driver's Signature:
[If driver is not the policyholder]
Date & Time:



Reporting Centre Personnel's Signature:
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24th April 2019, about 6:10pm, I was driving towards to BK 628A Highway Ave 11. In the way beside blk 433. Suddenly, a car (SKB 7118D) reversed out from my right side and knocked my right-side door.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2541Z
Vehicle Details	
Vehicle No.:	SJV6755G
Vehicle to be Exported:	No
Intended Deregistration Date:	09 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1NZY044105
Chassis No.:	MR053HY9305152910
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	05 Feb 2010
First Registration Date:	05 Feb 2010
Transfer Count:	4
Actual ARF Paid:	\$12,717.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2020
PARF Rebate Amount:	\$6,358.00
Intended COE Rebate Details	
COE Expiry Date:	04 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$1,473.00
Total Rebate Amount:	\$7,831.00

The information contained herein is correct as at 09 May 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Apr 2019		03 May 2019 13:28 Edit Adj Rpt	S\$1,300.00 Edit Estimates	S\$1,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	- ID: -								
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 2014325412								
Vehicle Reg. No.:	SJV6755G	Date of Loss:	24/04/2019 18:00 - :59 [110 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201828C02	Policy/Cover Note No.:	DMPCSN3079881801						
Vehicle Reg. No. (Insured):	SKQ7118D	Policy No. (Claimant):	999994370						
		Excess:	S\$500.00						
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV6755G (SNM19D201828C02)
[SKQ7118D]
TP
ALLSWELL LEASING & LIMOUSINE PTE LTD
Apr 24 2019 6:00PM
[-]
Allswell Motor Traders

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	25/04/19 14:38	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	25/04/19 14:37	Driving License [Linked Accident Report Documents]	 Load JPG	☒
2	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	25/04/19 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
Relabel/Reorder				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/19 11:55	General View	 Load JPG	☒
2	10/05/19 11:55	General View	 Load JPG	☒
3	10/05/19 11:55	General View	 Load JPG	☒
4	10/05/19 11:55	General View	 Load JPG	☒
5	10/05/19 11:55	General View	 Load JPG	☒
6	10/05/19 11:55	General View	 Load JPG	☒
7	10/05/19 11:55	General View	 Load JPG	☒
8	10/05/19 11:55	General View	 Load JPG	☒
9	10/05/19 11:55	General View	 Load JPG	☒
10	10/05/19 11:55	General View	 Load JPG	☒
11	10/05/19 11:55	General View	 Load JPG	☒
12	10/05/19 11:55	General View	 Load JPG	☒
13	10/05/19 11:55	General View	 Load JPG	☒
14	10/05/19 11:55	General View	 Load JPG	☒
15	10/05/19 11:55	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
16	10/05/19 11:55	General View	 Load JPG	☒
17	10/05/19 11:55	General View	 Load JPG	☒
18	10/05/19 11:55	General View	 Load JPG	☒
19	10/05/19 11:55	General View	 Load JPG	☒
20	10/05/19 11:55	General View	 Load JPG	☒
21	10/05/19 11:55	General View	 Load JPG	☒
22	10/05/19 11:55	General View	 Load JPG	☒
23	10/05/19 11:55	General View	 Load JPG	☒
24	10/05/19 11:55	General View	 Load JPG	☒
25	10/05/19 11:55	General View	 Load JPG	☒
26	10/05/19 11:55	General View	 Load JPG	☒
27	10/05/19 11:55	General View	 Load JPG	☒
28	10/05/19 11:55	General View	 Load JPG	☒
29	10/05/19 11:55	General View	 Load JPG	☒
30	10/05/19 11:55	General View	 Load JPG	☒
31	10/05/19 11:55	General View	 Load JPG	☒
32	10/05/19 11:55	General View	 Load JPG	☒
33	10/05/19 11:55	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/05/19 13:30	PRS - SJV6755G	 Load PDF	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	25/04/19 14:36	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	25/04/19 14:36	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	25/04/19 14:38	Accident Statement	 Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	25/04/19 14:37	Driving License	 Load JPG	☒
2	25/04/19 14:37	Accident Photo	 Load JPG	☒
3	25/04/19 14:37	Accident Photo	 Load JPG	☒
4	25/04/19 14:37	Accident Photo	 Load JPG	☒
5	25/04/19 14:37	Accident Photo	 Load JPG	☒
6	25/04/19 14:37	Accident Photo	 Load JPG	☒
7	25/04/19 14:37	Accident Photo	 Load JPG	☒
8	25/04/19 14:37	Accident Photo	 Load JPG	☒
9	25/04/19 14:37	Accident Photo	 Load JPG	☒
10	25/04/19 14:37	Accident Photo	 Load JPG	☒
11	25/04/19 14:37	Accident Photo	 Load JPG	☒
12	25/04/19 14:37	Accident Photo	 Load JPG	☒
13	25/04/19 14:37	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Aliswell Motor Traders (HQ)	Thumbnail	Print
1	25/04/19 14:36	Sketch Plan	 Load JPG	☒
2	25/04/19 14:36	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007807/USD3Q2

Date: 14/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3079881801

Claimant Vehicle
No: SJV6755G

Insured Vehicle
No: SKQ7118D

Date of Loss: 24/04/2019

Nature of Claim: TP

Claim
No: SNM19D201828C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV6755G**

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZY044105

Reg. Date: 05/02/2010 (Man. Year: 2009)

Chassis No: MR053HY9305152910

Colour: White

Odometer: 331271 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,539.00	750.00	789.00	51.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	900.00	500.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,939.00	1,650.00	1,289.00	43.86
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	2,939.00	1,300.00	1,639.00	55.77

INSPECTION

Date of Assignment: 03/05/2019

Date Inspected: 08/05/2019 Inspected At:

Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2019)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJV6755G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Badly Dented	820.00 F	*820.00 FL
2	1		*RH FRONT DOOR STRIP	Necessary	180.00 F	*180.00 FL
3	1		*RH REAR FENDER	Repair	499.00 F	*- FL
4	1		*SET DOOR CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,539.00	1,000.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	250.00
Total Parts (\$\$)	1,539.00	750.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING OF ALL AFFECTED PARTS (DOORX2,FENDER ROCKER ARM)	New	800.00	600.00
Gross Labour Cost (\$\$)			1,400.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >