

REF: CS/FCI19007815/TIVd3<sup>12</sup>

ews  
TANSIKH  
Signature

ASSIGNMENT (Office)

FCI

Date/Time: 3/5/19

TO: TWS / TP REP / OD REGS / ENA / RV / MY / FC

Subject Vehicle No: SMC1319E

Insured: SHB 20032

at Workshop no: Performance  
303 Alexandra Road

Tel: 6319 0174

Policy No: D19002894MFSH

Claim No: [Blank]

Make of Veh: [Blank] D.O.A: 30/04/2019

CA / REV / REP / REV 24 HRS: 1052

H.O.D. Endorsement

Date/Time: 2:43pm @ 3/5/19 Person Contacted: cerolite

Vehicle IN: (OFF)

Date/Time	Action/Instruction (✓) Estimate
	SMC1319E - X
	SHB 20032 - CS/TMI/8003217/K19d3n2 DUA: 16/2/2018
16/5/19	Email preli revised to FCI
11/6/19	Final fig \$3043.50 confirmed by email (Ref 1050-80, 267)

Surveyor

Tanphik

REF: FCI

ASSIGNMENT

From: Date: 15/5/19

Veh No: SMC1319E Yr Regn: 2018, June

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC1319E  
at Workshop n/s performance  
of 303 Alexandra Road

Make: BMW 216D C.C. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 18811 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: WSA2R32030V921409

Policy No.

C/No: Gen. Cond: Good / Fair / Poor / Burnt

Claims No.

Steering: Inorder / Jammed / Leaked / Burnt or

Sum Insured: Excess:

Brake: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / S/Rim / STD A/Rim or

Make of Veh: HIN

Tyre Size: F: 205/60R16  
R: .....

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Log transfer

Bal. or Market Value:

Front R/Bal. 6 mm Rear R/Bal. 6 mm

IDAC Accident Rpt: Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

D.O.A. D.O.I. 15/5/19 @ 2100

CA / REV / REP. / 24 HRS 1DS

Survey held at P.M.C.

Date: Person Contacted:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear n/s

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 JUL 2019

Date/Time, File Pass to?  : Preli. Report

Days Of Repair: 3

1)  : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee:	135
Transportation:	50
3 + RS, SI	12
Photos	
Others	
TOTAL	197

2) 116 - typist

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format: CWS

Lump Sum / I.B.I.: (\$) 3043.50



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002894MFSH

Our ref: CS/FCI19007815/T1vd3

Date: 16/5/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

**WITHOUT PREJUDICE**

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO SMC 1319E**


We thank you for your instruction on 3/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/5/2019 at the premises of M/s PERFORMANCE MOTOS LIMITED and have the following to report:-

Workshop Estimate Amount	: S\$4,094.30
Revised Estimate Amount	: S\$2,968.55
"Check" Items Amount	: S\$569.75
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automobile Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	02-05-2019	<b>Our Ref No.</b> D19002894MFSH
<b>Accident Date</b>	30-04-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB2003Z	<b>Third Party Vehicle.</b> SMC1319E
<b>Survey Location</b>	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
<b>Contact Person.</b>	CAROLINE	
<b>Contact No.</b>	0/ 63190174	<b>Fax No.</b> 64794601
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PERFORMANCE MOTORS LIMITED	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SITHARA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 11 June 2019 9:48 AM  
**To:** PBSP; Taufikh (LKKAuto); SUR  
**Subject:** RE: FINAL REPORT/ SMC1319E

Dear Caroline,

WITHOUT PREJUDICE

Confirm amount \$3,043.50 before GST

Repair days: 3 days

**Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Monday, 10 June 2019 4:57 PM  
**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT/ SMC1319E

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00  
Total Parts : 1,029.50  
Total Labour & Parts : 3,043.50

Repair days: 3

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 16 May 2019 12:27 PM  
**To:** 'CWS Motor Claims'  
**Cc:** 'Sithara'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19002894MFSH/1, SMC 1319E  
**Attachments:** SMC 1319E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMC 1319E  
Date of survey: 15/5/2019  
Number of days : 3 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Monday, 6 May 2019 8:13 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19002894MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Friday, 3 May 2019 2:20 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19002894MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Veron Chen (LKKAuto)**

---

**From:** Teng Wai Khan <teng.wai.khan@simedarby.com.sg>  
**Sent:** Wednesday, 15 May 2019 5:50 PM  
**To:** Taufikh (LKKAuto)  
**Cc:** Keith Leo Chi Yung; Cresendo Llorca Lagman; Han Kwan Yong  
**Subject:** SMC1319E photos before painting

Hi Taufik,

Please refer to photos attached before painting. No check item. Meantime, we will proceed with paint work.  
Thanks

Wed 15/05 @ 10AM  
S&R

SMC1319E

BMN Dealer

### Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601  
64796624

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- After sales (Motorpad) item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: **02 MAY 2019**  
Date:

GST REG. NO : M2 - 0020081

## ESTIMATE

Estimate No. : **b1 51057** Page No. : 1 of 4  
Date Estimated : **02/05/2019**  
Prepared By : **Han Kwan Yong**

**- ESTIMATE REPAIR FOR -**  
Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
Singapore 159942

**- ACCOUNT - 40000**  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC1319E	V926409	26/06/2018	216d AT	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	wee? 80.00

Total Labour 1: **2,570.00**

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER PANEL PRIMED (PDC)	1	1,029.50	de 1,029.50
RR BUMPER LH SIDE GUIDE	1	49.05	x? 49.05
RR BUMPER LH INNER SIDE GUIDE	1	60.05	wx } x? 60.05
DECOUPLING RING PDC TORQUE CONVERTER	1	5.05	x ne 5.05
PDC SENSOR MEDITERRANBLAU WC10	1	380.65	x? 380.65

Total Parts : **1,524.30**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 15/5/19 @ 210pm Claim No. \_\_\_\_\_  
Date & Time \_\_\_\_\_ Excess S\$ \_\_\_\_\_  
Surveyor's Name Tan Jia Sign [Signature]  
Surveyor's Tel 97-165214 Authorised Yes / No \_\_\_\_\_  
Authorised Date WP Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR (Yes / No) Yes PML Yes / No \_\_\_\_\_  
Surveyor's E-mail tanjia@lkkauto.com  
No. of Working Days Recommend 3 days

*[Signature]*  
16/5/19

4094-30

Labour 1	:	<b>2,570.00</b>
Parts	:	<b>1,524.30</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>286.60</b>
<b>Grand Total</b>	:	<b>4,380.90</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 51057  
Date Estimated : 02/05/2019  
Prepared By : Han Kwan Yong

Page No. :

**REPAIR FOR -**  
Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
  
Singapore 159942

**REPAIR FOR - 303**  
MS First Capital Insurance Limited  
6 Raffles Quay  
#21-00  
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC1319E	V926409	26/06/2018	216d AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper include removing attachments to facilitate repairs and knocking out dented areas caused by the accident	850.00		850.00	
To respray rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (PDC)	1,029.50	1.00		1,029.50

# SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,029.50
Total Labour & Parts :	3,043.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,043.50
GST @7%:	213.05
<b>Grand Total :</b>	<b>3,256.55</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19007815/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-06-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2003Z	Veh. Inspected	SMC 1319E
Policy No.		Coverage (\$)	0.00
Claim No.	D19002894MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	03/05/2019
2. Vehicle Particulars & Condition			
Make & Model	BMW 216D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA2B32030V926409	Colour	BLUE
Odometer	18811	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/04/2019	Inspection Date	15/05/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1319E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER PANEL PRIMED (PDC)(SN)	DEFORMED	1,029.50	1,029.50
1	RR BUMPER LH SIDE GUIDE (SN)	NOT NECESSARY	49.05	-
1	RR BUMPER LH INNER SIDE GUIDE (SN)	NOT NECESSARY	60.05	-
1	DECOUPLING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	5.05	-
1	PDC SENSOR MEDITERRANBLAU WC10 (SN)	NOT NECESSARY	380.65	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			1,604.30	1,109.50
<b>LABOUR</b>				
TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.			1,275.00	850.00
TO RESPRAY REAR BUMPER.			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	150.00
			2,490.00	1,934.00
<b>GRAND TOTAL</b>			<b>4,094.30</b>	<b>3,043.50</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,043.50</b>

Report Ref No. CS/FCI19007815/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.