

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/05/2019 15:15
Date Of Accident	02/05/2019 18:40
Exact Location Of Accident	JUNC OF BOON LAY AVE & BOON LAY DRIVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB6279U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KEM AUTO
Co Reg No	53309211J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97877114

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	GRAB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5105127209
Cover Note Number	

### Driver

Name of Driver	LIM CHEE CHONG
NRIC No	S9113810G
Date Of Birth	21/04/1991
Occupation	OUTDOOR
Date Of Driving Pass	19/08/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90227684
Fax Number	
Contact Number	
Email Address	BREMENLIM04@GMAIL.COM

Address	BLK 756 YISHUN STREET 72 #09-282
Postcode	760756
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG
Police Station Address	<b>ROAD:</b> 1 SEGAR ROAD , <b>POSTCODE:</b> 677738 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-8929999 - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20190502/2163

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME7634U
Vehicle Make/Model/Colour	NISSAN SYLPHY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG AH LECK
NRIC/Passport Number	S0379898D
Contact Number	67902684
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	LIM CHEE CHONG
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SJB6279U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 03/05/19 PM 3/5/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer to the police report: 7/20190502/2163

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 0324PM

03/05/19

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

shy 03/05/19



# Individual Statement



**SINGAPORE  
POLICE FORCE**



T/20190502/2163

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

2 of 3

Report No. T/20190502/2163

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	LIM CHEE CHONG	ID No.	S9113810G
Related Vehicle	SJB6279U (Car)	Contact No.	90227684
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	02/05/2019	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	Ong Ah Leck	ID No.	S0379898D
Related Vehicle	SME7634U (Car)	Contact No.	67902684
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 02/05/19, at about 1840hrs, I was driving my Toyota Vios, SJB6279U along Boon Lay Avenue towards the cross junction when the traffic light was red and I came to a stop. The Nissan Sylphy, SME7634U belonging to Ong Ah Leck then stopped behind my car. When the traffic light turn green, I was about to move off when the Nissan Sylphy vehicle behind me collided with my vehicle. I then came out of the car and told him to come out of the car as I saw that the rear end of my car had a few cracks and a dent at the bumper.

After he exit the car, we both exchange particulars and contact number. Ah Leck admitted that he did collide with my car because he was in a rush. however he claims that the collision was too small for the damage to be caused by him, and Ah Leck told me to let this matter go. I then told him that I will settle this incident with my insurance company and we both then parted ways.

I wish to state that he was uncooperative to exchange particulars and contact details throughout the whole incident. There was a in-car camera recording of this incident and the footage has been extracted.

Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190502/2163

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

1 of 3

Report No. T/20190502/2163

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/05/2019 23:22	Video Report No.:	Station Diary No.: 179
--	-------------------	---------------------------

Informant's Particulars				
Name of Informant: LIM CHEE CHONG		Address: APT BLK 756 YISHUN STREET 72 #09-282 SINGAPORE 760756		
ID Type / ID No.: NRIC NO / S9113810G		Contact No.: Home/Office: Mobile: 90227684		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 28	Date of Birth: 21/04/1991	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Hand/Pedal vehicle driver		Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/05/2019 18:40	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BOON LAY AVENUE BOON LAY DRIVE along Boon Lay Avenue before the cross junction between Boon Lay Drive and Boon Lay Avenue				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJB6279U	Car	TOYOTA	VIOS	White	Slightly Damaged	0
SME7634U	Car	NISSAN	SYLPHY	Grey	No Damage	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190502/2163

2 of 3

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677736  
Tel No: 1800-8929899

Report No. T/20190502/2163

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	LIM CHEE CHONG		ID No. S9113810G
Related Vehicle	SJB6279U (Car)		Contact No. 90227684
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	02/05/2019		Date Discharge NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	Ong Ah Leck		ID No. S0379898D
Related Vehicle	SME7634U (Car)		Contact No. 87902884
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 02/05/19, at about 1840hrs, I was driving my Toyota Vios, SJB6279U along Boon Lay Avenue towards the cross junction when the traffic light was red and I came to a stop. The Nissan Sylphy, SME7634U belonging to Ong Ah Leck then stopped behind my car. When the traffic light turn green, I was about to move off when the Nissan Sylphy vehicle behind me collided with my vehicle. I then came out of the car and told him to come out of the car as I saw that the rear end of my car had a few cracks and a dent at the bumper.

After he exit the car, we both exchange particulars and contact number. Ah Leck admitted that he did collide with my car because he was in a rush. However he claims that the collision was too small for the damage to be caused by him, and Ah Leck told me to let this matter go. I then told him that I will settle this incident with my insurance company and we both then parted ways.

I wish to state that he was uncooperative to exchange particulars and contact details throughout the whole incident. There was a in-car camera recording of this incident and the footage has been extracted.

Police Report



SINGAPORE  
POLICE FORCE



T/20190502/2163

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

3 of 3

Report No. T/20190502/2163

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
J /  
RYAN THEN YONG JIAN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 YEO GEAK ENG CECILIA  
Contact No: 65476404

Authentication Stamp  
NP103

Signature Of Informant:

Date/Time:  
02/05/2019 23:22

Classification Of Case: