

Date: 02.05.2019
Vehicle No: SMC9094A
Model: TOYOTA NOAH HYBRID 1.8X CVT
Chassis: ZWR800325163 - 2018
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: YK5661E
Date of Accident: 30.04.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR SIDE MIRROR ASSY RH	1	<i>nd/cm</i>	\$910.00 ✓
SUB TOTAL				\$910.00
LESS 25%				-\$227.50
PARTS TOTAL				\$682.50

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE & REPLACE DOOR SIDE MIRROR & ETC \$80.00 *601*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS \$120.00 *601*

TO CHECK & REFIX SIDE MIRROR WIRING & ETC \$30.00 *201*

LABOUR TOTAL \$230.00

ONG TOTAL \$912.50

*Not Authorised
Running Repair
1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: