

T-005/2002

ASS. REC. BY:

REF: CS3/MSG19007886/T1cd36

Special Instruction:

Surveyor: Tau KichASSIGNMENT (Office)

minim N

From (Person): Kathrine Wongof MSGDate/Time: 6.5.19 9.57a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: XD 7662MInsured: SFC 8823Cat Workshop m/s Koh Kock LeongTel: 68978787of NO 24 TUDS hve 2Policy No: 227072Claim No: 1000893136

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 2.5.20197.5.19 (After 12.00pm)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 6.5.19 10.58a.mPerson Contacted: ConnieVehicle IN OUT

Date/Time

Action/Instruction Estimate (✓)XD 7662M-xSFC 8823C - MBA/MSG15000 467/21 D.O.A - 08/01/201609/5/19 @ 1.35pm Checked with Kathy, they will not provide us the estimate.Dismantle: 10/5/2019

Surveyor *Tan Jho*

REF: **MS19**

ASSIGNMENT

From: _____ Date: **7.5.2019**

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **XD 7662M**
at Workshop m/s **Koh Kock Leong**
of **NO 24 Tuas Ave 2**

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: **After 12.00p.m**

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **mp**

Date: _____ Person Contacted:

Vehicle: IN / OUT

N/S	O/S

Veh No: **XD 7662M** Yr Regn: **2013 / Aug**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **Tipper truck**

Make: **Volvo FMX 370** C.C. **10837**

Colour: **white** A/C: Insured / Std / NI / NA

Sp. Reading: **484 458** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **yv2JIE/D9DA746436**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **315/80R22.5**
R: **(P)**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **E88ip/45**

Front

Rear

R/Bal. **8** mm R/Bal. **8/8** mm

L/Bal. **8** mm L/Bal. **8/8** mm

D.O.A. D.O.I. **7/5/19**

Survey held at **KKL 24 Tuas Ave 2**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range \$5,000 - \$6,000
	<i>[Signature]</i>
	4/7/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: **PRE**

Lump Sum / I.B.I. (\$)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 May 2019 15:47		06 May 2019 09:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LANG WOON KHIM, ID: S1610438H		
Main Claimant:	KOH KOCK LEONG ENTERPRISE PTE LTD, Co. Reg. No.: 199104084W		
Vehicle Reg. No.:	XD7662M	Date of Loss:	02/05/2019 00:00 - :59 [68 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	1000893136 Coverage: 25/01/2019 - 24/01/2020
Vehicle Reg. No. (Insured):	SFC8823C	Policy No. (Claimant):	
		Excess:	
Repairer:	Koh Kock Leong Construction Pte Ltd (HQ) NO 24 TUAS AVENUE 2, 639455 Tuas - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/05/2019]		
Driver/Custodian (Insured):	LEOW CHEW ENG (), NRIC: S1744267H Email:		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE. CONTACT: 6897 8787		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4084W
Vehicle Details	
Vehicle No.:	XD7662M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	VOLVO
Vehicle Model:	FMX370 64R DAY CAB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	D11291433
Chassis No.:	YV2J1E1D9DA746436
Maximum Power Output:	-
Open Market Value:	\$112,481.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$5,625.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$57,740.00
COE Rebate Amount:	\$24,772.00
Total Rebate Amount:	\$24,772.00

The information contained herein is correct as at 14 May 2019

OK

MS1319059374 / STA INSPECTION PTE LTD - Boon Lay
ENTRY DATE & TIME: 02/05/2019 11:09
SUBMITTED BY: Woodford Richard Vincent

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GI&A Records Management Centre established by the General Insurance Association of Singapore (GI&A) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/05/2019 11:09
Date Of Accident 02/05/2019 07:30
Exact Location Of Accident ALONG AYE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number XD7862M
Insured/Policyholder
Name Of Registered Owner KOH KOCK LEONG ENTERPRISE PTE LTD
Co Reg No 199104084W
Email Address ADMIN@KKLE.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-68978787
Vehicle Particulars
Manufacturer VOLVO
Model TIPPER TRUCK
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5102388228
Cover Note Number
Driver
Name of Driver VELLAICHAMY PREMKUMAR
Passport No/FIN G7287090K
Date Of Birth 18/05/1982
Occupation OUTDOOR
Date Of Driving Pass 04/04/2018
Driving Experience 1 YEAR AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-87087159
Fax Number
Contact Number OFFICE-68978787
Email Address NOEMAIL

Address 24 TUAS AVE 2
 Postcode 639455
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY
Other Information
 Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO WITH COMPANY
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFC8823C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LEOW CHEW ENG
 NRIC/Passport Number S1744267H
 Contact Number 96713498
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This form must be completed by the policyholder and/or the Authorized Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The accuracy and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Roadside Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will be a free of charge available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and its copies of the report being made available as a record.
8. **Consent under the Personal Data Protection Act (PDPA)**

I, the undersigned, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or provided by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers". The insurer's lawyers/law firms, the relevant authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of
 - (i) assessing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my insurance or responsibility to any other party;
 - (iv) administered by my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve the release of certain personal data about me in being about delivery of the value as well as the actual time of occurrence/road parking); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers (s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for use or more of the above purposes, and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be placed outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.


Sketch Plan #2

SKETCH PLAN

A: XD7662M

B: 9FC 8823C

Along AYE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time 2 May 2019 @ 7:30 AM

Accident Location Along AYE

On 2 May 2019 at about 7:30 am, I was driving a vehicle XD7662M at along AYE on the lane 3. I was on my track, suddenly the third party vehicle 9FC8823C on my left side merge lane cut into my lane and hit into my front left bumper. No one is injured. I have video recorded for your reference.


☐ Reporting Only ☐ Own Damage ☒ Third Party ☐ Claim at other workshop (OD/TP)

DECLARATION


I/We declare the information provided are true in every respect.

IMPORTANT NOTES:

This form is for use by the insured only. It is not to be used by the insurer or any other person. It is to be kept by the insured as a record of the accident.



Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 May 2019 15:47		06 May 2019 09:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LANG WOON KHIM, ID: S1610438H								
Main Claimant:	KOH KOCK LEONG ENTERPRISE PTE LTD, Co. Reg. No.: 199104084W								
Vehicle Reg. No.:	XD7662M	Date of Loss:	02/05/2019 07:00 - :59 [68 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 227072	Policy/Cover Note No.:	1000893136 (Comprehensive) Coverage: 24/01/2019 - 24/01/2020						
Vehicle Reg. No. (Insured):	SFC8823C	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Koh Kock Leong Construction Pte Ltd (HQ) NO 24 TUAS AVENUE 2, 639455 Tuas - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 07/05/2019]								
Driver/Custodian (Insured):	LEOW CHEW ENG (), NRIC: S1744267H Email:								
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE. CONTACT: 6897 8787								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD7662M (227072)
 [SFC8823C]
 TP
 KOH KOCK LEONG ENTERPRISE PTE LTD
 May 2 2019 7:00AM
 [LANG WOON KHIM]
 Koh Kock Leong Construction Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/05/19 12:55	General View	 Load JPG	☒
2	14/05/19 12:55	General View	 Load JPG	☒
3	14/05/19 12:55	General View	 Load JPG	☒
4	14/05/19 12:55	General View	 Load JPG	☒
5	14/05/19 12:55	General View	 Load JPG	☒
6	14/05/19 12:55	General View	 Load JPG	☒
7	14/05/19 12:55	General View	 Load JPG	☒
8	14/05/19 12:55	General View	 Load JPG	☒
9	14/05/19 12:55	General View	 Load JPG	☒
10	14/05/19 12:55	General View	 Load JPG	☒
11	14/05/19 12:55	General View	 Load JPG	☒
12	14/05/19 12:55	General View	 Load JPG	☒
13	14/05/19 12:55	General View	 Load JPG	☒
14	14/05/19 12:55	General View	 Load JPG	☒
15	14/05/19 12:55	General View	 Load JPG	☒
16	14/05/19 12:55	General View	 Load JPG	☒
17	14/05/19 12:55	General View	 Load JPG	☒
18	14/05/19 12:55	General View	 Load JPG	☒
19	14/05/19 12:55	General View	 Load JPG	☒
20	14/05/19 12:55	General View	 Load JPG	☒
21	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
22	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
23	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
24	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
25	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
26	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
27	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
28	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
29	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
30	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
31	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
32	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
33	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
34	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
35	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
36	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
37	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
39	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
40	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
41	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
42	14/05/19 12:55	Photographs of Damaged Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/05/19 15:49	NOTICE OF PRI & TP E-FILE REPORT	 Load PDF	
2	03/05/19 16:32	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007886/T1CD3E2

Date: 11/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000893136

Claimant Vehicle No : XD7662M

Insured Vehicle No : SFC8823C

Date of Loss: 02/05/2019

Nature of Claim: TP

Claim No: 227072

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD7662M

Make & Model: VOLVO FMX370, 10.8 D 64R DAYCAB (M)

Engine No: D11291433

Reg. Date: 30/08/2013 (Man. Year: 2013)

Chassis No: YV2J1E1D9DA746436

Colour: White

Odometer: 484458 km

Engine Capacity: 10837 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size: 315/80 R22.5 (D)

Front Left Side: EFFI PLUS 8 mm

Rear Left Side: EFFI PLUS 8/8 mm

Front Right Side: EFFI PLUS 8 mm

Rear Right Side: EFFI PLUS 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 07/05/2019 Inspected At:

Koh Kock Leong Construction Pte Ltd (HQ)
NO 24 TUAS AVENUE 2
Singapore 639455

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Jul 2019)

Parts: N/A VOLVO FMX370 10.8 D 64R DAYCAB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD7662M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >