

ASS. REC. 17

REC

CSB/LPC19007924/GSD302

Serial Instruction

Surveyor

Lmo Oieny

ASSIGNMENT (Office)

From (Person)

Ong Liti

of

LPC

Date/Time

6/5/19 @ 10:37am.

Estimated Cost

Bill to

OD / TP / WS / TP RES / OB RES / EVA / INV / MV / CS

To Inspect Vehicle No.

GBA 285R

Insured

GBC 235A

at Workshop m/s

Orion Autoclinic

Tel:

9328 0092

of

No. 25 / Kaki Bukit Rd 4 #03-31

Policy No.

Claim No.

18/19/19 / VCOS / 021737

Sum Insured

Excess:

Make of Veh:

D.O.A.

30/4/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

12:00pm 6/5/19

Person Contacted

Mr. Kenneth

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate Insp: 03-32	
	GBA 285R - CCG/MG18WS704/Aca3q ²	DVA: 29/3/2018
	GBC 235A - CCG/AX416010755/Gwg352	DVA: 9/5/2016

Surveyor: PKS
62REF: CPC

24867

ASSIGNMENT

(2021)

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Orion Auto

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$22K

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBA 285R Yr Regn: 27 Dec 2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick-up Double cabMake: Toyota Hilux C.C. 2982

Colour _____ A/C: Insured / Std / NI / NA

Sp. Reading 267723 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0E 812 G 60400 3877Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at w/sDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$4000COE \$13154Submit PRS Report.

RECEIVED 07 MAY 2019

Date/Time, File Pass to?

07/05/191) Types

Date/Time, File Return to?

2) _____



Preli. Report



Final Report

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee: 490

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

490Report Format: PRS

Lump Sum / I.B.I. (\$) _____

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 6 May 2019 10:37 AM
To: Yvonne; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Lonpac Insured GBC235A [EAL.2019.6303.MK.ya - GBA285R] Our Ref: 18/19/19/VC05/021737 [External General]

Lonpac External - General


Without Prejudice
Save as to Costs

Dear Yvonne

Please see our correct address below and update your record accordingly,

Dear Nivitha

Please see below and arrange survey.
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Yvonne [mailto:yvonne@ealc.com.sg]
Sent: Monday, 6 May, 2019 10:23 AM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: PRI: Lonpac Insured GBC235A [EAL.2019.6303.MK.ya - GBA285R]

Our ref : 2019.6303.MK.ya - GBA285R
Your ref : GBC235A

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

Lonpac Insurance Bhd (Singapore Branch)
No. 100 Beach Road, #19-00 Shaw Tower
Singapore 189702
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s lonpac Insurance Bhd (Singapore Branch) Vehicle GBA285R inspected as follows by Name:		
Before repair	Parts removed	After repair
_____ Signature	_____ Signature	_____ Signature
_____ Date/ Time:	_____ Date/ Time:	_____ Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE
CLAIMANT: NG PUAY HENG

ACCIDENT INVOLVING GBA285R & GBC235A ON 30 APRIL 2019 ALONG GAMBAS AVENUE AT ABOUT 1730 HOURS

We refer to the above matter wherein we are instructed to act for **NG PUAY HENG**, the owner of vehicle no. **GBA285R**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **GBA285R** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Orion Autoclinic Pte Ltd
No. 25 Kaki Bukit Road 4,
#03-31 Synergy@KB, Singapore 417800
Tel: 93280092(Mr Kenneth)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	2486J
Vehicle No.:	GBA285R
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HILUX DOUBLE CAB
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1KD7192301
Chassis No.:	MR0EZ12G604003877
Maximum Power Output:	-
Open Market Value:	\$25,950.00
Original Registration Date:	27 Dec 2006
First Registration Date:	27 Dec 2006
Transfer Count:	2
Actual ARF Paid:	\$28,545.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	26 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,249.00
COE Rebate Amount:	\$13,154.00
Total Rebate Amount:	\$13,154.00
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 06 May 2019

OK

► Toyota Hilux Used Vehicle List (2 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Hilux Double-Cab (COE till 06/2022) (Diesel)	\$26,800	\$8,500 /yr	10-Jul-2007	2,982 cc	-	ABWIN (1994) Pte Ltd	Available

Rare! Engine In Superb Condition. Extremely Quiet And Reliable Double Cab. Able To Register Under Personal Name. In House Loan Available! Fast Approval And Delivery!

Office No. - -

Joey - 85186788 | Alson - 93897875 | Siang - 90392228

Toyota Hilux Double-Cab (COE till 01/2027) (Diesel)	\$53,838	\$6,990 /yr	16-Jan-2007	2,982 cc	-	Hoe Beng Auto Trading	Available
--	-----------------	-------------	-------------	----------	---	-----------------------	------------------

100% In House Loan Available. View To Believe! Don't Miss, Call Today!

Office No. - 67450138 / 65523003

Eric - 83538778 | Agnes - 93680138 | Lee - 98300138

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

[Home](#) | [New Cars](#) | **[Used Cars](#)** | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Articles](#)

SUPREME

NEW CARS | PRE-LOVED CARS | INSURANCE

SEARCH Hilux Price Range ▼ Depreciation ▼ Year Reg ▼ Vehicle Type ▼

Home » Used Cars » ABWIN (1994) Pte Ltd » Toyota Hilux Double-Cab (COE till 06/2022)

► Toyota Hilux Double-Cab (COE till 06/2022)

[Overview](#) | [Financial](#) | [Accessories](#) | [Similar](#) | [Research](#) | [Photos](#) | [Map](#)

ABWIN 諭輝

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	\$26,800	Fuel Type	Diesel
Depreciation ?	\$8,510 /yr	Reg Date	10-Jul-2007 (3yrs 1mth 23days COE left)
Mileage	N.A.	Manufactured ?	2007
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$11,819 as of today (change)	OMV ?	\$24,978
COE ?	\$18,757	ARF ?	\$27,476
Engine Cap	2,982 cc	No. of Owners ?	2
Curb Weight ?	1,680 kg		
Type of Vehicle	Truck		

Description

Rare! Engine In Superb Condition. Extremely Quiet And Reliable Double Cab. Able To Register Under Personal Name. In House Loan Available! Fast Approval And Delivery!

Category

COE Car

Status

Available

Resources

Compare

Valuation - Free


[☆ Shortlist](#) | [Report Error](#)
Seller Information

Company A
»
»
a
(

Address 2
S

Contact Person(s) J
A

MSME19057221 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 03/05/2019 15:48
SUBMITTED BY: Chia Pei Ying

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 03/05/2019 16:15

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/05/2019 15:48
Date Of Accident 30/04/2019 17:30
Exact Location Of Accident GAMBAS AVE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBA285R
Insured/Policyholder
Name Of Registered Owner NG PUAY HENG
NRIC No S1432486J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90680064
Alternative Phone No OFFICE-90680064

Vehicle Particulars

Manufacturer TOYOTA
Model HILUX
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number Z19VC05001447
Cover Note Number

Driver

Name of Driver NG PUAY HENG
NRIC No S1432486J
Date Of Birth 08/03/1960
Occupation OUTDOOR
Date Of Driving Pass 24/08/1977
Driving Experience 41 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90680064
Fax Number
Contact Number OFFICE-90680064
Email Address NOEMAIL

Address	BLK 166A PUNGGOL CENTRAL #06-125
Postcode	821166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE WAITING TO EXIT THE SLIP ROAD, I WAS STATIONARY LOOKING OUT FOR ONCOMING TRAFFIC. VEHICLE B HIT ONTO MY REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC235A
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LU CHONG HUI
NRIC/Passport Number	
Contact Number	91779972
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While waiting to exit the SLP road, I was stationary looking out for oncoming traffic. Vehicle B hit onto my rear protection.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:Driver's Signature
(If driver is not the policyholder)
Date & Time:Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC19007924/Gsd3e2 Date: 14-05-2019 Code: LPC2	
				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBC 235A	Veh. Inspected	GBA 285R	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/021737	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	06/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HILUX	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR0EZ12G604003877	Colour	BLACK	
Odometer	267723 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	30/04/2019	Inspect Date / Time	06/05/2019 (05:00 PM)	
Survey held at	ORION AUTOMOBILE-25 KAKI BKT RD 4#03-31			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC19007924/Gsd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.