



SMRT Accident Vehicle Repair Estimates

Cecilia

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/05/2019
User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1325S
Case Reference Number	BUS/04/19/1066
Registration Date	25/3/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Kong Kok Siang
Type of Accident	Side Swipe
Accident Date and Time	27/4/2019 6:19 AM
Accident Reported Date and Time	29/4/2019 2:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101335
Special Instruction to ARC, if any	SMB1325S - RIGHT SIDE MIRROR PLS CHECK PA7272R - TP INSURED WITH CHINA TAIPING - LEFT PORTION DAMAGED
Prepared Date and Time	30/4/2019 1:22 PM
Chassis Number	WMAA2222D7001792
Mileage	
Work Shop	
Repair Completion Date and Time	

L/S \$1050/- 0.5 day.

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$265.00	\$132.50
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$896.33	\$896.33
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,161.33	\$1,028.83
Lump Sum Total	\$1,150.00	\$1,050.00
Number of Repair Days	0.5	0.5
Prepared / Adjusted By	Boon Chew Tay	Hwee Jie
ARC / Surveyor Sign Off Date	30/04/2019 1:27 PM	02/05/2019 11:27 AM
Signature		L+L
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/05/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$265.00	\$132.50
Total Labour	\$265.00	\$132.50

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR, VIEW:FRONT, R H, FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace
Total					\$1,244.90		\$1,120.41		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									