

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YN4723B18119

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Date: 04-05-19

Vehicle No: YN4723B

Model/Make: Mitsubishi

Canter FEB21ER4SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Door <i>70/Bent</i>	\$ 2,001.50	
2	Door Draught Weatherstrip <i>11</i>	\$ 408.40	<i>α</i>
3	Head Lamp <i>CNR</i>	\$ 1,712.80	
4	Head Lamp Clips 01 set <i>11</i>	\$ 23.00	SN X
5	Signal Lamp <i>SCN</i>	\$ 324.30	<i>+</i>
6	Signal Lamp Clips 01 set <i>11</i>	\$ 20.00	SN X
7	Side Lamp <i>320</i>	\$ 259.20	<i>+</i>
8	Step Garnish <i>CNR</i>	\$ 613.20	<i>+</i>
9	Bumper <i>Bent/320</i>	\$ 1,133.20	<i>+</i>
10	Bumper Clips 1 set <i>11</i>	\$ 50.00	SN X
11	Bumper Side <i>11/320</i>	\$ 375.00	<i>+</i>
	To check all wiring & electrical component for proper function	\$ 80.00	<i>20</i>
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	<i>30</i>
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 100.00	<i>60</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	<i>300</i>
	To putty & spray painting & including touch up paint on accident affected area	\$ 500.00	<i>450</i>

Total Parts & Labour of estimate for damaged vehicle

\$8,250.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - To be on a "Without Prejudice" basis
 - No money & no work is allowed
 - Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Authorized**LKK**3650/**3 Lh.**6/5/19**Take photo after repair**p-5607.13**50%**p-2803.56**calc - 860.00**3663.56*