

INS. CASE OWNER: Stally CC 4 AXA1900 7940, Eg 863% LKK: IDAC:

Surveyor: Steve DOI: 15/19 Date/Time: 6/15/19 Registered in Merit: \_\_\_\_\_

Pre-assign / CCU / FTE  
 Insured Vehicle No.: SUJ. 89714H Claim No.: SAMO 2M7W (11440)  
 Name of Insured: FEUET PANY LIMITED Policy No.: GA 717821  
 Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model: HONDA  
 Excess Sec II :SS \_\_\_\_\_ D.O.A.: 2014/1A Place of Accident: JURONG TOWN HALL RD  
 Is driver the owner? ( YES / NO ) Nature of Accident: \_\_\_\_\_

If NO, Driver Name / Age: \_\_\_\_\_ OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
 Driver Tel No.: \_\_\_\_\_ (VL: YES / NO ) Insured Liability: \* Final ? Yes / No

XE 501K → → → →  
 INSR: WSP: Tel: Liability: RMKS: Woon Meng  
 INSR: WSP: Tel: Liability: RMKS:  
 INSR: WSP: Tel: Liability: RMKS:  
 INSR: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE/PIC
<u>XE 501K - X</u>	Non-Reporting lr (1st)	
<u>SUJ 89714H - X</u>	Non-Reporting lr (2nd)	
	Non-Reporting lr (Final)	
	Notification lr (if non-pickup)	
	Call OI	<u>7 CPL</u>
	After call lr to OI	<u>2/7/19</u>
	Documentation Check List:	Handler Typist
<u>2/7/19</u>	Notification lr (if non-pickup)	<input checked="" type="checkbox"/>
<u>2/7/19</u>	After call lr to OI	<input checked="" type="checkbox"/>
<u>3/7/19</u>	Authorisation To Act	<input checked="" type="checkbox"/>
<u>3/7/19</u>	Release Voucher	<input checked="" type="checkbox"/>
<u>7/11</u>	Final Repair Bill	<input checked="" type="checkbox"/>
<u>7/11</u>	Car Rental Invoice	<input checked="" type="checkbox"/>
<u>7/11</u>	Towing Invoice	<input checked="" type="checkbox"/>
<u>7/11</u>	LTA / GIA	<input checked="" type="checkbox"/>
<u>7/11</u>	Medical Bill	<input checked="" type="checkbox"/>
<u>7/11</u>	PIR	<input checked="" type="checkbox"/>
<u>7/11</u>	Mandate/Reject Instruction	<input checked="" type="checkbox"/>
<u>7/11</u>	LOD	<input checked="" type="checkbox"/>
<u>7/11</u>	Payment Breakdown Form	<input checked="" type="checkbox"/>
<u>7/11</u>	Post-Repair Photos	<input checked="" type="checkbox"/>
<u>7/11</u>	Others	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_ Confirm by: Steve

FINALIZATION Date/Time: 3/7/19 / 1:27pm Confirm with: \_\_\_\_\_ Email  Call

FINAL SETTLEMENT Date/Time: 7/11/19 Confirm with: TEWA SAM SEW SOW Email  Call   
 Final Liability: \$ 100 (Agreed / Assessed) BOLA S/N No.: 15  
 Repair Cost: (WAST) \$ 4012.50  
 Loss of Rental (LOR): \$ \_\_\_\_\_ ( \_\_\_\_\_ days)  
 Loss of Use (LOU): \$ 1000.00 (5200 x 5 days)  
 Loss of Income (LOI): \$ \_\_\_\_\_ ( \_\_\_\_\_ x \_\_\_\_\_ days)  
 LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]  
 GIA/LTA Search: \$ 2.00  
 Medical: \$ \_\_\_\_\_  
 Disbursement: \$ \_\_\_\_\_ (e.g. Tow / Independent)  
 Legal Cost: \$ \_\_\_\_\_  
 Total: \$ 5014.50 Global Sum \$\$: 5010.00  
 If NO or B 28, Ass. Ltd: OI encroached into TP lane.  
 COPY SENT 7/11/19  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: TP  
 3) Survey fee: 83501-

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call   
 Payee 1: \$ 5010.00 Name 1: WOON MENG MOTOR PTE LTD  
 Payee 2: (Strike if N.A.) \$ \_\_\_\_\_ Name 2: \_\_\_\_\_  
 Payee 3: (Strike if N.A.) \$ \_\_\_\_\_ Name 3: \_\_\_\_\_



Joy

# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-00 Midview Building, Singapore 658578  
 Workshop: 50 Bukit Batok St 23, #01-00 Midview Building, Singapore 658578  
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7060 *6316 1131*  
 42, Sungai Kadul Ave, Singapore 729090 Tel: 63298523  
 ( Email Address : woonmeng @singnet.com.sg )  
 Co Reg No. 200503678M GST Reg No. 20-0903678M

## Estimate

## TP Claim

To : AXA Insurance Singapore Pte Ltd  
 Motor Claims Dept

Date : 10 May 2019

Dear Sirs :

Fax : 68804838

**RE : ESTIMATE COST FOR MITSUBISHI FV51 - XE501K  
 ACCIDENT INVOLVING XE501K AND SLJ8934H ON 29.04.2019**

ITEMS	DESCRIPTION	QTY	PRICE
1	Front bumper / <i>DD</i>	1pc	\$ 2,120.80 /
2	Front bumper bracket n/s <i>X</i> <i>NAI</i>	1pc	\$ 195.22 <i>X</i>
3	Front headlamp grille n/s. <i>?</i> <i>/ CPU</i>	1pc	\$ 197.80 /
4	Front fog lamp grille n/s. <i>?</i> <i>/ CUT</i>	1pc	\$ 174.69 /
5	Front bumper top n/s. <i>/ BR</i>	1pc	\$ 314.25 /
6	Front bumper side rubber n/s. <i>/ CUT</i>	1pc	\$ 181.22 /
7	Front step panel lower n/s. <i>/ BR</i> <i>(work)</i>	1pc	\$ 254.01 /
8	Front step aluminium lower n/s. <i>/ BR</i>	1pc	\$ 311.27 /
9	Front step aluminium center n/s. <i>?</i> <i>X</i> <i>NAI</i>	1pc	\$ 276.28 <i>X</i>
10	Front step panel center n/s. <i>?</i> <i>/ CUT</i>	1pc	\$ 304.67 /
11	Front step lower bracket @\$851.04ea <i>IT</i> <i>/</i>	1 pcs	\$ 1,702.08 <i>851.04 /</i>
12	Front wheel mudguard n/s. <i>X</i> <i>NAI</i>	1pc	\$ 698.96 <i>X</i>
			\$ 6,731.05
Less 25%			\$ (1,682.76) <i>4709.55</i>
Sum Carried Forward			\$ 5,048.29 <i>-25%</i>

Steve CLKK) with Prejandre 9/5/19  
 P/P L/S  
 Resny bef spray  
 4 days

P- 3532-16  
 L- 1130  
 4662-16  
 L/S - 3729.72  
 = 3750

<b>Sum Carried Forward</b>		<b>\$ 5,048.28</b>	
<b><u>Labour Charge &amp; Misc</u></b>			
To remove, replace & install damaged parts.	} }	\$ 800.00	600/
To remove & repair wiring and check.		\$ 80.00	30/
To putty & spray painting.		\$ 600.00	500/
<b>Total</b>		<b>\$ 6,508.28</b>	1130

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## Steve Chen (LKK Auto)

---

**From:** Heng Sew Sow <woonmeng@singnet.com.sg>  
**Sent:** Thursday, May 23, 2019 5:24 PM  
**To:** Steve Chen (LKK Auto)  
**Subject:** RE: XE501

Dear Steve

Accept your offer \$3750.00

Thank you.

Best Regards,  
Heng Sew Sow (Ms)  
Woon Meng Motor Pte Ltd  
Tel: 6316 1131/51  
Fax: 6316 7050

-----Original Message-----

**From:** Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)>  
**Sent:** Thursday, 23 May 2019 5:14 PM  
**To:** Heng Sew Sow <[woonmeng@singnet.com.sg](mailto:woonmeng@singnet.com.sg)>  
**Subject:** XE501

Dear Ms Heng,

The above lorry finalize \$3750 (L/S, before GST). 4 days.

Kindly confirm

Thanks

Best Regards,  
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0761N
Vehicle Details	
Vehicle No.:	XE501K
Vehicle to be Exported:	No
Intended Deregistration Date:	09 May 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FV51SS3VDEA
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	OM457LA457972C0289088
Chassis No.:	FV51SSA10071
Maximum Power Output:	-
Open Market Value:	\$112,288.00
Original Registration Date:	08 Apr 2015
First Registration Date:	08 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$5,615.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$45,027.00
COE Rebate Amount:	\$26,619.00
<b>Total Rebate Amount:</b>	<b>\$26,619.00</b>

The information contained herein is correct as at 09 May 2019

OK



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/07/2019

### Survey Details:

Date of loss	29-Apr-19
Date of appointment	6-May-19
Date of survey	9-May-19
Location of survey	WOON MENG MOTOR PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	XE 501K
Make and Model	MINI COOPER
Date of registration	8/4/2015
Excess	
Market Value	\$95,000
Parf Rebate	\$26,619
Nett Loss	\$68,381

### Repair details:

Initial Estimate	\$	6,508.28
------------------	----	----------

### Proposed/Revised repair cost:

Parts	\$	3,532.16
Check items (estimate)	\$	-
Labour	\$	1,130.00
<b>Total</b>	<b>\$</b>	<b>4,662.16</b>
Lump Sum(if applicable)	\$	3,750.00

Number of days for repair	4
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

--

**Mandate:**

Liability(TP)		%	
Proposed repair cost	\$	4,012.50	W/GST
Loss of use	\$	1,400.00	5days x \$280
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others	\$	-	
<b>Proposed Total</b>	<b>\$</b>	<b>5,415.50</b>	

◀◀ **<SEEK MANDATE IA> - S9M01M700 {ACCIDENT INVOLVING SLJ 8934H (OI) & XE 501K (TP) ON 29/04/2019}**

Type

🔍 Question

Message

Liability: 100% Inform OI about TP claim and NCD issue. Agreed to settle at best. We seek you mandate at \$5414.50 (claiming LOU). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Thanks - Cecilia 02/07/2019

Reply



# Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578  
Tel: +6563161131 / +6563161151 FAX: +6563167050  
Workshop 42, Sungei Kadut Ave Singapore 729666 Tel: +6563628523  
Email: woonmeng@singnet.com.sg  
Co Reg No.200603678M GST Reg No. 20-0603678M

TAX INVOICE NO: WM2019/C04289/may/TP

Date : 24 May 2019

AXA Insurance Singapore Pte Ltd  
8 Shenton Way # 27 - 01  
# 27- 01 AXA Tower  
Singapore 068811

Attn Motor Claims Department

Dear Sirs

**RE : REPAIR COST FOR MITSUBISHI FV51 - XE501K**  
**ACCIDENT INVOLVING XE501K & SLJ8934H ON 29.04.19**

<u>ITEM</u>	<u>DESCRIPTION</u>	<u>PRICE</u>
1	Lump sum repair cost	\$ 3,750.00
		<hr/>
		\$ 3,750.00
	<b>ADD GST 7%</b>	<b>\$ 262.50</b>
	<b>TOTAL AMOUNT S\$</b>	<b>\$ 4,012.50</b>

S/D : Four Hundred Twelve And Cents Fifty Only.

This is a computer-generated document. No signature is required.

◀ Re:<SEEK MANDATE IA> - S9M01M700 {ACCIDENT INVOLVING SLJ 8934H (OI) & XE 501K (TP) ON 29/04/2019}

Type

🔗 Question

Message

pls proceed

Reply



# Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578  
Tel: +6563161131 / +6563161151 FAX: +6563167050  
Workshop 42, Sungei Kadut Ave Singapore 729656 Tel: +6563628523  
Email: woonmeng@singnet.com.sg  
Co Reg No. 200603678M GST Reg No. 20-0603678M

AXA Insurance Singapore Pte Ltd  
8 Shenton Way # 27 - 01  
# 27- 01 AXA Tower  
Singapore 068811

24 May 2019

Attn: Motor Claim Dept.

Dear Sirs

**DIRECT SETTLEMENT FOR REPAIR OF MITSUBISHI FV51 - XE501K**

RE : ACCIDENT INVOLVING XE501K & SLJ8934H  
ALONG AYE EXIT TO JURONG TOWN HALL ROAD ON 29.04.19

We have been given the full authority to act on behalf of Yong Soon General Contractor Pte Ltd, registered owner of motor vehicle no: XE501K, which was involved and damaged in the above accident.

We were told that the said accident was caused solely due to the negligence of your insured driver. Therefore, we are compelled to claim against you for the losses incurred as follows:-

1) Cost of repairs.	\$ 4,012.50
2) Loss of use for 5days @280.00perday.	\$ 1,400.00
3) LTA search	\$ 2.00
TOTAL AMOUNT:-	<u>\$ 5,414.50</u>

We have told our client that this matter is strictly on a DIRECT SETTLEMENT basis. If you do not dispute liability, please arrange to let us have your payment for the sum of S/D :FIVE THOUSAND FOUR HUNDRED FORTEEN AND CENTS FIFTY ONLY in full and final settlement for our client's claim.

We enclose herewith the GIA report, Surveyor's report and the invoices for your attention.

We look forward to your early favourable reply.

Yours faithfully,

.....  
Chong Han Woon



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19007940/Egb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:STACEY

Date : 03-12-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 8934H	Veh. Inspected	XE 501K
Policy No.	GA303821	Coverage (\$)	0.00
Claim No.	S9M01M7W	Excess (\$)	0.00
Assign From		Assign Date	06/05/2019

## 2. Vehicle Particulars & Condition

Make & Model	mitsubishi fuso fv51	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	FV51SSA10071	Colour	WHITE
Odometer	254573	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	ADVANCE	5 mm
L/H Front Tyre	295/80 R22.5	ADVANCE	5 mm
R/H Rear Tyre	295/80 R22.5	ADVANCE	5 mm
L/H Rear Tyre	295/80 R22.5	ADVANCE	5 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	29/04/2019	Inspection Date	09/05/2019
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 501K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	DENTED	2,120.80	2,120.80
1	FRONT BUMPER BRACKET N/S (CONSISTENT)	NOT NECESSARY	195.22	-
1	FRONT HEADLAMP GRILLE N/S (CONSISTENT)	CRUSHED	197.60	197.60
1	FRONT FOG LAMP GRILLE N/S (CONSISTENT)	CUT	174.69	174.69
1	FRONT BUMPER TOP N/S (CONSISTENT)	BROKEN	314.25	314.25
1	FRONT BUMPER SIDE RUBBER N/S (CONSISTENT)	CUT	181.22	181.22
1	FRONT STEP PANEL LOWER N/S (CONSISTENT)	BROKEN	254.01	254.01
1	FRONT STEP ALUMINIUM LOWER N/S (CONSISTENT)	BROKEN	311.27	311.27
1	FRONT STEP ALUMINIUM CENTER N/S (CONSISTENT)	NOT NECESSARY	276.28	-
1	FRONT STEP PANEL CENTER N/S (CONSISTENT)	CUT	304.67	304.67
2	FRONT STEP LOWER BRACKET @\$851.04 (CONSISTENT)	BENT (1 PCS ONLY)	1,702.08	851.04
1	FRONT WHEEL MUDGUARD N/S (CONSISTENT)	NOT NECESSARY	698.96	-
	LESS 25% DISCOUNT		-1,682.76	-1,177.39
			5,048.29	3,532.16
<b>LABOUR</b>				
	TO REMOVE, REPLACE & INSTALL DAMAGED PARTS.		800.00	600.00
	TO REMOVE & REPAIR WIRING AND CHECK.		60.00	30.00
	TO PUTTY & SPRAY PAINTING.		600.00	500.00
			1,460.00	1,130.00
<b>GRAND TOTAL</b>			<b>6,508.29</b>	<b>4,662.16</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,750.00</b>

Report Ref No. CC4/ASM19007940/Egb3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Service Request Details

Claim	59ND1M7W
Reference	CC4/ASM19007940/Eg3a2 
Loss Date	29 April 2019
Report Date	30 Apr 2019 5:20:00 PM
Request Date	6 May 2019
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

**Actions**

Next Step Wait for Approve Invoice

<b>Vehicle Information</b>	
Incident Vehicle Registration #	XE501K
Make	TPYO MITSUBISHI
Model	TRUCK
Service Address	
...	

<b>Primary Contact/Insured</b>
KELLIST PANG LITHENG 34 WEST COAST LANE, HONG LEONG GARDEN, 127764, Singapore
KELLIST_@HOTMAIL.COM

<b>Claim Handler</b>
NG Stacey 6568804351 stacey.ng@axa.com.sg

### Additional Instructions

Messages <sup>4</sup> [Invoices](#) [History](#) [Documents](#) [Assessment](#) [Metrics](#) [Notes](#)

Document Type

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKXInvoice1 (4).pdf	Invoice	Supplier/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	11 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LK0inspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
LK0adjustments1 (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
GUA_SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM4.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
LETTER TO CI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	11 December 2019
MANDATE IA DO 020719.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
PWBF_CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
LOO AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
ESTIMATE LIST_MARKEED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019
IA-501K.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 May 2019
XE501K TP GUA REPORT PDF	Reports & Statement	GUA Report	DHANAK Raghav	6 May 2019

## Claim Portal

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP PRI FROM WORKSHOP.mng	Letters and Correspondence	Workshop	DHAKAL Raghav	6 May 2019
SL8934H INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	6 May 2019