



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19007945/Apa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 25-09-2020



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 2354B	Veh. Inspected	SKN 8165B
Policy No.	VA1/P1975317	Coverage (\$)	0.00
Claim No.	S9M01MEC	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	06/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTDGJ20W005001700	Colour	MAROON
Odometer	241659	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	VELOZZA	6 mm
L/H Front Tyre	215/45 R17	VELOZZA	6 mm
R/H Rear Tyre	215/45 R17	VELOZZA	6 mm
L/H Rear Tyre	215/45 R17	VELOZZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/04/2019	Inspection Date	07/05/2019
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------