| INS. CASE OWNER | CC 3 / CT 1900 this | 1 G 903/ DAC | |
|--|--|--|---|
| | ASSIGNMENT | 4/ 6/ | du |
| Surveys | NOI: | Date / Time: U | 3 4 |
| 4 | | Registered in Maximen | |
| Pre-assign / CCU | CTO CUCK | | |
| Insured Vehicle No | SJP 6115K | ε ±: | |
| Name of Insured | Thong Hory Diang. Policy No | | |
| L_U | | | |
| Insured Tel No. | HP: Make / N | fodel : | |
| Excess Sec II :SS | | Accident : | |
| Is driver the owner | YES (NO) Nature of Accident : | | |
| If NO, Driver Nar | | REPORT: YES / NO ; TP GIA REI | ORT: (FES / NO |
| Driver Tel | | iability: % Final? | Yes/No |
| SLM 4760 | C | | |
| INSRS: WSP: Tel: Liability: V RMRS: | Tel: WSP. | y: WS | SRS: SP: I: bility: IKS: |
| LARD/ Time | SUM 4761 C - X ; STP 6115 K - X | | |
| | | STAGE Non-Paragina by /1 of | DATE/PIC |
| 30/2 | - call of aways of TP Daim & NED ISSUE. Dayled | Non-Reporting ltr (1st): Non-Reporting ltr (2nd): | |
| | to cettle at best - star RMAII LOI. | Non-Reporting ltr (Final) | |
| 17/1/2020 | File pais to MK to submitty P telus | Notification ltr (if non-pickup): Call OI: | |
| Ehrandrina | Pitc process mile to supprist of the | The state of the s | CPL NUS |
| | | Documentation Check List: | |
| | | Notification ltr (if non-pickup) | |
| | | After call lir to OI: | |
| | | Authorization To Act: | |
| | | Release Voucher: | |
| | | Final Repair Bill: Car Rental Invoice: | |
| | | Towing Invoice | |
| | | LTA/GIA: | |
| | | Medical Bill: | |
| | | PIR: | |
| | | Mandate/Reject Instruction: | |
| | | | |
| | | LOD | V |
| RELIMINABLY ABUICE | Date/Time: | Payment Breakdown Form: | V |
| RELIMINARY ADVICE | Date/Time: Sent By: | Payment Breakdown Form Post-Repair Photos: | V |
| | | Payment Breakdown Form Post-Repair Photox: Others; | |
| NALIZATION | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photos: Others; Confirm by: | |
| INALIZATION epair Cost: P/P | Date/Time: Confirm with: SS > 630 (4 days) Reduction: 67 % | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: | Call |
| INALIZATION spair Cost: P/P INAL SETTLEMENT | Date/Time: Confirm with: SS > 630 (4 days) Reduction: 63 % Date/Time: Confirm with | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email Call | Call |
| EPAIR COST: P/P ENAL SETTLEMENT That Liability: | Date/Time: Confirm with: SS > 630 (4 days) Reduction; 63 % Date/Time: Confirm with | Payment Breakdown Form Post-Repair Photos: Others; Confirm by: Email Email If NO or B 28, Ass. Lia: | |
| INALIZATION Epair Cost: | Date/Time: Confirm with: SS > 630 (4 days) Reduction: 64 % Date/Time: Confirm with (Agreed / Assessed) BOLA S/N No.: Wy SS SS (days) | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: | P VEW |
| INALIZATION spair Cost: | Date/Time: Confirm with: SS > 630 (4 days) Reduction; 63 % Date/Time: Confirm with (Agreed / Assessed) BOLA S/N No.: Wy SS SS (days) SS (S x days) | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: | P VEW |
| INALIZATION cpair Cost: INAL SETTLEMENT mal Liability: cpair Cost: coss of Renthi (LOR): coss of Use (LOU); coss of Income (LOI): | Date/Time: Confirm with: S\$ > 630 | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: | P VEW |
| INALIZATION cpair Cost: INAL SETTLEMENT mal Liability: cpair Cost: coss of Rental (LOR): coss of Use (LOU): coss of Income (LOI): OR only LOU only | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photos: Others; Confirm by: Email Email If NO or B 28, Ass. Lia: | P VEW |
| INALIZATION spair Cost: | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: N VIVIVE A Not 1 | y ven w- whit argently |
| INALIZATION spair Cost: | Date/Time: Confirm with: SS > 630 (4 days) Reduction; 63 % Date/Time: Confirm with (Agreed / Assessed) BOLA S/N No.: Vy SS SS (days) SS (x days) SS (x days) LOR + LOU LOR + LOI [Tick only one] SS SS | Payment Breakdown Form Post-Repair Photox: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: New YVIVIO A Not 1 | y ven w- whit argently |
| INALIZATION Epair Cost: INAL SETTLEMENT INAL SETTLEMEN | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photox: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: New York (Confirm Confirm Confir | P ven. W - Whit Argently CVPrivate Settle |
| INALIZATION Epair Cost: INAL SETTLEMENT mil Liability: Epair Cost: 1000 of Renthi (LOR): 1000 of Income (LOI): 1000 of Income (L | Date/Time: Confirm with: SS > 630 (4 days) Reduction: 63 % Date/Time: Confirm with (Agreed / Assessed) BOLA S/N No.: 779 SS SS (days) SS (x days) SS (x days) LOR + LOU LOR + LOI [Tick only one] SS SS SS (e.g. Tow/ Independent) | Payment Breakdown Form Post-Repair Photox: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: New York (Confirm Confirm Confir | y ven w- whit argently |
| INALIZATION cpair Cost: INAL SETTLEMENT inal Liability: cpair Cost: oss of Rental (LOR): oss of Use (LOU): oss of Income (LOI): OR only LAUTA Search fedical: isbursement: cgal Cost otal: | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photox: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: New York (Confirm Confirm Confir | P ven |
| INALIZATION spair Cost: INAL SETTLEMENT inal Liability: spair Cost: oss of Rental (LOR): oss of Use (LOU): oss of Income (LOI): OR only LOU only IA/LTA Search fedical: isbursement: spair Cost otal: INAL PAYMENT | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: N VEVLY LE 2 Not 1) Claim status: Normal/Reje 2) Report Format: WP 3) Survey fee: 93 | P ven |
| INAL SETTLEMENT inal Liability: epair Cost: oss of Rental (LOR): oss of Use (LOU): oss of Income (LOI): | Date/Time: Confirm with: | Payment Breakdown Form Post-Repair Photos: Others: Confirm by: Email Email If NO or B 28, Ass. Lia: N VEVLY LE 2 Not 1) Claim status: Normal/Reje 2) Report Format: WP 3) Survey fee: 93 | P ven |



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info | | | |
|--|---------------------------|------------------------------|--|--|
| | Cust No/Name | /Mr Lim Sze Hwee (lin Zihui) | | |
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower | Reg No/Reg Date | SLM4760C*1F / 31/03/2017 | | |
| | Date In/Mileage | | | |
| Singapore 079909 | Chassis No | KNACC81CVH5058710 | | |
| Attn: Claims Dept. | Engine No | G4LEHS179007 | | |
| Contact No 63896111 | Make/Model | KIA/NIRO 1.6 A | | |
| | Colour/Trim | K3R / WK | | |

| unt No | Terms | Date/Time | Printed | CSE | Operator | | WIP No | | | |
|--------------|--|---|--|--|--|---|---|--|--|--|
| 0018 | Credit | THE PERSON NAMED IN | | DS | 303 / Renemer | | 23804 | | | |
| 0010 | 0,20,1 | | | | | Qty | Unit Price | Disc% | Am | ount |
| II PNT880 | 88 | 55.55.66.61 | STATE OF THE PARTY | | | | | | / | 250.00 |
| | | ING | | | | | | | 0 | |
| IPNT880 | 88 | | | | | | | - 1 | 80 | 100.00 |
| O CHECK | LIGHTIN | G/WIRING SY | STEM ON R | REAR ACCIDEN | IT | | | - 1 | | |
| | | | | | | | | - 1 | 200 | 600.00 |
| | | Andrew Water Company | | OTTOMATING TO | OTUE. | | | | 1-0 | 000.00 |
| TO REMOV | E & RE-I | NSTALL ALL | CARPETS/1 | RIMMING TO | GIVE | | | - 1 | | |
| | | R ON LHR AC | CIUENI AF | FECTED AREA | 13 | | | 1/01 | X | 600.00 |
| | | DOOD COMBON | ENTS /MECL | MOTUAL | | | | 10.0 | | |
| | | DOUR COMPON | ENTS/MEU | IMMI SHI | | pmg . | | | 900 | 1800.00 |
| | | OOR LHR GAR | NTSH LHR | OTR MIDGRED | | 100 | 1 | | , | |
| | | | 1011 | 6 | 110012 | | | | | |
| TRAIGHT | EN REFOR | M. ALTON ON | HR ACOLL | ENT AFFECTE | | 166 | フ | | | |
| | LITY CELL SI | | arm mager | | | | | | | |
| | 88 | | | | | | | | , X | 180.00 |
| | | | | | | | | NIV | 8 ~ | |
| MIPNT880 | 88 | | | | | | | | X | 50.00 |
| WHEEL BA | LANCING | | | | | | | | (120 | 1260.00 |
| | | | | | | | | | 420 | 1200.00 |
| | | IN REAR ACCI | DENT AFF | ECTED AREAS | a max X | 1 00 | 1217 00 | 0.00 | | 1317.00 |
| | | | | | 1-1001 | | | C. C | | 33.00 |
| MELL VYOLUME | | | | | 5 (| | | 12 (12 m) E (000) | | 26.00 |
| | | | | | 3) 1/0 | | | 373 min 1610 | | 11.00 |
| | | | | | 5 / | | | The Control of the Co | | 9.00 |
| | | | | | 1/ NCC | | | 0.00 | | 15.00 |
| | | | | | 1104 | 1.00 | 113.00 | 0.00 | | 113.00 |
| | | | | | - 5 am | 1.00 | 201.00 | 0.00 | | 201.00 |
| | | | | | - 1 MA | 1.00 | 144.00 | 0.00 | | 144.00 |
| | | Entlos W | EEL ASSY | LACUMINIUM | X Con MIV | 1.00 | | 0.00 | | 1250.00 |
| | | - V/ | LVE - TI | RE PRESSUR | | 1.00 | 125.00 | 0.00 | | 125.00 |
| NOTES | | | | | 7, | | | | | |
| | MIPNT880 DIAGNOST MIPNT880 TO CHECK AFFECTED MIPNT880 TO REMOV WAY ACCE MIPNT880 TO REPLA TO REPLA TO REPLA TO REPLA MIPNT880 WHEEL AL MIPNT880 WHEEL BA MIP | MIPNT88088 DIAGNOSTIC/SCANN MIPNT88088 TO CHECK LIGHTIN MIPNT88088 TO REMOVE & RE-I MAY ACCESS REPAI MIPNT88088 TO TRANSFER LHR MIPNT88088 TO REPLACE LHR D TO REPLACE LHR D TO REPLACE LHR D STRAIGHTEN, REFOR MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING O KS 77003 G5 000 KS 79310 2E 000 KS 79310 2E 000 KS 79310 2E 000 KS 86381 G5 000 KS 86383 G5 000 KS 87539 G5 000 KS 87539 G5 000 KS 87539 G5 000 KS 87731 G5 000 | Description IPNT88088 DIAGNOSTIC/SCANNING IPNT88088 TO CHECK LIGHTING/WIRING SYMMETER AREAS IPNT88088 TO REMOVE & RE-INSTALL ALL WAY ACCESS REPAIR ON LHR GAR TO REPLACE LHR DOOR, LHR GAR TO REPLACE LHR DOOR, LHR GAR TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL ALIGNMENT MIPNT88088 SPRAY PAINTING ON REAR ACCI KS 77003 G5 000 KS 79410 D8 000 KS 79310 ZE 000 KS 79310 ZE 000 KS 86383 G5 000 KS 87539 G5 000 KS 87731 G5 000 KS 87731 G5 000 KS 87751 G5 000W K KS 87751 G5 000W K KS 87741 G5 000 | Description of Good MIPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON FAFFECTED AREAS MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/T MAY ACCESS REPAIR ON LHR ACCIDENT AF MIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECH MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR TO REPLACE LHR DOOR, LHR GARNISH, LHR TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFI MISTORIAN AFFI MISTORIAN ACCIDENT ACCIDENT AFFI MISTORIAN ACCIDENT AFFI MISTORIAN ACCIDENT AFFI MISTORIAN ACCIDENT ACCIDENT AFFI MISTORIAN ACCIDENT ACCIDENT ACCIDENT AFFI MISTORIAN ACCIDENT ACCIDENT ACCIDENT ACCIDENT ACCIDE | Description of Goods / Services AIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS AIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO MAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREA AIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR OTR MILDGET TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 G5 000 LH PANEL ASSY-REAR D KS 79310 2E 000 LH UPR HINGE ASSY-RR KS 79310 2E 000 LH TAPE-RR DR BLACK KS 86383 G5 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH TAPE-RR DR BLACK KS 87751 G5 000W K LH SIDE SILL MLDG-AS LH GARNISH ASSY-OTR KS 87741 G5 000 KS 87741 G5 000 KS 87741 G5 000 KS 52910 G5 120 WHEEL ASSY-ALUMINIUM | Description of Goods / Services ITPNT88088 DIAGNOSTIC/SCANNING ITPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS AIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS AIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR QTR MUDG JETC TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 WHEEL BALANCING MIPNT88088 WHEEL BALANCING MIPNT88088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77003 G5 000 LH PANEL ASSY-REAR D KS 79310 ZE 000 LH LWR HINGE ASSY-RR KS 79310 ZE 000 LH TAPE-RR DR BLACK KS 86383 G5 000 LH TAPE-RR DR BLACK KS 87539 G5 000 LH TAPE-RR DR BLACK KS 87731 G5 000 KS 87751 G5 000W K LH SIDE SILL MLDG-AS LH GARNISH ASSY-RI KS 87751 G5 000W | Description of Goods / Services (IPNT88088 DIAGNOSTIC/SCANNING MIPNT88088 OF CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS MIPNT88088 OF REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS MIPNT88088 OF TRANSFER LHR DOOR COMPONENTS/MECHANISM MIPNT88088 OF REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED MIPNT88088 WHEEL ALIGNMENT MIPNT88088 WHEEL BALANCING MIPNT98088 | Description of Goods / Services IIPNT88088 DIAGNOSTIC/SCANNING IIPNT88088 O CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT IFFECTED AREAS IIPNT88088 O CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT IFFECTED AREAS IIPNT88088 O REPLACESS REPAIR ON LHR ACCIDENT AFFECTED AREAS IIPNT88088 O TRANSFER LHR DOOR COMPONENTS/MECHANISM IIPNT88088 O REPLACE LHR DOOR, LHR GARNISH, LHR OTR MILDGRETC OR REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS IIPNT88088 WHEEL BALANCING IIPNT88088 WHEEL ASSY-REAR D INDUITED INDUIT | Description of Goods / Services AIPNT88088 DIAGNOSTIC/SCANNING AIPNT88088 DIAGNOSTIC/SCANNING AIPNT88088 DIAGNOSTIC/SCANNING AIPNT88088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS AIPNT88088 TO RENOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE AVAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS AIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM AIPNT88088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM AIPNT88088 TO REPLACE LHR DOOR, LHR GARNISH, LHR QIR MEDGLETT TO REPLACE LHR DOOR, LHR GARNISH, LHR QIR MEDGLETT TO REPAIR LH SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS AIPNT88088 MIPELL ALIGNMENT MIPNT88088 MIPELL ALIGNMENT MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 77030 G5 000 LH PANEL ASSY-REAR D MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS KS 779310 2E 000 LH LWR HINGE ASSY-RR MIPNT98088 MIPNT98088 | Description of Goods / Services AT INTERBORS DIAGNOSTIC/SCANNING HIPNTB8088 DIAGNOSTIC/SCANNING HIPNTB8088 DIAGNOSTIC/SCANNING HIPNTB8088 TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT HIPFECTED AREAS HIPNTB8088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE HAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS HIPNTB8088 TO TRANSFER LHR DOOR COMPONENTS/MECHANISM HIPNTB8088 TO TRANSFER LHR BOOR, LHR GARNISH, LHR GIR MILDGJETT TO REPLACE LHR DOOR, LHR GARNISH, LHR GIR MILDGJETT TO REPLACE LHR DOOR, LHR GARNISH, LHR GIR MILDGJETT TO REPLACE LHR BOOR, LHR GARNISH, LHR GIR MILDGJETT TO REPLACE LHR DOOR COMPONENTS/MECHANISM HIPNTB8088 HHEEL ALIGNMENT HIPNTB8088 HHEEL ALIGNMENT HIPNTB8088 MIPNTB8088 MIPNTBROWN MIPNTB8088 MIPNTB8088 MIPNTBROWN MIPNTB8088 MIPNTBROWN MIPNTBROW |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info | | | |
|--|---------------------------|------------------------------|--|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower | Cust No/Hame | /Hr Lim Sze Hwee (1in Zihui) | | |
| | Reg No/Reg Date | SLM4760C*1F / 31/03/2017 | | |
| | Date In/Mileage | 04/05/2019/ 0 | | |
| Singapore 079909 | Chassis No | KNACC81CVH5058710 | | |
| Attn: Claims Dept. | Engine No | G4LEHS179007 | | |
| Contact No 63896111 | Make/Model | KIA/NIRO 1.6 A | | |
| | Colour/Trim | K3R / WK | | |

| Account No | Terms | Date/Time Printed | CSE | Operator | THE PERSON NAMED IN | WIP No | -5x5-111111 |
|-------------------|--------------|----------------------------|-------------|-----------------------|--|---------------------------|-------------|
| 0000018 | | 15/06/2019/ 07:54 | 05 | 303 / Renemer | | 23804 | |
| IZMES III | | Description of Good | s / Service | 3 | Qty | Unit Price Disc% | Amount |
| MIPNT880 | 88 | | | | | | 250.00 |
| | 1C/SCANNI | NG | | | | | 80.00 |
| MIPNTE80 | | /WIRING SYSTEM ON R | EAD ACCID | ENT | | | 00.00 |
| AFFECTED | | MIKING SISIEM ON N | EAR ACCED | CAI | | | |
| MIPNTSBO | 88 | | | | | | 300.00 |
| TO REMOV | E & RE-IN | STALL ALL CARPETS/T | RIMMING T | O GIVE | | - | |
| MAY ACCE | | ON LHR ACCIDENT AF | FECTEU AR | ENS | | | 900.00 |
| TO REPLA | CE LH SID | E SILL MLDG, LHR GAR | MISH, LHR | QTR MLDG,ETC | | | |
| TO REPAI | R LHR DOO | R | П | | Л - | | |
| | EN, REFORM | ALIGN ON THE ACCID | ENTTHEFED | ima | 11/10 | 2) | |
| AREAS MIPNT980 | 1RR | | 2) (C | | 166 | 7 | 420.00 |
| | | REAR ACCIDENT AFFE | CTED AREA | S | | | 15.00 |
| KS 87539 | | LH FILM - / | | | 1.00 | 15.00 0.00 113.00 0.00 | |
| KS 87731 | G5 000 | LH MLDG ASS LH SIDE SIL | | | 1.00 | 201.00 0.00 | 201.0 |
| | G5 000 | LH GARNISH | ASSY-QTR | 100 | 1.00 | 144.00 0.00 | |
| KS 52960 | 65 120 | CAP ASSY - | WHEEL HUB | / Cust .rsu | PP) 1.00 | 216.00 0.00 | 216.0 |
| Z NOTES | F 041 03 (DE | /2010 NI ONC MEE TO | scunni 1 | 109D EDGEDALE PLAINS | HDB | | |
| OUNER CI | LAIMING TH | IRD PARTY | 1 Jenoue 1 | 1030 COCCONEC TENTING | THE PERSON NAMED IN COLUMN TO PERSON NAMED I | | |
| | USE 04 DA | YS | | | | | |
| TP#: SJ | P6115K | TP INS: (| CHINA TAIR | PING | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Confirm & | accepted b | W | | | Parts | | 689. |
| 50m: 11m m | | A-H | 1. God | Biang | Labour | Menu | 0. |
| | | | | | Speciali | | 1,950. |
| | | manager & | | | Others(L | | 0. |
| FI | VAU12 | ATION | | | Sundry Total (w/ | (a GST) | 2,639. |
| | | and company stamp | | | 10521(0) | 0 9317 | |

Validity of this estimate is 16 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would montion that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

| Invoice Name & Address | | Owner Name & Vehicle Info |
|--|-----------------|------------------------------|
| | Cust No/Name | /Mr Lim Sze Hwee (lin Zihui) |
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower | Reg No/Reg Date | SLM4760C*1F / 31/03/2017 |
| | Date In/Mileage | 04/05/2019/ 0 |
| Singapore 079909 | Chassis No | KNACCB1CVH5058710 |
| Attn: Claims Dept. | Engine No | G4LEHS179007 |
| Contact No 63896111 | Make/Model | KIA/NIRO 1.6 A |
| UTANTARASING NARIOSOMESE | Colour/Trim | K3R / WK |

| Account No | Terms | Date/Time Printed | CSE | Operator | | WIP No | |
|------------|----------|---|--------|---------------|---|--|---------------|
| F0000018 | Credit | 04/05/2019/ 11:02 | DS | 303 / Renemer | | 23804 | |
| | | Description of Good | | | Qty | Unit Price Disc% | Amount |
| | REPLACEN | 5/2019 ALONG MEE TOH HIRD PARTY MENT CAR TP INS: C | | | 1100 | | |
| | | | st | ima | the Repaire | onsultants hence notify r of the following: before/after spray painting performation and part(s) during resurvers a subject to confirmation by s on a Without Prejudio | e" basis |
| | 400 | ays. | 147 | | Supplementa | dification(s) is allowed by item(s) must be resurveyed inal approval from Insurance to by Repairer | and ompany |
| | best | me parlot p | mos. | L | Date: | | |
| | Af | der paint r | of tos | | | | |
| | 6 | no Qiay - | 8 268 | 0181 | | | |
| | C | ays. the pollet point r no Qiay — 38/5/19. | | | | | |
| Confirm & | accepted | by | | | Parts Labour | | 3,244. |
| | | | | | Standard Speciali Others (L Sundry | st Job | 4,840. 0. |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Authorized signatory and company stamp

Date: 14/05/2019

51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

SNM19D201983C02/5

Our ref:

CC3/CTI19007968/Gga3

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLM 4760C

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/05/2019
at the premises of M/s Cycle & Carriage-Fulco Motor Dealer Pte Ltd and have the following to report:-

| Workshop Estimate Amount | : S\$ | 8,084.00 | |
|-------------------------------|-------|----------|----|
| Revised Estimate Amount | : S\$ | 3,673.00 | |
| "Check" Items Amount | : S\$ | | |
| Total (Including Check Items) | : S\$ | 3,673.00 | |
| Market Value | : S\$ | - (es | .) |
| LTA Reimbursement Value | : S\$ | - (es | .) |
| Nett Value | : S\$ | - (es | .) |

Description of Damage:

The vehicle sustained damages at the

N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

XING GUO QIANG

Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type: | Singapore NRIC |
|-------------------------------|---|
| Owner ID: | 2140Z |
| /ehicle Details | |
| /ehicle No.: | SLM4760C |
| /ehicle to be Exported: | No |
| ntended Deregistration Date: | 10 May 2019 |
| /ehicle Make: | KIA |
| /ehicle Model: | NIRO HYBRID 1.6 GDI DCT SUNROOF |
| Primary Colour: | Red |
| Manufacturing Year: | 2017 |
| Engine No.: | G4LEHS179007 |
| Chassis No.: | KNACC81CVH5058710 |
| Maximum Power Output: | 103.6 kW (138 bhp) |
| Open Market Value: | \$28,035.00 |
| Original Registration Date: | 31 Mar 2017 |
| First Registration Date: | 31 Mar 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,000.00 |
| Intended PARF Rebate Details | The result have been been a supplied to the second of the |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 30 Mar 2027 |
| PARF Rebate Amount: | \$3,750.00 |
| Intended COE Rebate Details | ASSAULT COST |
| COE Expiry Date: | 30 Mar 2027 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$54,000.00 |
| COE Rebate Amount: | \$42,590.00 |

The information contained herein is correct as at 10 May 2019

OK



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735 RECORDS MANAGEMENT CENTRE

Third Party Insurer Enquiry

Our Ref No:

GR-19-069976

Date of Request:

04/05/2019

Your Ref No:

Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd

330 Ubi Road 3 Singapore 408650

Dear Sir/Madam,

Enquiry Date

04/05/2019

Enquiry By

Renemer Bagang

TP Vehicle No.

SJP6115K

Accident Date

03/05/2019

Enquiry Result

| TP Vehicle No. | Insurer | Period of Insurance | Insurer Tel. No. |
|----------------|---|-----------------------|------------------|
| SJP6115K | China Taiping Insurance (Singapore) Pte. Ltd. | 24/04/2019-23/04/2020 | 6389 6111 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature,

12

Cecilia Chong (LKK Auto)

Cecilia Chong (LKK Auto) From:

Friday, 24 May 2019 2:05 PM Sent:

To: zhanghqwd@163.com

Hsiao Tong (LKKAuto); Admin A Cc:

Your ref: SJP 6115K (Our ref: CC3/CTI19007968/Gga3) *** ACCIDENT INVOLVING SJP Subject:

6115K & SLM 4760C ON 03/05/2019 ***

ZHANG HONG QIANG

Dear Sir/Madam,

ACCIDENT INVOLVING SJP 6115K & SLM 4760C ON 03/05/2019

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





LKK Save the Earth Print only when necessary



Contact us at

Hotline: (65) 6532 2888 E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act") Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore) Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.

MT/00617383

Type of Coverage / Driver Plan

Car Comprehensive (Value Plus Plan)

1) Vehicle Registration No.

SI M4760C

Chassis No.

KNACCB1CVH5058710

2) Name of Policy Holder

Lim, Sze Hwee

3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act

: 31/03/2019 00:00

4) Date/Time of Expiry of Insurance

: 30/03/2020 23:59

5) Persons or Classes of Persons Entitled to Drive

(a) Any named person under the policy who is driving on the Policyholder's permission.

(b) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Policyholder's permission

The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.

6) Limitations as to use'

Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business. Private car-pooling arrangements where you commute with passengers and split the fuel expense is covered under the standard policy, Grab Hitch will only be covered if this is the declared usage stated on your Policy Schedule. Only two rides are permitted a day. Other forms of commercial car-pooling or any ride hailing services (e.g. Grab, Go-Jek etc.) are not

"Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia). are not to be included under this heading.

Market Value

Own Damage Excess

S\$ 500.00 (before any applicable GST)

Windscreen Excess

S\$ 100.00 (before any applicable GST)

Choice of workshop

My Workshop/ My Authorised Distributor Workshop

Finance company / Hire Purchase

DBS BANK LIMITED

Main driver

Lim, Sze Hwee

Named driver

None

Important Note: This policy does not cover the Policyholder/drivers below the age of 30 and Policyholder/drivers who hold a valid driving licence of less than 2 years with the exception of the

main/named drivers above.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Com pensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Direct Asia Insurance (Singapore) Pte. Ltd.

Tesued on:

27/03/2019

Edip Okur (Chief Underwriting Officer)

Direct Asia Insurance (Singapore) Pte Ltd 20 Anson Road #08-01 Twenty Anson Singapore 079912 www.DirectAsia.com



Our Ref: SLM4760C Your Ref: SJP6115K

July 31, 2019

CHINA TAIPING INSURANCE SINGAPORE 3 ANSON ROAD # 16-00 SPRINGLEAF TOWER SINGAPORE 079909

Cc: LKK Auto Consultants Pte Ltd. 51 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Dear Sir/Madam,

Repair Services Rendered to Vehicle Reg. No. SLM4760C – Accident on 03/05/2019 ALONG MEE TOH SCHOOL BESIDE 109D EDGEDALE PLAINS HDB

We are pleased to enclose our invoice number 77453018 dated 23/07/2019 amounting as follows:

AR, REGISTERED

Cost of Repair \$\$ 2823.73 Loss of Use 04 days x \$\$80/DAY \$\$ 320.00 LTA Search Fee \$\$ 2.00

Grand Total S\$ 3145.73

In addition, attached are the supporting documents of repair services rendered to the abovementioned vehicle.

Please acknowledge receipt of the same.

Thank you.

Yours sincerely

Cycle & Carriage –Fulco Motor Dealer Pte Ltd Eunos Service Centre

SERVICE

Encs.



CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

TAX INVOICE

Co Reg No : 199707303Z

GST Reg No : 19-9707303-2

| Invoice Name & Address | | Owner Name & Vehicle Info |
|-------------------------------------|-----------------|------------------------------|
| CHINA TAIPING INSURANCE (SINGAPORE) | Cust No/Name | /Mr Lim Sze Hwee (lin Zihui) |
| 3 Anson Road #16-00 | Reg No/Reg Date | SLM4760C*1F / 31/03/2017 |
| Springleaf Tower | Date In/Mileage | 04/05/2019/ 42169 |
| Singapore 079909 | Chassis/Package | KNACC81CVH5058710 /KC17RT3 |
| Attn: Claims Dept. | Engine No | G4LEHS179007 |
| Contact No 63896111 | Make/Model | KIA/NIRO 1.6 A |
| | Colour/Trim | K3R / WK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Involce | Credit Note No |
|--|-------------------------------|------------------------|--------------|-------------------------|------------------|---|----------------|
| F0000018 | Credit | 23/07/2019/ 08:19 | DS | 323 / ChrisBulaclac | 23804 | 7745301 | 18 |
| Division. | | Description of Good | s / Service | s Qty | Unit Price | Disc% | Amount |
| S MIPNT880 | | | | | | | 250.00 |
| DIAGNOST S MIPNT880 | | ING | | | | | 90 0 |
| T 12 10 TO 1 | | G/WIRING SYSTEM ON RE | AP ACCID | ENT | | | 80.00 |
| AFFECTED | | of managed and an in | in nevie | EM I | | | |
| S MIPNT880 | 88 | | | | | | 300.0 |
| TO REMOV | E & RE-I | NSTALL ALL CARPETS/TI | RIMMING T | O GIVE | | | |
| | | R ON LHR ACCIDENT AF | FECTED AR | EAS | | | |
| S MIPNT880 | | ne esse wine sub-label | There is the | | | | 900.0 |
| TO REPLA | | DE SILL MEDG, LHR GAR | VISH, LHR | OTR MEDG-ETC | 1 77 | | |
| DOMESTIC AND STREET OF STREET | Committee of the committee of | M,ALIGN ON EHR ACCID | ENT REED | TED [_ ()] ()] | \\// | | |
| AREAS | en tuer on | ATTENDED OF LINE ACCES | | | \v/ | | |
| S MIPNT980 | 88 | | | | 2) | - 1 | 420.0 |
| SPRAY PA | INTING O | N REAR ACCIDENT AFFE | CTED AREA | S | - | | |
| X KS 87539 | | LH FILM - A | | | 15.00 | | 15,0 |
| X KS 87731 | | LH MLDG ASS | | 1.00 | 113.00 | Company College Committee | 113.0 |
| X KS 87751 X KS 87741 | | K LH SIDE SIL | | 1.00 | 201.00 | 0.00 | 201.0 |
| X KS 52960 | | CAP ASSY - 1 | | | 216.00 | 10.000,71.000,000 | 216.0 |
| Z NOTES | 42 160 | CM N331 - | MILLE TIOU | 1.00 | 210.00 | 0.00 | F.O.C |
| | ON 03/0 | 5/2019 ALONG MEE TOH | SCHOOL 1 | 09D EDGEDALE PLAINS HDB | | | |
| | | HIRD PARTY | | | | | |
| LOSS OF | | | | 202 | | | |
| TP#: SJP | 6115K | TP INS: C | HINA TAIP | ING | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Parts | | *** | | | Net | | 2,639.00 |
| Labour | | 689 | 3.7.7.7 | 7% GST o | T. 10 Van Calaba | 70.70 | 184.73 |
| Standard F | tenu | 1,7 | .00 | | | | |
| Specialist | Job | 1,950 | | | Total Payab | | 2,823.73 |
| Others (Lub | etc) | | .00 | | Pa | | 0.00 |
| Sundry | | | .00 | | Total De | 7.7 | 2,823.71 |
| Total (w/o | GST) | 2,639 | .00 | T.4.1 | Balance B/FI | | 34,516.06 |
| | | | | Total Pay | able or C/F | MD. | 37,339.79 |

Any dispute to the invoice must be made within 3 days.

Cheques should be crossed and made payable to CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - (SERVICE)

This is a computer generated document, no signature is required.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-19-069976

Date of Request:

04/05/2019

Your Ref No:

Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd

330 Ubi Road 3 Singapore 408650

Dear Sir/Madam,

Enquiry Date

04/05/2019

Enquiry By

Renemer Bagang

TP Vehicle No.

SJP6115K

. ccident Date

03/05/2019

Enquiry Result

| TP Vehicle No. | Insurer | Period of Insurance | insurer Tel. No. |
|----------------|---|-----------------------|------------------|
| SJP6115K | China Taiping Insurance (Singapore) Pte. Ltd. | 24/04/2019-23/04/2020 | 6389 6111 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-19-069976

Date of Request:

04/05/2019

Your Ref No:

Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd

330 Ubi Road 3 Singapore 408650

Dear Sir/Madam,

Enquiry Date

04/05/2019

Enquiry By

Renemer Bagang

TP Vehicle No.

SJP6115K

cident Date

03/05/2019

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry | 1.87 |
| GST Amount | 0.13 |
| Total Amount Due (GST Inclusive) | 2.00 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

REPAIRER CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - EUNOS LINK SERVICE CENTRE

MOTOR VEHICLE CLAIM DISCHARGE VOUCHER

| ATTN: | CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD |
|-------|---|
| | 3 Anson Road #16-00 |
| | Springleaf Tower |
| | Singapore 079909 |

| OWNER | LIM SZE HWEE (LIN ZIHUI) | VEHICLE NO | : <u>SLM4760C</u> |
|---------------|--------------------------|-------------|-------------------|
| VEHICLE MODEL | : KIA NIRO | THIRD PARTY | : <u>SJP6115K</u> |

ACCIDENT DATE : 03/05/2019 WIP NO : 23804

I/WE CERTIFY THAT THE VEHICLE HAS BEEN FULLY REPAIRED TO MY ENTIRE SATISFACTION AND THE PAYMENT OF REPAIRER'S CHARGES ARE CLAIMABLE UNDER THE POLICY WILL BE DEEMED IN FULL AND THE FINAL SETTLEMENT OF MY CLAIMS.

| | NA |
|-----|-----------------------|
| C | IER/INSUBED SIGNATURE |
| DA | ATE: |
| TIM | ME: |

LETTER OF AUTHORITY

| ACCIDENT INVOLV | ING S | LM4760C | AND | SJP6115K | ON | 3/5/2019 |
|------------------------------|--|------------------|-------------------|-------------------------------|------------------|--------------------|
| | Own V | ehicle's Number | | Other Vehicle's Numb | er | Date Of Accident |
| Mong | | MEE TOH SCH | OOL BESIDE 10 | D EDGEDALE PLAINS | HDB | |
| | | | Acci | dent Location | | |
| Y THE LETTER OF | AUTHORITY , I/We | | | LIM SZE HWEE (LIN | ZIHUI) | |
| | | | | iame of Policy Holder & NRIC/ | Passport/Fin # | |
| Of | | 25 PUNGGOL | FIELD WALK # | 12-21 SINGAPORE 828 | 751 | |
| | | | Address of Po | icy Holder | | |
| Owner of Vehicle I | Registration Number | SLM4760C | n Vehicle Number | hereby auth | orize Cycle & Ca | arriage-Fulco Moto |
| aler Pte Ltd. to | act for me with respe | ct to my claim | for repair cost a | and/or Loss of Use ("cl | aim") | |
| for my vehicle _ | SLM4760C Own Vehicle Number | _ that was dan | naged. | | | |
| | | | | settle my above men | | |
| CALIFORNIA ACTUAL CONTRACTOR | | | | ment being made in fa | | |
| Cycle & Carriage- | Fulco Motor Dealer P | te Ltd further | acknowledge t | hat any settlement th | e workshop may | reach |
| on my behalf is or | a without prejudice | and without ad | mission of liabi | lity basis in so far as th | e driver/owner, | /insurers |
| the vehicle/s is | concerned. | | | | | |
| | Dated this | 3 | | MAY | (Month) | 2019 (Year) |
| | M SZE HWEB (LIN-ZI gned By Claimant/Pol | | | | Signed by | "The Workshop" |
| 31 | Busy by significantly of | and the same | | | | |
| | | | | | V | |

Khanchna (LKK Auto)

From:

Khanchna (LKK Auto)

Sent:

Friday, 17 January 2020 11:38 AM

To:

Chee So Chow

Cc:

Alfred Toh: Admin A

Subject:

RE: OUR REF:SNM19D201983C02; Our vehicle = SJP6115K *** LKK REF;

CC3/CTI19007968/Gka3

WITHOUT PREJUDICE

Dear Ms. Chee,

We refer to the above matter and your e-mail below.

Please be informed that we have already surveyed the third party vehicle on 8/5/2019.

We were pending for Third party to submit the LOD and the supporting documents to us.

As instructed, we will submit our survey report on an urgent basis and also request third party for the LOD and relevant documents for your further action.

Thank you.

Wishing you a Happy and Prosperous Lunar New Year

N

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Sent: Friday, 17 January 2020 10:54 AM

To: Chee So Chow <sochow.chee@sg.cntaiping.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: OUR REF:SNM19D201983C02; Our vehicle = SJP6115K *** LKK REF: CC3/CTI19007968/Gka3

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Khanchna,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Wishing you a Happy and Prosperous Lunar New Year



Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chee So Chow <sochow.chee@sg.cntaiping.com>

Sent: Thursday, 2 January, 2020 11:45 AM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>

Subject: FW: OUR REF:SNM19D201983C02; Our vehicle = SJP6115K

Dear Sir / Madam

Please advise whether we have appointed you to conduct third party survey to the following vehicle:

Vehicle: SLM4760C

Date of accident 03.05.19

Workshop = Cycle & Carriage at Eunos Service Centre

If yes, please let us have the survey report urgently as Cycle & Carriage is chasing us to settle their client's third party claim.

Thank you.

Chee So Chow (Ms)

Deputy Manager Claims Department

Email: claimsdept@sg.cntaiping.com

sochow.chee@sg.cntaiping.com

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: (65) 6389 6176 | F: (65) 6224 7175 / (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer. This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| 1 | 1-15-1 | Affiliated to Federation Intern | ationale Des Experts En Autom | obile |
|-----|--|---|---|----------------------|
| CHI | NA TAIPING INSU | RANCE (S) PTE LTD | Ref : CC3/CTI190079 | 968/Gka3q2 |
| | NSON ROAD #16-0 INGLEAF TOWER | 00 SINGAPORE 079909 | Date: 23-01-2020 Code: CTI | |
| ١. | | Policy Particula | ars :- THIRD PARTY CLAI | M |
| | Insured Veh. | SJP 6115K | Veh. Inspected | SLM 4760C |
| | Policy No. | DMPCSN1504411904 | Coverage (\$) | 0.00 |
| | Claim No. | SNM19D201983C02 | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 08/05/2019 |
| 2. | THE RESERVE | Vehicle Pa | articulars & Condition | |
| | Make & Model | KIA NIRO 1.6 | c.c | 1580 |
| | Engine No. | HIDDEN | Year of Reg. | 2017 |
| | Chassis No. | KNACC81CVH5058710 | Colour | RED |
| | Odometer | 39920 | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. | | Con | ditions of Tyres | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 205/60 R16 | MICHELIN | 6 mm |
| | L/H Front Tyre | 205/60 R16 | MICHELIN | 6 mm |
| | R/H Rear Tyre | 205/60 R16 | MICHELIN | 6 mm |
| | L/H Rear Tyre | 205/60 R16 | MICHELIN | 6 mm |
| 4. | | Descri | ption of Damages | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE | N/S BODY. | |
| | DAMAGES SEE D | ETAILS. | | |
| 5. | | Gen | eral Information | And the party of the |
| | Accident Date | 03/05/2019 | Inspection Date | 08/05/2019 |
| | Survey held at | CYCLE & CARRIAGE.FULC | O MOTOR DEALER PL | |
| | 850 | NO.330 UBI ROAD 3 SINGAPORE 408650 | | |
| 5a. | | | Remarks | |
| | A)THE INSPECTION B)IN ACCORDANG | ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS | WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS | IS. SED REPAIRS. |
| 5b. | | Estima | ate Days of Repair | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 4760C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| :1 | LH PANEL ASSY -REAR D (SN) | TO REPAIR SEE LABOUR | 1,317.00 | |
| - 1 | LH UPR HINGE ASSY -RR (SN) | NOT NECESSARY | 33.00 | |
| 1 | LH LWR HINGE ASSY -RR (SN) | NOT NECESSARY | 26.00 | - |
| -1 | LH TAPE-RR DR BLACK (SN) | NOT NECESSARY | 11.00 | 9 |
| - 1 | LH TAPE-RR DR BLACK (SN) | NOT NECESSARY | 9.00 | |
| 1 | LH FILM -ANTI -CHIPP (SN) | NECESSARY | 15.00 | 15.00 |
| - 1 | LH MLDG ASSY -RR DR W (SN) | CUT | 113.00 | 113.00 |
| 1 | LH SIDE SILL MLDG -AS (SN) | CUT | 201.00 | 201.00 |
| 1 | LH GARNISH ASSY -QTR (SN) | CUT | 144.00 | 144.00 |
| -1 | WHEEL ASSY -ALUMINIUM (SN) | NOT NECESSARY | 1,250.00 | |
| 1 | VALVE -TIRE PRESSUR (SN) | NOT NECESSARY | 125.00 | |
| 1 | CAP ASSY -WHEEL HUB (SN) (ADDITIONAL) | CUT | 216.00 | 216.00 |
| | The state of the s | | 3,460.00 | 689.00 |
| | LABOUR | | | |
| | DIAGNOSTIC /SCANNING . | | 250.00 | 250.00 |
| | TO CHECK LIGHTING /WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS. | | 100.00 | 80.00 |
| | TO REMOVE & RE-INSTALL ALL CARPETS /TRIMMING TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS. | | 600.00 | 300.00 |
| | TO TRANSFER LHR DOOR COMPONENTS /MECHANISM . | NOT NECESSARY | 600.00 | 9 |
| | TO REPLACE LHR DOOR ,LHR GARNISH ,LHR QTR MLDG ,ETC .TO REPAIR LH SIDE SILL STRAIGHTEN ,REFORM ,ALIGN ON LHR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF LH PANEL ASSY -REAR D. | | 1,800.00 | 900.00 |
| | WHEEL ALIGNMENT. | NOT NECESSARY | 180.00 | |
| | WHEEL BALANCING . | NOT NECESSARY | 50.00 | |
| | SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS. | | 1,260.00 | 420.00 |
| | | | 4,840.00 | 1,950.00 |
| | GRAND TOTAL | | 8,300.00 | 2,639.00 |

Report Ref No. CC3/CTI19007968/Gka3q2





RECOMMENDED COST OF REPAIRS 2,639.00

Report Ref No. CC3/CTI19007968/Gka3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

Amon's

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.