

Surveyor: Kelvin

REF: CC3/1MI190079731/K19d3n2

Estimate No: _____
 To Insured Vehicle No: _____
 At Workshop no: _____
 Insured: _____
 Policy No: MJ000850
 Claims No: M1903746
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal. or Market Value: _____
 IDAG Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: 3 days Res.: Yes or No
 Cum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Ver: SHD 4456 B Reg: 28 Sep 2012
 Type: M/Car / M/Cycle / Bus / Van / Lorry / T/ / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Santa cc 199
 Colour: Blue A/C: Ins 6 d / Std / NI / NA
 Sp. Reading: 721055 T/Radio: Ins 6 d / Std / NI / NA
 Eng/No: _____
 C/No: KMHET41VMCA83374
 Gen. Cond: Good / Fb / Poor / Burnt
 Steering: Inor 6 / Jammed / Leaked / Burnt or
 Brake: Inor 6 / Jammed / Leaked / Burnt or
 Mod: Hll / S/Rim / 6 D A/Rim or
 Tyre Size: F: 215/60R16
 R: _____
 BS / DUH / EX/NOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Harada
 Front 3 mm Rear 3 mm
 R/Bal. 3 mm L/Bal. 3 mm
 D.O.A. 6/5/19 D.O.I. 6/5/19
 Survey held at LDAC (Logan)
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Roof/Top or
Front / Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 4456 B - CC/FCI1700797/Gv bmt DOA-12/03/2017 Toko 4
	SHD 8605P-X
08/5/19	Q.A. Sum. Email GIA to ESTIMATE to Tru.
13/5/19	Label 415 \$ 3854 3 Pgs. (Red \$ 640.88, 62%)
RECEIVED 14 MAY 2019	

Date/Time, File Print: ☐ : Prel. Report
☒ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: _____

Date/Time, File Return to:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Test/Repair (\$)
☐ : Other (\$)

Survey Fee:
 Transportation: 250
\$ + RS \$
 Fuel:
 Other:

250
10
260

Repair Estimate: MER-TP
3850

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 7 May 2019 9:54 AM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -COMFORTDELGRO ENGINEERING PTE LTD, DOA: 06/05/2019, SHD 4456B (TP VEHICLE), SLD 8605P (OI VEHICLE)
Attachments: SHD4456 GIA.pdf, SHD4456 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 4456B at M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 06/05/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/05/2019 11:25
Date Of Accident	06/05/2019 08:35
Exact Location Of Accident	ECP TOWARDS CHANGI BEFORE MARINE PARADE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4456B
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	OH LAM HUAT
NRIC No	S0814495H
Date Of Birth	15/04/1947
Occupation	OUTDOOR
Date Of Driving Pass	25/10/1966
Driving Experience	52 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90713197
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	229 #04-37 SERANGOON AVENUE 4
Postcode	550229
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD8605P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SH7712R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLA9451A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage FRT

No. Of Passenger (Including Driver)

SKETCH PLAN



A - SHD 4456B
 B - SLD 8605P
 C - SH 7712R
 D - SLA 9451A

Along ECP TWDS Changi Before Marine Parade Exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06.05.2019 at about 08:35 hours I was travelling along ECP TWDS Changi Before Marine
Parade Exit with One Male Passenger onboard .
While travelling straight on the extreme right lane , I saw Veh C (SH 7712R) - slow down and
stop . I followed too , suddenly I felt an impact from my taxi A - Rear portion causing my taxi to
surged forward and collided into Veh C .
After the accident my taxi sustain damages on both front and rear portion .
No injury in this accident .
I have company video to support my claims .
Veh B - Male Driver
Veh C - Male Driver
Veh D - Male Driver

DECLARATION

(/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 06.05.2019
 @ 10:30 hrs

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

06 MAY 2019

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 016 Wendy
NRIC/FIN No. 06 MAY 2019



REPAIR ESTIMATE*

VEHICLE NO : SHD 4456B

DATE : 6.05.2019

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 282.10
	Radiator Grille U Moulding			\$ 108.90
	Front Bumper Cover			\$ 544.50
	Front Bumper Sponge			\$ 136.30
	Front Bumper Reinforcement			\$ 504.10
	Front Bumper Bracket Top (LH/RH)	S	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH)	S	24.60	\$ 49.20
	SUB TOTAL			\$ 1,669.90
	LESS 20%			\$ 333.98
	DISCOUNTED TOTAL			\$ 1,335.92
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 350.00 200
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 50.00 20
	Towing Charge			\$ 50.00 20
	Remove/Refix Aircon & Refill Gas			\$ 150.00 20
	TOTAL LABOUR			\$ 850.00

P1

Nett

Nett

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>— x</i>			\$ 2,174.90
	Boot Lid Rubber <i>x su</i>			\$ 110.90
	Boot Lid Hinge (LH/RH) <i>x su</i>	\$	170.60	\$ 341.20
	Boot Lid Lock Upper <i>x su</i>			\$ 132.10
	Boot Lid Lock Lower <i>x su</i>			\$ 31.70
	Boot Lid Sonata Plate <i>✓ su</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>x h</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>— su</i>			\$ 26.10
	Boot Lid CRDI Plate <i>— su</i>			\$ 22.70
	Boot Lid Lamp (LH/RH) <i>x su</i>	\$	565.60	\$ 1,131.20
	Boot Lid Trimboard <i>x su</i>			\$ 165.40
	Boot Lid Trimboard Clips (11 pcs) <i>x su</i>			\$ 11.00
	Rear Bumper <i>— su</i>			\$ 578.40
	Rear Bumper Reinforcement <i>✓ su</i>			\$ 483.30
	Rear Bumper Clip <i>— su</i>			\$ 22.00
	Rear Bumper Bracket <i>x su</i>			\$ 49.00
	Rear Bumper Sponge <i>✓ su</i>			\$ 137.40
	Rear Bumper Under Cover <i>x su</i>			\$ 228.00
	Rear Bumper Protector (LH/RH) <i>x su</i>	\$	38.00	\$ 76.00
	Tail Lamp (LH/RH) <i>x su</i>	\$	697.80	\$ 1,395.60
	Rear Panel <i>x su</i>			\$ 526.70
	Rear Panel Garnish <i>x su</i>			\$ 95.80
	SUB TOTAL			\$ 7,807.20
	LESS 20%			\$ 1,561.44
	DISCOUNTED TOTAL			\$ 6,245.76
	Boot Lid Comfort Logo & Tel No. Sticker <i>— su</i>			\$ 30.00
	Rear No. Plate <i>x su</i>			\$ 25.00
	Rear Bumper Rubber Mat <i>— su</i>			\$ 50.00
				\$ 105.00
	Labour Charge			
	Panel Beating			\$ 830.00 ³⁰⁰
	Spray Painting Charge			\$ 750.00 ⁴⁰⁰
	Wiring Charge			\$ 50.00 ³⁰
	Tuff Kote			\$ 50.00 ³⁰
	TOTAL LABOUR			\$ 1,700.00
	ESTIMATE TOTAL			\$ 10,291.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/05/2019
Vehicle Reg. No.:	SHD4456B	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	28/09/2012
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAC195834	Chassis No:	KMHET41VMCA830374
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	7,740.88
Miscellaneous Items	10.00
Labour	2,500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,250.88
+ GST 7.00% (S\$)	717.56
Nett Amount (S\$)	10,968.44

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 May 2019)

Parts: 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD4456B/06/05/2019 18:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR GRILLE	20.00	0.00	*282.10 FL ✓
2	1		*RADIATOR GRILLE U MOULDING	20.00	0.00	*108.90 FL ✓
3	1		*FRT BUMPER COVER	20.00	0.00	*544.50 FL ✓
4	1		*FRT BUMPER SPONGE	20.00	0.00	*136.30 FL ✓
5	1		*FRT BUMPER REINFORCEMENT	20.00	0.00	*504.10 FL ✓
6	1		*FRT BUMPER BRACKET TOP LH	20.00	0.00	*22.40 FL ✓
7	1		*FRT BUMPER BRACKET TOP RH	20.00	0.00	*22.40 FL ✓
8	1		*FRT BUMPER BRACKET LH	20.00	0.00	*24.60 FL ✓
9	1		*FRT BUMPER BRACKET RH	20.00	0.00	*24.60 FL ✓
10	1		*FRT NUMBER PLATE	0.00	0.00	*25.00 F ✓
11	1		*FRT NUMBER PLATE TRIM COVER	0.00	0.00	*30.00 F ✓
12	1		*BOOTLID	20.00	0.00	*2,174.90 FL ✓
13	1		*BOOTLID RUBBER	20.00	0.00	*110.90 FL ✓
14	1		*BOOTLID HINGE LH	20.00	0.00	*170.60 FL ✓
15	1		*BOOTLID HINGE RH	20.00	0.00	*170.60 FL ✓
16	1		*BOOTLID LOCK UPPER	20.00	0.00	*132.10 FL ✓
17	1		*BOOTLID LOCK LOWER	20.00	0.00	*31.70 FL ✓
18	1		*BOOTLID SONATA PLATE	20.00	0.00	*43.60 FL ✓
19	1		*BOOTLID HYUNDAI PLATE	20.00	0.00	*24.20 FL ✓
20	1		*BOOTLID H EMBLEM	20.00	0.00	*26.10 FL ✓
21	1		*BOOTLID CRDI PLATE	20.00	0.00	*22.70 FL ✓
22	1		*BOOTLID LAMP LH	20.00	0.00	*565.60 FL ✓
23	1		*BOOTLID LAMP RH	20.00	0.00	*565.60 FL ✓
24	1		*BOOTLID TRIMBOARD	20.00	0.00	*165.40 FL ✓
25	10		*BOOTLID TRIMBOARD CLIPS	20.00	0.00	*10.00 FL ✓
26	1		*REAR BUMPER	20.00	0.00	*578.40 FL ✓
27	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*483.30 FL ✓
28	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL ✓
29	1		*REAR BUMPER BRACKET LH	20.00	0.00	*49.00 FL ✓
30	1		*REAR BUMPER SPONGE	20.00	0.00	*137.40 FL ✓
31	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL ✓
32	1		*REAR BUMPER PROTECTOR LH	20.00	0.00	*38.00 FL ✓
33	1		*REAR BUMPER PROTECTOR RH	20.00	0.00	*38.00 FL ✓
34	1		*TAIL LAMP ASSY LH	20.00	0.00	*697.80 FL ✓
35	1		*TAIL LAMP ASSY RH	20.00	0.00	*697.80 FL ✓
36	1		*REAR PANEL	20.00	0.00	*526.70 FL ✓
37	1		*REAR PANEL GARNISH	20.00	0.00	*95.80 FL ✓
38	1		*BOOTLID COMFORT LOGO	0.00	0.00	*20.00 F ✓
39	1		*BOOTLID TEL NO STICKER	0.00	0.00	*10.00 F ✓
40	1		*REAR NUMBER PLATE	0.00	0.00	*25.00 F ✓
41	1		*REAR BUMPER RUBBER MAT	0.00	0.00	*50.00 F ✓

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)

9,636.10

- List Item Discount on L Items (\$\$)

1,895.22

ComfortDelGro Engineering Pte Ltd/SHD4456B/06/05/2019 18:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						7,740.88

ComfortDelGro Engineering Pte Ltd/SHD4456B/06/05/2019 18:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	FRT PANEL BEATING	New 200	350.00
2	FRT SPRAY PAINTING CHARGE	New 200	250.00
3	FRT WIRING CHARGE	New x hr	50.00
4	FRT REMOVE/REFIX AIR & REFILL GAS	New x hr	150.00
5	REAR PANEL BEATING	New 300	850.00
6	REAR SPRAY PAINTING CHARGE	New 400	750.00
7	REAR WIRING CHARGE	New min	50.00
8	REAR TUFF KOTE	New 30	50.00
Gross Labour Cost (S\$)			2,500.00

ComfortDelGro Engineering Pte Ltd/SHD4456B/06/05/2019 18:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COMFORTDELGRO

Date/Time: 06.05.2019 13:58 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305292910

OMER

COMFORT TRANSPORTATION PTE LTD

OMER NO: 7010045

ESS: 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P)

JOINT CARD NO.

REGD NO: SHD4456B

MAKE: HYUNDAI

MODEL: SONATA

YR OF MANU: 28.09.2012

CHASSIS CODE: KMHET41VMCA830374

MILEAGE

FUEL: E 1/2 F

DATE/TIME IN: 06.05.2019 09:20

TARGET DATE


COMPLETION DATE/TIME

Tokio Marine

JOB DESCRIPTION

Accident Date: 06.05.2019
NATURE: 3P 06.05.2019

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Vehicle No: SHD4456B

Signature/Date: *Kalvin*

Name of Service Advisor

Date

Exit Pass

Vehicle No: SHD4456B

To be kept by Security Guard

of Service Advisor

returned to Service Reception upon collection

Our Job Ref No 305292910

Date : 11.05.19

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

FRAX:

Attn : Mr KALVIN ANG

Vehicle Reg No. SHD4456B CTPL

06.05.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:

- | | | |
|---|--|---|
| <p>1. The repair job shall bill to:</p> <p>2. The finalized amount shall be:</p> <p>(a) Spare Parts after List discount</p> <p>(b) Labour Charges</p> <p>Total for Part-By-Part Repair Cost</p> <p>(c) Lumpsum Repair (if applicable)</p> <p>Total for Lumpsum repair cost after Less:</p> <p>Final Lumpsum Repair cost</p> | <p>TOKIO MARINE</p> <hr/> <p>—</p> <hr/> <p>20%</p> | <p>SLD8605P</p> <hr/> <p>—</p> <hr/> <p>\$3,850.00</p> <p>\$3,850.00</p> |
|---|--|---|

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

Signature: 

Name: LIM KWOK ENG

Tel: 62148316

Fax: 65468158

We confirm the estimates and finalized amount

Signature: 

Name: Kuhn

Date: 13/5/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19007973/K1QD3N2

Date: 16/05/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ000850
Claimant Vehicle No :	SHD4456B	Insured Vehicle No :	SLD8605P
Date of Loss:	06/05/2019	Nature of Claim:	TP
		Claim No:	M1903246

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4456B	Engine No:	D4EAC195834
Make & Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Chassis No:	KMHET41VMCA830374
Reg. Date:	28/09/2012 (Man. Year: 2012)	Odometer:	721055 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,740.88	3,674.12	4,066.76	52.54
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,500.00	1,130.00	1,370.00	54.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,250.88	4,814.12	5,436.76	53.04
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	10,250.88	3,850.00	6,400.88	62.44
+ GST 7.00/7.00% (S\$)	717.56	269.50	448.06	62.44
Nett Amount (S\$)	10,968.44	4,119.50	6,848.94	62.44

INSPECTION

Date of Assignment:	07/05/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/05/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2019)	
Parts: 143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SHD4456B)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	282.10 FL	*282.10 FL
2	1		*RADIATOR GRILLE U MOULDING	Cracked	108.90 FL	*108.90 FL
3	1		*FRT BUMPER COVER	Deformed	544.50 FL	*544.50 FL
4	1		*FRT BUMPER SPONGE	Serviceable	136.30 FL	*- FL
5	1		*FRT BUMPER REINFORCEMENT	Serviceable	504.10 FL	*- FL
6	1		*FRT BUMPER BRACKET TOP LH	Serviceable	22.40 FL	*- FL
7	1		*FRT BUMPER BRACKET TOP RH	Serviceable	22.40 FL	*- FL
8	1		*FRT BUMPER BRACKET LH	Serviceable	24.60 FL	*- FL
9	1		*FRT BUMPER BRACKET RH	Serviceable	24.60 FL	*- FL
10	1		*FRT NUMBER PLATE	Missing	25.00 F	*25.00 F
11	1		*FRT NUMBER PLATE TRIM COVER	Cracked	30.00 F	*30.00 F
12	1		*BOOTLID	Buckled	2,174.90 FL	*2,174.90 FL
13	1		*BOOTLID RUBBER	Serviceable	110.90 FL	*- FL
14	1		*BOOTLID HINGE LH	Serviceable	170.60 FL	*- FL
15	1		*BOOTLID HINGE RH	Serviceable	170.60 FL	*- FL
16	1		*BOOTLID LOCK UPPER	Serviceable	132.10 FL	*- FL
17	1		*BOOTLID LOCK LOWER	Serviceable	31.70 FL	*- FL
18	1		*BOOTLID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
19	1		*BOOTLID HYUNDAI PLATE	Not Necessary	24.20 FL	*- FL
20	1		*BOOTLID H EMBLEM	Necessary	26.10 FL	*26.10 FL
21	1		*BOOTLID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
22	1		*BOOTLID LAMP LH	Serviceable	565.60 FL	*- FL
23	1		*BOOTLID LAMP RH	Serviceable	565.60 FL	*- FL
24	1		*BOOTLID TRIMBOARD	Serviceable	165.40 FL	*- FL
25	10		*BOOTLID TRIMBOARD CLIPS	Not Necessary	10.00 FL	*- FL
26	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
27	1		*REAR BUMPER REINFORCEMENT	Cracked	483.30 FL	*483.30 FL
28	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
29	1		*REAR BUMPER BRACKET LH	Serviceable	49.00 FL	*- FL
30	1		*REAR BUMPER SPONGE	Torn	137.40 FL	*137.40 FL
31	1		*REAR BUMPER UNDER COVER	Serviceable	228.00 FL	*- FL
32	1		*REAR BUMPER PROTECTOR LH	Serviceable	38.00 FL	*- FL
33	1		*REAR BUMPER PROTECTOR RH	Serviceable	38.00 FL	*- FL
34	1		*TAIL LAMP ASSY LH	Serviceable	697.80 FL	*- FL
35	1		*TAIL LAMP ASSY RH	Serviceable	697.80 FL	*- FL
36	1		*REAR PANEL	Repair	526.70 FL	*- FL
37	1		*REAR PANEL GARNISH	Serviceable	95.80 FL	*- FL
38	1		*BOOTLID COMFORT LOGO	Necessary	20.00 F	*20.00 FS
39	1		*BOOTLID TEL NO STICKER	Necessary	10.00 F	*10.00 FS
40	1		*REAR NUMBER PLATE	Serviceable	25.00 F	*- FS
41	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 FS

F=Franchise part. S=SpcNelt. L=ListItemDisc.

Sub Total (S\$) **9,636.10** **4,558.90**
 - List Item Discount on L Items 20.00/20.00% (S\$) **1,895.22** **884.78**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	3,674.12

7,740.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FRT PANEL BEATING	New	350.00	200.00
2	FRT SPRAY PAINTING CHARGE	New	250.00	200.00
3	FRT WIRING CHARGE	New	50.00	0.00
4	FRT REMOVE/REFIX AIR & REFILL GAS	New	150.00	0.00
5	REAR PANEL BEATING	New	850.00	300.00
6	REAR SPRAY PAINTING CHARGE	New	750.00	400.00
7	REAR WIRING CHARGE	New	50.00	0.00
8	REAR TUFF KOTE	New	50.00	30.00
Gross Labour Cost (S\$)			2,500.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >