

ASS. REC. BY:

REF: CS/C1119007974/Asd312

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Ang din Kiatof C12Date/Time: 6.5.19 17.43p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 3183JInsured: SLW 977Tat Workshop m/s SE AutomobileTel: 67895155of 23 Kaki Bukit Ave 4 #03-01Policy No: DMPCSN30042319000Claim No: SNM190202003102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5.5.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 7.5.19 9.33a.mPerson Contacted: JulieVehicle IN OUT

Date/Time	Action/Instruction
	Ishtamati (✓) Inspection: 8 Kaki Bukit Ave 4, #08-45
	SJC 3183J - CS3/INCL3000496/UYK 3-1 D.O.A - 05/01/2013
	SLW 977T - X

Surveyor

ASSIGNMENT

From: Date 7.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SK 3183J

at Workshop n/s SK Automobile

of 8 Raki Bukit Ave 4, #08-45

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SK3183J. Yr Regn: 2008 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis.

c.c 1794

Colour: Grey Silver.

A/C: Insured / Std / NI / NA

Sp. Reading: 179927

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053ZEE206107765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 07/05/19.

Survey held at SK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chng.

COE Expiry: 14/10/28.

10/06/19 Confirmed HS \$ 2,300/- @ 5 days with Adrian.
(\$ 4,310.83 Red - 5%)

RECEIVED 10 JUN 2019

Date/Time, File Pass to?

10/06/19

1) Typ: st

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$ 2,300/- 1/5)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 May 2019		06 May 2019 17:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	THL BUILDING CONSTRUCTION PTE LTD, Co. Reg. No.: 200515025R		
Main Claimant:	CARS FOR RENT (2016) PTE. LTD., Co. Reg. No.: 201609732N		
Vehicle Reg. No.:	SJK3183J	Date of Loss:	05/05/2019 18:00 - :59 [126 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202003C02	Policy/Cover Note No.:	DMPCSN30042319000 (Comprehensive)
Vehicle Reg. No. (Insured):	SLW977T	Policy No. (Claimant):	5080856074-02
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

9732N

Vehicle Details

Vehicle No.:

SJK3183J

Vehicle to be Exported:

No

Intended Deregistration Date:

06 May 2019

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA ALTIS 1.8 AUTO

Primary Colour:

Silver

Manufacturing Year:

2008

Engine No.:

1ZZ4787322

Chassis No.:

MR053ZEE206107765

Maximum Power Output:

97.0 kW (130 bhp)

Open Market Value:

\$19,246.00

Original Registration Date:

15 Oct 2008

First Registration Date:

15 Oct 2008

Transfer Count:

4

Actual ARF Paid:

\$19,246.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

14 Oct 2028

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

PQP Paid:

\$32,279.00

COE Rebate Amount:

\$30,465.00

Total Rebate Amount:

\$30,465.00

The information contained herein is correct as at 06 May 2019

OK

MVA319058323 / VAC - Kaki Bukit
 ENTRY DATE & TIME: 06/05/2019 16:06
 SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/05/2019 16:06
 Date Of Accident 05/05/2019 18:30
 Exact Location Of Accident SIMS AVENUE TWRDS PAYA LEBAR
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJK3183J
 Insured/Policyholder
 Name Of Registered Owner CARS FOR RENT (2016) PTE. LTD.
 Co Reg No 201609732N
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-80000000

Vehicle Particulars

Manufacturer TOYOTA
 Model COROLLA ALTIS 1.8 AUTO
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE(NOT GOT GRAB)
 Are you claiming under your own Insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number 5080856074-02
 Cover Note Number

Driver

Name of Driver CHUA BENG CHOON
 NRIC No S7044967F
 Date Of Birth 10/12/1970
 Occupation OUTDOOR
 Date Of Driving Pass 28/01/1993
 Driving Experience 26 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97809901
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address 1 HACIENDA GROVE #03-01
 Postcode 457908
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - NORMAL RENTAL
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle Involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : CHOW WAI YEE
 GENDER: : FEMALE
 Passenger 2 NAME: : RIAN CHUA
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLW977T
 Vehicle Make/Model/Colour TOYOTA LEXUS LS350 LUXURY MR (AUTO)
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TEOH HEE LAI
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4

Reporting Centre Singapore
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@siugnet.com.sg

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders,



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4

Reporting Centre
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 05 MAY 2019 @ 1830HRS. WHILE I WAS ALONG SIMS AVE. WHEN I STOPPED AT THE TRAFFIC LIGHT, WHILE I WAS STATIONARY VEHICLE B COLLIDED INTO MY VEHICLE REAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GRABMC SketchPlanForm_V1

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Singapore 415933
Reporting Centre Person's Signature
Tel: 67416697
Name: Fax: 67492305
NRIC/FIN No: Email: vackb@singnot.com.sg

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933
Tel: 6789 5155 Fax : 6783 5155

TO	: CHAINA TAIPING	DATE	: 6-May-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Shirley	VEHICLE NO	: SJK3183J
ADDRESS	:	MODEL	: TOYOTA ALTIS
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:	MRO53ZEE206107765	
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>chub</i>	1	\$654.00	\$ 654.00 486
2	REAR BUMPER REFLECTOR <i>new</i>	2	\$76.40	\$ 152.80
3	REAR BUMPER RETAINER (FRONT) <i>new</i>	2	\$64.20	\$ 128.40
4	REAR BUMPER SIDE RETAINER (BLACK) <i>new</i>	2	\$35.00	\$ 70.00
5	REAR BUMPER BRACKET <i>new</i>	2	\$78.00	\$ 156.00
6	REAR BUMPER SPONGE <i>chub</i>	1	\$169.40	\$ 169.40
7	REAR BUMPER PROTECTOR BAR <i>new</i>	1	\$124.20	\$ 124.20
8	BOOTLID <i>new</i>	1	\$689.00	\$ 689.00
9	BOOTLID TOP LOCK	1	\$158.20	\$ 158.20
10	BOOTLID LOWER LOCK	1	\$24.10	\$ 24.10
11	BOOTLID WEATHERSTRIP	1	\$165.90	\$ 165.90
12	BOOTLID LOGO	1	\$52.60	\$ 52.60
13	BOOTLID EMBLEM '1.6'	1	\$46.40	\$ 46.40
14	BOOTLID EMBLEM 'COROLLA'	1	\$65.30	\$ 65.30
15	BOOTLID EMBLEM 'ALTIS'	1	\$59.50	\$ 59.50

16	TAILLAMP LOWER BARCKET <i>3 per</i>	2	\$67.20	\$ 134.40	+
17	REAR FENDER INNER COWLING <i>3 per</i>	2	\$194.60	\$ 389.20	+
18	REAR END PANEL <i>dent</i>	1	\$548.00	\$ 548.00	✓
19	REAR END PANEL TOP GARNISH <i>dent</i>	1	\$178.50	\$ 178.50	✓
20	REAR FLOOR PANEL TOP BOARD <i>14 per</i>	1	\$119.20	\$ 119.20	+

1675.70
1256.77

TOTAL PRICE \$ 4,085.10
LESS 25% \$ 1,021.28
SUB TOTAL PRICE \$ 3,063.83

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS <i>new</i>	10	\$ 6.50	\$ 65.00	30
2	BOOT LID INSULATOR CLIP <i>2</i>	10	\$ 6.50	\$ 65.00	+
3	TAILLAMP CLIPS <i>14 per</i>	4	\$ 8.00	\$ 32.00	+
4	REAR FENDER COWLING CLIPS <i>12</i>	12	\$ 6.50	\$ 78.00	+
5	REAR FENDER INNER TRIMD CLIPS <i>12</i>	12	\$ 6.50	\$ 78.00	+
6	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	6	\$ 6.50	\$ 39.00	10
7	REAR END PANEL INSULATION SEAL <i>1</i>	1	\$ 120.00	\$ 120.00	60
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200
		TOTAL		\$ 697.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,200.00	600	
2	TO SPRAY PAINT AFFECTED AREA	\$1,000.00	600	
3	TUFF COAT	\$180.00	60	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$150.00	50	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	
7	TRANSFER BOOTLID MECHANISM	\$60.00	X	
8	CONDUCT WATER LEAKAGE TEST	\$100.00	X	

TOTAL \$2,850.00

TOTAL PARTS COST : \$ 3,760.83
TOTAL LABOUR COST : \$ 2,850.00
TOTAL REPAIR COST : \$ 6,610.83

1380

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian King -
L/S 07/05/19.
05 Days.

Total: 2946.77
L/S: 2.3k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'best offer' basis
- No illegal modifications allowed
- Supplementary items must be approved
- is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007974/ASD3N2

Date: 13/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30042319000	
Claimant Vehicle No :	SJK3183J	Insured Vehicle No :	SLW977T	
Date of Loss:	05/05/2019	Nature of Claim:	TP	Claim No: SNM19D202003C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK3183J	Engine No:	1ZZ4787322
Make & Model:	TOYOTA COROLLA ALTIS, 1.8 (A)	Chassis No:	MR053ZEE206107765
Reg. Date:	15/10/2008 (Man. Year: 2008)	Odometer:	179927 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,760.82	1,556.77	2,204.05	58.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,390.00	1,460.00	51.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,610.82	2,946.77	3,664.05	55.43
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	6,610.82	2,300.00	4,310.82	65.21
+ GST 7.00/7.00% (\$\$)	462.76	161.00	301.76	65.21
Nett Amount (\$\$)	7,073.58	2,461.00	4,612.58	65.21

INSPECTION

Date of Assignment:	06/05/2019	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Date Inspected:	07/05/2019 Inspected At:	

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK3183J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	654.00 FL	*486.00 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	152.80 FL	*- FL
3	2		*REAR BUMPER RETAINER (FRONT)	Not Necessary	128.40 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER (BLACK)	Necessary	70.00 FL	*70.00 FL
5	2		*REAR BUMPER BRACKET	Not Necessary	156.00 FL	*- FL
6	1		*REAR BUMPER SPONGE	Cracked	169.40 FL	*169.40 FL
7	1		*REAR BUMPER PROTECTOR BAR	Not Necessary	124.20 FL	*- FL
8	1		*BOOTLID	Repair	689.00 FL	*- FL
9	1		*BOOTLID TOP LOCK	Not Necessary	158.20 FL	*- FL
10	1		*BOOTLID LOWER LOCK	Not Necessary	24.10 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Not Necessary	165.90 FL	*- FL
12	1		*BOOTLID LOGO	Necessary	52.60 FL	*52.60 FL
13	1		*BOOTLID EMBLEM 1.6	Necessary	46.40 FL	*46.40 FL
14	1		*BOOTLID EMBLEM COROLLA	Necessary	65.30 FL	*65.30 FL
15	1		*BOOTLID EMBLEM SLTIS	Necessary	59.50 FL	*59.50 FL
16	2		*TAILLAMP LOWER BRACKET	Not Necessary	134.40 FL	*- FL
17	2		*REAR FENDER INNER COWLING	Not Necessary	389.20 FL	*- FL
18	1		*REAR END PANEL	Dented	548.00 FL	*548.00 FL
19	1		*REAR END PANEL TOP GARNISH	Deformed	178.50 FL	*178.50 FL
20	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	119.20 FL	*- FL
21	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
22	10		*BOOT LID INSULATOR CLIP	Not Necessary	65.00 FS	*- FS
23	4		*TAILLAMP CLIPS	Not Necessary	32.00 FS	*- FS
24	12		*REAR FENDER COWLING CLIPS	Not Necessary	78.00 FS	*- FS
25	12		*REAR FENDER INNER TRIM CLIPS	Not Necessary	78.00 FS	*- FS
26	1		*REAR END PANEL TOP GARNISH CLIPS (6 Pcs)	Necessary	39.00 FS	*10.00 FS
27	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
28	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,782.10	1,975.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,021.28	418.93
Total Parts (\$\$)	3,760.82	1,556.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,200.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	600.00
3	TUFF COAT	New	180.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	150.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANFER BOOTLID MECHANISM	New	60.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			2,850.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >