




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17020720/Utd3s2-1	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 14-05-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGZ 5309H	Veh. Inspected	FW 1737J	
Policy No.	DMHCSN1675381600	Coverage (\$)	0.00	
Claim No.	SNM17D05972C02	Excess (\$)	0.00	
Assign From	ALFRED TOH	Assign Date	07/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	KAWASAKI KRR ZX150	c.c	148	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	KR150KA55575	Colour	GREEN	
Odometer	16549	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90-80-17	SWALLOW	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	110-70-17	SWALLOW	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/10/2017	Inspection Date	31/10/2017	
Survey held at	OCCI_SONO MOTOR.COM 225 KAKI BUKIT ROAD 4 #01-38 SYNERGY SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		