

ASSIGNMENT (Office)

Surveyor

Taufik

REF: CS/FCI/19007991/RTVd3ⁿ²

Special Instruction

CWS

Estimated Cost

Karen Tan

of

FCI

Date/Time

12:12pm @ 6/5/19

Estimated Cost

Bill to

OD / WS / TP RES / OD RES / KYA / INV / MYTC

To Inspect Vehicle No.

SGN 6468M

Insured

SHD 3326A

at Workshop n/o

Wah Hong Motor

Tel

65155988

of

38 Joh Guan Rd East #01-57

Policy No

Claim No

019002898MFST

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

30/04/2019

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:24pm @ 6/5/19

Person Contacted

sunny

Vehicle

② OUT

Date/Time

Action/Instruction (✓) Estimate

SGN 6468M-X

SHD 3326A-NA/AIG15000511/r3

BOA: 24/12/2014

7/5/19

Email preli revised to FCI

21/5/19

LS \$1300 confirmed by email (Ref 942, 429)

mv: \$41K (est) LTA: \$38,960 NV: \$2040

DATE

Tan

REF

FCI

ASSIGNMENT

CoE - 2026 Nov.

Figure: _____ Date: _____
 Estimated Cost: _____
 ODI / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop info: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: \$41K
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Turn Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

NIS	O/S
X	

Veh No: SGN 6468M Yr Regn: 2006 / Nov
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Altis C/C: 1598
 Colour: Red A/C: Insured / Std / Nil / NA
 Sp. Reading: 57262 T/Radio: Insured / Std / Nil / NA
 Eng No: _____
 C/Nr: MK0537EC107134098
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/70R14
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 6/5/19020204
 Survey held at: Wan Hong
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

RECEIVED 28 MAY 2019

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

2) 28/5- typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format: CWS
 Lump Sum / L.B.I: (\$) 130012

Survey Fee:	110
Transportation:	50
3 + 10% :	50
Photos:	39
Other:	
TOTAL	249

38704900010102 401-57



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002898MFSH

Our ref: CS/FCI19007991/T1vd3

Date: 7/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SGN 6468M


We thank you for your instruction on 6/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 6/5/2019 at the premises of M/s WAH HONG MOTORS & CREDIT PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$2,242.00
Revised Estimate Amount	: S\$1,890.00
"Check" Items Amount	: S\$180.00
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-05-2019	Our Ref No. D19002898MFSH
Accident Date	30-04-2019	Claim Type. Third Party
Insured Vehicle	SHD3326A	Third Party Vehicle. SGN6468M
Survey Location	38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB	
Contact Person.	SUNNY TEE	
Contact No.	65155988/ 62630568	Fax No. 68966321
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WAH HONG MOTORS & CREDIT PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 7 May 2019 2:26 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002898MFSH/1, SGN 6468M
Attachments: SGN 6468M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGN 6468M
Date of survey: 6/5/2019
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 6 May 2019 12:32 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002898MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 6 May 2019 12:12 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002898MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 27 May 2019 5:07 PM
To: Michael Tee
Cc: SUR; Taufikh (LKKAUTO)
Subject: RE: SGN6468M (3) (And Can You Finalisation)

Dear Michael,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michael Tee <michael@wahhong.sg>
Sent: Monday, 27 May 2019 1:22 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: Re: SGN6468M (3) (And Can You Finalisation)

OK FOR Lump Sum At \$1,300.00 5 Days LOU

On 27 May 2019, at 1:19 pm, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Michael,

WITHOUT PREJUDICE

Offer Lump Sum \$1300 @ 5 working days.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michael Tee <michael@wahhong.sg>
Sent: Friday, 24 May 2019 2:39 PM
To: SUR <sur@lkkauto.com>

Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: SGN6468M (3) (And Can You Finalisation)

<MARKING.pdf>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5915C
Vehicle Details	
Vehicle No.:	SGN6468M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	3ZZ4610946
Chassis No.:	MR053ZEC107134098
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,498.00
Original Registration Date:	24 Nov 2006
First Registration Date:	24 Nov 2006
Transfer Count:	0
Actual ARF Paid:	\$13,027.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$51,641.00
COE Rebate Amount:	\$38,960.00
Total Rebate Amount:	\$38,960.00

The information contained herein is correct as at 07 May 2019

OK



Name: LEE AH KHIM
 Address: Blk 206 Bukit Batok Street 21 #11-74
 Singapore 650206
 Policy Number: D 300072715 QMY
 Quotation for Reinstste / Repairs for Vehicle

Date: 2/5/19
 Vehicle No: SGN6468M

Parts Replacement-Cost Price

Cost Price

1 Pc Rear Bumper
 1 Pc Rear End Panel
 1 Pc Rear Lamp Panel Below
 1 Pc Rear Rivet
 1 Pc Rear L/H Lamp - photo.
 1 Pc Rear L/H Side Bumper Retainer
 1 Pc Rear R/H Side Bumper Retainer
 1 Pc Rear L/H Side Bumper Bracket

\$ 360.00 *600*
 \$ 410.00 *600*
 \$ 85.00 *600*
 \$ 8.00 *200*
 \$ 180.00 *200*
 \$ 22.00 *200*
 \$ 22.00 *200*
 \$ 55.00 *200*

25%

25% - 705

7/5/19

Tanaka 77495149
-wp
6/5/19 @ 210pm
humpson
Result after repair
sure (humpson)
5 days

\$ 1,142.00

1 job

To remove and replace all the parts mentioned above and knocking and straighten up the necessary affected areas

\$ 650.00 *500*

1 job

To spray painting on affected areas

\$ 450.00 *950*

Labour's Total : \$ 1,100.00

Sub-Total : \$ 2,242.00

GST 7% : \$ 156.94

Grand Total : \$ 2,398.94

1655
1153 1300

[Signature]
 Michael Tee
 Wah Hong Motors & Credit Pte Ltd
 Tel: 67737377
 Fax: 68966321
 Email: michael@wahhong.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WAH HONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19007991/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3326A	Veh. Inspected	SGN 6468M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002898MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	06/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053ZEC107134098	Colour	RED	
Odometer	57262	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	MICHELIN	6 mm	
L/H Front Tyre	185/70 R14	MICHELIN	6 mm	
R/H Rear Tyre	185/70 R14	MICHELIN	6 mm	
L/H Rear Tyre	185/70 R14	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/04/2019	Inspection Date	06/05/2019	
Survey held at	WAH HONG & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 6468M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRACKED	360.00	360.00
1	REAR END PANEL	BENT	410.00	410.00
1	REAR LAMP PANEL BELOW	BENT	85.00	85.00
1	REAR RIVET	NECESSARY	8.00	8.00
1	REAR L/H LAMP	NOT NECESSARY	180.00	-
1	REAR L/H SIDE BUMPER RETAINER	NECESSARY	22.00	22.00
1	REAR R/H SIDE BUMPER RETAINER	NOT NECESSARY	22.00	-
1	REAR L/H SIDE BUMPER BRACKET	CRACKED	55.00	55.00
	LESS 25% DISCOUNT		-	-235.00
			1,142.00	705.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE AND KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS.		650.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		450.00	450.00
			1,100.00	950.00
	GRAND TOTAL		2,242.00	1,655.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS/FCI19007991/T1vd3n2

MARKET VALUE: \$41,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$38,960.00=NETT VALUE: \$2,040.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.