

Tayuk

REF: ASM(AXA)

2014/11/10

## ASSIGNMENT

From:

Date:

9/5/2014

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKD 3108C

at Workshop m/s

volkswagen

of

1 kampong Ampat (Macpherson)

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2pm (waiting)  
Edmund

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

9118K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKD 3108C

Yr Regn:

2014 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf

C.C.

1395

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

3314

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NVW 227447 JV 220610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

9/5/19 220P

Survey held at

VW Kg Ampat

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / E.B.I: (\$ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$ )

☐

Interview (\$ )

☐

Tech. Invs (\$ )

☐

Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL