

CS/FCI 19008019 / Nvd3 / N2  
 ASSIGNMENT (Office)  
 Person (Person) Mdy chua of FCI Date/Time 8:20am @ 7/5/19  
 Estimated Cost Bill to  
 OD / TP / WS / TP RES / OF RES / EVA / INV / MY / CS  
 To Inspect Vehicle No. SLJ 6209G Insured SHB 6610U  
 at Workshop n/a JA Autocare Tel 94513429  
 of 8 Calvi Blvd Ave & # 02-37 premier  
 Policy No. Claim No. 019002961 MP&H  
 Sum Insured Excess  
 Make of Veh. D.O.A. 06/05/2019  
 (Client's Record)

CA / REV / REP. / REV. 24 HRS 1DS  
 Date/Time: 9:46am @ 7/5/19 Person Contacted Juny H.O.D. Endorsement  
 Vehicle IN / OUT

| Date/Time      | Action/Instruction (✓) Estimate   |
|----------------|-----------------------------------|
|                | SLJ 6209G-X                       |
|                | SHB 6610U - CS/GH1/7022365/K1/bn2 |
|                | DOA: 20/11/2017                   |
| <u>14/5/19</u> | Email preli revised to FCI        |

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Fel**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 6209Gat Workshop m/s JA

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \$586

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

SIA / PR Seen: ✓ Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

4450613

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: 4450613

Date / Time Action / Instruction

Ref 738727/5/19 1/5 \$6500 conf. with Jerry (Ref 7452.97, 531)Veh No: SLJ 6209G Regn: 9.13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or GAMake: Citroen GRAND CHASSO 15.98Colour: white A/C: Insured / Std / NI / NASp. Reading: 89654 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF7UA5FV8CJ795130Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/50 R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mmRear R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 6/5/19D.O.I. 13/5/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 165

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) 28/5 - typistAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: CWSLump Sum / I.B.I. (\$) 6500/-3x15 = 45170 + 45505081396

RECEIVED 28 MAY 2019



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002961MFSH

Our ref: CS/FCI19008019/Uvd3

DATE: 14/5/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

**INITIAL INSPECTION REPORT OF VEHICLE NO SLJ 6209G**


We thank for your instruction on 7/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 13/5/2019 at the premises of M/s JA AUTOCARE PTE LTD

|                          |                |
|--------------------------|----------------|
| Workshop Estimate Amount | : S\$13,952.97 |
| Revised Estimate Amount  | : S\$9,784.80  |
| "Check" Items Amount     | : S\$          |
| Market Value             | : S\$          |
| LTA Reimbursement Value  | : S\$          |
| Nett Value               | : S\$          |

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:  
Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                             |                      |               |
|--------------------|-------------------------------------------------------------|----------------------|---------------|
| Date               | 06-05-2019                                                  | Our Ref No.          | D19002961MFSH |
| Accident Date      | 06-05-2019                                                  | Claim Type.          | Third Party   |
| Insured Vehicle    | SHB6610U                                                    | Third Party Vehicle. | SLJ6209G      |
| Survey Location    | 8 KAKI BUKIT AVE 4 #02-37 PREMIER@KAKI BUKIT                |                      |               |
| Contact Person.    | JENNY CHEW                                                  |                      |               |
| Contact No.        | 94513529/ 94513529                                          | Fax No.              | 0             |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                      |               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                      |               |
| Contact Person     | NA                                                          | Fax No.              | 68416315      |
| Contact Number.    | NA                                                          |                      |               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                     |                      |     |
|-------------------|---------------------|----------------------|-----|
| Cc : Workshop     | JA AUTOCARE PTE LTD | Attention.           | NIL |
| Cc : TP Solicitor | NA                  | TP Solicitor Fax No. | NA  |
| Officer Incharge  | MAY CHUA            |                      |     |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 14 May 2019 2:57 PM  
**To:** 'CWS Motor Claims'  
**Cc:** 'May Chua Hui Chin'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19002961MFSH/1, SLJ 6209G  
**Attachments:** SLJ 6209G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLJ 6209G  
Date of survey: 13/5/2019  
Number of days : 5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 7 May 2019 10:39 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19002961MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 7 May 2019 8:20 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; May Chua Hui Chin <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19002961MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                           |
|-------------------------------|---------------------------|
| Owner ID Type:                | Singapore NRIC            |
| Owner ID:                     | 0173I                     |
| Vehicle Details               |                           |
| Vehicle No.:                  | SLJ6209G                  |
| Vehicle to be Exported:       | No                        |
| Intended Deregistration Date: | 14 May 2019               |
| Vehicle Make:                 | CITROEN                   |
| Vehicle Model:                | GRAND C4 PICASSO 1.6I EGS |
| Primary Colour:               | White                     |
| Manufacturing Year:           | 2012                      |
| Engine No.:                   | 10FJBS1710610             |
| Chassis No.:                  | VF7UA5FV8CJ795130         |
| Maximum Power Output:         | 115.0 kW (154 bhp)        |
| Open Market Value:            | \$23,906.00               |
| Original Registration Date:   | 03 Sep 2013               |
| First Registration Date:      | 03 Sep 2013               |
| Transfer Count:               | 1                         |
| Actual ARF Paid:              | \$25,469.00 12734         |
| Intended PARF Rebate Details  |                           |
| PARF Eligibility:             | Yes                       |
| PARF Eligibility Expiry Date: | 02 Sep 2023               |
| PARF Rebate Amount:           | \$17,828.00               |
| Intended COE Rebate Details   |                           |
| COE Expiry Date:              | 02 Sep 2023               |
| COE Category:                 | A - Car (1600cc & below)  |
| COE Period(Years):            | 10                        |
| QP Paid:                      | \$76,223.00               |
| COE Rebate Amount:            | \$32,785.00               |
| <b>Total Rebate Amount:</b>   | <b>\$50,613.00</b>        |

The information contained herein is correct as at 14 May 2019

OK

**JA AUTOCARE PTE LTD**

8 Kaki Bukit Ave 4

#02-37 Premier@Kaki Bukit

Singapore 415875

Tel : 94513429

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

Date 08.05.2019

Vehicle no : SLJ 6209G

Model: Citroen Picasso

DOA : 06.05.2019

Not Adult  
 1/s \$ 6500/  
 Take, Mr. H. H. H. H. H.  
 13/5/19  
 Sdy.

**PARTS**

|                                       |             |                    |               |
|---------------------------------------|-------------|--------------------|---------------|
| 01) Tail gate                         | DD/Ref 1980 | \$ 2,850.00        | ✓             |
| 02) Tail gate centre garnish          | 11          | \$ 350.80          | ×             |
| 03) Tail gate rubber                  | 2W1         | \$ 250.80          | ✓             |
| 04) Tail gate inner garnish           | 11          | \$ 850.00          | ×             |
| 05) Rear windscreen moulding          | ner         | \$ 150.20          | ✓             |
| 06) Citroen logo                      | ner 90      | \$ 120.00          | ✓             |
| 07) Citroen emblem                    | ner 80      | \$ 100.00          | ✓             |
| 08) c4 emblem                         | ner 81      | \$ 110.00          | ✓             |
| 09) Picasso emblem                    | ner 95      | \$ 110.00          | ✓             |
| 10) Rear bumper                       | DD          | \$ 1,350.00        | ✓             |
| 11) Rear bumper reinforcement         | Ref 615     | \$ 850.00          | ✓             |
| 12) Rear bumper lower lamp lh         | one         | \$ 220.50          | ✓             |
| 13) Rear bumper garnish lh            | DD 320      | \$ 360.00          | ✓             |
| 14) Rear bumper bracket @\$80.00 x 2  | 11          | \$ 160.00          | ×             |
| 15) Rear bumper retainer \$120.50 x 2 | one 90      | \$ 241.00          | ✓             |
| 16) Rear bumper clips                 | ner 50      | \$ 80.00           | ✓             |
| 17) Rear panel                        | DD 980      | \$ 1,500.00        | ✓             |
| 18) Tail lamp assy lh                 | 11          | \$ 1,100.00        | ×             |
|                                       |             | \$ 10,753.30       |               |
|                                       |             | Less 10%           | \$ (1,075.33) |
|                                       |             | <b>\$ 9,677.97</b> |               |

**S/Nett**

|                                     |                           |                    |         |
|-------------------------------------|---------------------------|--------------------|---------|
| 18ef 19) Reverse sensor             | <del>4x\$250</del> should | \$ 1,000.00        | 250 s.w |
| 20) Rear number plate with casing   | 11                        | \$ 75.00           | ×       |
| 21) Rear windscreen sealant & clips | ner                       | \$ 60.00           | 40      |
|                                     |                           | <b>\$ 1,135.00</b> |         |

7-6365  
 102  
 542081



**Tel : 94513429**

Attn: Motor Claims Department

DOA : 06.05.2019

- 22) To check wiring
- 23) to dismantle & refix reverse sensor
- 24) To apply anti rust
- 25) To dismantle upholstery etc
- 26) To dismantle and refix rear windscreen glass
- 27) To knock out dents on affected areas and renew parts
- 28) To putty & respray painting

|    |                 |      |
|----|-----------------|------|
| \$ | 120.00          | 30   |
| \$ | 80.00           | 50   |
| \$ | 100.00          | 60   |
| \$ | 100.00          | 80   |
| \$ | 140.00          | 120  |
| \$ | 1,200.00        | 800  |
| \$ | 1,400.00        | 1000 |
| \$ | <u>3,140.00</u> |      |

|             |              |
|-------------|--------------|
| Grand Total | \$ 13,952.97 |
|-------------|--------------|

FOR JA AUTOCARE PTE LTD

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                            |                             |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                         |                                                                                            | Ref : CS/FCI19008019/Uvd3n2 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                            | Date : 28-05-2019           |  |  |
|                                                                                                                                                                                        |                                                                                            | Code : FCI2                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                            |                             |                                                                                     |  |
| Insured Veh.                                                                                                                                                                           | SHB 6610U                                                                                  | Veh. Inspected              | SLJ 6209G                                                                           |  |
| Policy No.                                                                                                                                                                             |                                                                                            | Coverage (\$)               | 0.00                                                                                |  |
| Claim No.                                                                                                                                                                              | D19002961MFSH                                                                              | Excess (\$)                 | 0.00                                                                                |  |
| Assign From                                                                                                                                                                            | MAY CHUA                                                                                   | Assign Date                 | 07/05/2019                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                            |                             |                                                                                     |  |
| Make & Model                                                                                                                                                                           | CITROEN GRAND C4<br>PICASSO (A)                                                            | c.c                         | 1598                                                                                |  |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                     | Year of Reg.                | 2013                                                                                |  |
| Chassis No.                                                                                                                                                                            | VF7UA5FV8CJ795130                                                                          | Colour                      | WHITE                                                                               |  |
| Odometer                                                                                                                                                                               | 89654                                                                                      | Steering                    | IN ORDER                                                                            |  |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                   | Modification                | SPORTS RIM                                                                          |  |
| General                                                                                                                                                                                | GOOD                                                                                       |                             |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                            |                             |                                                                                     |  |
|                                                                                                                                                                                        | Size                                                                                       | Make                        | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                                                                         | 215/50 R17                                                                                 | YOKOHAMA                    | 6 mm                                                                                |  |
| L/H Front Tyre                                                                                                                                                                         | 215/50 R17                                                                                 | YOKOHAMA                    | 6 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                                                                          | 215/50 R17                                                                                 | YOKOHAMA                    | 6 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                                                                          | 215/50 R17                                                                                 | YOKOHAMA                    | 6 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                            |                             |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                         |                                                                                            |                             |                                                                                     |  |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                            |                             |                                                                                     |  |
| Accident Date                                                                                                                                                                          | 06/05/2019                                                                                 | Inspection Date             | 13/05/2019                                                                          |  |
| Survey held at                                                                                                                                                                         | JA AUTOCARE PTE LTD<br>8 KAKI BUKIT AVE 4<br>#02-37 PREMIER@KAKI BUKIT<br>SINGAPORE 415875 |                             |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                            |                             |                                                                                     |  |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                            |                             |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                            |                             |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                            | <b>5 Working Days</b>       |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6209G

| Qty                                | Description of Parts                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--------------------------------------|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                      |               |                           |                   |
| 1                                  | TAIL GATE                            | DENTED / BENT | 2,850.00                  | 1,980.00          |
| 1                                  | TAIL GATE CENTRE GARNISH             | NOT NECESSARY | 350.80                    | -                 |
| 1                                  | TAIL GATE RUBBER                     | TWISTED       | 250.80                    | 250.80            |
| 1                                  | TAIL GATE INNER GARNISH              | NOT NECESSARY | 850.00                    | -                 |
| 1                                  | REAR WINDSCREEN MOULDING             | NECESSARY     | 150.20                    | 150.20            |
| 1                                  | CITROEN LOGO                         | NECESSARY     | 120.00                    | 90.00             |
| 1                                  | CITROEN EMBLEM                       | NECESSARY     | 100.00                    | 80.00             |
| 1                                  | C4 EMBLEM                            | NECESSARY     | 110.00                    | 85.00             |
| 1                                  | PICASSO EMBLEM                       | NECESSARY     | 110.00                    | 95.00             |
| 1                                  | REAR BUMPER                          | DISTORTED     | 1,350.00                  | 1,350.00          |
| 1                                  | REAR BUMPER REINFORCEMENT            | BENT          | 850.00                    | 615.00            |
| 1                                  | REAR BUMPER LOWER LAMP LH            | CRACKED       | 220.50                    | 220.50            |
| 1                                  | REAR BUMPER GARNISH LH               | DISTORTED     | 360.00                    | 320.00            |
| 2                                  | REAR BUMPER BRACKET @\$80.00         | NOT NECESSARY | 160.00                    | -                 |
| 2                                  | REAR BUMPER RETAINER @\$120.50       | N/S CRACKED   | 241.00                    | 90.00             |
| 1                                  | REAR BUMPER CLIPS                    | NECESSARY     | 80.00                     | 50.00             |
| 1                                  | REAR PANEL                           | DENTED        | 1,500.00                  | 980.00            |
| 1                                  | TAIL LAMP ASSY LH                    | NOT NECESSARY | 1,100.00                  | -                 |
|                                    | LESS 10% DISCOUNT                    |               | -1,075.33                 | -635.65           |
|                                    |                                      |               | 9,677.97                  | 5,720.85          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                      |               |                           |                   |
| 1                                  | SET REVERSE SENSOR (SN)              | SHORTED       | 1,000.00                  | 250.00            |
| 1                                  | REAR NUMBER PLATE WITH CASING (SN)   | NOT NECESSARY | 75.00                     | -                 |
| 1                                  | REAR WINDSCREEN SEALANT (SN)         | NECESSARY     | 60.00                     | 40.00             |
|                                    |                                      |               | 1,135.00                  | 290.00            |
| <b><u>LABOUR</u></b>               |                                      |               |                           |                   |
|                                    | TO CHECK WIRING.                     |               | 120.00                    | 30.00             |
|                                    | TO DISMANTLE & REFIX REVERSE SENSOR. |               | 80.00                     | 50.00             |
|                                    | TO APPLY ANTI RUST.                  |               | 100.00                    | 60.00             |
|                                    | TO DISMANTLE UPHOLSTERY ETC.         |               | 100.00                    | 80.00             |

Report Ref No. CS/FCI19008019/Uvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                  | Description of Parts                                  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|-------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                      | TO DISMANTLE AND REFIX REAR WINDSCREEN GLASS.         |           | 140.00                    | 120.00            |
|                                                                      | TO KNOCK OUT DENTS ON AFFECTED AREAS AND RENEW PARTS. |           | 1,200.00                  | 800.00            |
|                                                                      | TO PUTTY & RESPRAY PAINTING.                          |           | 1,400.00                  | 1,000.00          |
|                                                                      |                                                       |           | 3,140.00                  | 2,140.00          |
| GRAND TOTAL                                                          |                                                       |           | 13,952.97                 | 8,150.85          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                       |           |                           | 6,500.00          |

Report Ref No. CS/FCI19008019/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.