

(08/11/19)

Surveyor *Frank*

REF:

*8047 / 141**43502*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SJZ 7846A*at Workshop m/s *CYCLE & CARRIAGE*of *188, PANGKUN LOOP*Insured: *AXA*

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *49K*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

*SJZ 7846A*Yr Regn: *2010 / DEC*Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES Benz 8250CH1 C.C. : 1796

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading:

79825

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2120 472A 343578

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/05/19

D.O.I.

10/06/19

Survey held at

C8C (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4350Z
Vehicle Details	
Vehicle No.:	SJZ7846A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	27186030149047
Chassis No.:	WDD2120472A343578
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$59,522.00
Original Registration Date:	28 Dec 2010
First Registration Date:	28 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$59,522.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2020
PARF Rebate Amount:	\$32,737.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$62,502.00
COE Rebate Amount:	\$9,644.00
Total Rebate Amount:	\$42,381.00

The information contained herein is correct as at 11 Jun 2019

OK

49,000
 42,381
 6619