

Date: 07.05.2019

AXA INSURANCE
8 SHENTON WAY, #24-01 AXA TOWER
SINGAPORE 068811
TEL: 6880 4888
Attn: Motorcycle Claims Dept (Third-party Claim)

Our Client: FBN4498Z APRILIA RX125
Your Insured: FBH299P
Accident on PIE (11KM)

Estimate repair for the above mentioned motor-cycle:

Original Parts:

NO	QTY	DESCRIPTION	PRICE
1	1 PC	HEADLIGHT ASSY / <i>SCR.</i>	\$ 400.00
2	1 PC	METER / <i>SCR.</i>	\$ 350.00
3	1 PC	COWLING / <i>mis.</i>	\$ 380.00
4	1 PC	INNER COWLING / <i>cut.</i>	\$ 280.00
5	1 PC	MUDGUARD / <i>CRA</i>	\$ 250.00
6	1 PC	SIGNAL RH FRONT / <i>x NN</i>	\$ 130.00 x
7	1 PC	BRAKE PUMP ASSY RH / <i>cut.</i>	\$ 550.00
8	1 PC	BRAKE LEVER / <i>br.</i>	\$ 130.00
9	1 PC	THROTTLE ASSY / <i>cut.</i>	\$ 460.00
10	1 PC	HANDLEBAR	\$ 410.00
11	1 PC	HANDLE GRIP	\$ 80.00
12	1 PC	COVER RH / <i>cut.</i>	\$ 380.00
13	1 PC	DECAL RH / <i>cut.</i>	\$ 280.00
14	1 PC	FOOTREST RH / <i>cut.</i>	\$ 160.00
15	1 PC	BRAKE PEDAL / <i>cut.</i>	\$ 140.00
16	1 PC	PILLION FOOTREST / <i>cut.</i>	\$ 90.00
17	1 PC	PILLION FOOTREST BRACKET / <i>cut.</i>	\$ 260.00
18	1 PC	EXHUAUST / <i>cut.</i>	\$ 700.00
19	1 PC	SIGNAL RH REAR / <i>cut.</i>	\$ 130.00
20	1 SET	MIRROR / <i>cut.</i>	\$ 230.00
21	1 PC	COVER LH / <i>CRA</i>	\$ 370.00
22	1 PC	DECAL LH / <i>CRA</i>	\$ 280.00
23	1 PC	GEAR PEDAL / <i>BT.</i>	\$ 160.00
Sub-Total			\$ 4,080.00
less 10% discount			\$ 408.00
			\$ 3,672.00

Nett Prices Parts:

24	NUMBER PLATE / <i>mis.</i>	\$ 50.00	20.
25	LABOUR	\$ 550.00	220
		\$ 4,272.00	240
add 7% GST		\$ 299.04	
Grand Total		\$ 4,571.04	3795

Please contact CK / Ahmad before sending surveyor to our workshop to assess the damages.

Thank You.

From
CK
Looi's Motor Enterprise Pte Ltd
E-Mail: loois@singnet.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Please Acknowledge Received:
Signature: _____
Date: _____

2 Days.
part by part.
After repair photos.
Emo Qian (LKK)
82880282
08/5/19.

6600
11%
8940