

00000000

ASS. REC. BY:

REF: CS3/MSG19005497/Rlyd3⁰²

al instruction:

SUBV/OT
Merimun

Rasa

ASSIGNMENT (Office)

From (Person): Monica chong Pizhen of MS19

Date/Time: 06/05/2019

Estimated Cost: Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No. SK961986

Insured: SGV 4578A

at Workshop n/o: Hong San Hong Wei

Tel: 91091660 / 62708936

of BIK 1002 Bukit Merah Lane 3 # 01-85

Policy No. A80405609QMY

Claim No: 583165

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20.1.2019

CA / REV / REP. / REV 24 HRS

"WP"


Date/Time: 28.3.19 9.

Person Contacted: Sam

H.O.D. Endorsement:

Vehicle (IN) OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|---|
| | SGV 4578A - X |
| | SGV 4578A - AA/MSG19005497/24 D.O.A. - 20/01/2019 |
| | Dismantle. 27/3/2019 |



15/5/2019

Do Not Finalise

15/5/19 Submit LS \$1900, (Red 400, 1790), 3 days

RECEIVED 10 MAY 2019


Surveyor: Kame

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKG 61986
 at Workshop m/s: HONG SAN HONG WEL
 of: 1002, BUKIT. MERAH LN 3# 01-85
 Insured: MS14
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition) 2pm - 4pm
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKG 61986 Yr Regn: Sep / 12
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: VOLVO S80 C.C: 1596
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 184650 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YU1AS48H B01165724
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Mod: Nil / ☒ STD A/Rim or
 Tyre Size: F: 225/50ZR17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho

| Front | Rear |
|-----------------------|-----------------------|
| R/Bal. <u>6</u> mm | R/Bal. <u>6</u> mm |
| L/Bal. <u>6</u> mm | L/Bal. <u>6</u> mm |
| D.O.A. <u>28/1/19</u> | D.O.I. <u>28/6/19</u> |

Survey held at: HONG SAN HONG WEL

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
N/S here

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: Estimated repair range \$3,000 - \$4,000

Kumho
29/3/2019.

Date/Time, File Pass 517 ☐ : Proff. Report
☐ : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

| | |
|-----------------|-----|
| Survey Fee: | 120 |
| Transportation: | |
| Photo: | |
| Others: | 10 |
| TOTAL: | 130 |

Report Format: PRE
 Lump Sum / I.B.E: (\$)

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Monday, 6 May 2019 6:02 PM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto); assignments
Subject: Report Send Back Alerts - SKG6198G (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report-CS3/MSG19005497/R1CD3E2

| | | | |
|----------------------|------------------------------|---|----------------------------|
| 06 May 2019 09:26 | Ins Send Back Adj Rpt | Paper adjustment (2 accident reports, repair bill, TP survey report & photos, insured's scene photos) | [I] Monica Chur Zhen |
| 06 May 2019 09:26 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2019/05/08. | [I] Merimen Administration |
| 06 May 2019 09:26 | Adj Mandate Set | Maintained. | [I] Merimen Administration |

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Monday, 6 May 2019 9:40 AM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SKG6198G (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,

The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

红山鸿伟私人有限公司 
HONG SAN HONG WEI PTE LTD

Block 1002, Bukit Merah Lane 3, #01 - 85, Singapore 159719. H/P : 9109 1660

Tel & Fax : 6270 8936 Email: hshw85@yahoo.com

15 April 2019

LOH YAU HOW

C/O Block 1001 Bukit Merah Lane 3

#01-55 / #01 - 85 Singapore 159718

FINAL REPAIR BILL FOR VEHICLE NO. SKG 6198 G

Lump Sum Repair \$2,300.00Nett

PRECISION APPRAISAL SERVICES



Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

To:

LOH YAU HOW

C/O Block 1001 Bukit Merah Lane 3

#01-55 / #01 - 85 Singapore 159718

Invoice No.: 190402

DATE : 15 April 2019

| <u>DESCRIPTION</u> | | | AMOUNT |
|--------------------------|--|---------------|-----------------|
| Vehicle Registration No. | : SKG 6198 G | | |
| Type of Claims | : Third Party Claims | | |
| Our Reference No. | : PAS/HSHW/190402/TP | | |
| Your Reference No. | : - | | |
| Inspection Report Fees | : (including transportation charges & photographs) | | \$520.00 |
| Reinspection Report Fees | : - | | |
| Transportation Charges | : - | | |
| Additional Photographs | : - | | |
| Others (Specify) | : - | | |
| DOLLARS | FIVE HUNDRED AND TWENTY ONLY | TOTAL: | \$520.00 |



PRECISION APPRAISAL SERVICE

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

327 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

LOH YAU HOW

**C/O Block 1001 Bukit Merah Lane 3
#01-55 / #01 - 85 Singapore 159718**

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 20 January 2019
Assignment Date : 26 March 2019
Inspection Date : 26 March 2019
Our Reference No. : PAS/HSHW/190402/TP

Inspection Report Date : 15 April 2019

Workshop Name :

HONG SAN HONG WEI PTE LTD

Inspection Address :

Block 1001 Bukit Merah Lane 3

#01-55 / #01 - 85 Singapore 159718

PARTICULARS OF VEHICLE

| | | | | |
|-------------------|--|-------------------|----------|------|
| Registration No. | : SKG 6198 G | Mileage | : 184650 | Km/h |
| Make/Model | : VOLVO S80 T4 1.6 AT ABS D/AB 2WD 4DR TURBO | Radio/Casette | : Fitted | |
| Yr of Manuf/Regn | : 2012 | CD Disc Player | : Fitted | |
| Carrying Capacity | : 4Seater | Air Conditioner | : Fitted | |
| Chassis No. | : YV1A548HBD1165724 | Clock | : Fitted | |
| Engine No. | : B4164T4121329 | Seat Belt | : Fitted | |
| Colour | : Metallic Grey | Wing Mirror Other | : Fitted | |
| Class | : Passenger (Private) | Accessories | : Fitted | |

E-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -
Wreck Value (Parf) : -

TYRE SIZE & CONDITION

| | | | | | |
|----------------|--------------|------|----------------|--------------|------|
| Front N/s Size | : 225/50ZR17 | 80 % | Front O/s Size | : 225/50ZR17 | 80 % |
| Make | : KUMHO | | Make | : KUMHO | |
| Rear N/s size | : 225/50ZR17 | 80 % | Rear O/s Size | : 225/50ZR17 | 80 % |
| Make | : KUMHO | | Make | : KUMHO | |
| Spare Size | : 225/50ZR17 | 80 % | Spare Size | | |
| Make | : KUMHO | | Make | | |

Jack & Tools : Intact/Missing


Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its Rear N/s Portion. (see Diagram D)

**GENERAL DESCRIPTION OF DAMAGES**

Parts damaged were :

The rear bumper and lower spoiler were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 26/03/2019 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Hong San Hong Wei Pte Ltd as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$ 2,300.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

| | Repairer's | | Our | |
|---------------------|------------|--------|---------|--------|
| | Estimate | Amount | Revised | Amount |
| Spares Parts | 2901 | 70 | 1846 | 53 |
| Towing Charges | X | X | X | X |
| PB Labour Charges | 600 | 00 | 480 | 00 |
| Others Misc Charges | 200 | 00 | 130 | 00 |
| Paintwork | 600 | 00 | 400 | 00 |
| Total | \$ 4301 | 70 | \$ 2856 | 53 |

Under normal circumstances, the duration of repairs should not exceed Three (03) days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) & Public Holidays waiting time frame.

Attached photographs taken during inspection Twenty - Six (26) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 28/03/2019, we examined the extent of damages
3. On 01/04/2019, we examined the repaired vehicle.

Yours Faithfully,




T F NG PHILIP FOO
ACII CAE, AMIMI
AIAME, AMSAE-A
 Licensed Appraiser/Adjuster

VEHICLE REGN NO : SKG 6198 G
 OUR REFERENCE : PAS/HSHW/190402/TP
 INSPECTION REPORT DATE : 15-Apr-19

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO : 1

| S/No | Qty | Parts / Labour Descriptions | Remarks / Condition | Repairer's Estimate Amount \$ cts | Recommendation / Revised Amount \$ cts |
|-------------------|-------|---|---------------------|--------------------------------------|---|
| | | <u>PARTS SUPPLY - LIST ITEMS</u> | | | |
| 1 | 1pc | Rear bumper | Badly dented | 1254.00 | 1254.00 |
| 2 | 1pc | Rear bumper bracket n/s | Bent | 85.70 | 85.70 |
| 3 | 10pcs | Rear bumper clip@\$5 | Necessary | 50.00 | 50.00 |
| 4 | 2pcs | Rear bumper sensor@\$154 | Dented/Jammed | 308.00 | 308.00 X |
| 5 | 1pc | N/s Taillamp | Cracked | 354.00 | 354.00 |
| | | | 1743.70 | 2051.70 | 2051.70 |
| | | | 10% | - | 205.17 |
| | | Less:10% discount | 1569.33 | 2051.70 | 1846.53 |
| | | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | 1pc | Rear bumper lower spoiler | Defaced | 850.00 | Repair |
| | | Total spare parts | | 2901.70 | 1846.53 |
| | | <u>LABOUR & MISC. CHARGES</u> | | | |
| 1 | | Remove the necessary affected parts, | 1569.33 | | |
| | | straighten rear panel and replace parts | 830.00 | 600.00 | 300 480.00 |
| 2 | | Putty and spraypaint | 2399.33 | | |
| | | (include rear bumper and spoiler) | 20% | 600.00 | 400.00 |
| 3 | | Check electrical | 1919.46 | 50.00 | 40.00 |
| 4 | | Remove and refit rear bumper sensors | 43.1,900 | 100.00 | 60.00 |
| 5 | | Rewire rear portion | | 50.00 | 30.00 |
| | | Note:Recommended lump sum | 3 days | | 830 |
| | | repair at \$2,300.00nett | | | |
| SUB / GRAND TOTAL | | | | 4301.70 | 2856.53 |

PRECISION APPRAISAL SERVICES

[Signature]

C

C











SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------------------------|
| Date Of Report | 20/01/2019 16:29 |
| Date Of Accident | 20/01/2019 13:30 |
| Exact Location Of Accident | PIE TOWARD TUAS 2KM BEFORE PIE/BKE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKG6198G |
| Insured/Policyholder | |
| Name Of Registered Owner | LOH YAU HOW |
| NRIC No | S1655725J |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-91998860 |
| Alternative Phone No | OFFICE-91998860 |

Vehicle Particulars

| | |
|--|--------------------------------------|
| Manufacturer | VOLVO |
| Model | S80 T4 1.6 AT ABS D/AB 2WD 4DR TURBO |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------|
| Name of Insurance Company | EQ INSURANCE COMPANY LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPPHQ18-007724 |
| Cover Note Number | |

Driver

| | |
|----------------------|--------------------------|
| Name of Driver | LOH YEEN SHONG |
| NRIC No | S9543218B |
| Date Of Birth | 19/11/1995 |
| Occupation | INDOOR |
| Date Of Driving Pass | 13/01/2015 |
| Driving Experience | 4 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91998860 |
| Fax Number | |
| Contact Number | |
| Email Address | YEENSHONG.REAL@GMAIL.COM |

| | |
|---|----------|
| Address | NIL |
| Postcode | |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | CHILDREN |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | |
| | NAME: : ANGELINE |
| | GENDER: : FEMALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

I SKG6198G was driving along PIE TOWARD TUAS 2KM BEFORE PIE/BKE on the 1st lane with a normal speed. As I was following the traffic ahead suddenly the vehicle in front make a jam brake. So I apply my brake to avoid the contact with the vehicle in front. Suddenly I felt an impact coming from my rear vehicle. I immediately stop my vehicle and get down from my vehicle and discover that the 3rd party SGV4578A had collided onto my rear vehicle. It involved 3 vehicles and the last vehicle registration number SKT996R. I manage to take some photos at the scene and exchange particular with the other party's. There was a traffic police that came to the scene to assist us, no injuries was involved.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-------------------------------|
| Vehicle Registration Number | SGV4578A |
| Vehicle Make/Model/Colour | MITSUBISHI/LANCER 1.6 M/BLACK |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | JIM CHEE XIAN |
| NRIC/Passport Number | S8533872B |
| Contact Number | 97351322 |
| Address | |

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKT996R
Vehicle Make/Model/Colour VOLKSWAGEN/GOLF A7 1.2
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAY JUNYANG
NRIC/Passport Number S8139662J
Contact Number 97990112
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy/liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded to the insurers. If the Gik Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.
- Consent under the Personal Data Protection Act (PDPA)**
 - I understand, acknowledge, agree and consent that:
 - (i) My insurer, my insurer and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (ii) collectively the "Purposes";
 - (iii) all insurers who have insured vehicles involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iv) my Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARI
REPORTING OFFICER
MUHAMMAD SUMARDI BIN
MOHO AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I SKG6198G was driving along PIE TOWARD TUAS 2KM BEFORE PIE/BKE on the 1st lane with a normal speed. As I was following the traffic ahead suddenly the vehicle in front make a jam brake. So I apply my brake to avoid the contact with the vehicle in front. Suddenly I felt an impact coming from my rear vehicle. I immediately stop my vehicle and get down from my vehicle and discover that the 3rd party SGV4578A had collided onto my rear vehicle. It involved 3 vehicles and the last vehicle registration number SKT996R. I manage to take some photos at the scene and exchange particular with the other party's. There was a traffic police that came to the scene to assist us, no injuries was involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

20 January 2019 at 3:58 PM

Date/Time:

20 January 2019 at 3:58 PM

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| | EFFECTIVE DATE |
|--|----------------|
| Class 2 Motor Car< 3000kg with <=7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg | 13 Jan 2015 |

NP 428A

Licence No: 595432188

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------------|
| Date Of Report | 21/01/2019 14:15 |
| Date Of Accident | 20/01/2019 13:20 |
| Exact Location Of Accident | PIE (TUAS) NEAR STEVEN RD EXIT |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SGV4578A |
| Insured/Policyholder | |
| Name Of Registered Owner | JIM CHEE XIAN |
| NRIC No | S8533872B |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97351322 |
| Alternative Phone No | Office-97351322 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | MITSUBISHI |
| Model | LANCER 1.6 M |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | A80405609QMY |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------------|
| Name of Driver | JIM CHEE XIAN (REN ZHIXIAN) |
| NRIC No | S8533872B |
| Date Of Birth | 13/10/1985 |
| Occupation | INDOOR |
| Date Of Driving Pass | 27/03/2007 |
| Driving Experience | 11 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97351322 |

| | |
|---|-----------------------------------|
| Fax Number | |
| Contact Number | OFFICE-97351322 |
| EMail Address | NOEMAIL |
| Address | BLK 142 TECK WHYE LANE #12-283 |
| Postcode | 680142 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - - - |
| Insurance Company of Driver's Own Vehicle | - - - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 4 |
| Passenger 1 | Name: : TIFFANY KWA Gender: : Female |
| Passenger 2 | Name: : JIM HOCK SWEE Gender: : Male |
| Passenger 3 | Name: : ANG PHUAY TIANG Gender: : Female |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG THE STATED VENUE AS FRONT VEHICLE WAS IN STATIONARY POSITION. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION. AFTER AN IMPACT, MY VEHICLE MOVED FORWARD AND HIT ONTO VEHICLE C REAR PORTION.

Attachment(s)

| | |
|---|---------------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | VIDEO FOOTAGE WITH DRIVER |
| Was there any audio recorded? | NO |

| | |
|-------------------------------------|----------------------|
| Vehicle Registration Number | SKT996R |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | TAY JUNYANG |
| NRIC/Passport Number | S8139662J |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | 2 |
| Passenger 1 | Name: : Gender: : |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-------------------------------------|----------------|
| Vehicle Registration Number | SKG6198G |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | LOH YEEN SHONG |
| NRIC/Passport Number | S9543218B |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

| | |
|---|-----------------------------|
| Name | JIM CHEE XIAN (REN ZHIXIAN) |
| Approximate Age | |
| Injuries Sustain | BODY |
| Injured person in which vehicle? | SGV4578A |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | |
| Postcode | |

DETAILS OF INJURED PERSON 2

| | |
|---|-------------|
| Name | TIFFANY KWA |
| Approximate Age | |
| Injuries Sustain | BODY |
| Injured person in which vehicle? | SGV4578A |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | |
| Postcode | |

DETAILS OF INJURED PERSON 3

| | |
|---|---------------|
| Name | JIM HOCK SWEE |
| Approximate Age | |
| Injuries Sustain | BODY |
| Injured person in which vehicle? | SGV4578A |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | |
| Postcode | |

DETAILS OF INJURED PERSON 4

| | |
|---|-----------------|
| Name | ANG PHUAY TIANG |
| Approximate Age | |
| Injuries Sustain | BODY |
| Injured person in which vehicle? | SGV4578A |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | |
| Postcode | |

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

SKETCH PLAN

Sketch plan showing a road layout with dashed lines. A vehicle labeled 'A' with license plate '36VU52EA' is positioned on the right side of the road. A vehicle labeled 'C' with license plate 'JRG0926' is positioned on the left side of the road. A vertical line is labeled 'C' and 'A'.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Describe the circumstances of the accident in the space provided below. The area is divided into sections by horizontal lines. A diagonal line is drawn across the middle section.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

| | | |
|---|--|--|
| <p>Policyholder's Signature</p> <p>Date & Time:</p> | <p>Driver's Signature</p> <p>(if driver is not the policyholder)</p> <p>Date & Time:</p> | <p>Reporting Centre Personnel's Signature</p> <p>Name:</p> <p>NRIC/PIN No:</p> |
|---|--|--|

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)


























| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 20 Jan 2019 | | 27 Mar 2019 17:32 Edit Adj Rpt | S\$1,900.00 Edit Estimates | S\$1,900.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | JIM CHEE XIAN , ID: S8533872B | | | | | | | | |
| Main Claimant: | LOH YAU HOW , ID: S16557253 | | | | | | | | |
| Vehicle Reg. No.: | SKG6198G | Date of Loss: | 20/01/2019 13:00 - :59 [75 Months and 26 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 583165 | Policy/Cover Note No.: | A80405609QMY (Comprehensive) Coverage: 15/06/2016 - 14/06/2019 | | | | | | |
| Vehicle Reg. No. (Insured): | SGV4578A | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Hong San Hong Wei Pte Ltd (HQ) Blk 1002 Bukit Merah Lane 3 #01-85, 159719 Bukit Merah - Tel: 91091660 / 62708936 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/05/2019] | | | | | | | | |
| Driver/Custodian (Insured): | JIM CHEE XIAN (33 / Male) , NRIC: S8533872B Email: | | | | | | | | |
| Adj Asg. Remarks: | LIAB 100% SJE DISAGREE APPOINT LKK. pls contact: Mr Sam (h/p: 9109 1660). On WP. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> MSIG_SG (06/05/2019): Report Send Back Alerts - SKG6198G (TP) | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SKG6198G (583165)
[SGV4578A]
TP
LOH YAU HOW
Jan 20 2019 1:00PM
[JIM CHEE XIAN]
Hong San Hong Wei Pte Ltd

| Upload Documents Upload Photos Compose New Letter | | | View <input type="button" value="View in Browser"/> | |
|---|-----------------|---|---|-------------------------------------|
| Video | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 28/02/19 15:10 | Video - Accident from last vehicle SKT996R | Load MP4 | <input type="checkbox"/> |
| 2 | 04/03/19 15:06 | SKG6198G video | Load MP4 | <input type="checkbox"/> |
| 3 | 04/03/19 15:06 | SKT996R Rear View video | Load MP4 | <input type="checkbox"/> |
| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 22/02/19 16:54 | Accident Statement From: SC - Reg. No: SGV4578A, Claimant: JIM CHEE XIAN | Load HTM | <input type="checkbox"/> |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 02/04/19 16:33 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 02/04/19 16:33 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 02/04/19 16:33 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 02/04/19 16:33 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 02/04/19 16:33 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 02/04/19 16:33 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 02/04/19 16:33 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 29 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 02/04/19 16:33 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 22/02/19 16:54 | TP SKG6198G E-REPORT <small>From: SC - Reg. No: SGV4578A, Claimant: LIM CHEE XIAN</small> |  Load PDF | |
| 2 | 04/03/19 09:25 | SKT996R |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 04/03/19 09:25 | SKT996R 2 |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 04/03/19 09:25 | SGV4578A_1 |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 04/03/19 09:25 | SKG6198G |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 04/03/19 09:25 | SKG6198G 1 |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 27/03/19 11:13 | SJE DISAGREE APPOINT LKK |  Load PDF | |
| 8 | 27/03/19 11:13 | PRI NOTICE |  Load PDF | |
| 9 | 27/03/19 11:13 | WOKSHOP DETAILS |  Load PDF | |
| 10 | 27/03/19 11:13 | surveyor listing from lawyer |  Load PDF | |
| 11 | 06/05/19 09:24 | SURVEY PHOTOS |  Load PDF | |
| 12 | 06/05/19 09:24 | REPAIR BILL, SURVEY REPORT |  Load PDF | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 16/05/19 16:08 | Colour Photo |  Load PDF | |
| 2 | 16/05/19 16:08 | PRS Invoice |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005497/R1VD3E2
Date: 16/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A80405609QMY
Claimant Vehicle No: SKG6198G Insured Vehicle No: SGV4578A
Date of Loss: 20/01/2019 Nature of Claim: TP Claim No: 583165

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG6198G Engine No: B4164T4121329
Make & Model: VOLVO S80, 3.2 (A) Chassis No: YV1AS48HBD1165724
Reg. Date: 25/09/2012 (Man. Year: 2012) Odometer: 184650 km
Colour: Grey
Engine Capacity: 1596 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R17 Rear Tyre Size: 225/50Z R17
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 2,901.70 | 1,569.33 | 1,332.37 | 45.92 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,400.00 | 800.00 | 600.00 | 42.86 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,301.70 | 2,369.33 | 1,932.37 | 44.92 |
| Approved Total (Overridden) (S\$) | | 1,900.00 | | |
| Nett Amount (S\$) | 4,301.70 | 1,900.00 | 2,401.70 | 55.83 |

INSPECTION

Date of Assignment: 27/03/2019
Date Inspected: 28/03/2019 Inspected At: Hong San Hong Wei Pte Ltd (HQ)
Singapore 159719
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 16 May 2019) |
| Parts: | 143 | VOLVO S80 3.2 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKG6198G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|--------------|------------|--------------|
| 1 | 1 | | *REAR BUMPER | Badly Dented | 1,254.00 F | *1,254.00 FL |
| 2 | 1 | | *REAR BUMPER BRACKET N/S | Bent | 85.70 F | *85.70 FL |
| 3 | 10 | | *REAR BUMPER CLIP | Necessary | 50.00 F | *50.00 FL |
| 4 | 2 | | *REAR BUMPER SENSOR | Serviceable | 308.00 F | *- FL |
| 5 | 1 | | *N/S TAILLAMP | Cracked | 354.00 F | *354.00 FL |
| 6 | 1 | | *REAR BUMPER LOWER SPOILER | Repair | 850.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (S\$) | 2,901.70 | 1,743.70 |
| - List Item Discount on L Items 0.00/10.00% (S\$) | 0.00 | 174.37 |
| Total Parts (S\$) | 2,901.70 | 1,569.33 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN REAR PANEL AND REPLACE PARTS | New | 600.00 | 300.00 |
| 2 | PUTTY AND SPRAYPAINT (INCLUDE REAR BUMPER AND SPOILER) | New | 600.00 | 400.00 |
| 3 | CHECK ELECTRICAL | New | 50.00 | 40.00 |
| 4 | REMOVE AND REFIT REAR BUMPER SENSORS | New | 100.00 | 60.00 |
| 5 | REWIRE REAR PORTION | New | 50.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 1,400.00 | 800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >