

22/03/2002

ASS. REC. BY:

REF: CS/CT1190081001 E yd307

Special Instruction:

Survivor:

Steve

ASSIGNMENT (Office)

From (Person):

ong chin kiat

of

CT1

Date/Time:

8.5.19 14.36p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GW 7868M

Insured:

YM 6583E

at Workshop m/s

Ryder Auto

Tel:

97924673

of

2 Kaki Bukit Ave 2 #02-19

Policy No:

DM CVSN 19152819000

Claim No:

SAM 190202010002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time:

8.5.19 3.10p.m

Person Contacted:

Chan

Vehicle (IN) / OUT

Date/Time

Action/Instruction (✓) Estimate

GW 7868M-X

YM 6583E-X

Steve

REF: CTI

ASSIGNMENT

From: Date: 9.5.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GW7868W

at Workshop m/s Ryder Auto

of 2 Kaki Bukit Ave 2 # 02-19

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GW7868W

Yr Regn: 1/11/03

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar

C.C. 31543

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 355569

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN 1SF4F232 0851186

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195R15C

R:

155/R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GT Radial

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 4/5/19

D.O.I. 9/5/19

Survey held at

Ryder

Des. of Damages: Fr / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 33,009

* finalize \$3750, 4 days (16/5/19)

PV - 13,598

(Red 4562.02, 589)

NV - 19,492

RECEIVED 17 MAY 2019

16/5/2019

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: 4

1)



: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

2)

17/5 - typist

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Transportation

S + RS, SI

Photos

Others

TOTAL

Report Format:

merimen

Lump Sum / I.B.I. (\$

3250/-

Survey Fee:	220
Transportation	
S + RS, SI	
Photos	
Others	
TOTAL	220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019		08 May 2019 14:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MCT RENTALS PTE LTD, Co. Reg. No.: 201800101W		
Main Claimant:	PROMPT ART ENTERPRISE, Co. Reg. No.: 27795100C		
Vehicle Reg. No.:	GW7868M	Date of Loss:	04/05/2019 10:00 - :59 [186 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202010C02	Policy/Cover Note No.:	DMCVSN19152819000 (Comprehensive) Coverage: 01/04/2019 - 31/03/2020
Vehicle Reg. No. (Insured):	YM6583E	Policy No. (Claimant):	Z/19/VC00/10238
		Excess:	S\$0.00
Repairer:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/05/2019]		
Driver/Custodian (Insured):	MURUGAIYAN SARAVANAN (44 / Male) , NRIC: F7974575T Email:		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5100C
Vehicle Details	
Vehicle No.:	GW7868M
Vehicle to be Exported:	No
Intended Deregistration Date:	10 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	2003
Engine No.:	QD32183328
Chassis No.:	JN1SF4F23Z0851186
Maximum Power Output:	-
Open Market Value:	\$20,898.00
Original Registration Date:	01 Nov 2003
First Registration Date:	01 Nov 2003
Transfer Count:	0
Actual ARF Paid:	\$1,045.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,100.00
COE Rebate Amount:	\$13,598.00
Total Rebate Amount:	\$13,598.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 10 May 2019

OK

- Liverpool Football Club - 2018/19 season YNWA
- New housing rules from this Friday
- G vs nonG COE in this current climate

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.98W.P.A \$0 Admin Fees! 10YV
Finance 2 Years Warranty \$1800
Down Monthly From \$488
GV Credit Pte Ltd StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sales

Browse by Category

« Back (1 2 3 4 5) Next »

Sort by Date Posted 20 results/page

94 vehicles

Nissan Cabstar

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Cabstar	Any	Any	Any	Any	Any	Any	Available



Nissan Cabstar (COE till 04/2022)

Fuel Type: Diesel

High Value! Cash Rebate \$10,000 After Usage! Well-Maintained! Good Condition! Ideal For Short Term Business! Free 6 Months Road Tax And Inspection! Call Now For Our Friendly Assistance!

Net Link Partners Pte Ltd

Posted: 04-May-2019

Tags: 2002 Nissan Cabstar, 2002 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$26,800

\$9,010 /yr

05-Apr-2002

3,153 cc

-

Truck

Available



Nissan Cabstar G (COE till 04/2021)

Fuel Type: Diesel

Call Our Friendly Sales Team For Viewing Now. In House Loan Available.

Hui Hua Credit Pte Ltd

Posted: 09-May-2019

Tags: 2006 Nissan Cabstar, 2006 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$16,800

\$8,610 /yr

22-Apr-2006

3,153 cc

-

Truck

Available



Nissan Cabstar G (COE till 07/2021)

Fuel Type: Diesel

Well Maintained, Engine In Tip-Top Condition. Comes With Half Canopy.

Posted: 29-Apr-2019

Tags: 2006 Nissan Cabstar, 2006 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$18,500

\$8,310 /yr

04-Aug-2006

3,153 cc

-

Truck

Available



Nissan Cabstar (COE till 07/2022)

Fuel Type: Diesel

Paintwork In Pristine Condition! Current Owner Under Utilised! One Of The Most Fuss Free 10 Footers! Reliable & Economical! Maintenance Cheap As Well! Call Now & Dont Miss Out On This Workhorse!

Prem Roy Motoring

Posted: 07-May-2019

Tags: 2008 Nissan Cabstar, 2008 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$24,000

\$7,440 /yr

29-Feb-2008

2,953 cc

259,000 km

Truck

Available



The Mitsubishi Outlander is no-frills good

The Mitsubishi Outlander now comes with a 2.0-litre front-wheel drive variant, and is more appealing than ever.

Find out more!



Nissan Cabstar (COE till 08/2022)

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 04-May-2019

Tags: 2008 Nissan Cabstar, 2008 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$21,800

\$6,580 /yr

02-Apr-2008

2,953 cc

-

Truck

Available



Nissan Cabstar (COE till 08/2022)

Fuel Type: Diesel

Engine And Gearbox Superly Taken Care Of, No Other Repair Needed, Paint Can Be Arranged, Call Now, Dont Miss This Beauty.

SG Motor Link Pte Ltd

Posted: 30-Apr-2019

Tags: 2008 Nissan Cabstar, 2008 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$18,800

\$5,680 /yr

28-Apr-2008

2,953 cc

-

Truck

Available



Nissan Cabstar (COE till 05/2023)

Fuel Type: Diesel

Selling Near The Scrap Value Only.

Posted: 26-Apr-2019

Tags: 2008 Nissan Cabstar, 2008 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

\$19,000

\$4,760 /yr

08-May-2008

2,953 cc

-

Truck

Available

Nissan Cabstar (COE till 07/2027)

Fuel Type: Diesel

Worth Buying In Market! Yearly Depreciation Only \$6k! Engine Gearbox Condition Tip Top! New Paintwork! Full Canopy! 2 Weeks Warranty! High Loan

\$55,800

\$6,780 /yr

12-May-2008

2,953 cc

-

Truck

Available

Compare



MSME19058223 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 06/05/2019 15:13
 SUBMITTED BY: Wen Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/05/2019 15:13
 Date Of Accident 04/05/2019 10:45
 Exact Location Of Accident UBI ROAD 3.
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GW7868M
Insured/Policyholder
 Name Of Registered Owner PROMPT ART ENTERPRISE
 Co Reg No 27795100C
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-91924395

Vehicle Particulars

Manufacturer NISSAN
 Model CABSTAR
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number Z/19/VC00/10238
 Cover Note Number

Driver

Name of Driver ISLAM SHAFIQUK
 NRIC No G8422159M
 Date Of Birth 15/05/1988
 Occupation INDOOR
 Date Of Driving Pass 01/03/2016
 Driving Experience 3 YEARS AND 2 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91924395
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address 2 DEFU LANE 10 #02-537 DEFU INDUSTRIAL ESTATE
 Postcode 539183
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG UBI ROAD 3. VEHICLE AHEAD SLOWED DOWN AND STOPPED AT THE T-JUNCTION WAITING TO TURN. I FOLLOWED SUIT. MOMENT LATER WHILE MY VEHICLE WAS STILL STATIONARY, VEHICLE B REAR ENDED MY VEHICLE.

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM6583E
 Vehicle Make/Model/Colour
 Details Of Properties VEH B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG UBI ROAD 3. VEHICLE AHEAD SLOWED DOWN AND STOPPED AT THE T-JUNCTION WAITING TO TURN. I FOLLOWED SUIT. MOMENT LATER WHILE MY VEHICLE WAS STILL STATIONARY, VEH-B REAR-ENDED MY VEHICLE.

DECLARATION

I/ We declare the foregoing particulars are true in every respect.

PROMPTART ENTERPRISE

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC / FIN No.:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) at Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 41792
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Veh #

Date:

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 41792

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

GW7868M Pg 1/1

GW7868M

Model : NISSAN CABSTAR (1/11/2003)

Date Of Accident: 4/5/19 3P : YM6583E (Containing)

Location : UBI ROAD 3

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
<u>List Items</u>					
1 pc	Rear tail-gate / DD			1,920.60	1620 /
	Sub-Total			1,920.60	
	After -30%			1,344.42	1134 /
<u>Special Nett Items</u>					
12 pcs	Rear tail-gate o/s & n/s lock * R (RM) DD			213.60	106.80
1 pc	Rear tail-gate lower panel / DD			492.20	/
3 pcs	Rear tail-gate hinges / DD			192.20	/
1 pc	Rear tail-gate 70 km/h emblem / MEC			25.00	/
1 pc	Rear tail-gate 10 PAX emblem / MEC			25.00	/
2 pcs	Rear o/s & n/s tail-lamp / DR 239 x 1 pc			788.40	478 /
2 pcs	Rear o/s & n/s tail-lamp bracket / DD 65 x 2			293.60	130 /
2 pcs	O/s & n/s tail-gate lock x R			419.40	X
1 pc	O/s tail-gate lower panel / DD			788.40	750 /
2 pcs	O/s & n/s tail-gate hinges x DD NM			640.80	X
2 pcs	O/s & n/s stopper rubber x NM			50.00	X
4 pcs	O/s & n/s tailgate stopper bracket x NM			364.00	X
1 pc	Rear tow hook x NM			345.00	X
1 pc	Rear reverse sensor / DR			280.00	200 /
	Sub-Total			4,917.60	1899.20
<u>Labour</u>					
1	To dismantle, straighten and rewelding.			800.00	450 /
2	To spray painting.			600.00	400 /
3	To remove and replace rear reverse sensor.			50.00	20
4	To weld back railing			50.00	30
5	To re-seal anti-rust.			50.00	30
	Sub-Total			1,550.00	1030
	Total			7,812.02	
	After -20%			6,249.62	

Chan San Choon
Director
DipCE, AAE MIMI, MSAE(Aust)



Authorised Workshop
Authorised Reporting Centre

8778 1999
24 hr accident call

Mobil 1

bizSAFE

Steve (LKK)
881
8322 8813

with Prepaid
4 days
L/S
Rm At spg

8/5/19 11.00 am

4063.20
4/5 - 3250.56
= 3250

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 17 May 2019 7:52 AM
To: 'Ryder Auto workshop'; Steve Chen (LKK Auto); SUR
Subject: RE: GW7868M Finalize

Dear Orson,

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

OIC -Ong Chin Kiat, Ref No: SNM19D202010C02

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Thursday, 16 May 2019 1:36 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: Re: GW7868M Finalize

Dear steve,

We gladly accept your offer, kindly view attached after paint. Please advice who to LOD.

Thank you

Rgds

Orson


Ryder Auto Pte Ltd


2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921
Tel : 67418277 Fax: 67468277

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390

 **BOK SENG**
(heavy vehicles, marine vessels)

 **iW**
Authorized Workshop
Authorized Reporting Centre

 8778 1999
24 hr accident call

Mobil 

 **bizSAFE**

On Fri, May 10, 2019 at 5:41 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Orson,

As per our communication earlier. The above vehicle finalize \$3250 (L/S, before GST). 4 days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Steve Chen (LKK Auto)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Thursday, May 16, 2019 1:36 PM
To: Steve Chen (LKK Auto)
Subject: Re: GW7868M Finalize
Attachments: 99268ce2-dc22-414d-bb89-e4406623013d.jpg; 53f8c554-6c35-4c9f-a41b-0511a53f4016.jpg; cf27cee0-af3f-40af-b225-b179fce6a3d2.jpg


Dear steve,

We gladly accept your offer, kindly view attached after paint. Please advice who to LOD.


Thank you

Rgds

Orson



2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921
Tel : 67418277 Fax: 67468277



5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



On Fri, May 10, 2019 at 5:41 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Orson,

As per our communication earlier. The above vehicle finalize\$3250 (L/S, before GST). 4 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 May 2019		08 May 2019 14:36 Edit Adj Rpt	S\$3,250.00 Edit Estimates	S\$3,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MCT RENTALS PTE LTD , Co. Reg. No.: 201800101W								
Main Claimant:	PROMPT ART ENTERPRISE , Co. Reg. No.: 27795100C								
Vehicle Reg. No.:	GW7868M	Date of Loss:	04/05/2019 10:00 - :59 [186 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202010C02	Policy/Cover Note No.:	DMCVSN19152819000 (Comprehensive) Coverage: 01/04/2019 - 31/03/2020						
Vehicle Reg. No. (Insured):	YM6583E	Policy No. (Claimant):	Z/19/VC00/10238						
		Excess:	S\$0.00						
Repairer:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/05/2019]								
Driver/Custodian (Insured):	MURUGAIYAN SARAVANAN (44 / Male) , NRIC: F7974575T Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GW7868M (SNM19D202010C02)**
[YM6583E]

TP


















PROMPT ART ENTERPRISE

May 4 2019 10:00AM













[MCT RENTALS PTE LTD]

Ryder Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)								Thumbnail	Print	
1	06/05/19 15:47	Accident Statement								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
2	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
3	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
4	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
5	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
6	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
7	10/05/19 08:16	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>	
8	10/05/19 08:16	Chassis Number								Load JPG	<input checked="" type="checkbox"/>	
9	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
10	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
11	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
12	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
13	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
14	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
15	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
16	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
17	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
18	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
19	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
20	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
21	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
22	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
23	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
24	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
25	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
26	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
27	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
28	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
29	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
30	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
31	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
32	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
33	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	
34	10/05/19 08:16	General View								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/05/19 08:16	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/19 13:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/19 13:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/19 13:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/19 14:31	INSURED YM6583E GIA REPORT	 Load PDF	
2	08/05/19 14:35	PRS	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/05/19 15:47	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	06/05/19 15:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/05/19 15:34	Accident Sketch Plan	 Load TIF	
2	06/05/19 15:34	Accident Sketch Plan	 Load TIF	
3	06/05/19 15:34	Accident Sketch Plan	 Load TIF	
4	06/05/19 15:34	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19008100/EVD3E2

Date: 03/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19152819000

Claimant Vehicle
No: GW7868MInsured Vehicle
No: YM6583E

Date of Loss: 04/05/2019

Nature of Claim: TP

Claim
No: SNM19D202010C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GW7868M**

Make & Model: NISSAN CABSTAR, 3.2 D (M)

Engine No: QD32183328

Reg. Date: 01/11/2003 (Man. Year: 2003)

Chassis No: JN1SF4F23Z0851186

Colour: Silver

Odometer: 355569 km

Engine Capacity: 3153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C

Front Left Side: GTRadial 5 mm

Rear Left Side: GTRadial 5 mm

Front Right Side: GTRadial 5 mm

Rear Right Side: GTRadial 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,262.02	3,033.20	3,228.82	51.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,030.00	520.00	33.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,812.02	4,063.20	3,748.82	47.99
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	7,812.02	3,250.00	4,562.02	58.40

INSPECTION

Date of Assignment: 08/05/2019

Date Inspected: 09/05/2019 Inspected At:

 Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @
 Kaki Bukit
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jun 2019)	
Parts:	N/A	NISSAN CABSTAR 3.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW7868M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE	Dented	1,920.60 FL	*1,620.00 FL
2	1		*REAR TAIL-GATE O/S & N/S LOCK	O/S Dented	213.60 FS	*106.80 FS
3	1		*REAR TAIL-GATE LOWER PANEL	Dented	492.20 FS	*492.20 FS
4	1		*REAR TAIL-GATE HINGES (3PCS)	Dented	192.20 FS	*192.20 FS
5	1		*REAR TAIL-GATE 70 KM/H EMBLEM	Necessary	25.00 FS	*25.00 FS
6	1		*REAR TAIL-GATE 10 PAX EMBLEM	Necessary	25.00 FS	*25.00 FS
7	2		*REAR O/S & N/S TAIL-LAMP	Broken	788.40 FS	*478.00 FS
8	2		*REAR O/S & N/S TAIL-LAMP BRACKET	Dented	293.60 FS	*130.00 FS
9	2		*O/S & N/S TAIL-GATE LOCK	Repair	419.40 FS	*- FS
10	2		*O/S & N/S TAIL-GATE HINGES	Not Necessary	640.80 FS	*- FS
11	2		*O/S & N/S STOPPER RUBBER	Not Necessary	50.00 FS	*- FS
12	4		*O/S & N/S TAILGATE STOPPER BRACKET	Not Necessary	364.00 FS	*- FS
13	1		*REAR TOW HOOK	Not Necessary	345.00 FS	*- FS
14	1		*REAR REVERSE SENSOR	Broken	280.00 FS	*200.00 FS
15	1		*O/S TAIL-GATE LOWER PANEL	Dented	788.40 FS	*250.00 FS
					Sub Total (\$\$)	6,838.20 3,519.20
					- List Item Discount on L Items 30.00/30.00% (\$\$)	576.18 486.00
					Total Parts (\$\$)	6,262.02 3,033.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY PAINTING	New	600.00	450.00
2	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	50.00	20.00
3	TO WELD BACK RAILING	New	50.00	30.00
4	TO RE-SEAL ANTI-RUST	New	50.00	30.00
5	TO DISMANTLE, STRAIGHTEN AND REWELDING	New	800.00	500.00
Gross Labour Cost (\$\$)			1,550.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >