

15/12/19

INS. CASE OWNER:

PC

CCU / AXA1900 8108

LKK:

IDAC:

Surveyor:

Rahul

DOI:

ASSIGNMENT

3/6/19

Date / Time:

8/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGV 21957

Name of Insured:

Wong Kai Tow

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

4/5/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: LEE KWAN SIEN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SAMOIMEN/114725

Policy No.:

6A 1709011

Make / Model:

MITSUBISHI

Place of Accident:

MNR WORKING HUMAN & KNE KNO1

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SEF 8215

INSRS:
WSP:
Tel:
Liability:
RMKS:

ck

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

SEF 8215

SGV 21957

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

Rahul

Email ☐ Call ☐

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 9340.00

(10 days)

Reduction: \$7414.00 % 21

FINAL SETTLEMENT

Date/Time: 30/9/19 7:30pm

Confirm with:

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost: (W/CST)

SS 9993.80

Loss of Rental (LOR):

SS 1100.00

(11 days)

X \$100

Loss of Use (LOU):

SS -

(S x days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search:

SS -

Medical:

SS -

Disbursement:

SS -

Legal Cost:

SS -

Total:

SS 11093.80

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 11,093.80

Name 1:

Cycle & Carriage Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#3501-

COPY SENT
27/10/19

(08/11/13)

ASS. REC. BY: John

REF

Asm (AXA)

1-42C

ASSIGNMENT

From:

Date: 3.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 82015at Workshop m/s Cycle & Carriageof 209 Pandan Gardens

Insured:

Policy No.:

Claims No.:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

58K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

100%

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKZ 82015Yr Regn: 2016 / FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI LANCER 1.6A c.c. 1590

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

045232

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRCYLAGU004034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/05/19

D.O.I.

03/06/19

Survey held at

Cycle (PG)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PIP \$9340/- (Red = \$2414.00 / 21.1.)

* 10 repair days + 1 PRS = 11 days.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Cuttilan Tuan Azhari	Cust No/Name /CUTTILAN TUAN AZHARI
BLK 149 BISHAN ST 11	Reg No/Reg Date SKZ8201S*1F / 04/02/201
#09-19	Date In/Mileage / 0
SINGAPORE 570149	Chassis No JMYSRCY1AGU004034
Contact No Mobile: 96645013	Engine No 4A92CG5829
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	07/05/2019/ 16:03	QUE	261 / Edwin Caina	39516			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2750 3300.00
RENEW & RE-ALIGN RR DAMAGED PORTION:								
-RENEW RR BUMPER , BOOTLID & RR END PNL								
-REPAIR RR FLR PNL , RR FENDER LH & RR FENDER RH								2310 2520.00
E PNT98000								
RESPRAY RR BUMPER , RR END PNL , RR FLR PNL , RR FENDER LH ,								120.00
RR FENDER RH & BOOTLID								120.00
E PNT88000								
REMOVE & REFIT BOOTLID COMPONENT								30 50.00
E PNT88000								
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET								200.00
A 54900099								
CHECK WIRING & ELECTRICAL SYSTEM								80 120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								80 100.00
USING HI-SCAN PRO TEST								PM 220.00
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								30 50.00
M SUNDRY								
SUPPLY RR NUMBER PLATE WITH CASING								PM 220.00
E PNT88000								
REMOVE & REFIT REVERSE SENSOR								40.00
M SUNDRY								
SUPPLY REVERSE SENSOR								30 50.00
M SUNDRY								
SUPPLY C&C BADGE								
M SUNDRY								
Sundries					1.00	852.00	00.00	852.00
M FACE, RR BUMPER					1.00	20.00	00.00	20.00
M COVER, RR BUMPER					8.00	2.00	00.00	16.00
M CLIP, ENG ROOM COVER					1.00	17.00	00.00	17.00
M BRKT, R/BMPR FACE SUPT, LH					1.00	17.00	00.00	17.00
M BRKT, R/BMPR FACE SUPT, RH								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Cuttilan Tuan Azhari	Cust No/Name /CUTTILAN TUAN AZHARI
BLK 149 BISHAN ST 11	Reg No/Reg Date SKZ8201S*1F / 04/02/201
#09-19	Date In/Mileage / 0
SINGAPORE 570149	Chassis No JMYSRCY1AGU004034
Contact No Mobile: 96645013	Engine No 4A92CG5829
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	07/05/2019/ 16:03	QUE	261 / Edwin Caina	39516

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REINFORCEMENT,RR BUMPER <i>bt</i>	1.00	231.00	00.00	231.00
M BRACKET,LICENSE PLATE LAMP <i>mis</i>	2.00	13.00	00.00	26.00
M PANEL,TRUNK LID <i>bt</i>	1.00	760.00	00.00	760.00
M HINGE,TRUNK LID,LH <i>? xsuc</i>	1.00	92.00	00.00	92.00
M HINGE,TRUNK LID,RH <i>? xsuc</i>	1.00	92.00	00.00	92.00
M WEATHERSTRIP,TRUNK LID <i>mis</i>	1.00	182.00	00.00	182.00
M GAS SPRING,TRUNK LID <i>? xsuc</i>	2.00	66.00	00.00	132.00
M LATCH,TRUNK LID <i>? xsuc</i>	1.00	74.00	00.00	74.00
M MARK,THREE-DIA <i>ne</i>	1.00	51.00	00.00	51.00
M MARK,LANCER <i>ne</i>	1.00	51.00	00.00	51.00
M PANEL,RR END <i>bt</i>	1.00	556.00	00.00	556.00
M TRIM,TRUNK ROOM RR END <i>at</i>	1.00	164.00	00.00	164.00
M CLIP,RR END TRIM <i>ne</i>	2.00	3.00	00.00	6.00
M LAMP ASSY,COMB,RR LH <i>? xsuc</i>	1.00	365.00	00.00	365.00
M LAMP ASSY,COMB,RR RH <i>? xsuc</i>	1.00	365.00	00.00	365.00
M LAMP ASSY,TAIL,LH <i>? xsuc</i>	1.00	191.00	00.00	191.00
M LAMP ASSY,TAIL,RH <i>? xsuc</i>	1.00	191.00	00.00	191.00
M REFLECTOR LH <i>ca</i>	1.00	36.00	00.00	36.00
M REFLECTOR RH <i>? xsuc</i>	1.00	36.00	00.00	36.00

SURVEYOR NAME:

Rasul - Hp 90010068

SURVEYOR SIGNATURE:

Rasul

DATE:

03/06/19 @ 1630 hrs

REMARKS:

*10 days**Repair before print*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *ca* after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett 11,446.00
7% GST on 11446.00 801.22

Total Payable 12,247.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CC4/Asm19008108/121963 Cecilia

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cuttilan Tuan Azhari	Cust No/Name	/CUTTILAN TUAN AZHARI
C/O AXA INSURANCE PTE LTD	Reg No/Reg Date	SKZ8201S*1F / 04/02/2016
MOTOR CLAIM DEPARTMENT	Date In/Mileage	03/06/2019/ 45232
8 SHENTON WAY #24-01	Chassis/Package	JMYSRCY1AGU004034 /DC15(F)
SINGAPORE 068811	Engine No	4A92CG5829
Contact No	Make/Model	MIT/16MY LANCER EX 1.6 4AT
03/06/	Colour/Trim	D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSA00001	Cash	20/06/2019/ 08:32	TLE	881 / Jojo Cheng	39516		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2750.00
RENEW RR BUMPER , BOOTLID & RR END PANEL							
REPAIR RR FLR PANEL , RR FENDER LH & RR FENDER RH							
E PNT98000							2310.00
SPARY PAINT RR BUMPER, RR END PANEL, RR FLOOR PANEL , RR FENDER LH ,							
RR FENDER RH & BOOTLID							
E PNT88000							120.00
REMOVE & REFIT BOOTLID COMPONENT							
E PNT88000							120.00
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							80.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
E PNT88000							80.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							40.00
SUPPLY C&C BADGE							
M SUNDRY							30.00
SUNDRIES							
S SPECIALISTJOB							80.00
TO SUPPLY FRONT LICENSE PLATE RECTANGUALR & BLACK							
S SPECIALISTJOB							220.00
SUPPLY REVERSE SENSOR MIT EX / D06							
X FACE,RR BUMPER				1.00	852.00	00.00	852.00
X CLIP,ENG ROOM COVER				10.00	2.00	00.00	20.00
X BRKT,R/BMPR FACE SUPT,LH				1.00	17.00	00.00	17.00
X BRKT,R/BMPR FACE SUPT,RH				1.00	17.00	00.00	17.00
X REINFORCEMENT,RR BUMPER				1.00	231.00	00.00	231.00
X BRACKET,LICENSE PLATE LAMP				2.00	13.00	00.00	26.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Cuttilan Tuan Azhari	Cust No/Name /CUTTILAN TUAN AZHARI
C/O AXA INSURANCE PTE LTD	Reg No/Reg Date SKZ8201S*1F / 04/02/2016
MOTOR CLAIM DEPARTMENT	Date In/Mileage 03/06/2019/ 45232
8 SHENTON WAY #24-01	Chassis/Package JMYSRCY1AGU004034 /DC15(F)
SINGAPORE 068811	Engine No 4A92CG5829
Contact No	Make/Model MIT/16MY LANCER EX 1.6 4AT
03/06/	Colour/Trim D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSA00001	Cash	20/06/2019/ 08:32	TLE	881 / Jojo Cheng	39516

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X PANEL,TRUNK LID	1.00	760.00	00.00	✓760.00
X WEATHERSTRIP,TRUNK LID	1.00	182.00	00.00	✓182.00
X MARK,THREE-DIA	1.00	51.00	00.00	✓51.00
X PANEL,RR END	1.00	556.00	00.00	✓556.00
X TRIM,TRUNK ROOM RR END	1.00	164.00	00.00	✓164.00
X CLIP,RR END TRIM	2.00	3.00	00.00	✓6.00
X REFLECTOR LH	1.00	36.00	00.00	✓36.00
X BUZZER,KEYLESS OPERATIO,RR	1.00	170.00	00.00	170.00
X SHIELD,RR WHEELHOUSE,RH	1.00	32.00	00.00	32.00
X REINFORCEMENT,RR BUMPER	1.00	90.00	00.00	90.00
X CLIP,SPLASH SHIELD	4.00	3.00	00.00	12.00
X MARK,LANCER	1.00	*58.00	00.00	✓58.00
Z TEXT				

AXA TP CLAIM SGV2195J

DOA: 04/05/2019

SURVEYOR: RASUL LKK 03/06/2019

SUPP

* Price Change.

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	3,280.00			
Labour	5,610.00			
Standard Menu	0.00	7% GST on	9340.00	9,340.00
Specialist Job	300.00			653.80
Diagnostics Job	0.00			
Sundry/Others	150.00			
Total(w/o GST)	9,340.00		Total Payable	9,993.80

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : AXA INSURANCE SINGAPORE PTE LTD

REGISTRATION NO : SKZ8201S

S/N	Description	Qty	Unit Price	Disc%	Amount
PARTS					
1	BUZZER, KEYLESS OPERATIO, RR <i>con</i>	1.00	170.00	0.00	170.00 ✓
2	SHIELD, RR WHEELHOUSE, RH <i>af</i>	1.00	32.00	0.00	32.00 ✓
3	REINFORCEMENT, RR BUMPER <i>bt</i>	1.00	90.00	0.00	90.00 ✓
4	CLIP, SPLASH SHIELD <i>nu</i>	4.00	3.00	0.00	12.00 ✓
Total					304.00
7 % GST					21.28
Grand Total					325.28

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

Surveyor : Rasul - LKK
 Company : AXA
 DOA : 04/05/2019
 CSE : Edwin
 Date of Survey : 03/06/2019

VEHICLE NO : SKZ8201S
 MODEL : MIT/ 16MY LANCER EX 1.6 4AT
 WIP : 39516

Material	:	\$	3,280.00
Labour	:	\$	6,060.00
Sub-Total	:	\$	9,340.00
Less Excess	:	\$	-
Total	:	\$	9,340.00
GST 7%	:	\$	653.80
Grand Total	:	\$	9,993.80
Finalise By/Date	:	JoJo dtd	20/06/2019

Email : 20/6/19 8:43am

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 10 WORKING DAYS + 4 Days (2) Weekends
 + Days () Public Holiday
 + 1 Survey - 03/06/2019 - Mon
 TOTAL DAYS REPAIR TOOK = 15

☒ TP Claim AXA - SGV2195J

☒ Claim GIA / LTA fee \$ 2.00

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



Service Request Details

Claim

S9M01MEN

Reference

None

Loss Date

4 May 2019

Report Date

6 May 2019 12:00:00 AM

Request Date

8 May 2019

Due Date

15 May 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

person: edwin

T: 11.54a.m

V: Out

E: v

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKZ8201S

Model

LANCER EX-1.6 (A)

Service Address

...

Primary Contact/Insured

WONG KAI TOW

BLK 533 HOUGANG AVENUE 6, #12-347, 530533, Singapore

98335321

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>
Sent: Wednesday, 8 May, 2019 8:52 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Andre Chow En De; Coco Lu Ting; Don Bong Kiong Hua; Tay Jian Ye
Subject: SKZ82015 / SGV2195J TP CLAIM DOA: 04.05.2019
Attachments: [Untitled].pdf

Categories: Raghav


Officer in Charge,

May we check for the liability of accident?

Thank you

Best Regards,

Edwin Caina
Advisor- Customer Service



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • H: +65 91819978 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/09/2019

Survey Details:

Date of loss	4-May-19
Date of appointment	8-May-19
Date of survey	3-Jun-19
Location of survey	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKZ 8201S
Make and Model	MITSUBISHI LANCER EX 1.6 AT LED TAIL LAMP
Date of registration	4/2/2016
Excess	
Market Value	\$58,000
Parf Rebate	\$44,397
Nett Loss	\$13,603

Repair details:

Initial Estimate	\$ 11,446.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,280.00
Check items (estimate)	\$ -
Labour	\$ 6,060.00
Total	\$ 9,340.00
Lump Sum(if applicable)	\$ -

Number of days for repair	10
---------------------------	----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

10 RECOMMENDED REPAIR DAYS + 1 PRS= 11 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 9,993.80	W/GST
Loss of use	\$ -	
Loss of rental	\$ 1,100.00	11days x \$100
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 11,093.80	



<MANDATE IA> -S9M01MEW {ACCIDENT INVOLVING SGV 2195J (OI) & SKZ 8201S (TP) ON 04/05/2019}

Type

Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$11,093.80(CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL / INSTRUCTION. THANKS - CECILIA

Reply



Re:<MANDATE IA> -S9M01MEW {ACCIDENT
INVOLVING SGV 2195J (OI) & SKZ 8201S (TP) ON
04/05/2019}

Type

🔗 Question

Message

Please proceed

Reply

Our ref : SKZ8201S
Your ref : SGV2195J

Date: 03rd September 2019

Ms Joy Irene (Case Handler)
LKK AUTO CONSULTANTS PTE. LTD.
Blk. 51 Paya Ubi Industrial Park
Ubi Avenue 1 #02-25
Singapore 408933

Dear Sir/ Madam,

RE: SUBMISSION OF DOCUMENTS FOR SKZ8201S – DOA: 04/05/2019

Kindly be informed that our customer, Mr Cuttilan Tuan Azhari , owner of vehicle registration no. SKZ8201S (insured with AIG) holds vehicle registration no. SGV2195J which is insured with you at the time of an accident liable and hereby submitting a claim against your insured for the cost incurred.

On behalf of our customer, we provide the following claim for your settlement as below:

Repair Cost	:	\$ 9,993.80	
Loss of Rental/ Use	:	\$ 1,100.00	(\$ 100.00 x 11 days)
Total	:	<u>\$11,093.80</u>	


We are pleased to enclose the documents as set out in the attached checklist.

Please contact Mr. Andre Chow En De at 91449137 or email him at andre.chow@cyclecarriage.com.sg **within 7 working days** from the date of this letter should there be any missing documents or any other additional documents required. If we do not hear from you during these 7 days, we would take it that all documents submitted to you are complete and in order.

Cheque should be make payable to Cycle & Carriage Automotive Pte. Ltd.

We look forward to receiving your early settlement of the invoice(s). Thank you.

Yours faithfully,
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



MANAGER
SERVICE OPERATIONS - PG



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**TAX INVOICE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cuttilan Tuan Azhari C/O AXA INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811 Contact No 03/06/	Cust No/Name	/CUTTILAN TUAN AZHARI
	Reg No/Reg Date	SKZ8201S*1F / 04/02/2016
	Date In/Mileage	03/06/2019/ 45232
	Chassis/Package	JMYSRCY1AGU004034 /DC15(F)
	Engine No	4A92CG5829
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
CSA00001	Cash	02/09/2019/ 09:51	TLE	881 / Jojo Cheng	39516	41441001		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER , BOOTLID & RR END PANEL REPAIR RR FLR PANEL , RR FENDER LH & RR FENDER RH								2750.00
E PNT98000 RESPARY RR BUMPER, RR END PANEL, RR FLOOR PANEL , RR FENDER LH , RR FENDER RH & BOOTLID								2310.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT								120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD,TRIM & CARPET								120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								80.00
M SUNDRY SUPPLY C&C BADGE								40.00
M SUNDRY SUNDRIES								30.00
S SPECIALISTJOB TO SUPPLY FRONT LICENSE PLATE RECTANGUALR & BLACK								80.00
S SPECIALISTJOB SUPPLY REVERSE SENSOR MIT EX / D06								220.00
X	FACE,RR BUMPER				1.00	852.00	00.00	852.00
X	CLIP,ENG ROOM COVER				10.00	2.00	00.00	20.00
X	BRKT,R/BMPR FACE SUPT,LH				1.00	17.00	00.00	17.00
X	BRKT,R/BMPR FACE SUPT,RH				1.00	17.00	00.00	17.00
X	REINFORCEMENT,RR BUMPER				1.00	231.00	00.00	231.00
X	BRACKET,LICENSE PLATE LAMP				2.00	13.00	00.00	26.00

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Cuttilan Tuan Azhari	Cust No/Name /CUTTILAN TUAN AZHARI
C/O AXA INSURANCE PTE LTD	Reg No/Reg Date SKZ8201S*1F / 04/02/2016
MOTOR CLAIM DEPARTMENT	Date In/Mileage 03/06/2019/ 45232
8 SHENTON WAY #24-01	Chassis/Package JMYSRCY1AGU004034 /DC15(F)
SINGAPORE 068811	Engine No 4A92CG5829
Contact No	Make/Model MIT/16MY LANCER EX 1.6 4AT
03/06/	Colour/Trim D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSA00001	Cash	02/09/2019/ 09:51	TLE	881 / Jojo Cheng	39516	41441001

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X PANEL,TRUNK LID	1.00	760.00	00.00	760.00
X WEATHERSTRIP,TRUNK LID	1.00	182.00	00.00	182.00
X MARK,THREE-DIA	1.00	51.00	00.00	51.00
X PANEL,RR END	1.00	556.00	00.00	556.00
X TRIM,TRUNK ROOM RR END	1.00	164.00	00.00	164.00
X CLIP,RR END TRIM	2.00	3.00	00.00	6.00
X REFLECTOR LH	1.00	36.00	00.00	36.00
X BUZZER,KEYLESS OPERATIO,RR	1.00	170.00	00.00	170.00
X SHIELD,RR WHEELHOUSE,RH	1.00	32.00	00.00	32.00
X REINFORCEMENT,RR BUMPER	1.00	90.00	00.00	90.00
X CLIP,SPLASH SHIELD	4.00	3.00	00.00	12.00
X MARK,LANCER	1.00	58.00	00.00	58.00

Z TEXT

AXA TP CLAIM SGV2195J

DOA: 04/05/2019

SURVEYOR: RASUL LKK 03/06/2019

*Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!*

Parts	3,280.00	Nett	9,340.00
Labour	5,610.00	7% GST on 9340.00	653.80
Standard Menu	0.00		
Specialist Job	300.00	Total Payable	9,993.80
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	150.00	Total Due	9,993.80
Total(w/o GST)	9,340.00		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19008108/R1gb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 01-11-2019



ATTN: KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 2195J	Veh. Inspected	SKZ 8201S
Policy No.	GA217090/1	Coverage (\$)	0.00
Claim No.	S9M01MEN	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	08/05/2019

2. Vehicle Particulars & Condition

Make & Model	mitsubishi LANCER 1.6 (A)	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JMYSRCY1AGU004034	Colour	BLUE
Odometer	045232	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/05/2019	Inspection Date	03/06/2019
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8201S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE, RR BUMPER (SN) (CONSISTENT)	DEFORMED	852.00	852.00
1	COVER, RR BUMPER (SN) (CONSISTENT)	BENT	20.00	20.00
8	CLIP, ENG ROOM COVER (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	BRKT, R/BPR FACE SUPT, LH (SN) (CONSISTENT)	NECESSARY	17.00	17.00
1	BRKT, R/BPR FACE SUPT, RH (SN) (CONSISTENT)	NECESSARY	17.00	17.00
1	REINFORCEMENT, RR BUMPER (SN) (CONSISTENT)	BENT	231.00	231.00
2	BRACKET, LICENSE PLATE LAMP (SN) (CONSISTENT)	MISSING	26.00	26.00
1	PANEL, TRUNK LID (SN) (CONSISTENT)	BENT	760.00	760.00
1	HINGE, TRUNK LID, LH (SN) (CONSISTENT)	NOT NECESSARY	92.00	-
1	HINGE, TRUNK LID, RH (SN) (CONSISTENT)	NOT NECESSARY	92.00	-
1	WEATHERSTRIP, TRUNK LID (SN) (CONSISTENT)	NECESSARY	182.00	182.00
2	GAS SPRING, TRUNK LID (SN) (CONSISTENT)	NOT NECESSARY	132.00	-
1	LATCH, TRUNK LID (SN) (CONSISTENT)	NOT NECESSARY	74.00	-
1	MARK, THREE-DIA (SN) (CONSISTENT)	NECESSARY	51.00	51.00
1	MARK, LANCER (SN) (CONSISTENT)	NECESSARY	58.00	58.00
1	PANEL, RR END (SN) (CONSISTENT)	BENT	556.00	556.00
1	TRIM, TRUNK ROOM RR END (SN) (CONSISTENT)	CUT	164.00	164.00
2	CLIP, RR END TRIM (SN) (CONSISTENT)	NECESSARY	6.00	6.00
1	LAMP ASSY, COMB, RR LH (SN) (CONSISTENT)	NOT NECESSARY	365.00	-
1	LAMP ASSY, COMB, RR RH (SN) (CONSISTENT)	NOT NECESSARY	365.00	-
1	LAMP ASSY, TAIL, LH (SN) (CONSISTENT)	NOT NECESSARY	191.00	-
1	LAMP ASSY, TAIL, RH (SN) (CONSISTENT)	NOT NECESSARY	191.00	-
1	REFLECTOR LH (SN) (CONSISTENT)	CRACKED	36.00	36.00
1	REFLECTOR RH (SN) (CONSISTENT)	NOT NECESSARY	36.00	-
1	FRT NUMBER LATE WITH CASING (SN) (CONSISTENT)	BENT	80.00	80.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	220.00	220.00
1	C&C BADGE (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	BUZZER, KEYLESS OPERATION, RR (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	170.00	170.00
1	SHIELD, RR WHEELHOUSE, RH (SN) (CONSISTENT) (ADD	CUT	32.00	32.00

Report Ref No. CC4/ASM19008108/R1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REINFORCEMENT, RR BUMPER (SN) (CONSISTENT) (ADDITIONAL)	BENT	90.00	90.00
4	CLIP, SPLASH SHIELD (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	12.00	12.00
			5,224.00	3,650.00
	LABOUR			
	RENEW & RE-ALIGN RR DAMAGED PORTION: RENEW RR BUMPER, BOOTLID & RR END PNL; REPAIR RR FLR PNL, RR FENDER H & RR FENDER RH.		3,300.00	2,750.00
	RESPRAY RR BUMPER, RR END PNL, RR FLR PNL, RR FENDER LH, RR FENDER RH & BOOTLID.		2,520.00	2,310.00
	REMOVE & REFIT BOOTLID COMPONENT.		120.00	120.00
	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET.		120.00	120.00
	CHECK WIRING & ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST.		200.00	200.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.		120.00	80.00
	REMOVE & REFIT REVERSE SENSOR.		100.00	80.00
			6,530.00	5,690.00
	GRAND TOTAL		11,754.00	9,340.00
RECOMMENDED COST OF REPAIRS				9,340.00

Report Ref No. CC4/ASM19008108/R1gb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.