(08/11/13)
ASS. REC. BY: Rosul

REF Asm (AXA)

1042C

ASSIGNMENT

From: Date: 3.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 8201S

at Workshop m/s cycle & carriage

of 209 Pandan Gardens

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: 58K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp'?

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKZ 8201S Yr Regn: 2016 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MITSUBISHI LANCER 1.6A c.c 1590

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading 045232 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSRCY1AGU0040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	04/05/19	D.O.I.	03/06/19

Survey held at cycle (PG)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)
☐ : Interview ($)
☐ : Tech. Invs ($)
☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:
Transportation: __S + RS, __SI
Photos
Others
TOTAL