

22/03/2002

ASS. REC. BY:

REF: CS/FC2190081191 DS d3er

Special Instruction:

(WS) Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Eileen Lee

of

FC2

Date/Time: 8.5.19 4.05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 7183U

Insured:

SHA 4428Z

at Workshop m/s

SG 98 moto

Tel:

64 524898

of

Bik 4001 Bmr Industrial Park 1 #01-21

Policy No:

Claim No:

D19003022MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5.5.2019

CA / REV / REP. / REV 24 HRS

"W"

10.5.19 After 12.00pm

Date/Time: 8.5.19 4.27pm

Person Contacted:

Rose

H.O.D. Endorsement:

Vehicle IN (OUT)

| Date/Time | Action/Instruction ( ✓ ) Estimate                                    |
|-----------|--|
|           | FBC 7183U - NBA/INC 1900351414 D.O.A 23/02/2019                      |
|           | SHA 4428Z - NS/INC 18015574/ Clubs 2 D.O.A - 24/03/2018              |
| 10/05/19  | @ 17:13 pm revert pending estimate from repairer to Eileen via email |
|           |  |
|           |  |

Surveyor

ASSIGNMENT

COT2 Feb 2023

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 ~~5~~ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh.No:

FBC 71834

Yr Regn: 2008/June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Bajaj Pulsar

C.C

199

Colour

Black

A/C: Insured / Std / NI / NA

Sp.Reading

24271

T/Radio: Insured / Std / NI / NA

Eng/No:

5CGBPM 09037

C/No:

MD2DHJC23PCM06621

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

90 / 90 - 17

R:

120 / 80 - 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

05/05/2019

D.O.I.

10/05/2019

Survey held at

SG 98 AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/3 Body 7 0/3 Paint

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHA, 44282

MV - \$5K

LTA - \$2,615.00

Nett - \$2,385.00

Pending estimate. bilce up abt 4 yrs.

RECEIVED 20 AUG 2019

MV 5K

LTA 2.6K

Nett 2.4K

06/08/2019 - Jnan 2/3 2800/-  
with 4 days 7 yrs.  
(\$1,845.50 Red - 40%)

Date/Time, File Pass to?

20/03/19

1)

Types

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

: S + RS, SI

: Photos

: Others

TOTAL

135

50

58

243

Report Format :

Lump Sum / I.B.I: (\$ 2,800/- 1/5 )

**MOTOR SURVEY ASSIGNMENT**

|                    |  |                               |
|--------------------|--|-------------------------------|
| Date               | 08-05-2019                                   | Our Ref No. D19003022MFSH     |
| Accident Date      | 05-05-2019                                   | Claim Type. Third Party       |
| Insured Vehicle    | SHA4428Z                                     | Third Party Vehicle. FBC7183U |
| Survey Location    | BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 |                               |
| Contact Person.    | LEENA  |                               |
| Contact No.        | 64524898/ 0                                  | Fax No. 64524868              |
| Survey Type        | WITHOUT PREJUDICE: LIABILITY UNCLEAR:        |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                 |                               |
| Contact Person     | NA   | Fax No. 68416315              |
| Contact Number.    | NA   |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                     |                         |
|-------------------|---------------------|-------------------------|
| Cc : Workshop     | SG 98 MOTOR PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                  | TP Solicitor Fax No. NA |
| Officer Incharge  | EILEEN LEE          |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

|   |                   |
|---|-------------------|
| <b>Vehicle Owner Particulars</b>  |                   |
| Owner ID Type:  | Singapore NRIC    |
| Owner ID:   | 5256J             |
| <b>Vehicle Details</b>  |                   |
| Vehicle No.:  | FBC7183U          |
| Vehicle to be Exported:   | Yes               |
| Intended Deregistration Date:   | 10 May 2019       |
| Vehicle Make:   | BAJAJ             |
| Vehicle Model:  | PULSAR 200 DTS-I  |
| Primary Colour:   | White             |
| Secondary Colour:   | Grey              |
| Manufacturing Year:   | 2008              |
| Engine No.:   | JCGBPM09037       |
| Chassis No.:  | MD2DHJCZZPCM06621 |
| Maximum Power Output:   | -                 |
| Open Market Value:  | \$1,500.00        |
| Original Registration Date:   | 16 Jun 2008       |
| First Registration Date:  | 16 Jun 2008       |
| Transfer Count:   | 4                 |
| Actual ARF Paid:  | \$225.00          |
| <b>Intended PARF Rebate Details</b>   |                   |
| PARF Eligibility:   | No                |
| PARF Eligibility Expiry Date:   | -                 |
| PARF Rebate Amount:   | \$0.00            |
| <b>Intended COE Rebate Details</b>  |                   |
| COE Expiry Date:  | 28 Feb 2023       |
| COE Category:   | D - Motorcycle    |
| COE Period(Years):  | 5                 |
| PQP Paid:   | \$3,438.00        |
| COE Rebate Amount:  | \$2,615.00        |
| <b>Total Rebate Amount:</b>   | <b>\$2,615.00</b> |
| <b>Message</b>  |                   |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                   |

The information contained herein is correct as at 10 May 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

|                            |                          |
|----------------------------|--------------------------|
| Date Of Report             | 08/05/2019 14:59         |
| Date Of Accident           | 05/05/2019 17:30         |
| Exact Location Of Accident | FARRER PARK STATION ROAD |
| Country/State of Loss      | SINGAPORE                |

#### DETAILS OF OWN VEHICLE

|                             |                          |
|-----------------------------|--------------------------|
| Vehicle Registration Number | FBC7183U                 |
| <b>Insured/Policyholder</b> |                          |
| Name Of Registered Owner    | BATHURUDEEN MOHAMED GANI |
| NRIC No                     | S8275256J                |
| Email Address               | SOULRIDER707@HOTMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-90054727     |
| Alternative Phone No        | OTHERS-90054727          |

#### Vehicle Particulars

|  |                        |
|--|------------------------|
| Manufacturer   | BAJAJ                  |
| Model  | PULSAR-200CC DTS-I (M) |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE            |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                     |
| If No, Please state action to be taken                                       | THIRD PARTY            |
| Vehicle Category   | MOTORCYCLE             |

#### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | THIRD PARTY FIRE AND/OR THEFT          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5104121589                             |
| Cover Note Number         |  |

#### Driver

|                      |                          |
|----------------------|--------------------------|
| Name of Driver       | BATHURUDEEN MOHAMED GANI |
| NRIC No              | S8275256J                |
| Date Of Birth        | 10/05/1982               |
| Occupation           | INDOOR                   |
| Date Of Driving Pass | 18/05/2006               |
| Driving Experience   | 12 YEARS AND 11 MONTHS   |
| Gender               | MALE                     |
| Mobile Number        | (LOCAL) +65-90054727     |
| Fax Number           |                          |
| Contact Number       | OTHERS-90054727          |
| Email Address        | SOULRIDER707@HOTMAIL.COM |

|   |                                       |
|---|---------------------------------------|
| Address   | BLK 467 NORTH BRIDGE ROAD<br>#04-5037 |
| Postcode  | 190467                                |
| Was driver an employee of the Insured's Company     | NO                                    |
| If No, Relationship of the Driver with the Insured  | OWNER                                 |
| Vehicle Registration Number of Driver's Own Vehicle | -                                     |
|   | -                                     |
|   | -                                     |
| Insurance Company of Driver's Own Vehicle           | -                                     |
|   | -                                     |
|   | -                                     |

#### General Information of the Accident

|                    |                            |
|--------------------|----------------------------|
| Type Of Accident   | COLLISION - MAJOR/MINOR RD |
| Weather Conditions | CLEAR                      |
| Road Surface       | DRY                        |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?   | YES |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER ATTACHED - TYPE OF ACCIDENT HEAD TO SIDE

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |           |
|-------------------------------------|-----------|
| Vehicle Registration Number         | SHA4428Z  |
| Vehicle Make/Model/Colour           |           |
| Details Of Properties               |           |
| Vehicle Category                    | TAXI      |
| Name of Driver                      | KEVIN KOH |
| NRIC/Passport Number                |           |
| Contact Number                      |           |
| Address                             |           |
| Postcode                            |           |
| Insurance Company Name              |           |
| Nature Of Damage                    |           |
| No. Of Passenger (Including Driver) |           |

#### DETAILS OF INJURED PERSON 1

|      |                          |
|------|--------------------------|
| Name | BATHURUDEEN MOHAMED GANI |
|------|--------------------------|

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SWOLLEN RIGHT TOE

FBC7183U

NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


FARRER PARK STATION ROAD


On the Material date + time, I was riding my bike no: FBC7183U along Farrer Station Road. The road was a 2 way direction. (1 way up + 1 way down). The traffic flow was light and weather was fine + dry. I was heading towards Birch Road. As I was cruising at about 10-15 km/h after the 'Hump' I noticed a Blue Comfort Delgro taxi stationary on my left. I then sounded my horn to alert the driver that I'm approaching. As I was passing by the taxi the driver suddenly without any warning or signal make a right turn into One-Farrer Hotel and swipe (collided) into the left side of my bike. The impact caused me to fall off to my right. No Police or ambulance was at scene. The taxi driver Mr. Kevin Koh alighted + apologized to me + admitted his fault. He then advised me to forward all my damages to his Insurance Company. I sustained injuries to my right toe (swollen). The next day - 06/05/19 - I went to Healthway medical at Towns Rd to seek treatment to my toe and was give 2 days medical leave. I'm lodging this report for Insurance claim purpose. The taxi Regn no: SHA 44282 + damaged to right front fender area. my bike FBC7183U left + right side damaged. That's all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 13 May 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBC 7183U

Pulsar Bajaj 200 DTSi

ACCIDENT DATE: 5 May 2019

| <u>Description</u>            | <u>Qty</u> | <u>Quotation \$</u> |
|-------------------------------|------------|---------------------|
| 1 Head Lamp Assy Cnt          | 1          | 250.00 ✓            |
| 2 Handle Bar H/L              | 1          | 135.00 X            |
| 3 Front Mudguard Repair       | 1          | 195.00 X            |
| 4 Brake Lever Cnt             | 1          | 95.00 ✓             |
| 5 Mirror RH H/L               | 1          | 85.00 X             |
| 6 Tank Dent                   | 1          | 450.00 ✓            |
| 7 Foot Brake Pedal H/L        | 1          | 85.00 X             |
| 8 Exhaust Pipe Dent/Cnt       | 1          | 580.00 ✓            |
| 9 Exhaust Guard Cnt           | 1          | 400.00 ✓            |
| 10 Footrest Bracket LH broken | 1          | 135.00 ✓            |
| 11 Gear Shifter Bt            | 1          | 150.00 ✓            |
| 12 Sprocket Guard broken      | 1          | 350.00 ✓            |
| 13 Side Cover LH broken       | 1          | 185.00 ✓            |
| 14 Coolant Tank Bt/Cnt        | 1          | 250.00 ✓            |
| 15 Fork LH Bt                 | 1          | 280.00 ✓            |
| 16 Fork Oil Seal H/L          | 1          | 135.00 ✓            |
| 17 Front Wheel Shaft Cnt/Bt   | 1          | 135.00 ✓            |
| 18 Balancer - Bar end Cnt RH  | 1          | 150.00 ✓            |

|           |          |
|-----------|----------|
| Sub-Total | 4,045.00 |
| Less 10%  | 404.50   |
| Sub-Total | 3,640.50 |

3545.00

3190.50

VEHICLE NO : FBC 7183U

Pulsar Bajaj 200 DTSi

Nett Items

|            |   |          |       |
|------------|---|----------|-------|
| 1          | Rear Carrier box NH                     | 250.00   | X     |
| 2          | Pulsar tank emblem x 2 NH               | 125.00   | ✓     |
| 3          | Towing fee NH                           | 40.00    | ✓     |
| 4          | Remove & replace parts, align & etc     | 250.00   | 200/- |
| 5          | Remove & replace fork & top up fork oil | 90.00    | 80/-  |
| 6          | Putty & respray paint                   | 250.00   | 150/- |
| Sub-Total  |   | 1,005.00 |       |
| Nett Total |   | 4,645.50 |       |

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/05/2019 @ 1430hrs

N/A Antenna

✓ Sum 4 days.

yan

LKK Auto




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |                             |   |
|--|---|-----------------|-----------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD   |   |                 | Ref : CS/FCI19008119/Dsd3e2 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877  |   |                 | Date : 21-08-2019           |  |
|  |   |                 | Code : FCI2                 |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                 |                             |   |
| Insured Veh.   | SHA 4428Z   | Veh. Inspected  | FBC 7183U                   |   |
| Policy No.   |   | Coverage (\$)   | 0.00                        |   |
| Claim No.  | D19003022MFSH   | Excess (\$)     | 0.00                        |   |
| Assign From  | EILEEN LEE  | Assign Date     | 08/05/2019                  |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |                             |   |
| Make & Model   | BAJAJ PULSAR  | c.c             | 199                         |   |
| Engine No.   | HIDDEN  | Year of Reg.    | 2008                        |   |
| Chassis No.  | MD2DHJCZZPCM06621   | Colour          | BLACK                       |   |
| Odometer   | 24271   | Steering        | IN ORDER                    |   |
| Brakes   | IN ORDER  | Modification    | SPORTS RIM                  |   |
| General  | GOOD  |                 |                             |   |
| <b>3. Conditions of Tyres</b>  |   |                 |                             |   |
|  | Size  | Make            | Balance                     |   |
| R/H Front Tyre   | 90/90-17  | BRIDGESTONE     | 2 mm                        |   |
| L/H Front Tyre   |   |                 | mm                          |   |
| R/H Rear Tyre  | 120/80-17   | BRIDGESTONE     | 2 mm                        |   |
| L/H Rear Tyre  |   |                 | mm                          |   |
| <b>4. Description of Damages</b>   |   |                 |                             |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY.<br>DAMAGES SEE DETAILS.   |   |                 |                             |   |
| <b>5. General Information</b>  |   |                 |                             |   |
| Accident Date  | 05/05/2019  | Inspection Date | 10/05/2019                  |   |
| Survey held at   | SG 98 MOTOR PTE LTD<br>BLK 4001 ANG MO KIO INDUSTRIAL PARK 1<br>#01-21 SINGAPORE 569622 |                 |                             |   |
| <b>5a. Remarks</b>   |   |                 |                             |   |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                             |   |
| <b>5b. Estimate Days of Repair</b>   |   |                 |                             |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   |                 | <b>4 Working Days</b>       |   |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 7183U

| Qty                                | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |                      |                           |                   |
| 1                                  | HEAD LAMP ASSY  | CUT                  | 250.00                    | 250.00            |
| 1                                  | HANDLE BAR  | NOT NECESSARY        | 135.00                    | -                 |
| 1                                  | FRONT MUDGUARD  | TO REPAIR SEE LABOUR | 195.00                    | -                 |
| 1                                  | BRAKE LEVER   | CUT                  | 95.00                     | 95.00             |
| 1                                  | MIRROR RH   | NOT NECESSARY        | 85.00                     | -                 |
| 1                                  | TANK  | DENTED               | 450.00                    | 450.00            |
| 1                                  | FOOT BRAKE PEDAL  | NOT NECESSARY        | 85.00                     | -                 |
| 1                                  | EXHAUST PIPE  | DENTED / CUT         | 580.00                    | 580.00            |
| 1                                  | EXHAUST GUARD   | CUT                  | 400.00                    | 400.00            |
| 1                                  | FOOTREST BRACKET LH   | BROKEN               | 135.00                    | 135.00            |
| 1                                  | GEAR SHIFTER  | BENT                 | 150.00                    | 150.00            |
| 1                                  | SPROCKET GUARD  | BROKEN               | 350.00                    | 350.00            |
| 1                                  | SIDE COVER LH   | BROKEN               | 185.00                    | 185.00            |
| 1                                  | COOLANT TANK  | BENT / CUT           | 250.00                    | 250.00            |
| 1                                  | FORK LH   | BENT                 | 280.00                    | 280.00            |
| 1                                  | FORK OIL SEAL   | NECESSARY            | 135.00                    | 135.00            |
| 1                                  | FRONT WHEEL SHAFT   | CUT / BENT           | 135.00                    | 135.00            |
| 1                                  | BALANCER-BAR END RH   | CUT                  | 150.00                    | 150.00            |
|                                    | LESS 10% DISCOUNT   |                      | -404.50                   | -354.50           |
|                                    |   |                      | 3,640.50                  | 3,190.50          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |                      |                           |                   |
| 1                                  | REAR CARRIER BOX (SN)   | NOT NECESSARY        | 250.00                    | -                 |
| 1                                  | PULSAR TANK EMBLEM X2 (SN)  | NECESSARY            | 125.00                    | 125.00            |
|                                    |   |                      | 375.00                    | 125.00            |
| <b><u>LABOUR</u></b>               |   |                      |                           |                   |
|                                    | TOWING FEE.   |                      | 40.00                     | 40.00             |
|                                    | REMOVE & REPLACE PARTS,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD. |                      | 250.00                    | 200.00            |
|                                    | REMOVE & REPLACE FORK & TOP UP FORK OIL.                                      |                      | 90.00                     | 80.00             |

Report Ref No. CS/FCI19008119/Dsd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty   | Description of Parts   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|------------------------|-----------|---------------------------|-------------------|
|   | PUTTY & RESPRAY PAINT. |           | 250.00                    | 150.00            |
|   |                        |           | 630.00                    | 470.00            |
|   | GRAND TOTAL            |           | 4,645.50                  | 3,785.50          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                        |           |                           | 2,800.00          |

Report Ref No. CS/FCI19008119/Dsd3e2

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,615.00=NETT VALUE: \$2,385.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.