

27/03/2002

ASS. REC. BY:

REF: CS³ CT219008121 Ecd302 Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 8.5.19 3.35pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 8364Y Insured: SMH 6916Y

at Workshop m/s TJ Car Care Services Tel: 97575155

of Block 1010 Bukit Merah Lane 3 # 01-115

Policy No: mpcsn30280419000 Claim No: SNM19d 202024cov

Sum Insured: Excess:

Make of Veh: D.O.A. 05/5/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"rwp"

9.5.19 (After 1.00pm)

Date/Time: 8.5.19 4.40pm Person Contacted: Boon H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLK 8364Y - NBA / AIG 190079831Y DOA - 05/05/2019
	SMH 6916Y - NBA / AIG 190079831Y DOA - 05/05/2019
21/6/19	submit PRS. No Mention.

Surveyor: **Steve**

REF: **C71**

ASSIGNMENT

From: _____ Date: **9.5.2019**
 Estimated Cost: _____
 OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLK 8364Y**
 at Workshop m/s **TJ car care**
 of **Black 1010 Bukit Merah Lane 3 #01-115**
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: **After 1.00pm**

N/S	O/S
XX	

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **"up"**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLK 8364Y** Yr Regn: **31/01/17**
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Audi A8L** C.C. **2995**
 Colour: **Green** A/C: Insured / Std / NI / NA
 Sp. Reading: **47605** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WAUZZZ4H3HN011507**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ Rrim / STD A/Rim or
 Tyre Size: F: **255/45 R 19**
 R: **21**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Pirelli**

Front		Rear
R/Bal. 7 mm		R/Bal. 7 mm
L/Bal. 7 mm		L/Bal. 7 mm
D.O.A. 5/5/19		D.O.I. 9/5/19

Survey held at **TJ car care**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MR-245K

Repair large SK-6K, 5 days

RECEIVED 21 JUN 2019

31/5/2019

Date/Time, File Pass w?

11/6/2019

Date/Time, File Return to?

2)

Report Format: **WER-PRS**

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

150

150

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 8 May 2019 3:35 PM
To: Accident@kscgp.com
Cc: 'assignments'
Subject: RE: Notice to conduct pre-repair survey (Your Ref: SMH 6916Y; OurRef: SLK 8364Y/GT/jn/ws) / our rref: snm19d202024

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Wednesday, 8 May, 2019 3:26 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: Notice to conduct pre-repair survey (Your Ref: SMH 6916Y; OurRef: SLK 8364Y/GT/jn/ws) / our rref: snm19d202024

Dear Sirs,

We enclose herewith our 2nd Notice to conduct pre-repair survey. Our client is not agreeable with your proposed list of surveyors.

The workshop's details are as follows:
TJ Car Care Services

Block 1010 Bukit Merah Lane 3

#01-115

Singapore 159724

Contact: Mr Lim Boon Leong (h/p: 9757 5155)

Thank you.

Regards,
Wan Sim
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Chong Boon Sen [<mailto:boonsen.chong@sg.entaiping.com>]

To: accident@kscgp.com

Sent: Wed, 8 May 2019 05:51:05 +0000

Subject:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG

KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]

Sent: Wednesday, 8 May 2019 11:35 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Notice to conduct pre-repair survey (Your Ref: SMH 6916Y; Our Ref: SLK 8364Y/GT/jn/ws)

Dear Sirs,

We enclose herewith our 1st Notice to conduct pre-repair survey for your necessary action.

Thank you.

Regards,

Wan Sim

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information

contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0651D
Vehicle Details	
Vehicle No.:	SLK8364Y
Vehicle to be Exported:	No
Intended Deregistration Date:	09 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QU (PI)
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	CRE151986
Chassis No.:	WAUZZZ4H3HN011507
Maximum Power Output:	228.0 kW (305 bhp)
Open Market Value:	\$80,274.00
Original Registration Date:	31 Jan 2017
First Registration Date:	31 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$116,494.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2027
PARF Rebate Amount:	\$87,370.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,106.00
COE Rebate Amount:	\$41,014.00
Total Rebate Amount:	\$128,384.00

The information contained herein is correct as at 09 May 2019

OK

500+ dealers competed to buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.98%P.A \$0 Admin Fees@Gv
Finance.2 Years Warranty \$46000
Down Monthly From \$988
GV Credit Pte Ltd StarAd



KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

view our cars


Browse by Category

Sort by Date Posted20 results/page

1 vehicles

Audi A8L

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A8L		Any	Any	2017	Any	Any	Any	Availabl
	Audi A8L 3.0A TFSI Quattro		\$268,999	\$24,710 /yr	22-Dec-2017	2,995 cc	9,100 km	Luxury	Availabl
Low Mileage 9,100km! 5 Years Audi Agent Warranty Till Dec 2022! Fully Audi Agent Servicing Since Day One! AUDI Management Unit! Classy Nougat Brown Interior! Loan Available! Lowest Bank Interest Rate ...									
Premium Automobiles									
Posted: 03-May-2019 Tags: 2017 Audi A8L, 2017 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads20 results/pag

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2019 12:11
Date Of Accident	05/05/2019 17:00
Exact Location Of Accident	ALONG UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8364Y
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92414201
Alternative Phone No	OFFICE-92414201

Vehicle Particulars

Manufacturer	AUDI
Model	A8L
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994316
Cover Note Number	

Driver

Name of Driver	VAN ZONNEVELD SYLVIA
Passport No/FIN	G3471922K
Date Of Birth	27/08/1969
Occupation	INDOOR
Date Of Driving Pass	04/08/1988
Driving Experience	30 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92414201
Fax Number	
Contact Number	OTHERS-92414201
Email Address	NOEMAIL

Address	3 MOUNT PLESENT DRIVE
Postcode	298381
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH6916Y
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE WEI CHUEN
NRIC/Passport Number	S8460530A
Contact Number	96822619
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Along Upper Steeplecross Road



B) SMH 6916Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped slowly to yield to bus who was standing still at bus stop and gave light to merge into traffic. I stopped before the yellow line with yellow cross. The car behind us apparently saw too late that I stopped and bumped into us from behind.

It happened at exit 15 from ME
Up Sarangoon Rd

1/We declare the foregoing particulars are true in every respect

Direct Signature
(If direct is not the policyholder)
Date & Time

Reporting Cause Personnel's Signature
Name *[Signature]*
NRIC/IN No. *[Signature]*

6/5/2019
3:30 pm






























...CLAIM SUBFOLDER...(Pending for Survey Report)








































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2019		21 Jun 2019 11:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD , Co. Reg. No.: 200710651D								
Vehicle Reg. No.:	SLK8364Y	Date of Loss:	05/05/2019 17:00 - :59 [27 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202024C02	Policy/Cover Note No.:	DMPCSN30280419000						
Vehicle Reg. No. (Insured):	SMH6916Y	Policy No. (Claimant):	999994316						
		Excess:	S\$0.00						
Repairer:	TJ Car Care Services (HQ) Blk 1010, #01-115, Bukit Merah Lane 3, 159724 Bukit Merah - Tel: 62768567								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 02/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

















*SLK8364Y (SNM19D202024C02)
[SMH6916Y]
TP
GOLDBELL CAR RENTAL PTE LTD
May 5 2019 5:00PM
[-]
TJ Car Care Services

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	07/05/19 12:33	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	07/05/19 12:29	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	07/05/19 12:32	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	07/05/19 12:32	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	07/05/19 12:32	Driving License [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	07/05/19 12:32	Driving License [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
15	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/06/19 14:01	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
30	21/06/19 14:01	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
31	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/06/19 14:01	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	21/06/19 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	07/05/19 12:32	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 12:32	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	07/05/19 12:33	Accident Statement	 Load HTM	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	07/05/19 12:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	07/05/19 12:32	Identification Card		Load JPG	<input checked="" type="checkbox"/>
12	07/05/19 12:32	Identification Card		Load JPG	<input checked="" type="checkbox"/>
13	07/05/19 12:32	Driving License		Load JPG	<input checked="" type="checkbox"/>
14	07/05/19 12:32	Driving License		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	07/05/19 12:32	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 12:32	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008121/ECD3E2

Date: 21/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30280419000

Claimant Vehicle
No : SLK8364YInsured Vehicle
No : SMH6916Y

Date of Loss: 05/05/2019

Nature of Claim: TP

Claim
No: SNM19D202024C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK8364Y**

Make & Model: AUDI A8 L, 3.0 (A)

Engine No: CRE151986

Reg. Date: 31/01/2017 (Man. Year: 2016)

Chassis No: WAUZZZ4H3HN011507

Colour: Green

Odometer: 47605 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/06/2019

Date Inspected: 09/05/2019 Inspected At:

TJ Car Care Services (HQ)
Blk 1010, #01-115, Bukit Merah Lane 3
Singapore 159724

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2019)

Parts: 143 AUDI A8 L 3.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK8364Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >