

Surveyor

Taufik

REF

CS3/CT119008129/Alcd30r

Total Instruction

ASSIGNMENT (OFFICE)

From (Person)

Chong Swen Sun

of

CTE

Date/Time

7/5/19 @ 3:58pm

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SJH 4643H

Insured

GBEG586L

at Workshop n/a

77 Motorsports

Tel:

88111121

of

48 tuh Guan Rd East #01-103

Policy No.

DMVEN30141619011

Claim No.

SNM19D2019 87C02

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

4:31pm @ 8/5/19

Person Contacted

Ken

Vehicle

IN OUT

Date/Time

Action/Instruction (X) Estimate

SJH 4643H - NA/CT119007558/R3

DUA: 3/5/19

Dismantle: 9/5/2019

After repair: 15/5/2019

Barrymore

Tanp

REF:

(CT)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT
 Ken.

-PRS-

Veh No: SSH4643H Y Regn: Aug / 08
 Type: Mop / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mitsubishi Lancer 1499
 Color: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 148961 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JMYSRCY2ABU007911
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225 / 45 R17
 R: 225 / 45 R17
 GS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: C
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.L: 8/5/19 @ 420pm
 Survey held at TT Motorsport
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: 8811121
No GIA

\$4000 - \$5000 - 7 days
48 Toh Gua Rel Est. #01-103

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 7
 Resurvey No. of Trip: 2

Date/Time, File Return to?
 2)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:	<u>150</u>
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	<u>150</u>

Report Format: PRS

Lump Sum / L.B.k (\$)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 7 May 2019 3:58 PM
To: Lua Siew Hui
Cc: wendy_jiang@rssolomon.com; 'assignments'
Subject: RE: YOUR REF: RSS/1905-7233 (TT) (PD) / OUR REF: SNM19D201987C02

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lua Siew Hui [mailto:lua_siewhui@rssolomon.com]
Sent: Tuesday, 7 May, 2019 11:41 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: wendy_jiang@rssolomon.com
Subject: Re: YOUR REF: RSS/1905-7233 (TT) (PD) / OUR REF: SNM19D201987C02

Dear Boon Sen,

We thank you for your email.

We write to inform that our client will be appointing his own Surveyors.

In this regard, please arrange your surveyors to contact Mr. Ken of TT Motorsports at mobile no. 88111121 for a pre-repair survey of our client's vehicle located at 48 Toh Guan Road East #01-103 Enterprise Hub Singapore 608586.

Yours sincerely

Lua Siew Hui | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors | Commissioner for Oaths

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e lua_siewhui@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

On Tue, May 7, 2019 at 11:00 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We refer to your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJH4643H		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	LANCER 1.5 MIVEC GLS 4A/T		
Chassis No. :	JMYSRCY2A8U007911		
Propellant :	Petrol		
Engine No. :	4A910101822		
Engine Capacity :	1499 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1750 kg		
Unladen Weight :	1313 kg		
Year Of Manufacture :	2008		
Original Registration Date :	08 Aug 2008		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
PQP Paid :	\$17,099.00		
COE Expiry Date :	07 Aug 2023		
Road Tax Expiry Date :	07 Feb 2020		
Inspection Due Date :	07 Aug 2020		
Intended Transfer Date :	20 Aug 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	622C
Vehicle Details	
Vehicle No.:	SJH4643H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	4A910101822
Chassis No.:	JMYSRCY2A8U007911
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,230.00
Original Registration Date:	08 Aug 2008
First Registration Date:	08 Aug 2008
Transfer Count:	2
Actual ARF Paid:	\$16,230.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$13,559.00
Total Rebate Amount:	\$13,559.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/05/2019 13:21
Date Of Accident	03/05/2019 17:15
Exact Location Of Accident	137 TECK WHYE LANE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH4643H
Insured/Policyholder	
Name Of Registered Owner	TAN POH GEE ANTHONY
NRIC No	S1159622C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98967680
Alternative Phone No	OTHERS-98967680

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.5 MIVEC GLS 4A/T (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA378175/1
Cover Note Number	

Driver

Name of Driver	ONG JUN WEI, MARCUS
NRIC No	S9619724A
Date Of Birth	06/06/1996
Occupation	OUTDOOR
Date Of Driving Pass	15/05/2015
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98959827
Fax Number	
Contact Number	
EEmail Address	MOJW96@GMAIL.COM

Address	APT BLK 530A JURONG WEST AVENUE 1 #13-921
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6586L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG NGEE SAN
NRIC/Passport Number	S1322350E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car A, was stationary at double yellow line. car B was reversing out from a loading / unloading area. The rear right corner of car B hit onto left front corner of car A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 6/5/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

13:01

Common Statement

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 6/5/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

13:01

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2019		21 Aug 2019 11:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TAN POH GEE ANTHONY, ID: S1159622C								
Vehicle Reg. No.:	SJH4643H	Date of Loss:	03/05/2019 17:00 - :59 [128 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201987C02	Policy/Cover Note No.:	DMCVSN30141619011						
Vehicle Reg. No. (Insured):	GBE6586L	Policy No. (Claimant):	GA378175/1						
		Excess:	S\$0.00						
Repairer:	Tt Motorsport Pte Ltd (TT MOTORSPORT PTE LTD) 48 TOH GUAN ROAD EAST #01-103 ENTERPRISE HUB, 608586 Jurong East - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJH4643H (SNM19D201987C02)**
[GBE6586L]

TP















































TAN POH GEE ANTHONY

May 3 2019 5:00PM

[-]

Tt Motorsport Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)		Thumbnail	Print
1	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	06/05/19 14:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	06/05/19 14:30	Chassis Number [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	06/05/19 14:30	Odometer Reading [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
2	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
3	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
4	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
5	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
6	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
7	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
8	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
9	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
10	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
11	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
12	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
13	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
14	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
15	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
16	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
17	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
18	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
19	21/08/19 12:45	General View		Load JPG	<input checked="" type="checkbox"/>
20	21/08/19 12:45	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
21	21/08/19 12:45	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
22	21/08/19 12:45	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
23	21/08/19 12:45	Photographs of Damaged Parts		Load JPG	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
24	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/19 12:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	29/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
1	06/05/19 14:27	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 14:28	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 14:28	Owner's IC and Licence	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
		[Linked Accident Report Documents]		
4	06/05/19 14:28	Driver's IC and Licence [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 14:28	Certificate of Insurance [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
1	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	06/05/19 14:30	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	06/05/19 14:30	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
10	06/05/19 14:30	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
1	06/05/19 14:27	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 14:28	Common Statement	Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 14:28	Owner's IC and Licence	Load JPG	<input checked="" type="checkbox"/>
4	06/05/19 14:28	Driver's IC and Licence	Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 14:28	Certificate of Insurance	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008129/T1CD3E2

Date: 03/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30141619011

Claimant Vehicle
No : SJH4643HInsured Vehicle
No : GBE6586L

Date of Loss: 03/05/2019

Nature of Claim: TP

Claim
No: SNM19D201987C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH4643H**

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)

Engine No: 4A910101822

Reg. Date: 08/08/2008 (Man. Year: 2008)

Chassis No: JMYSRCY2A8U007911

Colour: Blue

Odometer: 148961 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 08/05/2019 Inspected At:

Tt Motorsport Pte Ltd (TT MOTORSPORT
PTE LTD)
48 TOH GUAN ROAD EAST #01-103
ENTERPRISE HUB
Singapore 608586

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2019)
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH4643H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >