

ASB PWD BY 08/FWD19008131/4qdzek

Manus clara li PWD 8/5/19 @ 10:20am

Estimated Cost PWD

OD ☒ W/TP REG / OD RES / EVA / INV / MYTC

To Inspect Vehicle No QZ8022P Insured SJM 4065A

at Workshop no Imperium Automotive Tel 9748 9940

of 25 Kalei Bukit Rd 4 #01-49

Policy No PNPV2019-00107607 Claim No 1201900012016/CL

Sum Insured 06/05/2019

Make of Veh (Client's Record) 06/05/2019

CA / REV / REP / REV 24 HRS

Date/Time 11:37am 8/5/19 Person Contacted Shaun Vehicle ☒ DIT

Date/Time	Action/Instruction (✓) Estimate
	<u>QZ8022P - x</u>
	<u>GM amba - selection 2007 Arde</u>

2019/05/06

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: Gx8022P  
 at Workshop m/s 1 min.  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: 186

IDAC Accident Rpt: Consistent? : Yes or No

GIA / BR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: 2405 2nd Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: Gx8022P Yr Regn: 8106  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or carMake: Toyota Dyna C.C. 2986Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 557887 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFUF34Y003012172

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NIT / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14 Van maxR: 155 R12

BS (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 5 mm R/Bal: 5/5 mmL/Bal: 5 mm L/Bal: 5/5 mmD.O.A. 6/5/19 D.O.I. 8/5/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 15 MAY 2019

Date/Time, File Pass to?

1) 15/5/19

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: mer-7PLump Sum / I.B.I. (\$ 4000)

TOTAL

200

50

50

10

310

Meinmen

Markus

clara li

CS/FWD19008131/49d302

ASSIGNMENT (Office)

PWD

Date/Time: 8/5/19 @ 10:20am

OD ☒ WS ☐ TP ☐ RES ☐ OD ☐ RES ☐ EVA ☐ INV ☐ MY ☐ CS

To Inspect Vehicle No.

GZ8022P

Insured

SJM406SA

at Workshop of

Imperium Automotive

Tel

9748 9940

at

25 Kalei Bulkit Rd 4 #01-49

Policy No

PNPV2019-00007607

Claim No

1201900012016/CL

Sum Insured

Excess

Make of Veh

(Client's Record)

P.O.A

06/05/2019

CA / REV / REP / REV 24 HRS

Date/Time

11:37am 8/5/19

Person Contacted

Sharon

HOV/Endorsement

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

GZ8022P-x

SJM406SA-CS/CT119007907/Asds

DOA: 8/5/2019

09/5/19 @

2:11pm returned to Clara Li via Meinmen.

(08/11/13) wel  
ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:  
Estimated Cost:  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: Gx8022P  
at Workshop m/s 1 m/s  
of  
Insured:  
Policy No.  
Claims No.  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

Veh No: Gx8022P Yr Regn: 81 06  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car  
Make: Toyota Dyna c.c 2986  
Colour: S.blu A/C: Insured / Std / NI / NA  
Sp. Reading: 557887 T/Radio: Insured / Std / NI / NA  
Eng/No:

C/No: JTFUF34Y003012172  
Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14 Van max  
R: 155 R12

BS: DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or


Front Rear  
R/Bal: 5 mm R/Bal: 5/5 mm  
L/Bal: 5 mm L/Bal: 5/5 mm  
D.O.A: 6/5/19 D.O.I: 8/5/19  
Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 186

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

net 5097

Date: Vehicle: IN / OUT

Person Contacted: 2408-2000

Date / Time Action / Instruction

9/5/19 COE 31-7-2021 +1A9903  
confirmed 1/5 & 4000 with shown. (Red & 4866.33, 55%)

RECEIVED 15 MAY 2019

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 5

1) 15/5. 10/15/19

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Report Format: 1002-7P

Lump Sum / I.B.I: (\$ 4000 )

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )

) \$ + RS. \$

) Photos

) Others

TOTAL

200

50

50

10

310

## Nivitha (LKK Auto)

---

**From:** clara.li@fwd.com  
**Sent:** Wednesday, 8 May 2019 10:20 AM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: Accident involving GZ8022P & SJM4065A on 06.05.2019 Our Ref: 1201900012016/CL  
**Attachments:** PRI 190368.pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Attached is the TP GIA report.

Please create the case in Merimen.

Thank you.

Regards,  
Clara

---

**From:** Alfred Ng [mailto:alfred\_ng@juseq.com.sg]  
**Sent:** Wednesday, 8 May, 2019 10:19 AM  
**To:** Clara Li Zirong - SGUser  
**Cc:** Motor Claims SG - SG Common  
**Subject:** Re: Accident involving GZ8022P & SJM4065A on 06.05.2019

Your ref: 1201900012016/CL

Our ref: JEQ/190368/0519/IMP

Dear Clara,

We refer to your email dated 7 May 2019.

Our client is agreeable to appoint the following surveyor as our single joint expert.

LKK Auto Consultants Pte Ltd.

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

**IMPERIUM AUTOMOTIVE**  
25 Kaki Bukit Road 4 #01-49,  
[Synergy@KB](mailto:Synergy@KB)  
Singapore 417800

Tel: 9748 9940 Fax: 6346 7213

Mr. Shawn Tan

With Regards

Alfred Ng

Executive

On behalf of Mr Michael Yap

M/s JusEquity Law Corporation

No. 171 Chin Swee Road

#02-01/02/06 Singapore 169877

Tel : 6536 9339

Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

**From:** clara.li@fwd.com

**To:** zul@juseq.com.sg

**Cc:** alfred\_ng@juseq.com.sg ; motorclaims.sg@fwd.com

**Sent:** Tuesday, May 07, 2019 5:33 PM

**Subject:** RE: Accident involving GZ8022P & SJM4065A on 06.05.2019 O ref: JEQ/190368/0519/IMP (zl) Our Ref: 1201900012016/CL

**WITHOUT PREJUDICE**

Dear Sir/ Madam,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

*\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.*

Kind Regards,

Clara Li


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E [clara.li@fwd.com](mailto:clara.li@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



**From:** zul [<mailto:zul@juseq.com.sg>]

**Sent:** Tuesday, 7 May, 2019 4:16 PM

**To:** Motor Claims SG - SG Common

**Cc:** 'Alfred Ng'

**Subject:** Accident involving GZ8022P & SJM4065A on 06.05.2019 O ref: JEQ/190368/0519/IMP (zl) Our Ref: 1201900012016/CL

Dear Sir,

Please refer to our notice of accident.

Regards,

Zul

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6536 9339

Fax: 6536 5368

E-mail: [zul@juseq.com.sg](mailto:zul@juseq.com.sg)

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.





# JusEquity Law Corporation

**ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS**

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Email : [claims@juseq.com.sg](mailto:claims@juseq.com.sg)

Fax : (65) 6536 5388 (Litigation & Conveyancing)

website : [www.juseq.com.sg](http://www.juseq.com.sg)

Our Ref: JEQ/190368/0519/IMP (zl)

Your Ref: **SJM4065A**

7 May 2019

**MOHAMMAD HAFIZ BIN ABDUL JABBAR**  
465 Choa Chu Kang Avenue 4 #08 – 03  
Singapore 680465

By Post Only

**FWD SINGAPORE PTE LTD**  
Singapore

By Email: [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

Dear Sir

**ACCIDENT INVOLVING GZ8022P & SJM4065A ON 06.05.2019**

We act for the owner of vehicle no. GZ8022P.

We hereby notify you of a road traffic accident on **6 May 2019** at about **0900 hrs**, at BKE towards Changi involving our client's vehicle and vehicle registration no. **SJM4065A** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 09 May 2019

**Preliminary Advice**

Insured Vehicle No	: SJM4065A	Accident Date	: 06/05/2019
TP Vehicle No	: GZ8022P	Assignment Date	: 08/05/2019
Make	: TOYOTA DYNA 150	Est. Duration of Repair	: 5.00
Date of Inspection	: 08/05/2019		
Inspection At	: IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ) 25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB SINGAPORE 417800		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident. The chassis frame affected due to collision.

Repairer's Estimate (Gross)	:S\$	8,866.33
Revised Amount	:S\$	5,039.43
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,039.43
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 3294W

### Vehicle Details

Vehicle No.: GZ8022P  
Vehicle to be Exported: No  
Intended Deregistration Date: 09 May 2019  
Vehicle Make: TOYOTA  
Vehicle Model: DYNA 150 D  
Primary Colour: Silver  
Manufacturing Year: 2006  
Engine No.: 5L5658725  
Chassis No.: JTFUF34Y003012172  
Maximum Power Output: -  
Open Market Value: \$23,681.00  
Original Registration Date: 31 Aug 2006  
First Registration Date: 31 Aug 2006  
Transfer Count: 2  
Actual ARF Paid: \$1,185.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Jul 2021  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 5  
PQP Paid: \$22,247.00  
COE Rebate Amount: \$9,903.00  
**Total Rebate Amount: \$9,903.00**

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 08 May 2019

OK

## Scared of Driving At Night?

Driving At Night? These "X-Ray Vision" Glasses Improve Night Vision By 80%

Ad

Toyota Dyna Price Range Depreciation &gt; 10 year Vehicle Type Submit

Advanced Search

Home &gt; Used Cars &gt; Pan Pac Automobile Pte Ltd &gt; Toyota Dyna 150 3.0M (COE till 12/2021)

## Toyota Dyna 150 3.0M (COE till 12/2021)

Overview Financial Accessories Similar Research Photos Map

Price	\$19,800	Lifespan	11-Dec-2026
Depreciation	\$7,620 /yr	Reg Date	12-Dec-2006 (2yrs 7mths 3days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$12,596 as of today (change)	OMV	\$24,285
COE	\$24,349	No. of Owners	3
Engine Cap	2,982 cc		
Curb Weight	1,800 kg		
Type of Vehicle	Truck		



Location Map

[Shortlist](#) [Compare](#) [Add note](#)  
[Report Error](#) [More Actions](#)

## Features

Being One Of The Most Reliable Commercial Vehicle In The Market Now. High Performance With Low Maintenance And Fuel Efficient. Buy With Ease Of Mind. View specs of the Toyota Dyna 150 (2014)

## Accessories

CD Player, New Paintwork.

## Description

Very Well Maintained By Previous Owner. No Repairs Needed. Paint Work And Servicing All Done Up. Own This With Peace Of Mind.

## Category

COE Car

## Status

Available

## Resources



## Car Valuation - Free

Find out the market value of your existing car for free. Get started



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 06-Apr-2019 | Last Updated on: 07-Apr-2019

## Upfront Payment:

[+ more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$1,980 (change)	Maximum 90% Loan
1st Instalment	\$642	Based on 4.5% interest rate

## Products and Services

[+ View All](#)
[Compare](#)

## Seller Information

Company	Pan Pac Automobile Pte Ltd • dealer's picklist • 3 vehs sold   24 vehs available	
Address	8 Cheng Charn Road Search cars nearby this location	
Location	Link (THM) Building	
Office No	68711109	
Contact Person(s)	Dennis	90463387
	ISAAC	91695221
	ALEX	87972000

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/05/2019 15:13
Date Of Accident	06/05/2019 09:00
Exact Location Of Accident	BKE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ8022P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RENTZ
Co Reg No	53193294W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93731641
Alternative Phone No	OFFICE-93731641

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5072303359-03
Cover Note Number	

### Driver

Name of Driver	KHAN RUBEL
Passport No/FIN	G6723278Q
Date Of Birth	10/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	27/12/2017
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93731641
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 596B #09-327 ANG MO KIO STREET 52
Postcode	562596
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE
Passenger 5	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM4065A
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBE633Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GY8793C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:



# Sketch Plan #2

SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Front car suddenly jam brake I apply my brake in time.

CAR B collided into my rear.

I did not collided into CAR D rear portion.

DECLARATION  
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/05/2019 15:13
Date Of Accident	06/05/2019 09:00
Exact Location Of Accident	BKE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ8022P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RENTZ
Co Reg No	53193294W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93731641
Alternative Phone No	OFFICE-93731641
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5072303359-03
Cover Note Number	
<b>Driver</b>	
Name of Driver	KHAN RUBEL
Passport No/FIN	G6723278Q
Date Of Birth	10/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	27/12/2017
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93731641
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 595B #09-327 ANG MO KIO STREET 52  
 Postcode 562596  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 6  
 Passenger 1 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 2 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 3 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 4 NAME: : UNKNOWN  
 GENDER: : MALE  
 Passenger 5 NAME: : UNKNOWN  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJM4065A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBE633Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GY8783C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

NOT ALLOWED  
H/W  
2/5/19  
8/5/19  
8 May 2019

Vehicle No.: GZ 8022 P

Model: Toyota Dyna

QTY	DESCRIPTION	AMT \$
<u>List Items</u>		
1	Rear tailgate <i>Self / ID</i>	\$ 1,465.60
2	Rear tailgate lock hinges <i>2</i>	\$ 290.00 X
1	Rear tailgate lower panel <i>Self / ID</i>	\$ 878.50
2	Rear tailgate lower stopper rubbers <i>N/S 70mm</i>	\$ 145.20 1PC
2	Rear tailgate lower stopper brackets <i>N/S Self</i>	\$ 213.00 1PC
2	Rear taillamps <i>N/S 320</i>	\$ 679.40 1PC
2	Rear taillamp panels <i>N/S Self</i>	\$ 599.00 1PC
1	Rear number plate panel <i>Self</i>	\$ 98.50
1	Rear number plate lamp <i>11</i>	\$ 89.70 X
1	Rear spare tyre <i>11</i>	\$ 289.70 X
1	Rear spare tyre carrier support <i>11</i>	\$ 625.00
1	Rear exhaust pipe <i>11</i>	\$ 852.60 X
1	Rear exhaust mounting <i>11</i>	\$ 48.90 X
		\$ 6,275.10
	Discount 25%	\$ 1,568.78
		\$ 4,706.33

1-3885.90  
2914.42

## Special Nett Items

1	Rear tailgate "13PAX" sticker <i>201</i>	\$ 25.00 10
1	Rear tailgate "70KM/H" sticker <i>201</i>	\$ 25.00 10
1	Rear step bar <i>Self</i>	\$ 250.00 200
1	Rear number plate <i>Self</i>	\$ 50.00 15
1	Rear spare tyre rim <i>11</i>	\$ 350.00 X
		\$ 700.00

## S/N.

## Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 30
2	To remove and refit inner garnishes.	\$ 11 150.00 X
3	To remove, refit and replace exhaust silencer and mountings.	\$ 11 150.00 X
4	To apply tuff kote.	\$ 180.00 60
5	Panel beating.	\$ 1,500.00 1000
6	To respray painting on the affected areas.	\$ 1,400.00 800
		\$ 3,460.00

5039.42  
22  
4031

Grand Total : \$ 8,866.33

## ...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 May 2019 <a href="#">Edit Reg</a>		08 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$4,000.00</b> <a href="#">Edit Estimates</a>	<b>\$4,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>












































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>Mohammad Hafiz Bin Abdul Jabbar</b> , ID: S8944255I									
Main Claimant: <b>RENTZ</b> , Co. Reg. No.: 53193294W									
Vehicle Reg. No.: <b>GZ8022P</b>		Date of Loss: 06/05/2019 09:00 - :59 <b>[152 Months and 6 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / 1201900012016</b>		Policy/Cover Note No.: <b>PNPV2019-00002607 (Comprehensive)</b>							
Vehicle Reg. No. (Insured): <b>SJM4065A</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Imperium Automotive - Kaki Bukit (HQ)</b> 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940									
Handling Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 17/05/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GZ8022P (1201900012016)  
[SJM4065A]  
TP  
RENTZ  
May 6 2019 9:00AM  
[Mohammad Hafiz Bin Abdul Jabbar]  
Imperium Automotive - Kaki Bukit

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 14:21	Adjuster Immediate Advice	 Load HTML	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 10:00	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	15/05/19 10:00	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
4	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
5	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
6	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
7	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
8	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
9	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
10	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
11	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
12	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
13	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
14	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
15	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
16	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
17	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
18	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
19	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
21	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
22	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
23	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
24	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
25	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
26	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/05/19 10:00	General View	 Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
67	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
68	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
69	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
70	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
71	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
72	15/05/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
73	15/05/19 10:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/05/19 10:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/05/19 10:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/05/19 10:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	09/05/19 13:28	E-filed GIA report	 Load PDF	

### Documents Checklist



**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19008131/UQD3E2

Date: 15/05/2019

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00002607

Claimant Vehicle No: GZ8022P Insured Vehicle No: SJM4065A

Date of Loss: 06/05/2019 Nature of Claim: TP Claim No: 1201900012016

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GZ8022P</b>	Engine No:	5L5658725
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34Y003012172
Reg. Date:	31/08/2006 (Man. Year: 2006)	Odometer:	557887 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	155 R12 (D)
Front Left Side:	VANMAX 5 mm	Rear Left Side:	Dunlop 5/5 mm
Front Right Side:	VANMAX 5 mm	Rear Right Side:	Dunlop 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,406.32	3,149.42	2,256.90	41.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,890.00	1,570.00	45.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,866.32</b>	<b>5,039.42</b>	<b>3,826.90</b>	<b>43.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,866.32</b>	<b>4,000.00</b>	<b>4,866.32</b>	<b>54.89</b>

### INSPECTION

Date of Assignment: 08/05/2019

Date Inspected: 08/05/2019 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)  
25 Kaki Bukit Road 4, #01-49  
Synergy@KB  
Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 15 May 2019)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GZ8022P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent / Dented	1,465.60 FL	*1,465.60 FL
2	2		*REAR TAILGATE LOCK HINGES	Repair	290.00 FL	*- FL
3	1		*REAR TAILGATE LOWER PANEL	Bent / Dented	878.50 FL	*878.50 FL
4	1		*REAR TAILGATE LOWER STOPPER RUBBERS	N/S Torn	145.20 FL	*72.60 FL
5	1		*REAR TAILGATE LOWER STOPPER BRACKETS	N/S Bent	213.00 FL	*106.50 FL
6	1		*REAR TAILLAMPS	N/S Broken	679.40 FL	*339.70 FL
7	1		*REAR TAILLAMP PANELS	N/S Bent	599.00 FL	*299.50 FL
8	1		*REAR NUMBER PLATE PANEL	Bent	98.50 FL	*98.50 FL
9	1		*REAR NUMBER PLATE LAMP	Not Necessary	89.70 FL	*- FL
10	1		*REAR SPARE TYRE	Not Necessary	289.70 FL	*- FL
11	1		*REAR SPARE TYRE CARRIER SUPPORT & CHAIN	Bent / Jammed	625.00 FL	*625.00 FL
12	1		*REAR EXHAUST PIPE	Not Necessary	852.60 FL	*- FL
13	1		*REAR EXHAUST MOUNTING	Not Necessary	48.90 FL	*- FL
14	1		*REAR TAILGATE 13PAX STICKER	Necessary	25.00 FS	*10.00 FS
15	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
16	1		*REAR STEP BAR	Bent	250.00 FS	*200.00 FS
17	1		*REAR NUMBER PLATE	Bent	50.00 FS	*15.00 FS
18	1		*REAR SPARE TYRE RIM	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (S\$)</b>	<b>6,975.10</b>	<b>4,120.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>1,568.78</b>	<b>971.48</b>
<b>Total Parts (S\$)</b>	<b>5,406.32</b>	<b>3,149.42</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	0.00
3	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
4	TO APPLY TUFF KOTE	New	180.00	60.00
5	PANEL BEATING	New	1,500.00	1,000.00
6	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	800.00
Gross Labour Cost (\$\$)			<b>3,460.00</b>	<b>1,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >