

Surveyor: NAZ

REF:

CC3/MSG19008138/NAH302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: 9BA2158L - MS16

Policy No. A28926340MKC

Claims No. 560468

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Secn: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: _____ % Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SG 5817R Yr Regn: 7 Jul 2018

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 c.o. 10,518

Colour: GREEN A/C: Insured / Std / Nil / NA

Sp. Reading: 126359 T/Radiq: Insured / Std / Nil / NA

Eng/No: _____

C/No: WMAA95ZZXG7003470

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SIRIm / STD / VRIm or

Tyre Siz: F: 275/70 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / CR

TOYO / YOKO or (6) FIREENZA BS CONTINENTAL

Front R/Bal. 6 mm Rear R/Bal. 6, 6 mm

L/Bal. 6 mm L/Bal. 6, 6 mm

D.O.A. 216118 U.O.I. 715/19

Survey held at SMRT WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision

INC P.P.

Date / Time	Action / Instruction
	<u>SG 5817R - X</u>
	<u>9BA 2158L - X</u>
	<u>no policy found.</u>
<u>23/7/19</u>	<u>FINALISED PART BY PART REPAIR \$962.00 / 2 REPAIR DAYS</u> <u>CRed: 700, 42%</u>

RECEIVED 24 JUL 2019

[Signature]
21/7/2019

Date/Time, File Pass to? Prelim Report

1) 24A Typist Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / (B): (\$) 962/-

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee: 150

Transportation: _____

Add Fee: Site Insp (\$ _____) S + RS _____

Interview (\$ _____) Photos _____

Tech. Invo (\$ _____) Others _____

Weekend (\$ _____)

TOTAL 161

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 7 June 2018 5:11 PM
To: 'Motor Survey'
Cc: KKLau; SUR; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD, DOA: 2/6/2018, SG 5817R (TP VEHICLE), GBA 2158L (OI VEHICLE)
Attachments: sg 5817r est.pdf; sg 5817r gia.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SG 5817R at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thanks you

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | Singapore

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/06/2018 10:34
Date Of Accident	02/06/2018 12:35
Exact Location Of Accident	JURONG WEST STREET 64 - BEF BS: 22499 -OPP BLK 662
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SG5817R
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-80000000
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MAN
Model	A95-10.5 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	
Driver	
Name of Driver	WONG WAI LONG
NRIC No	S2692089B
Date Of Birth	14/04/1966
Occupation	OUTDOOR
Date Of Driving Pass	17/06/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	20

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG JURONG WEST STREET 64 ON THE 2ND LANE HEADING TOWARDS BUS STOP 22499 (OPP BLK 662C) . WHILE PASSING THE YELLOW BOX AT THE TRAFFIC LIGHT JUNCTION, A COMMERCIAL VAN CAME OUT FROM JURONG POINT CARPARK EXIT AND COLLIDED ONTO MY BUS LEFT REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA2158L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2019

User ID : KimBock

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPAIR LEFT REAR PORTION		\$1,060.00				530			
Total Labour		\$1,060.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO PUTTY & RESPRAY		\$602.00				432			
Total Spray Painting & Panel Beating		\$602.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

NA2 LK11
 715/19 1645
 LHS PIP
 2 DAYS
 AFTER REPAIR PHOTOS

 7/6/19

1662

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2019

User ID : KimBock

Section A - Accident Details	
Registration Number	SG5817R
Case Reference Number	BUS/06/18/5007
Registration Date	6/7/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	WONG WAI LONG
Type of Accident	HEAD TO SIDE
Accident Date and Time	6/2/2018 12:35 PM
Accident Reported Date and Time	6/7/2018 10:18 AM
Is Surveyor Required?	Yes
Survey by	MSIG
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5817R - LEFT REAR PORTION GBA2158L (TP) - INSURED WITH MSIG
Prepared Date and Time	07/06/2018 10:33 AM
Chassis Number	WMAA95ZZXG7003470
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$802.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$0.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	07/05/2019 2:07 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	




SMRT Accident Vehicle Repair Breakdown

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5817R
Case Reference Number	BUS/06/18/5007
Registration Date	7/6/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	WONG WAI LONG
Type of Accident	HEAD TO SIDE
Accident Date and Time	2/6/2018 12:35 PM
Accident Reported Date and Time	7/6/2018 10:18 AM
Is Surveyor Required?	Yes
Survey by	MSIG
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101416
Special Instruction to ARC, if any	SG5817R - LEFT REAR PORTION GBA2158L (TP) - INSURED WITH MSIG
Prepared Date and Time	07/06/2018 10:33 AM
Chassis Number	WMAA95ZZXG7003470
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,662.00	\$962.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Naz
Arc / Surveyor Sign Off Date	07/05/2019 2:07 PM	07/05/2019 5:28 PM
Signature		↑
Remarks		

Section C - Quotation and Accident Case Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
--



SMRT Accident Vehicle Repair Breakdown

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : CatherineLee

Part 1 - Labour Works						
Job Scope		Quotation from AR		Adjusted by Surveyor, if applicable		
Total Labour						
Part 2 - Spray Painting & Panel Beating Related Works						
Job Scope		Quotation from ARC		Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY		\$602.00		\$432.00		
Total Spray Painting & Panel Beating		602.00		\$432.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense						
Job Scope		Quotation from ARC		Adjusted by Surveyor, if applicable		
Total Other Costs						
Part 4 - Spare Parts / Material Usage						
Part Number	Portion	Stock Number	Part Name	Quantity	Estimator Approved	Surveyor Approved
Added Spare Parts / Material Usage After Surveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	ARC Check	Surveyor Check

LABOUR \$530
 SPRAY \$432
 TOTAL \$962 1/2 DAYS

FINALIZED PART BY PART REPAIR \$962.00 / 2 REPAIR DAYS

NAZ LICK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018		10 Jun 2019 13:50 Edit Adj Rpt	S\$962.00 Edit Estimates	S\$962.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YI JIN ENTERPRISE , Co. Reg. No.: 0								
Main Claimant:	SMRT BUSES LTD , Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SG5817R	Date of Loss:	02/06/2018 12:00 - :59 [10 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560468	Policy/Cover Note No.:	A28926340MKC (TP, Fire & Theft) Coverage: 02/04/2018 - 01/04/2019						
Vehicle Reg. No. (Insured):	GBA2158L	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 11/06/2019]								
Driver/Custodian (Insured):	CHANG YONG KUI (), NRIC: S1408960H, Tel: +6597874287 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SG5817R (560468)**
[GBA2158L]
TP
SMRT BUSES LTD
Jun 2 2018 12:00PM
[YI JIN ENTERPRISE]
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser
Assessment Reports						1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print
1	10/06/19 13:04	Accident Statement <small>From:SC - Reg. No: GBA2158L, Claimant: YI JIN ENTERPRISE</small>			Load HTM	<input type="checkbox"/>
Photos/Images						3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
2	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
3	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
4	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
5	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
6	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
7	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
8	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
9	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
10	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
11	23/07/19 17:39	General View			Load JPG	<input checked="" type="checkbox"/>
12	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
13	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
14	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
15	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
16	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
17	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
18	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
19	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
20	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
21	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
22	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>
23	23/07/19 17:40	Chassis Number			Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19008138/NTD3E2

Date: 26/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28926340MKC
Claimant Vehicle No : SG5817R	Insured Vehicle No :	GBA2158L
Date of Loss: 02/06/2018	Nature of Claim:	TP
		Claim No: 560468

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5817R	Engine No:	50344561104459
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZXG7003470
Reg. Date:	04/07/2017 (Man. Year: 2016)	Odometer:	126359 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Fireza 6 mm	Rear Left Side:	Continental 6/6 mm
Front Right Side:	Fireza 6 mm	Rear Right Side:	Continental 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,662.00	962.00	700.00	42.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,662.00	962.00	700.00	42.12

INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	07/05/2019 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jul 2019)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5817R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR LEFT REAR PORTION	New	1,060.00	530.00
2	TO PUTTY & RESPRAY	New	602.00	432.00
Gross Labour Cost (S\$)			1,662.00	962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >