



Your Ref: AEMD/105/009/2019/007

Date: 15th May 2019

Our Ref: CS1/SPF19008148/K1sd3s2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(S'pore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 8545G
INSURED VEHICLE: QX 755C ACCIDENT DATE: 24/01/2019**

We thank you for your instruction on 08/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 8545G from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 8545G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 8545G
Make & Model	: Hyundai I40
Year of Registration	: 2015
Chassis Number	: KMHLB41UMFU065798
Engine Capacity	: 1685 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.