

ASS. REC. BY:

REF: CS3/CT119008173/TICd3⁵⁷

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Chong Ben Sen

of

CT1

Date/Time: 9.5.19 11.21am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMF 3685T

Insured: GBB 5783G

at Workshop m/s Blunel Automotive

Tel: 6745 2088

of Blk 1 Kati Bukit Ave 6 # 01-55

Policy No: DMCVSN30196419000

Claim No: SM19D20206802

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05. 2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9.5.19 11.40 am

Person Contacted:

Sally

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMF 3685T - X

GBB 5783G - X

After repair: 15/5/2019

Surveys REF: C72

PRS

ASSIGNMENT

From: Date: 9.5.2019

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SMF 3685 T

at Workshop n/s Blumel Automotive
of BLK 1 Kaki Bukit Ave 6 #01-55

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "OP"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMF 3685 T Yr Regn: April 06

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota A11's C.C. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading 13515 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/70R14
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.L. 9/5/140 745pm

Survey held at Blumel

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No GIA, 9600-4700, delays.

RECEIVED 20 JUN 2019

18.6.2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$))

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019		10 May 2019 13:56 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SHANGHAI KONG HUNG CHING, Co. Reg. No.: 01346300D		
Main Claimant:	RPM AUTOMOBILE LEASING LLP, Co. Reg. No.: T17LL1820G		
Vehicle Reg. No.:	SMF3685T	Date of Loss:	08/05/2019 10:00 - :59 [156 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202068C02	Policy/Cover Note No.:	DMCVSN30196419000 (Comprehensive)
Vehicle Reg. No. (Insured):	GBB5783G	Policy No. (Claimant):	5094743286-01
		Excess:	S\$0.00
Repairer:	Bluewel Automotive Service Pte Ltd (HQ) 1 KAKI BUKIT AVE 6 AUTOBAY @ KAKI BUKIT #01-28/37/53/55 SINGAPORE 417883, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/05/2019]		
Driver/Custodian (Insured):	KONG LIANG WOH (64 / Male) , NRIC: S0096679G Email:		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

ALL ASSOCIATED TASKS □

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 9 May 2019 11:21 AM
To: Igene Lim
Cc: assignments; Ong Chin Kiat
Subject: RE: PRE-REPAIR SURVEY ON SMF 3685T / OUR REF: SNM19D202068

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Igene Lim [mailto:igene.lim@mneduco.com.sg]
Sent: Thursday, 9 May, 2019 11:08 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: PRE-REPAIR SURVEY ON SMF 3685T / OUR REF: SNM19D202068

WITHOUT PREJUDICE

Our Ref: MN.IG.B1.1913061

Dear Sir

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Dear Sirs

1. We refer to your email below.
2. We are instructed by **RPM AUTOMOBILE LEASING LLP**, the claimant and/or **BLUWEL AUTOMOTIVE SERVICE PTE LTD**, the motor workshop for **SMF 3685T** that they are not agreeable to any of the motor surveyors as proposed by you.
3. **In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016)**, we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd)	6.	ANDREW HOW (Prominent Appraiser Services)
2.	MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7.	NG KONG BENG PATRICK (Carlink Consultancy)
3.	DIXON YEO (Treasure Appraisal Services)	8.	ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4.	ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)	9.	NICKY SEAH (Absolute Appraisal Services)
5.	AMAS ONG AEON Auto Consultants LLP)	10.	LOI BOON HUAN (PAR Automotive)

4. Kindly let us know **within two (2) working days** whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

With thanks & regards,

Igene

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) **6509-8480** if you have received this message in error. Thank you.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 9 May 2019 10:26 AM

To: Serene Tan <serene.tan@mneduco.com.sg>

Subject: RE: PRE-REPAIR SURVEY ON SMF 3685T / OUR REF: SNM19D202068

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
WITHOUT PREJUDICE
Our Ref: MN.IG.B1.1913061
Dear Sirs,
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Serene Tan [<mailto:serene.tan@mneduco.com.sg>]

Sent: Thursday, 9 May, 2019 9:56 AM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; LOD <lod@sg.cntaiping.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: PRE-REPAIR SURVEY ON SMF 3685T

WITHOUT PREJUDICE

Our Ref: MN.IG.B1.1913061

Dear Sirs,

Notice of Accident dated **09/05/2019** attached herein.

With thanks & regards,

Igene

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) **6509-8480** if you have received this message in error. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	1820G
Vehicle Details	
Vehicle No.:	SMF3685T
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	3ZZ4556766
Chassis No.:	MR053ZEC107116516
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,950.00
Original Registration Date:	10 Apr 2006
First Registration Date:	10 Apr 2006
Transfer Count:	5
Actual ARF Paid:	\$18,645.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$8,315.00
Total Rebate Amount:	\$8,315.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jun 2019

OK

MSME19060367 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 09/05/2019 16:46
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/05/2019 16:46
Date Of Accident 08/05/2019 10:30
Exact Location Of Accident CTE SLIP RD TO PIE KALLANG
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMF3685T
Insured/Policyholder
Name Of Registered Owner RPM AUTOMOBILE LEASING LLP
Co Reg No T17LL1820G
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No Office-67790012
Vehicle Particulars
Manufacturer TOYOTA
Model COROLLA
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5094743286-01
Cover Note Number
Driver
Name of Driver LIM SIEW HENG
NRIC No S1347200I
Date Of Birth 06/04/1959
Occupation OUTDOOR
Date Of Driving Pass 06/04/1978
Driving Experience 41 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number (LOCAL) +65-96636459

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 57 TELOK BLANGAH HEIGHTS #11-149
Postcode	100057
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELING ALONG CTE SLIP ROAD TOWARDS PIE KALLANG. THE VEHICLE IN FRONT OF ME STOP SO I STOP. VEHICLE B BEHIND ME DID NOT STOP IN TIME SO HE KNOCK ONTO THE REAR OF MY CAR A.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB5783G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KONG LIANG WOH
NRIC/Passport Number	S0096679G
Contact Number	
Address	
Postcode	

6/20/2019

E-FILE

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

RPM AUTOMOBILE LEASING LLP
 P No.: T17LL1820G
 West Coast
 31 West Coast
 Singapore
 Tel: 0017 Fax

Policyholder's Signature

Date & Time: 8/5/19, 5:15pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 8/5/19, 5:15pm

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

BUNNEL

GIA/IMC SketchPlanForm_V3

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along CTE Slip road toward PIE Kallang. The vehicle in front of me stop so I stop. Vehicle B behind me did not stop in time so he knock the rear of my car A.

RPM AUTOMOBILE LEASING LLP
 No. 71/LLT820G
 Declaration
 We declare the foregoing particulars are true in every respect.
 Singapore 17864
 Tel: 679 0012 Fax: 679 0012

Policyholder's Signature

Date & Time: 8/5/19, 5:15pm

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 8/5/19, 5:15pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

2

Sketch Plan #3

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019		10 May 2019 13:56 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SHANGHAI KONG HUNG CHING, Co. Reg. No.: 01346300D		
Main Claimant:	RPM AUTOMOBILE LEASING LLP, Co. Reg. No.: T17LL1820G		
Vehicle Reg. No.:	SMF3685T	Date of Loss:	08/05/2019 10:00 - :59 [156 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202068C02	Policy/Cover Note No.:	DMCVSN30196419000 (Comprehensive)
Vehicle Reg. No. (Insured):	GBB5783G	Policy No. (Claimant):	5094743286-01
		Excess:	S\$0.00
Repairer:	Bluewel Automotive Service Pte Ltd (HQ) 1 KAKI BUKIT AVE 6 AUTOBAY @ KAKI BUKIT #01-28/37/53/55 SINGAPORE 417883, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/05/2019]		
Driver/Custodian (Insured):	KONG LIANG WOH (64 / Male), NRIC: S0096679G Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF3685T (SNM19D202068C02)**
[GBB5783G]

TP
RPM AUTOMOBILE LEASING LLP
May 8 2019 10:00AM
[SHANGHAI KONG HUNG CHING]
Bluewel Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼






















Assessment Reports

1 per page ▼

No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	09/05/19 16:55	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
21	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
24	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
25	20/06/19 15:42	General View	 Load JPG	<input checked="" type="checkbox"/>
26	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
27	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
28	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
29	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
30	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
31	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
32	20/06/19 15:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=821602&extid=303481&... 2/3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI19008173/T1CD3S2**Date:** 04/07/2019REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30196419000
Claimant Vehicle No :	SMF3685T	Insured Vehicle No :	GBB5783G
Date of Loss:	08/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202068C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3685T	Engine No:	3ZZ4556766
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053ZEC107116516
Reg. Date:	10/04/2006 (Man. Year: 2006)	Odometer:	135159 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/70R14	Rear Tyre Size:	185/70R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/05/2019	Bluewel Automotive Service Pte Ltd (HQ) 1 KAKI BUKIT AVE 6 AUTOBAY @ KAKI BUKIT #01-28/37/53/55 SINGAPORE 417883 Singapore 417883
Date Inspected:	09/05/2019 Inspected At:	
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 04 Jul 2019)

Parts: 143 TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF3685T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >