

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Not Allowed  
H/S  
Take the other 19  
H/S  
10/5/19  
9/5/2019

M/S AXA INSURANCE SINGAPORE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR YM7000P

TO SUPPLY :

List Items

- |   |      |                                     |
|---|------|-------------------------------------|
| 1 | 1 PC | FRONT BUMPER                        |
| 2 | 1 PC | RH STEP GARNISH                     |
| 3 | 1 PC | RH WIPER GARNISH                    |
| 4 | 1 PC | FRONT RH DOOR                       |
| 5 | 1 PC | FRONT RH DOOR HINGE                 |
| 6 | 1 PC | FRONT RH DOOR WING MIRROR           |
| 7 | 1 PC | FRONT RH CORNER PANEL               |
| 8 | 1 PC | FRONT RH CORNER PANEL BLACK GARNISH |
| 9 | 1 PC | HEADLAMP RH                         |

LESS 25%

10 DOOR ARTWORK

Labour Charge

11 WIRING

12 TUFF KOTE

13 LABOUR CHARGE

14 SPRAY PAINTING

|       |    |            |     |
|-------|----|------------|-----|
| DD/24 | \$ | 549.60     | —   |
| CU    | \$ | 318.30     | —   |
| DD/CN | \$ | 286.40     | —   |
| DD/24 | \$ | 1,742.60   | —   |
| TM    | \$ | 189.60     | —   |
|       | \$ | 819.70     | ?   |
| DD    | \$ | 313.70     | —   |
| SLD   | \$ | 117.80     | —   |
| SLD   | \$ | 1,156.70   | —   |
|       | \$ | 5,494.40   |     |
|       | \$ | (1,373.60) |     |
|       | \$ | 4,120.80   |     |
| ner   | \$ | 280.00     | 200 |
|       | \$ | 30.00      | 20  |
|       | \$ | 80.00      | 50  |
|       | \$ | 880.00     | 520 |
|       | \$ | 880.00     | 600 |
|       | \$ | 6,270.80   |     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: